

SERVICE @ RIVERVIEW PTE LTD

10, Ang Mo Kio Autopoint #04-11

Ang Mo Kio Industrial Park 2A

Singapore 568047

Tel : 6481 9810 / 64814849 Fax : 6481 6256

Email : riverview@singnet.com.sg

Buss.reg.No : 200910700K

Lump Sum repair
Cen 20%

SBW 6689D

supplementary parts

Driver's seat belt

Mercedes E250

List Price

Mers Cen 10%

In 585 ✓

10%

Labour charges

801

1) To Renew & install driver's seat belt

\$150

2) To check with Mers star diagnose
Computer & clear all fault code

¹⁵⁰
\$250

7450