

155200

INS. CASE OWNER:

CC 4/LPC1900 5123, 4/10/19 LKK: IDAC:

Surveyor:

Wm... (handwritten)

DOI:

ASSIGNMENT

1/1/19 (handwritten)

Date / Time:

10/1/19 (handwritten)

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBE 533D

Claim No.:

19/10/19/05/01547

Name of Insured:

MMA NEW POUKRY PARKMOLE

Policy No.:

21AR10500562

Insured Tel No.:

HP:

Make / Model:

TOYOTA

Excess Sec II :SS

D.O.A.:

1/1/19 (handwritten)

Place of Accident:

501 JURONG WEST ST 51 CP

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

UM Kim Poh

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SJK 16194



INSRS: WSP: Ngee Tel: Liability: RMKS: seng



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/Time	STAGE	DATE / PIC
14/6/19	Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OE: After call ltr to OE:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OE	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: SS (days) Reduction: % Email Call

FINAL SETTLEMENT Date/Time: 12/7/19 Confirm with: MC Tan Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: NIL OLD REVERSED

Repair Cost: SS 2700.00

Loss of Rental (LOR): SS (days)

Loss of Use (LOU): SS 250.00 (S 50 x 5 days)

Loss of Income (LOI): SS (S x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search SS 8.00

Medical: SS -

Disbursement: SS - (e.g. Tow/ Independent)

Legal Cost SS -

Total: SS 2958.00 Global Sum SS:

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: SS 2958.00 Name 1: Ngee Seng Auto Works

Payee 2: (Strike if N.A.) SS Name 2:

Payee 3: (Strike if N.A.) SS Name 3:

COPY SENT 17/7/19

(Handwritten signature)

Surveyor: MUMS

ASSIGNMENT

From: _____ Date: 21/3/2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJX 1617 U

at Workshop m/s Ngee Eng Auto

of Blk 302 2A Ubi Rd 1 # 0150

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SJX 16174 Yr Regn: 5110

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Toyota Vios c.c 1497

Colour: Gray A/C: Insured / Std / NI / NA

Sp. Reading: 173753 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR 053H49305165944

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 16k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (wp)

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Dayton

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A. 19/3/19	D.O.I. 21/3/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	LTA 9808
	L/S - \$2700 (Red \$3541.32 / 57%)

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS, SI

Photos

Others

TOTAL



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC19005123/Uhb3

Date: 22.03.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJX1617U


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21.03.2019 at the premises of M/s Ngee seng Auto Works and have the following to report:-

Workshop Estimate Amount	: S\$	<u>6,241.30</u>
Revised Estimate Amount	: S\$	<u>3,223.80</u>
"Check" Items Amount	: S\$	<u>379.80</u>
Market Value	: S\$	<u>-</u>
LTA Reimbursement Value	: S\$	<u>-</u>
Nett Value	: S\$	<u>-</u>

Description of Damage:

The vehicle sustained damages at the
N/S Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser



NGEE SENG AUTO WORKS 誼盛摩哆

REGISTRATION NO: 52791500M

Blk. 3022A, Ubi Road 1, #01-50, Singapore 408716. Tel: 6841 2276 Fax: 6743 9006

ALL TYPES OF MOTOR REPAIRS SERVICES, SPRAY PAINTING & INSURANCE CLAIMS.

LONPAC INS BHD
100, Beach Road
#19-00, Shaw Tower
Singapore 189702

ESTIMATE : TP19004
Date : :20/03/2019
Ref No : :SJX 1617 U
Policy No.: :
Page : :01

*Not Added
note
2/5 2700/-
500/-
21/3/19
When the Accident*

RE : VEHICLE NO. SJX 1617 U TOYOTA VIOS

Qty	Description	Unit Price	Amount
1	REAR BUMPER <i>Deep cut</i>		\$466.30
1	REAR BUMPER SIDE RETAINER (FRONT) <i>cut</i>		\$75.20
1	REAR BUMPER SIDE RETAINER (REAR) <i>11</i>		\$76.20 X
1	REAR FENDER LH <i>500/500/100</i>		\$890.40
1	REAR FENDER INNER TRIM <i>11</i>		\$296.30 X
1	PETOL DOOR <i>2</i>		\$195.50 X
1	PETOL DOOR CABLE <i>11</i>		\$106.40 X
1	REAR WINDSCREEN MOULDING <i>11</i>		\$162.50
1	TAILLAMP LH <i>11</i>		\$362.30 X
	SUB TOTAL		\$2,631.10
	LESS 25 %		\$657.78
	TOTAL (1)		\$1,973.32
	SPECIAL NETT ITEM		
1	REAR BUMPER CLIPS (SET) <i>11</i>		\$48.00
1	REAR BUMPER REVERSE SENSOR w/unit <i>200</i>		\$300.00
1	WINDSCREEN SEALANT <i>11</i>		\$80.00
1	SPORT RIM <i>11</i>		\$580.00 X
	TOTAL (2)		\$1,008.00
	LABOUR		
	TO REMOVE & REFIX WINDSCREEN		\$200.00 120
	TO REMOVE & REFIX CUSHION SEAT		\$180.00 100
	TO RUST PROOF AFFECTER AREAS		\$100.00 50
	TO REMOVE & REFIX PETOL TANK		\$150.00 60
	TO REMOVE & REFIX REVERSE SENSOR		\$100.00 50
	TO REMOVE & REFIX RIM		\$80.00 X
	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT		\$150.00 60
	TO PANEL BEATING		\$1,200.00 800
	TO SPRAY PAINTING		\$1,100.00 700
	TOTAL SPARE PARTS & LABOUR CHARGES		\$3,260.00
			\$6,241.32 3423.80

Let's Auto Consultants hence notify the Receiver of the following:

LABOUR CHARGES

- To repair damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:



NGEE SENG AUTO WORKS 誼盛摩哆

REGISTRATION NO: 52791500M

Blk. 3022A, Ubi Road 1, #01-50, Singapore 408716. Tel: 6841 2276 Fax: 6743 9006

ALL TYPES OF MOTOR REPAIRS SERVICES, SPRAY PAINTING & INSURANCE CLAIMS.

LONPAC INS BHD
100, Beach Road
#19-00, Shaw Tower
Singapore 189702

*Not Added
nlr
2/5 9
5/1
21/3/19
who plus Added up*

ESTIMATE : TP19004
Date : :20/03/2019
Ref No : :SJX 1617 U
Policy No.: :
Page : :01

RE : VEHICLE NO. SJX 1617 U TOYOTA VIOS

Qty	Description	Unit Price	Amount
1	REAR BUMPER <i>Deep cut</i>		\$466.30
1	REAR BUMPER SIDE RETAINER (FRONT) <i>cut</i>		\$75.20
1	REAR BUMPER SIDE RETAINER (REAR) <i>nlr</i>		\$76.20 X
1	REAR FENDER LH. <i>500/500/100</i>		\$890.40
1	REAR FENDER INNER TRIM <i>nlr</i>		\$296.30 X
1	PETOL DOOR <i>nlr</i>		\$195.50 X
1	PETOL DOOR CABLE		\$106.40 ?
1	REAR WINDSCREEN MOULDING <i>nlr</i>		\$162.50 ✓
1	TAILLAMP LH <i>nlr</i>		\$362.30 X
	SUB TOTAL		\$2,631.10
	LESS 25 %		\$657.78
	TOTAL (1)		\$1,973.32
	SPECIAL NETT ITEM		
1	REAR BUMPER CLIPS (SET) <i>nlr</i>		\$48.00 ✓
1	REAR BUMPER REVERSE SENSOR w/unit		\$300.00 ?
1	WINDSCREEN SEALANT <i>nlr</i>		\$80.00 40
1	SPORT RIM <i>nlr</i>		\$580.00 X
	TOTAL (2)		\$1,008.00
	LABOUR		
	TO REMOVE & REFIX WINDSCREEN		\$200.00 120
	TO REMOVE & REFIX CUSHION SEAT		\$180.00 100
	TO RUST PROOF AFFECTER AREAS		\$100.00 50
	TO REMOVE & REFIX PETOL TANK		\$150.00 60
	TO REMOVE & REFIX REVERSE SENSOR		\$100.00 50
	TO REMOVE & REFIX RIM		\$80.00 X
	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT		\$150.00 60
	TO PANEL BEATING		\$1,200.00 800
	TO SPRAY PAINTING		\$1,100.00 700
	LABOUR CHARGES		\$3,260.00
	TOTAL SPARE PARTS & LABOUR CHARGES		\$6,241.32

LONPAC Insurance Company
 The Pricer Group of Companies
 • To be used for repair only
 • To be used for damaged parts during a survey
 • Parts prices are subject to confirmation
 • This party survey is on a "Without Prejudice" basis
 • No legal modification(s) is allowed
 • Supplemental work(s) must be reapproved and is subject to final approval from Insurance Company
 Acknowledged by (Repairer)
 Signature:

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 20 March 2019 2:52 PM
To: assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: ACCIDENT INVOLVING GBE533D & SJX1617U ON 19.3.2019 [External Confidential]
Attachments: 20032019143738.pdf

3.40pm 20/3/19
Mr. Ng

Lonpac External - Confidential

Our Ref : 19/19/19/VC05/021547

Dear Nivitha,

Please see attached and proceed with the survey.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

W



LONPAC INSURANCE BHD(S98FC5635C)

300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel No.62507388 Fax No.62962706

To : Date : 20/3/2019
Company : Ngee Seng Auto Works Fax No : 67439006
From : Gerald No.of pages :
Our Ref : 19/19/19/VC05/021547
Your Ref :

**WITHOUT PREJUDICE
SAVE AS TO COSTS**

If copies are not well received, please call us immediately

ACCIDENT INVOLVING SJX1617U & GBE533D ON 19.3.2019

We refer to your fax of 20 March 2019.

We intend to conduct a pre-repair survey of your client's vehicle and enclose a list of motor surveyors from LKK Auto Consultants Pte Ltd.

Please revert.

Yours faithfully

Gerald Poh
Senior Executive (Claims)
Email : mt_claim@lonpac.com

LKK Auto Consultants Pte Ltd

No.	Name of Surveyor	Please tick
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Mohammed Rasul	
5	Adrian Ling	
6	Marcus Chua	✓
7	Kenneth Kong	
8	Bryan Ang	
9	Muhammad Nazril Bin Abdullah	
10	Ong Hwee Jie	
11	Steve Chen	



NGEE SENG AUTO WORKS 誼盛摩哆

REGISTRATION NO: 52791500M

Blk. 3022A, Ubi Road 1, #01-50, Singapore 408716. Tel: 6841 2276 Fax: 6743 9006

ALL TYPES OF MOTOR REPAIRS SERVICES, SPRAY PAINTING & INSURANCE CLAIMS.

LONPAC INS BHD
100 Beach Road
#19-00, Shaw Tower
Singapore 189702

021547



Your Ref : GBE 533 D
Our Ref : SJX 1617 U
Date : 20-03-2019

Dear Sir / Mdm,

NOTIFICATION OF ACCIDENT

ACCIDENT INVOLVING: GBE 533 D ALONG CARPARK OF
BLK 504 JURONG WEST ST. 51 ON 19-03-2019

We act for LIM YEOW CHONG, in the accident above.

Please note that our client's motor vehicle SJX 1617 U is now at the following workshop .

M/s Ngee Seng Auto Works
Blk 3022A Ubi Road 1
#01-50 Singapore 408716

Contact Person: Mr. Ng 96319168

PLEASE NOTE that if you fail to carry out pre-repair inspection or waive the pre-accident inspection within 2 days from the receipt of this Notice, our client may proceed to have his motor vehicle repaired.

Please give us written notice of the completion of pre-repair inspection or waivers as the cases may be to facilitate the repairs which can only commence after receipt of the written notice.

Yours faithfully



NGEE SENG AUTO WORKS




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC19005123/Udb3s2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 19-07-2019	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	GBE 533D	Veh. Inspected
	Policy No.	Z19VC05001542	Coverage (\$)
	Claim No.	19/19/19/VC05/021547	Excess (\$)
	Assign From	GERALD POH	Assign Date
			20/03/2019
2. Vehicle Particulars & Condition			
	Make & Model	TOYOTA VIOS (A)	c.c
	Engine No.	HIDDEN	Year of Reg.
	Chassis No.	MR053HY9305165944	Colour
	Odometer	173153	Steering
	Brakes	IN ORDER	Modification
	General	GOOD	SPORTS RIM
3. Conditions of Tyres			
		Size	Make
	R/H Front Tyre	185/60R15	DAYTON
	L/H Front Tyre	185/60R15	DAYTON
	R/H Rear Tyre	185/60R15	DAYTON
	L/H Rear Tyre	185/60R15	DAYTON
			Balance
			6 mm
			6 mm
			6 mm
			6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
	Accident Date	19/03/2019	Inspection Date
	Survey held at	NGEE SENG AUTO WORKS BLK. 3022A, UBI ROAD 1, #01-50 SINGAPORE 408716.	
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.			
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 1617U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEEP CUT	466.30	466.30
1	REAR BUMPER SIDE RETAINER (FRONT)	BENT	75.20	75.20
1	REAR BUMPER SIDE RETAINER (REAR)	NOT NECESSARY	76.20	-
1	REAR FENDER LH	BADLY DENTED / CRACKED	890.40	890.40
1	REAR FENDER INNER TRIM	NOT NECESSARY	296.30	-
1	PETROL DOOR	TO REPAIR SEE LABOUR	195.50	-
1	PETROL DOOR CABLE	NOT NECESSARY	106.40	-
1	REAR WINDSCREEN MOULDING	NECESSARY	162.50	162.50
1	TAILLAMP LH	NOT NECESSARY	362.30	-
	LESS 25% DISCOUNT		-657.78	-398.60
			1,973.32	1,195.80
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	REAR BUMPER REVERSE SENSOR W/UNIT (SN)	DAMAGED	300.00	200.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	SPORT RIM (SN)	NOT NECESSARY	580.00	-
			1,008.00	288.00
<u>LABOUR</u>				
	TO REMOVE & REFIX WINDSCREEN.		200.00	120.00
	TO REMOVE & REFIX CUSHION SEAT.		180.00	100.00
	TO RUST PROOF AFFECTED AREAS.		100.00	50.00
	TO REMOVE & REFIX PETROL TANK.		150.00	60.00
	TO REMOVE & REFIX REVERSE SENSOR.		100.00	50.00
	TO REMOVE & REFIX RIM.	NOT NECESSARY	80.00	-
	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT.		150.00	60.00
	TO PANEL BEATING. INCLUSIVE OF THE REPAIR OF PETROL DOOR.		1,200.00	800.00
	TO SPRAY PAINTING.		1,100.00	700.00
			3,260.00	1,940.00

Report Ref No. CC4/LPC19005123/Udb3s2



GRAND TOTAL		6,241.32	3,423.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,700.00

Report Ref No. CC4/LPC19005123/Udb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.