



NGEE SENG AUTO WORKS 誼盛摩哆

REGISTRATION NO: 52791500M

Blk. 3022A, Ubi Road 1, #01-50, Singapore 408716. Tel: 6841 2276 Fax: 6743 9006

ALL TYPES OF MOTOR REPAIRS SERVICES, SPRAY PAINTING & INSURANCE CLAIMS.

LONPAC INS BHD

100, Beach Road

#19-00, Shaw Tower

Singapore 189702

ESTIMATE :TP19004

Date : :20/03/2019

Ref No : :SJX 1617 U

Policy No.: :

Page :01

RE : VEHICLE NO. SJX 1617 U TOYOTA VIOS

*not added
n/a
h/s
21/3/19
who the other rep*

Qty	Description	Unit Price	Amount
1	REAR BUMPER <i>Deep cut</i>		\$466.30
1	REAR BUMPER SIDE RETAINER (FRONT) <i>cut</i>		\$75.20
1	REAR BUMPER SIDE RETAINER (REAR) <i>n/a</i>		\$76.20 X
1	REAR FENDER LH. <i>500/500/cut</i>		\$890.40
1	REAR FENDER INNER TRIM <i>n/a</i>		\$296.30 X
<i>petrol</i>	1 PETOL DOOR <i>2</i>		\$195.50 X
<i>petrol</i>	1 PETOL DOOR CABLE		\$106.40 ?
1	REAR WINDSCREEN MOULDING <i>new</i>		\$162.50 ✓
1	TAILLAMP LH <i>n/a</i>		\$362.30 X
SUB TOTAL			\$2,631.10
LESS 25 %			\$657.78
TOTAL (1)			\$1,973.32
SPECIAL NETT ITEM			
1	REAR BUMPER CLIPS (SET) <i>new</i>		\$48.00 ✓
1	REAR BUMPER REVERSE SENSOR <i>w/unit</i>		\$300.00 ?
1	WINDSCREEN SEALANT <i>new</i>		\$80.00 40
1	SPORT RIM <i>11</i>		\$580.00 X
TOTAL (2)			\$1,008.00
LABOUR			
TO REMOVE & REFIX WINDSCREEN			\$200.00 120
TO REMOVE & REFIX CUSHION SEAT			\$180.00 100
TO RUST PROOF AFFECTER AREAS			\$100.00 50
TO REMOVE & REFIX PETOL TANK			\$150.00 60
TO REMOVE & REFIX REVERSE SENSOR			\$100.00 50
TO REMOVE & REFIX RIM			\$80.00 2
TO CONDUCT COMPUTERISED WHEEL ALIGNMENT			\$150.00 60
TO PANEL BEATING			\$1,200.00 800
TO SPRAY PAINTING			\$1,100.00 700
TOTAL SPARE PARTS & LABOUR CHARGES			\$3,260.00
			\$6,241.32

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey the repairer's work
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: