

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 17 Jun 2019

Preliminary Advice

Vehicle No	: SLA4515H	Accident Date	: 16/03/2019
Make	: TOYOTA HARRIER	Policy No.	: D19MTPV01003094
Assignment Date	: 21/03/2019	Excess	: S\$0.00
Date of Inspection	: 22/03/2019	Est. Duration of Repair	: 4 days
Inspection At	: Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,248.40 (inclusive supplementary)
Revised Amount	:S\$	3,422.30 (inclusive supplementary)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,422.30

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	92,000.00
COE / PARF Rebate	:S\$	57,071.00
Salvage Value	:S\$	
Margin for Repair	:S\$	34,929.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :