

Surveyor

Kenneth

## ASSIGNMENT (Office)

From (Person): Goh Pau Loong

of SMO

Date/Time: 21.3.19 13:37 pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLA 45154

Insured:

at Workshop n/s Ah Lim Motor Company

Tel: 6483 1244

of 10 Ang Mo Kio Industrial Park 2A # 01-09

Policy No: D19MTPV01003094

Claim No: CM7D1901327

Sum Insured:

Excess:

waived

Make of Veh:

D.O.A. 16.3.2019

(Client's Record)

22.3.2019 (10:30a.m)

CA REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 21.3.19 2.15pm

Person Contacted:

zila

Vehicle IN/OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|---------------------------------|
|           | SLA 45154 - X                   |
| 17/6      | \$ 3422.30 Cash                 |
|           | ( \$ 1,826.10 Red - 35% )       |
|           |                                 |
|           |                                 |

REF: SMO

## ASSIGNMENT

From:

Date: 22/3/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No

SLA 4515H

at Workshop m/s

Ah Lim Motor

of 10 AMK Ind. Park 2A #01-09

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

Waived \$/-

(Client's Record)

Make of Veh:

10-30cm  
(cracking)

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

852/c

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.:

Yes or No

Lump Sum:

1-B.1

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLA 4515H Yr Regn: 03, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy / Harrier

C.C.

1986

Colour:

M. Black

A/C

Insured / Std / NI / NA

Sp. Reading:

99168

T/Radio: Insured / Std / NI / NA

Eng/No:

ZS460 0072553

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/55R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

16/3/19

D.O.I.

22/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED: 8 JUN 2019

Date/Time, File Pass to?

18/06/19

1)

Type

Date/Time, File Return to?

2)

☐

: Prefl. Report

☒

: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation

S + R/S

Photos

Others

TOTAL

250

11

261

Report Format :

Lump Sum (I.B.) \$ 3,422.30 p/c

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: GNOH PAU LOONG

Date: 25 Mar 2019

## Preliminary Advice

|                    |                                                                                                            |                         |                   |
|--------------------|------------------------------------------------------------------------------------------------------------|-------------------------|-------------------|
| Vehicle No         | : SLA4515H                                                                                                 | Accident Date           | : 16/03/2019      |
| Make               | : TOYOTA HARRIER                                                                                           | Policy No.              | : D19MTPV01003094 |
| Assignment Date    | : 21/03/2019                                                                                               | Excess                  | : S\$0.00         |
| Date of Inspection | : 22/03/2019                                                                                               | Est. Duration of Repair | : 4 days          |
| Inspection At      | : Ah Lim Motor Company (AMK)<br>10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint<br>Singapore 568047 |                         |                   |

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 5,091.10 |
| Revised Amount              | :S\$ | 1,913.00 |
| Check Items (Estimated)     | :S\$ | 2,606.60 |
| Total                       | :S\$ | 4,519.60 |
| Lump Sum Repair             | :S\$ |          |

### Total Loss Consideration

|                    |      |           |
|--------------------|------|-----------|
| New for Old Value  | :S\$ |           |
| Pre-Accident Value | :S\$ | 92,000.00 |
| COE / PARF Rebate  | :S\$ | 57,071.00 |
| Salvage Value      | :S\$ |           |
| Margin for Repair  | :S\$ | 34,929.00 |

### Remarks

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: GNOH PAU LOONG

Date: 17 Jun 2019

**Preliminary Advice**

|                    |                                                                                                            |                         |                   |
|--------------------|------------------------------------------------------------------------------------------------------------|-------------------------|-------------------|
| Vehicle No         | : SLA4515H                                                                                                 | Accident Date           | : 16/03/2019      |
| Make               | : TOYOTA HARRIER                                                                                           | Policy No.              | : D19MTPV01003094 |
| Assignment Date    | : 21/03/2019                                                                                               | Excess                  | : S\$0.00         |
| Date of Inspection | : 22/03/2019                                                                                               | Est. Duration of Repair | : 4 days          |
| Inspection At      | : Ah Lim Motor Company (AMK)<br>10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint<br>Singapore 568047 |                         |                   |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

|                             |      |                                    |
|-----------------------------|------|------------------------------------|
| Repairer's Estimate (Gross) | :S\$ | 5,248.40 (inclusive supplementary) |
| Revised Amount              | :S\$ | 3,422.30 (inclusive supplementary) |
| Check Items (Estimated)     | :S\$ | 0.00                               |
| Total                       | :S\$ | 3,422.30                           |
| Lump Sum Repair             | :S\$ |                                    |

**Total Loss Consideration**

|                    |      |           |
|--------------------|------|-----------|
| New for Old Value  | :S\$ |           |
| Pre-Accident Value | :S\$ | 92,000.00 |
| COE / PARF Rebate  | :S\$ | 57,071.00 |
| Salvage Value      | :S\$ |           |
| Margin for Repair  | :S\$ | 34,929.00 |

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

| Case | Notified                    | Est Submitted                       | Adj Assigned                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status                               |
|------|-----------------------------|-------------------------------------|--------------------------------|---------|---------------|------------|--------------------------------------|
| Main | 18 Mar 2019<br>Sendback Est | 20 Mar 2019<br>10:58<br>\$55,091.10 | 21 Mar 2019<br>13:37<br>Assign |         |               |            | <b>New Assignment</b><br>Cancel Case |

| Main                             | Reference                                                                                                             | Claim Details                                                  | Documents                                                                       | Show All                          |                          |             |              |            |       |
|----------------------------------|-----------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|---------------------------------------------------------------------------------|-----------------------------------|--------------------------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b>   |                                                                                                                       |                                                                |                                                                                 |                                   |                          |             |              |            |       |
| Insured:                         |                                                                                                                       | MUHAMMAD BASHIR BIN AZAM KHAN, ID: S6933442C, Tel: +6593859452 |                                                                                 |                                   |                          |             |              |            |       |
| Vehicle Reg. No.:                | SLA4515H                                                                                                              | Date of Loss:                                                  | 16/03/2019 07:00 - :59<br>[36 Months and 15 Days From<br>LTA Reg Date (Man Yr)] |                                   |                          |             |              |            |       |
| Claim Type:                      | OD / CMTD1901387                                                                                                      | Policy/Cover Note No.:                                         | D19MTPV01003094<br>(Comprehensive)                                              |                                   |                          |             |              |            |       |
|                                  |                                                                                                                       | Excess:                                                        | \$40.00                                                                         |                                   |                          |             |              |            |       |
| Repairer:                        | Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244 |                                                                |                                                                                 |                                   |                          |             |              |            |       |
| Handling Insurer:                | Sampo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]                  |                                                                |                                                                                 |                                   |                          |             |              |            |       |
| Adjuster:                        | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/04/2019]                                     |                                                                |                                                                                 |                                   |                          |             |              |            |       |
| Driver/Custodian:                | AMIR KHAN (52 / Male), NRIC: S1738682D, Tel: +6590612708 Email: NOEMAIL                                               |                                                                |                                                                                 |                                   |                          |             |              |            |       |
| Adj Asg. Remarks:                | - VEH CMG TMR 22/03/19 - EXCESS WAIVED - TO AUTHORISE IF CONSISTENT                                                   |                                                                |                                                                                 |                                   |                          |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b>  |                                                                                                                       |                                                                |                                                                                 |                                   |                          |             |              |            |       |
|                                  |                                                                                                                       |                                                                | <a href="#">View All</a>                                                        | <a href="#">Compose Case Mail</a> |                          |             |              |            |       |
| There are no mail for this case. |                                                                                                                       |                                                                |                                                                                 |                                   |                          |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b>      |                                                                                                                       |                                                                |                                                                                 |                                   |                          |             |              |            |       |
|                                  |                                                                                                                       | <a href="#">View All</a>                                       | <a href="#">Search Tasks</a>                                                    | <a href="#">Create New Task</a>   | <a href="#">Complete</a> |             |              |            |       |
| Due Date                         | Priority                                                                                                              | Type                                                           | Task Group                                                                      | Subject                           | Handler                  | Assigned By | Completed On | Created On | Done? |
| No results.                      |                                                                                                                       |                                                                |                                                                                 |                                   |                          |             |              |            |       |

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Tuesday, 18 June 2019 3:19 PM  
**To:** 'Mui Hong @ Ah Lim Motor'  
**Subject:** RE: Draft Finalisation - SLA4515H

Dear Mui Hong,

Confirmed final fig of \$ 3,422.30 (part by part) @ 4 days of repairs before excess \$ 0/- & GST.

Final invoice and all supporting documents sent over to Sompoo Insurance Singapore Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Mui Hong @ Ah Lim Motor [mailto:[muihong@ahlimmotor.com.sg](mailto:muihong@ahlimmotor.com.sg)]  
**Sent:** Friday, 14 June 2019 5:23 PM  
**To:** ShirleyHiew@lkkauto.com  
**Subject:** FW: Draft Finalisation - SLA4515H

Resend

Best Regards,

Kee Mui Hong  
Ah Lim Motor @ AMK  
10, Ang Mo Kio Industrial Park 2A  
#01-09 AMK Autopoint S568047  
Tel : 6483 1244 Fax : 6483 6170

---

**From:** Mui Hong @ Ah Lim Motor  
**Sent:** Monday, 27 May 2019 3:34 PM  
**To:** 'Kennethkong@lkkauto.com' <[Kennethkong@lkkauto.com](mailto:Kennethkong@lkkauto.com)>  
**Subject:** Draft Finalisation - SLA4515H

Dear Kenneth,

Pls see attached the Draft Finalisation - SLA4515H for your approval

Pls advise

Best Regards,

Kee Mui Hong  
Ah Lim Motor @ AMK  
10, Ang Mo Kio Industrial Park 2A

## View Received Message

This mail is associated with :

**SLA4515H (CMTD1901387)**

OD

Mar 16 2019 7:00AM

[MUHAMMAD BASHIR BIN AZAM KHAN]

Ah Lim Motor Company

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** Sampo Insurance Singapore Pte. Ltd. (SOMPO\_SG), sent on 17/06/2019 10:56 AM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$3422.30) - SLA4515H - Claim Handler: GNOH PAU LOONG

Approved:3422.30.

### DOCUMENTS SUMMARY

There are no documents.

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

|                |                |
|----------------|----------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID:      | 3442C          |

### Vehicle Details

|                                     |                                       |
|-------------------------------------|---------------------------------------|
| Vehicle No.:                        | SLA4515H                              |
| Vehicle to be Exported:             | No                                    |
| Intended Deregistration Date:       | 16 Mar 2019                           |
| Vehicle Make:                       | TOYOTA                                |
| Vehicle Model:                      | HARRIER PREMIUM 2.0 A                 |
| Primary Colour:                     | Black                                 |
| Manufacturing Year:                 | 2015                                  |
| Engine No.:                         | 3ZRB730483                            |
| Chassis No.:                        | ZSU600072553                          |
| Maximum Power Output:               | 111.0 kW (148 bhp)                    |
| Open Market Value:                  | \$30,475.00                           |
| Original Registration Date:         | 01 Mar 2016                           |
| First Registration Date:            | 01 Mar 2016                           |
| Transfer Count:                     | 0                                     |
| Actual ARF Paid:                    | \$29,665.00                           |
| <b>Intended PARF Rebate Details</b> |                                       |
| PARF Eligibility:                   | Yes                                   |
| PARF Eligibility Expiry Date:       | 28 Feb 2026                           |
| PARF Rebate Amount:                 | \$22,248.00                           |
| <b>Intended COE Rebate Details</b>  |                                       |
| COE Expiry Date:                    | 28 Feb 2026                           |
| COE Category:                       | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years):                  | 10                                    |
| QP Paid:                            | \$50,089.00                           |
| COE Rebate Amount:                  | \$34,823.00                           |
| <b>Total Rebate Amount:</b>         | <b>\$57,071.00</b>                    |

The information contained herein is correct as at 16 Mar 2019

OK

# AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A  
 #01-09 AMK AUTOPOINT Singapore 568047  
 Tel: 6483 1244 Fax: 6483 6170 Email: ahlmmc@singnet.com.sg  
 GST Reg No: M9-0009639-E

**SURVEYOR COPY**

INSURER: Sompoo Insurance Singapore Pte. Ltd. (HQ)

## PARTICULARS OF CLAIM

|                               |                                    |                       |              |
|-------------------------------|------------------------------------|-----------------------|--------------|
| Claim Type:                   | OD (OWN DAMAGE)                    | Ref. No:              |              |
| Policy No:                    | D19MTPV01003094                    | Date of Loss:         | 16/03/2019   |
| Vehicle Reg. No.:             | SLA4515H                           | Driveable?            |              |
| Driver Age/Info:              | 52 / MALE                          | Party At Fault:       | UNKNOWN      |
| TP Injury Involved?           | NO                                 | Third Party Involved? | YES          |
| Insured/Claimant:             | MUHAMMAD BASHIR BIN AZAM KHAN      | Contact No:           | +6593859452  |
| Driver:                       | AMIR KHAN                          |                       |              |
| Make/Model:                   | TOYOTA HARRIER, 2.0 PREMIUM (A)    | Vehicle Reg. Date:    | 01/03/2016   |
| Vehicle Colour:               | BLACK                              |                       |              |
| Engine No:                    | 3ZRB730483                         | Chassis No:           | ZSU600072553 |
| Odometer:                     | 0 KM                               |                       |              |
| Paint Type:                   |                                    |                       |              |
| Total Loss?                   | NO                                 |                       |              |
| Est. Duration of Repair (day) | 5-7 days                           |                       |              |
| Description of Accident/Loss  | REFER TO THE SKETCH PLAN BY DRIVER |                       |              |
| Remarks:                      | CAR NOT IN - TO BE ARRANGE         |                       |              |
| Present Location:             | AH LIM MOTOR COMPANY (AMK)         |                       |              |

## COST OF CLAIMS

|                           | Amount          |
|---------------------------|-----------------|
| Parts                     | 3,611.10        |
| Miscellaneous Items       | 0.00            |
| Labour                    | 1,480.00        |
| Paintwork Labour          | 0.00            |
| Towing                    | 0.00            |
| <b>Gross Total (\$\$)</b> | <b>5,091.10</b> |
| <b>+ GST 7.00% (\$\$)</b> | <b>356.38</b>   |
| <b>Nett Amount (\$\$)</b> | <b>5,447.48</b> |

This claim is handled by: ZILA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Mar 2019)

Parts: M1-SUV TOYOTA HARRIER 2.0 Premium (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ah Lim Motor Company/SLA4515H/20/03/2019 10:58

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

| No. | Qty | Part No. | Particulars                               | %Disc | %Depr | Amount      |    |
|-----|-----|----------|-------------------------------------------|-------|-------|-------------|----|
| 1   | 1   |          | *FRONT BONNET OUTER CHROME MOUDLING       | 0.00  | 0.00  | *105.00 F   | X  |
| 2   | 1   |          | *FRONT GRILLE ASSY                        | 0.00  | 0.00  | *180.00 F   | -  |
| 3   | 8   |          | *FRONT GRILLE CLIPS                       | 0.00  | 0.00  | *8.00 F     | +  |
| 4   | 2   |          | *HEADLAMP WITH HID                        | 0.00  | 0.00  | *1,800.00 F | 2+ |
| 5   | 4   |          | *HEADLAMP CLIPS                           | 0.00  | 0.00  | *6.00 F     | X  |
| 6   | 1   |          | *FRONT BUMPER                             | 0.00  | 0.00  | *250.00 F   | ✓  |
| 7   | 1   |          | *FRONT BUMPER SIDE RETAINER LH            | 0.00  | 0.00  | *35.00 F    | ✓  |
| 8   | 12  |          | *FRONT BUMPER CLIPS                       | 0.00  | 0.00  | *12.00 F    | X  |
| 9   | 1   |          | *FRONT BUMPER SPONGE                      | 0.00  | 0.00  | *40.00 F    | 2  |
| 10  | 1   |          | *FRONT BUMPER REINFORCEMENT               | 0.00  | 0.00  | *130.00 F   | X  |
| 11  | 1   |          | *FRONT BUMPER LOWER AIR GRILLE            | 0.00  | 0.00  | *90.00 F    | 2  |
| 12  | 1   |          | *FRONT BUMPER LOWER LIP BLACK             | 0.00  | 0.00  | *125.00 F   | 2  |
| 13  | 1   |          | *FOGLAMP LH                               | 0.00  | 0.00  | *100.00 F   | X  |
| 14  | 1   |          | *FOGLAMP OUTER COVER LH                   | 0.00  | 0.00  | *60.00 F    | X  |
| 15  | 1   |          | *FRONT FENDER LH                          | 0.00  | 0.00  | *280.00 F   | ✓  |
| 16  | 10  |          | *FRONT FENDER COWLING CLIPS               | 0.00  | 0.00  | *15.00 F    | X  |
| 17  | 10  |          | *RADIATOR SUPPORT PANEL TOP GARNISH CLIPS | 0.00  | 0.00  | *15.00 F    | X  |
| 18  | 1   |          | *NUMBER PLATE                             | 0.00  | 0.00  | *35.00 FS   | ✓  |

F=Franchise part. S=SpcNett.

Sub Total (S\$) 3,286.00  
 + Margin on L,N Items 10.00% (S\$) 325.10

Total Parts (S\$) 3,611.10

Ah Lim Motor Company/SLA4515H/20/03/2019 10:58. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

| No                      | Particulars                                                                                                                                                                           | Lab.Type | Amount            |
|-------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-------------------|
| <u>Labour Items</u>     |                                                                                                                                                                                       |          |                   |
| 1                       | TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.                           | New      | 40.00 <i>20</i>   |
| 2                       | TO RESET HEADLAMP HID;ENGINE LIGHT                                                                                                                                                    | New      | 180.00 <i>120</i> |
| 3                       | TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD FRONT BUMPER REINFORCEMENT.TO KNOCK & REPAIR FRON DOO RLH;FRONT BONNET INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME. | New      | <i>400</i> 540.00 |
| 4                       | TO SPRAY FRONT BONNET;FRONT DOOR LH;FRONT BUMPER;FRONT BUMPER REINFORCEMENT.                                                                                                          | New      | <i>600</i> 720.00 |
| Gross Labour Cost (S\$) |                                                                                                                                                                                       |          | <u>1,480.00</u>   |

Ah Lim Motor Company/SLA4515H/20/03/2019 10:58. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

# AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A  
#01-09 AMK AUTOPOINT Singapore 568047  
Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST Reg No: M9-0009639-E

## (SUPPLEMENTARY)

INSURER: Sompoo Insurance Singapore Pte. Ltd. (HQ)

### PARTICULARS OF CLAIM

|                     |                               |                       |             |
|---------------------|-------------------------------|-----------------------|-------------|
| Claim Type:         | OD (Own Damage)               | Ref. No:              |             |
| Policy No:          | D19MTPV01003094               | Date of Loss:         | 16/03/2019  |
| Vehicle Reg. No.:   | SLA4515H                      | Driveable?            |             |
| Driver Age/Info:    | 52 / MALE                     | Party At Fault:       | UNKNOWN     |
| TP Injury Involved? | NO                            | Third Party Involved? | YES         |
| Insured/Claimant:   | MUHAMMAD BASHIR BIN AZAM KHAN | Contact No:           | +6593859452 |
| Driver:             | AMIR KHAN                     |                       |             |

|                 |                                 |                    |              |
|-----------------|---------------------------------|--------------------|--------------|
| Make/Model:     | TOYOTA HARRIER, 2.0 Premium (A) | Vehicle Reg. Date: | 01/03/2016   |
| Vehicle Colour: | Black                           |                    |              |
| Engine No:      | 3ZRB730483                      | Chassis No:        | ZSU600072553 |
| Odometer:       | 0 KM                            |                    |              |

Paint Type:  
Total Loss? **NO**  
Est. Duration of Repair (day) 5

Description of Accident/Loss REFER TO THE SKETCH PLAN BY DRIVER  
Present Location: AH LIM MOTOR COMPANY (AMK)

### COST OF CLAIMS

|                                   |                 |
|-----------------------------------|-----------------|
| Parts                             | 157.30          |
| Miscellaneous Items               | 0.00            |
| Labour                            | 0.00            |
| Paintwork Labour                  | 0.00            |
| Towing                            | 0.00            |
| <b>Gross Total (S\$)</b>          | <b>157.30</b>   |
| <b>+ GST 7.00% (S\$)</b>          | <b>11.01</b>    |
| <b>Nett Amount (S\$)</b>          | <b>168.31</b>   |
| <b>+ Previous Estimates (S\$)</b> | <b>5,447.48</b> |
| <b>Claim Total (S\$)</b>          | <b>5,615.79</b> |

## Reference

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

Ah Lim Motor Company/SLA4515H/28/03/2019 09:53. Not valid without Reference section.  
Generated using Merlimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

There are no labour items selected.

Ah Lim Motor Company/SLA4515H/28/03/2019 09:53. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LIK Asio Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

AH LIM MOTOR COMPANY

\*10 ANG MO KIO PARKS 2A

#01-09 AMK AUTO POINT

SINGAPORE 568047

TEL: 64831244 FAX: 64836170

ATTN: SIMON 96205405

WINDSHIELD GLASS  
Dept Direct: 6417 9791 / 6745 9628



Dept Direct: 6205 9610

Dept Direct: 6205 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),  
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201903-13149

DATE : 27/03/2019

CUSTOMER ID : AHL008

VEH REG. NO. : SLA4515H

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

| SQ | STOCKID                       | DESCRIPTION             | StkLoc         | QTY | U/PRICE | AMOUNT |
|----|-------------------------------|-------------------------|----------------|-----|---------|--------|
| 1. | T53112-48150<br>ZSU60 AVU65   | FRT BUMPER LWR GRILL    | U1<br>L3-O2    | 1   | 90.00   | 90.00  |
| 2. | T52614-48040/1<br>ZSU60 AVU65 | FRT BUMPER SPONGE       | U1<br>L2-P2    | 1   | 40.00   | 40.00  |
| 3. | T52538-48010<br>ZSU60 AVU65   | FRT BUMPER TOP BEAM L.H | U1<br>SUPPLIER | 1   | 48.00   | 48.00  |
| 4. | T52411-48020<br>ZSU60 AVU65   | FRT BUMPER LWR SKIRT    | U1<br>SUPPLIER | 1   | 125.00  | 125.00 |

Page 2

SUB-TOTAL : 303.00  
ADD GST 7.00 % 21.21

E. & O.E TOTAL AMOUNT SGD : 324.21

[P] 27/03/2019 9:42:42AM

[E] 27/03/2019 9:29:59AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : STEVEN

This is computer generated document.

No signature is required.



\*AR201903-13149\*

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS  
Dept Direct: 6417 9791 / 6745 9026

Arrange By

1/2/2019

*SPM*



Dept Direct: 6200 9616

Dept Direct: 6305 9011

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY  
10 ANG MO KIO PARKS 2A  
#01-09 AMK AUTO POINT

SINGAPORE 568047  
TEL: 64831244 FAX: 64836170  
ATTN: SIMON 96205405

TAX INVOICE : AR201903-12897  
DATE : 26/03/2019  
CUSTOMER ID : AHL008  
VEH REG. NO. : SLA4515H  
TERMS : 30 days  
PO NO. :  
PAGE NO. : Page 1 of 1  
CURR : SGD

| SQ | STOCKID                     | DESCRIPTION              | StkLoo            | QTY | U/PRICE  | AMOUNT |
|----|-----------------------------|--------------------------|-------------------|-----|----------|--------|
| 1  | T53101-48722/B30<br>ZSU60   | RAD GRILLE ( PREMIUM )   | CC<br>CC12-N-01B  | 1   | 180.00 ✓ | 180.00 |
| 2  | T52536-48030<br>ZSU60 AVU65 | FRT BUMPER S/RETAINER LH | CC<br>CC12-O-07B6 | 1   | 35.00 ✓  | 35.00  |
| 3  | T53812-48190<br>ZSU60 AVU65 | FRT FENDER LH            | CC<br>CC12-M-09E  | 1 ✓ | 280.00 ✓ | 280.00 |
| 4  | T81150-48890<br>ZSU60 AVU65 | HEAD LAMP LH ASSY        | CC<br>CC12-B-04C  | 1 ✓ | 900.00 ✓ | 900.00 |
| 5  | T52119-4A914<br>ZSU60       | FRT BUMPER               | CC<br>NEW         | 1 ✓ | 250.00 ✓ | 250.00 |

*Page 1*

SUB-TOTAL : 1,645.00  
ADD GST 7.00 % 115.15

E & O.E

TOTAL AMOUNT SGD : 1,760.15

[P] 26/03/2019 3:06:43PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 26/03/2019 2:57:09PM

JAE Auto Pte. Ltd.

Sales Executive: STEVEN

This is computer generated document.  
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672  
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS  
Dept Direct: 6417 9791 / 6745 9828



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY  
10 ANG MO KIO PARKS 2A  
#01-09 AMK AUTO POINT

SINGAPORE 568047  
TEL : 64831244 FAX : 64836170  
ATTN : SIMON 96205405

TAX INVOICE : AR201903-13165  
DATE : 27/03/2019  
CUSTOMER ID : AHL008  
VEH REG. NO. : SLA4515H  
TERMS : 30 days  
PO NO. :  
PAGE NO. : Page 1 of 1  
CURR : SGD

| SQ STOCKID                     | DESCRIPTION            | StkLoc            | QTY | U/PRICE | AMOUNT |
|--------------------------------|------------------------|-------------------|-----|---------|--------|
| 1. T52029-48010<br>ZSU60 AVU65 | FRT BUMPER UPPER REINF | CC<br>CC12-H-08A1 | ✓   | 95.00   | 95.00  |

SUB-TOTAL : 95.00  
ADD GST 7.00 % 6.65

E. & O E TOTAL AMOUNT SGD: 101.65

[P] 27/03/2019 9:38:37AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 27/03/2019 9:38:06AM

JAE Auto Pte. Ltd.

Sales Executive: STEVEN

This is computer generated document.  
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Sompo Insurance Singapore Pte. Ltd.  
50 Raffles Place, #05-01/06, Singapore Land Tower  
Singapore 048623

Our File No: CS/SMO19005125/KSD3N2

Date: 19/06/2019

## REFERENCE

|                   |                               |                  |                 |
|-------------------|-------------------------------|------------------|-----------------|
| Insured/Claimant: | MUHAMMAD BASHIR BIN AZAM KHAN | Policy No:       | D19MTPV01003094 |
| Date of Loss:     | 16/03/2019                    | Nature of Claim: | OD              |
|                   |                               | Claim No:        | CMTD1901387     |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                                 |             |              |
|-----------------------------|---------------------------------|-------------|--------------|
| Reg No:                     | SLA4515H                        | Engine No:  | 3ZRB730483   |
| Make & Model:               | TOYOTA HARRIER, 2.0 Premium (A) | Chassis No: | ZSU600072553 |
| Reg. Date:                  | 01/03/2016 (Man. Year: 2015)    | Odometer:   | 99168 km     |
| Colour:                     | Metallic Black                  |             |              |
| Engine Capacity:            | 1986 cc                         |             |              |
| Market Value/New Car Price: | S\$92,000.00                    |             |              |
| Sum Insured (S\$):          | Market Value/New Car Price      |             |              |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

## CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 235/55R19     | Rear Tyre Size:  | 235/55R19     |
| Front Left Side:  | Yokohama 5 mm | Rear Left Side:  | Yokohama 5 mm |
| Front Right Side: | Yokohama 5 mm | Rear Right Side: | Yokohama 5 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                | Repairer's      | Adjuster's      | Difference      | Diff %       |
|-------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                         | 3,768.40        | 2,282.30        | 1,486.10        | 39.44        |
| Miscellaneous Items           | 0.00            | 0.00            | 0.00            |              |
| Labour                        | 1,480.00        | 1,140.00        | 340.00          | 22.97        |
| Paintwork Labour              | 0.00            | 0.00            | 0.00            |              |
| Towing                        | 0.00            | 0.00            | 0.00            |              |
| <b>Gross Total (S\$)</b>      | <b>5,248.40</b> | <b>3,422.30</b> | <b>1,826.10</b> | <b>34.79</b> |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>367.39</b>   | <b>239.56</b>   | <b>127.83</b>   | <b>34.79</b> |
| <b>Nett Amount (S\$)</b>      | <b>5,615.79</b> | <b>3,661.86</b> | <b>1,953.93</b> | <b>34.79</b> |

## INSPECTION

|                             |            |                   |                                                                                                          |
|-----------------------------|------------|-------------------|----------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 21/03/2019 | Present Location: | Ah Lim Motor Company (AMK)                                                                               |
| Date Inspected:             | 22/03/2019 | Inspected At:     | Ah Lim Motor Company (AMK)<br>10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint<br>Singapore 568047 |
| Estimated Period of Repair: | 4.0 days   |                   |                                                                                                          |

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

|                      |                                                                                                                                                                              |                                                                  |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 19 Jun 2019)                    |
| <b>Parts:</b>        | M1-SUV                                                                                                                                                                       | TOYOTA HARRIER 2.0 Premium (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLA4515H)                                                                                                                                    |                                                                  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                  |

## Recommended Parts

| No.                     | Qty | Part No. Particulars                               | Condition       | Repairer's | Amount    |
|-------------------------|-----|----------------------------------------------------|-----------------|------------|-----------|
| 1                       | 1   | *FRONT BONNET OUTER CHROME MOUDLING<br>(WCP)       | Serviceable     | 105.00 F   | *- F      |
| 2                       | 1   | *FRONT GRILLE ASSY<br>(WCP)                        | Cracked         | 180.00 F   | *180.00 F |
| 3                       | 8   | *FRONT GRILLE CLIPS<br>(WCP)                       | Not Necessary   | 8.00 F     | *- F      |
| 4                       | 1   | *HEADLAMP WITH HID<br>(WCP)                        | N/s Mtg Cracked | 1,800.00 F | *900.00 F |
| 5                       | 4   | *HEADLAMP CLIPS<br>(WCP)                           | Not Necessary   | 6.00 F     | *- F      |
| 6                       | 1   | *FRONT BUMPER<br>(WCP)                             | Cracked         | 250.00 F   | *250.00 F |
| 7                       | 1   | *FRONT BUMPER SIDE RETAINER LH<br>(WCP)            | Distorted       | 35.00 F    | *35.00 F  |
| 8                       | 12  | *FRONT BUMPER CLIPS<br>(WCP)                       | Not Necessary   | 12.00 F    | *- F      |
| 9                       | 1   | *FRONT BUMPER SPONGE<br>(WCP)                      | Cracked         | 40.00 F    | *40.00 F  |
| 10                      | 1   | *FRONT BUMPER REINFORCEMENT<br>(WCP)               | Repair          | 130.00 F   | *- F      |
| 11                      | 1   | *FRONT BUMPER LOWER AIR GRILLE<br>(WCP)            | Cracked         | 90.00 F    | *90.00 F  |
| 12                      | 1   | *FRONT BUMPER LOWER LIP BLACK<br>(WCP)             | Mtg Cracked     | 125.00 F   | *125.00 F |
| 13                      | 1   | *FOGLAMP LH<br>(WCP)                               | Serviceable     | 100.00 F   | *- F      |
| 14                      | 1   | *FOGLAMP OUTER COVER LH<br>(WCP)                   | Serviceable     | 60.00 F    | *- F      |
| 15                      | 1   | *FRONT FENDER LH<br>(WCP)                          | Buckled         | 280.00 F   | *280.00 F |
| 16                      | 10  | *FRONT FENDER COWLING CLIPS<br>(WCP)               | Not Necessary   | 15.00 F    | *- F      |
| 17                      | 10  | *RADIATOR SUPPORT PANEL TOP GARNISH CLIPS<br>(WCP) | Not Necessary   | 15.00 F    | *- F      |
| 18                      | 1   | *NUMBER PLATE                                      | Dented          | 35.00 FS   | *35.00 FS |
| <b>Supplementary #1</b> |     |                                                    |                 |            |           |
| 19                      | 1   | *HEADLAMP LOWER BRACKET LH<br>(WCP)                | Bent            | 48.00 F    | *48.00 F  |
| 20                      | 1   | *BUMPER UPPER REINFORCEMENT<br>(WCP)               | Distorted       | 95.00 F    | *95.00 F  |

F=Franchise part. S=SpcNett.

|                                                 |                 |                 |
|-------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (S\$)</b>                          | <b>3,429.00</b> | <b>2,078.00</b> |
| <b>+ Margin on L,N Items 10.00/10.00% (S\$)</b> | <b>339.40</b>   | <b>204.30</b>   |
| <b>Total Parts (S\$)</b>                        | <b>3,768.40</b> | <b>2,282.30</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars                                                                                                                                                                           | Lab.Type | Repairer's | Amount   |
|-------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|------------|----------|
| <u>Labour Items</u>     |                                                                                                                                                                                       |          |            |          |
| 1                       | TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.                           | New      | 40.00      | 20.00    |
| 2                       | TO RESET HEADLAMP HID;ENGINE LIGHT                                                                                                                                                    | New      | 180.00     | 120.00   |
| 3                       | TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD FRONT BUMPER REINFORCEMENT.TO KNOCK & REPAIR FRON DOO RLH;FRONT BONNET INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME. | New      | 540.00     | 400.00   |
| 4                       | TO SPRAY FRONT BONNET;FRONT DOOR LH;FRONT BUMPER;FRONT BUMPER REINFORCEMENT.                                                                                                          | New      | 720.00     | 600.00   |
| Gross Labour Cost (S\$) |                                                                                                                                                                                       |          | 1,480.00   | 1,140.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >