

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 264P**AAD1903-134***Not Authored
b. 8/3/16*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

SHD 264P

VF1ABL15AUC282374

RENAULT

LATITUDE

16.3.2019

EQ

4/2/2016

LIST

1	1	BUMPER COVER FRT	\$	R	1,259.42	}
2	1	BUMPER SPOILER FRT	\$	SL	181.75	
3	1	BUMPER ABSORBER FRT	\$	SL	394.68	
4	1	BUMPER RETAINER FRT LH	\$	SL	151.41	
5	1	BUMPER SUPPORT FRT	\$	SL	123.88	
6	1	BUMPER RETAINER FRT RH	\$	SL	150.77	
7	1	BUMPER SUPPORT FRT	\$	SL	123.88	
8	1	BUMPER UNDERTRAY FRT	\$	SL	472.83	
9	1	BUMPER GRILLE LOWER FRT	\$	SL	266.80	
10	1	BUMPER FOG LAMP GRILLE LH	\$	SL	207.21	
11	1	BUMPER FOG LAMP GRILLE RH	\$	SL	207.21	
12	1	BUMPER BEAM FRT	\$	R	914.08	
13	1	TOW COVER FRT	\$	SL	28.61	
14	1	RADIATOR GRILLE	\$	SL	1,707.78	
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	SL	225.36	
16	1	RADIATOR GRILLE FRAME	\$	SL	1,353.75	
17	1	FRAME FULL SUPPORT PANEL	\$	SL	615.90	
18	1	FRAME FULL SUPPORT BRACKET	\$	R	89.79	
19	1	HEADLAMP LH	\$	SL	1,184.43	
20	1	HEADLAMP RH	\$	SL	1,184.43	
21	1	HEADLAMP PANEL FRT LH	\$	R	152.15	
22	1	HEADLAMP PANEL FRT RH	\$	R	152.15	

TOTAL	\$	11,148.30
10%	\$	1,114.83
	\$	10,033.47

Trans-cab Auto Services Pte Ltd

AAD1903-134

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 264P

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	na	52.00	}	X
2	1SET	BUMPER CLIP FRT	\$	na	66.00		
3	1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00		
4	1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50		
5	1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00		
6	1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50		
7	1	TOW COVER FRT	\$	na	14.50		
8	1SET	RADIATOR GRILLE SCREW	\$	na	16.00		
9	1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00		
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00		
11	2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00		
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00		
21	1	Windscreen moulding	\$	na	100.00		
22	1SET	Front licence plate with holder	\$	na	80.00		

TOTAL	\$	562.50
TOTAL PARTS	\$	10,595.97

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 3,000.00 *del*

To apply paint protection system (PPS) maintain and enhancement

\$ na 380.00 X

Putty and spray painting of the affected portion.

\$ 3,000.00 *2201*

To rust-proofing of the affected areas.

\$ na 170.00 X

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ na 380.00 X

Trans-cab Auto Services Pte Ltd

AAD1903-134

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 264P

To check steering geometry and computer wheel alignment	\$	na 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	na 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 1d
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	na 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	na 380.00 X
To replace, refix and top up coolant for radiator	\$	na 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	na 170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	na 170.00 X

TOTAL	\$	9,140.00
--------------	-----------	-----------------

Over All Total	\$	19,735.97
-----------------------	-----------	------------------

(LUMP SUM) Repair Days**10-DAYS**

1 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: