

ASS. REC. BY:

REF: CS/FCI 19005131 / Ktd 3n2

Special Instruction:

SW/Veyo's

Kenneth

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time: 21/3/19 @ 10:40am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SKK 3077X

Insured:

SH 6506B

at Workshop m/s:

YAS Group

Tel:

9179 6610

of

160 Sin Ming Drive # 0304

Policy No:

Claim No:

D19001939MPSH

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A.

17/03/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12:37pm @ 21/3/19

Person Contacted:

Vincent

Vehicle (IN) OUT

Date/Time

Action/Instruction (✓) Estimate

SKK 3077X CS3 / MSG 16 015270 / Sgbs 2 - 1

D.O.A - 11/8/2016

SHB 6506B - CS/FCI 18017409 / Agbn 2

D.O.A - 20/9/2018

25/3@4:10pm. Rented via preli advice email.

REF: FCI

ASSIGNMENT

From: Date: 21/3/19

Estimated Cost:

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKK 3077 X

at Workshop m/s: YAS Auto

of 160 Sin Ming Drive # 03-07

Insured:

Policy No:

Claims No:


Sum Insured: Excess:

(Client's Record)

Make of Veh: Vincent @ 91796610

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$52k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (wp)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKK 3077X Yr Regn: 06 / 13

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen A) Golf G.C. 1395

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 204132 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVW 888 AU ZDW 15729P

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: R: 225 / 45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front	Rear
R/Bal. 4 mm	R/Bal. 4 mm
L/Bal. 4 mm	L/Bal. 4 mm
D.O.A. 17/3/19	D.O.I. 21/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015 R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No GIA prior, got injury.

11 Apr 8210d email

7/5 @ Check with Vincent lump sum \$2100 - (3 days) L Red.

confirm.

RECEIVED 07 MAY 2019

Date/Time, File Pass to?

1) 7/5 Tyast

Date/Time, File Return to?

2)

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others:

TOTAL

Report Format: TP

Lump Sum / I.B.I: (\$) 2100

140

50

50

17

257



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001817MFSH

Date: 25/3/2019

Our Ref: CS/FCI19004884/Jtd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKK 3077X

Please be informed that we had conducted the inspection of the abovementioned vehicle 25/3/2019 at the premises of M/s VAS Group have the following to report: -

Workshop Estimate Amount	: S\$ <u>5,085.95</u>
Revised Estimate Amount	: S\$ <u>2,670.99</u>
"Check" Items Amount	: S\$ <u>0.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the
o/s front portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kenneth

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	20-03-2019	Our Ref No.	D19001939MFSH
Accident Date	17-03-2019	Claim Type.	Third Party
Insured Vehicle	SH6506B	Third Party Vehicle.	SKK3077X
Survey Location	160 Sin Ming Drive #03-07 Sin Ming Autocity		
Contact Person.	MR VINCENT		
Contact No.	62644555/ 91796610	Fax No.	0
Survey Type	WITHOUT PREJUDICE:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	VAS MOTOWERKZ PTE LTD	Attention.	NIL
Cc : TP Solicitor	HIN TAT AUGUSTINE & PARTNERS	TP Solicitor Fax No.	NA
Officer Incharge	KARENT		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Nivitha (LKK Auto)

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Thursday, 21 March 2019 10:40 AM
To: assignments
Subject: FW: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKK3077X & YOUR REF: D19001939MFSH & OUR REF. TCL.GCN.AN.50163.19.VAS - ACCIDENT INVOLVING SKK3077X & SH6506B ON 17/03/19

Importance: High

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Anil Kumar <anil@htapartners.com.sg>
Sent: Thursday, 21 March 2019 10:39 AM
To: karentan@msfirstcapital.com.sg; CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Cc: Tan Vincent (tanvin13@yahoo.com.sg) <tanvin13@yahoo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKK3077X & YOUR REF: D19001939MFSH & OUR REF. TCL.GCN.AN.50163.19.VAS - ACCIDENT INVOLVING SKK3077X & SH6506B ON 17/03/19
Importance: High

Without Prejudice

Urgent Reminder

Dear Karen,

We refer to your email dated even date.

Our client is agreeable to use **Mr. Kenneth Kong of M/s LKK Auto Consultants Pte Ltd** from your list to conduct the joint pre-repair survey as a single joint expert for our client's vehicle SKK3077X as follows:

Kindly contact the person-in-charge to arrange for the inspection of the vehicle. Please be informed that the said vehicle can be inspected at: -

Venue : **VAS GROUP PTE LTD**
160 Sin Ming Drive
#03-07 Sin Ming Autocity
Singapore 575722

Contact Person : Mr Vincent : 91796610 (Important: Kindly contact Mr Vincent, prior to arranging your appointed surveyor going down to inspect our client's vehicle for the above matter)

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference.

Best regards,

Anil (Secretary)
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext.256
Direct Fax: 63383536
Fax : 6533 0313

From: Anil Kumar

Sent: Wednesday, March 20, 2019 6:01 PM

To: karentan@msfirstcapital.com.sg; 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>

Cc: Tan Vincent (tanvin13@yahoo.com.sg) <tanvin13@yahoo.com.sg>

Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKK3077X & YOUR REF: D19001939MFSH & OUR REF. TCL.GCN.AN.50163.19.VAS - ACCIDENT INVOLVING SKK3077X & SH6506B ON 17/03/19

Importance: High

Without Prejudice

Dear Karen,

We refer to your email dated even date.

Our client is agreeable to use **Mr. Kenneth Kong of M/s LKK Auto Consultants Pte Ltd** from your list to conduct the joint pre-repair survey as a single joint expert for our client's vehicle SKK3077X as follows:

Kindly contact the person-in-charge to arrange for the inspection of the vehicle. Please be informed that the said vehicle can be inspected at: -

Venue : **VAS GROUP PTE LTD**
160 Sin Ming Drive
#03-07 Sin Ming Autocity
Singapore 575722

Contact Person : Mr Vincent : 91796610 (Important: Kindly contact Mr Vincent, prior to arranging your appointed surveyor going down to inspect our client's vehicle for the above matter)

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference.

Best regards,

Anil (Secretary)
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext.256
Direct Fax: 63383536
Fax : 6533 0313

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>

Sent: Wednesday, March 20, 2019 5:40 PM

To: Ruby Ong <ruby@htapartners.com.sg>

Cc: Karen Tan <karentan@msfirstcapital.com.sg>; CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>

Subject: Our Ref: D19001939MFSH Pre-Repairs Assessment Request for SKK3077X - accident involving with SH6506B

Without Prejudice

Dear Sirs,

We refer to your survey request,

Please find below our list of surveyors for your reference. Kindly select from our list below and inform us of your choice within the next 2 days.

1. LKK Auto Consultants Pte Ltd
2. Vicom Ltd

Once you inform us of your choice, the surveyor will be appointed within 2 working days of your email.

If you do not agree to any of the surveyors above, you may proceed to appoint your own surveyor. In this instance, we will also appoint a surveyor from our list above to conduct the PRI. Upon completion of repairs, please contact our appointed surveyor to conduct a physical re-inspection of the vehicle.

Kindly provide Workshop details to process.

Thank you.

Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited

From: Anil Kumar
Sent: Wednesday, March 20, 2019 2:25 PM
To: 'MOTORCLAIMS@MSCAPITAL.COM.SG' <MOTORCLAIMS@MSCAPITAL.COM.SG>;
motor_claims@msfirstcapital.com.sg
Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKK3077X [OUR REF. TCL.GCN.AN.50163.19.VAS]
Importance: High

Reminder

Dear Sirs,

Kindly let us have your reply to our email dated 19th March 2019 on a urgent basis.

Best regards,

Anil (Secretary)
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext.256
Direct Fax: 63383536
Fax : 6533 0313

From: Ruby Ong
Sent: Tuesday, March 19, 2019 5:36 PM
To: motor_claims@msfirstcapital.com.sg
Cc: Anil Kumar <anil@htapartners.com.sg>
Subject: FW: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKK3077X [OUR REF. TCL.GCN.AN.50163.19.VAS]
Importance: High

Your ref: SH 6506B
Our ref: TCL.GCN.an.50163.19.vas

WITHOUT PREJUDICE

19 March 2019

URGENT

MS First Capital Insurance Ltd
36 Robinson Road
16-01 City House
Singapore 068811
Attn: Motor Claims Dept

By Email only

Dear Sirs

CLAIMANT: TAN MAY LAN

NOTICE OF ACCIDENT AND PRE-REPAIR SURVEY - ACCIDENT INVOLVING SKK 3077X & SH 6506B ALONG CORPORATION ROAD ON 17 MARCH 2019 @ 1220HRS

We are instructed by Tan May Lan to notify you of a road traffic accident on 17 March 2019 at about 1220hrs along Corporation Road involving our client's vehicle registration number SKK 3077X and vehicle registration number SH 6506B driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext 278
Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 25 March 2019 4:18 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001939MFSH/1
Attachments: PRELI ADVISED SKK 3077X.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SKK 3077X**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 21 March 2019 2:37 PM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D19001939MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

Driver's NRIC & Driving License Pg. 1

REPUBLIC OF SINGAPORE DRIVING LICENCE

Update Number: **S9931997F**
Name: **SHAUN TIA YOU RUI**
Birth Date: **26 Sep 1999**
Issue Date: **26 Apr 2018**

002797204H

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9931997F



Name

SHAUN TIA YOU RUI

谢友锐

Race

CHINESE

Date of birth

26-09-1999

Sex

M

Country/Place of birth

SINGAPORE

S9931997F

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES:

EFFECTIVE DATE

Class 3 Motor cars with unladen weight \leq 3000kg with \leq 7 passengers, exclusive of driver; and other motor vehicles with unladen weight \leq 2500kg **26 Apr 2018**

NP 428A



Licence No: S9931997F

5293014



NRIC No. **S9931997F**



Date of issue

09-04-2014

Address

**APT BLK 326 BUKIT BATOK STREET 33
#01-71
SINGAPORE 650326**

Police Report Pg. 1



Police Station Of Origin:
Hong Kah North NPP
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No: 1800-5879999

1 of 3
Report No: T201903182152

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/03/2019 18:45
Vide Report No.:
Station Diary No.: 42

Name of Informant: SHAUN TIA YOU RUI
Address: APT BLK 326 BUKIT BATOK STREET 33 #01-71 SINGAPORE 650326
ID Type / ID No.:
NRIC NO / S9531957F
Contact No.:
Home/Office: Mobile: 91172421
Nationality:
SINGAPORE CITIZEN
Email:
Sex: Male Age: 19 Date of Birth: 25/09/1999 Type of Informant: Driver
Race: Chinese Language: English Institution / School Name: Republic Polytechnic
Occupation: Student Driving Licence Information: Class: 3 Date of Expiry:

STEP 1: ACCIDENT INFORMATION

Type of Accident	Injury	Others	Drunk	Date/Time of Accident	Type of Location
None	None	None	None	17/03/2019 00:24	Street Road

Location:
Along Road 1
CORPORATION ROAD

Weather	Road Surface	Road Speed Limit
Clear	Dry	30

Traffic Flow	Traffic Contrbution	Traffic Volume
One Way	Pedestrian Crossing	No Traffic

Type of Collision:
Between Moving Vehicles - Side Swipe - Same Direction

Anyone conveyed by ambulance:
No

Vehicle No	Vehicle Type	Damage	Driver
SH6506B	Car	Scratched	
SHK3077A	Car	Scratched	

No Pedestrian Involved No
No Pedestrian Injured No Use of Pedestrian Crossing No



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Hong Kah North NPP
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No: 1800-3679999



T20190318/2152

2 of 3

Report No. T20190318/2152

CONTINUATION OF REPORT

Name	WONG YEW CHEE	ID No.	S0147284D
Related Vehicle	SH6506B (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Name	SHAUN TIA YOU RUI	ID No.	S9931997F
Related Vehicle	SKK307X (Car)	Contact No.	91172421
Hospital/Clinic	FAMILY CARE CLINIC PTE LTD	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	18/03/2019	Date Discharge	18/03/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details:

On the 17/03/2019 at 0025hrs, I was driving my car along Corporation Road. I had to make a left turn into Jurong West Avenue 1. The left turn lane had two lanes. I positioned myself on the left most lane. There a blue taxi on the 2nd left turn lane. When the traffic was dead, I began to turn.

Somehow the taxi cut into my lane and grazed onto the right side of my car. We aligned and exchanged particulars. My car had a dent on the right fender and scratches on my front bumper. My rims have dents as well. My engine mounting is loose. My front right headlight cannot be turned on. The taxi suffered a scratch on the rear passenger door. I felt some pains in my neck, shoulder and right thumb. I went to see the doctor today and was given 3 days MO.



Police Station Of Origin:
Hong Kah North NPP
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No: 1800-5679929



T201903182152

Page 3

Report No. T201903182152

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of the Police Reference Certificate with this report. The certificate will be used to provide a copy to the relevant authorities.

Signature Of Officer Receiving Report J) Staff Sgt SATHISH ANANTHAN ALAGUDASS	Signature Of Informant
Signature Of Interpreter Not applicable	Date/Time 18/03/2019 14:45
Officer In Charge Of Case TPI/AET/ STANLEY TING STEPHENS Contact No: 65476411	Officer Receiving Case
Singapore Police Force	

Not Authored
11/12/82100/3
Running After Paint
3 days

ESTIMATE ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SKK 3077X VW GOLF

Report No.: CT 003/19

<u>S/No</u>	<u>QTY</u>	<u>Description</u>	<u>Condition/Remarks</u>	<u>Repairer's Estimates</u>
-------------	------------	--------------------	--------------------------	-----------------------------

REPLACEMENT OF DAMAGED PARTS

1)	1	Front bumper	Torn	<i>Buck</i> \$ 1,169.00 ✓
2)	1set	Front bumper clips	Necessary	<i>m</i> \$ 50.00 ✓
3)	1	Front bumper side holders RH	Necessary	<i>\$m</i> \$ 49.00 x
4)	1	Front fender RH <i>545.20</i>	Dented	<i>Bu</i> \$ 588.00 ✓
5)	1	Front headlamp assy RH	Cracked	<i>SL</i> \$ 1,245.00 x
				\$ 3,101.00
Less 5%				\$ 155.05

\$ 2,945.95

6) Sport Rim

Pick 1.12 SL \$ 450.00 ** 50.00*

PARTS CHARGES

\$ 3,395.95

LABOUR CHARGES

7)	Panel beat front support panel. Straighten front right chassis. Remove and replace all damaged parts.		\$ 800.00	<i>400</i>
8)	Check lightings and wiring.		\$ 60.00	<i>150</i>
9)	Rust proofing treatment on affected area.		\$ 160.00	<i>300</i>
10)	Spray painting on affected area.		\$ 1,000.00	<i>4400</i>
11)	Computerize 4 wheel alignment		<i>200</i> \$ 120.00	<i>100</i>

Total (Labour): \$ 2,140.00

LKK Auto Consultants hence notify the Repairer of the following:

Total: \$ 5,085.95

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

POINT OF IMPACT

At the front portion right side of the vehicle.

Acknowledged by Repairer:
Signature:
Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19005131/Ktd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 08-05-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6506B	Veh. Inspected	SKK 3077X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001939MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	21/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN GOLF (A)	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WWWZZAUZDW157299	Colour	RED	
Odometer	204132	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	GOODYEAR	4 mm	
L/H Front Tyre	225/45 R17	GOODYEAR	4 mm	
R/H Rear Tyre	225/45 R17	GOODYEAR	4 mm	
L/H Rear Tyre	225/45 R17	GOODYEAR	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/03/2019	Inspection Date	21/03/2019	
Survey held at	VAS GROUP PTE LTD 160 SIN MING DRIVE #03-07 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKK 3077X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	BUCKLED / DENTED	1,169.00	1,169.00
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER SIDE HOLDERS RH	SERVICEABLE	49.00	-
1	FRONT FENDER RH	BUCKLED	588.00	545.20
1	FRONT HEADLAMP ASSY RH	SERVICEABLE	1,245.00	-
	LESS 5% DISCOUNT		-155.05	-88.21
			2,945.95	1,675.99
	SPECIAL NETT ITEMS			
1	SPORT RIM (LOCAL REPAIR)(SN)	SCRATCHED	450.00	50.00
			450.00	50.00
	LABOUR			
	PANEL BEAT FRONT SUPPORT PANEL.STRAIGHTEN FRONT RIGHT CHASSIS.REMOVE AND REPLACE ALL DAMAGED PARTS.		800.00	400.00
	CHECK LIGHTINGS AND WIRING.		60.00	15.00
	RUST PROOFING TREATMENT ON AFFECTED AREA.		160.00	30.00
	SPRAY PAINTING ON AFFECTED AREA.		1,000.00	440.00
	COMPUTERIZE 4 WHEEL ALIGNMENT.		120.00	60.00
			2,140.00	945.00
	GRAND TOTAL		5,535.95	2,670.99
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,100.00

Report Ref No. CS/FCI19005131/Ktd3n2

KSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.