

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHB 6710P (Supplementary)

DATE : 21.03.2019

MAKE :

TEL : 6542 5119

MODEL : MERCEDES BENZ VIANO (REAR)

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Airbag Control Unit activated			\$ 2,380.00
	Front Safety Belt (LH/RH) o/s activated w/s nm		\$ 1,850.00	\$ 3,700.00
	Rear Bumper Side Top Cover (RH) broken nm			\$ 165.00
	SUB TOTAL		4230.00	\$ 6,245.00
	LESS 10%		3807.00	\$ 624.50
	DISCOUNTED TOTAL			\$ 5,620.50
	Labour Charge			
	Diagnostic & Resetting SRS Airbag System rep			\$ 550.00
	Remove/Refix Safety Belt			\$ 380.00
	Diagnostic & Resetting To Erase Fault Code rep			\$ 480.00
	TOTAL LABOUR		300.00	\$ 1,410.00
	ESTIMATE TOTAL			\$ 7,030.50
			4107.00	

Ign 21/03/2019

2kk Auto

[Signature]

AK Wang

pls ign

earlier

copy

Th

more X

**150/-*

150/-

X

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.