

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0369/2019/KK
Date	:	21-Mar-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured veh no : SLN 6072 L

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 65321818 - Fax: 6516 0904

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Tuan Geng Xing
Address	:	Blk 473C Upper Serangoon Cresent #16-341 Singapore 533473
Telephone	:	HP +65 98211445
Type of Claim	:	Third Party Claim
Policy No.	:	1800040535
Vehicle No	:	SKQ 8233 Y
Model Code	:	Audi A4 SEDAN 2.0 TFSI
Model / Year	:	19-04-18
Engine No	:	CVK 058391
Chassis No	:	WAUZZZF4XJA142652
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	19-Mar-19
Place of Accident	:	Gate Of Bethel Pre School Upp Serangoon Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKQ 8233 Y

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 /	
2	To dismantle and renew rear bumper. Re-organize crash management components. Reinstall all parts removed.	\$ 900.00 500	
3	To respray rear bumper.	\$ 800.00 550	
4	To carry out diagnostic check.	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		: <u>\$ 2,252.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SKQ 8233 Y**

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		<u>S/Nett</u>	<u>Remark</u>
1	REAR BUMPER <i>repair</i>	\$ 2,015.00	
2	REAR BUMPER FIXING PARTS ?	\$ 66.00	
3	REAR BUMPER SECURING TRIP ?	\$ 203.00	
4	REAR BUMPER SPOILER ?	\$ 227.00	
5	REAR LIGHT REFLECTOR - LH ?	\$ 38.00	
6	REAR BUMPER CARRIER X	\$ 819.00	
7	GUIDE SECTION - LH ?	\$ 40.00	
8	LOWER GUIDE SECTION - LH ?	\$ 20.00	
9	REAINER AERIAL - LH ?	\$ 23.00	
10	ANTENNA ASSEMBLY ?	\$ 164.00	
11	REAR SENSOR X	\$ 231.00	
12	LED TAIL LIGHT - INNER <i>scr</i>	\$ 931.00	
13	TRIM TAIL LIGHT - INNER <i>scr</i>	\$ 27.00	
14	LED TAIL LIGHT - OUTER <i>scr</i>	\$ 931.00	
15	TRIM TAIL LIGHT - OUTER <i>scr</i>	\$ 27.00	
16	SUNDRIES ?	\$ 300.00	
TOTAL SPARE PARTS		\$ 6,062.00	
TOTAL LABOUR CHARGES		\$ 2,252.00	
GRAND TOTAL		\$ 8,314.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: *RASUL - Hp 90010068*
: *25/03/19 @1350*
:
: *3 days*
:
: *Resurvey be*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant