

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0369/2019/KK
Date	:	21-Mar-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured veh no : SLN 6072 L

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Motor Claims Dept

Tel: 65321818 - Fax: 6516 0904

Tel: 6841 0055 - Fax: 6256 4315

Hi Rasul

3 days - ok - jb - 11 May 19

Owner's Name	:	Mr Tuan Geng Xing
Address	:	Blk 473C Upper Serangoon Crescent #16-341 Singapore 533473
Telephone	:	HP +65 98211445
Type of Claim	:	Third Party Claim
Policy No.	:	1800040535
Vehicle No	:	SKQ 8233 Y
Model Code	:	Audi A4 SEDAN 2.0 TFSI
Model / Year	:	19/4/2018
Engine No	:	CVK 058391
Chassis No	:	WAUZZZF4XJA142652
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	19-Mar-19
Place of Accident	:	Gate Of Bethel Pre School Upp Serangoon Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKQ 8233 Y

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	\$ 360.00 ✓
2	To dismantle and renew rear bumper. Re-organize crash management components. Reinstall all parts removed.	\$ 900.00	\$ 500.00 ✓
3	To respray rear bumper.	\$ 800.00	\$ 550.00 ✓
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00 ✓
TOTAL LABOUR CHARGES		: <u>\$ 2,252.00</u>	<u>\$ 1,602.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SKQ 8233 Y**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER	\$ 2,015.00	
2	REAR BUMPER FIXING PARTS	\$ 66.00	
3	REAR BUMPER SECURING TRIP	\$ 203.00	
4	REAR BUMPER SPOILER	\$ 227.00	
5	REAR LIGHT REFLECTOR - LH	\$ 38.00	
6	REAR BUMPER CARRIER	\$ 819.00	
7	GUIDE SECTION - LH	\$ 40.00	
8	LOWER GUIDE SECTION - LH	\$ 20.00	
9	REAINER AERIAL - LH	\$ 23.00	
10	ANTENNA ASSEMBLY	\$ 164.00	
11	REAR SENSOR	\$ 231.00	
12	LED TAIL LIGHT - INNER	\$ 931.00	\$ 744.80
13	TRIM TAIL LIGHT - INNER	\$ 27.00	\$ 21.52
14	LED TAIL LIGHT - OUTER	\$ 931.00	\$ 744.80
15	TRIM TAIL LIGHT - OUTER	\$ 27.00	\$ 21.52
16	SUNDRIES	\$ 300.00	\$ 15.92
TOTAL SPARE PARTS		\$ 6,062.00	\$ 1,548.56
TOTAL LABOUR CHARGES		\$ 2,252.00	\$ 1,602.00
GRAND TOTAL		\$ 8,314.00	\$ 3,150.56

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.