

REF CS/GAI 19005146 / R19d3

Report of Accidents

Accident Ref: 19005146

Estimate No:

Rasul

ASSIGNMENT (Office)

From (Person)

Kelvin Ngian

GAI

Bill to

Date/Time: 20/3/19 @ 5.02pm

Estimated Cost

OD / TR / WS / TP / RES / OF / RES / EVA / INV / MY / CS

To Inspect Vehicle No:

GBE 1652L

Insured

GBA 9617H

at Workshop no:

Falcon Air Auto

Tel:

6779 5665

of

No-8 Pandan Loop (Blk K/Blk 1)

Claim No

CLMOMV060003625

Policy No:

Excess

Name Insured

D.O.B

12/3/19

Make of Veh:
(Client's Record)

22/3/19 @ 10-12am

H.O.D. Endorsement

CA / REV / REP / REV 24 HRS

Date/Time: 11.21am @ 21/3/19

Person Contacted

Andy

Vehicle In

LOUT

Date/Time Action/Restriction (✓) Estimate

GBE 1652L -X

GBA 9617 H -X

25/3/19 @ 2.21pm. Revised to Kelvin by email.

06/8/19 @ 8.52am. Rasel finalised final fig 86886.60, 7 days.

(Red 8 2081.00, 23%)

no long sum.


06/8/19 Submit Preli-report, exclude check item B 264p)

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: GBE 1652L
 at Workshop m/s Falcon - AR
 of No. 8, person have BLK K
 Insured: GAI
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR - Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBE 1652L Yr Regn: 2015 / 80P
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or PICK-UP
 Make: SPRINT ACTYON SP2-6 C.C. 1998
 Colour: BLACK A/C: Insured / Std / NI / NA
 Sp. Reading: 233465 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KPADAIETSFP225/29
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/75R16C
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or FALCON
 Front 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 12/03/19 D.O.I. 22/03/19
 Survey held at FALCON-AR
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
06/08/19	- CR check To verify whether front have any vehicle. ask tip if got video later
	- Great Answer GIA27
	- To submit accordingly first.
	- To submit just later guide as check to verify on consistency.

Date/Time, File Pass to?

1) 06/08/19

Date/Time, File Return to?

2) _____

☒ : Preli. Report
☐ : Final Report

Days Of Repair: 7Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee: 250

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format: 7PLump Sum / I.B.I. (\$) 6886.60

Nivitha (LKK Auto)

From: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Sent: Wednesday, 20 March 2019 5:02 PM
To: Admin-D (LKKAuto); 'Admin A'
Subject: TP survey - CLMOMVC000003625 : GBE1652L CLAIMING TP AGAINST GBA9617H (GAIC) DOA 12/03/2019
Attachments: SAS2567535.PDF; ESTIMATE & VEHICLE SEARCH.pdf; GBA9617H.pdf

Hi team

TP survey please.

Thanks
Kelvyna

From: ANDY <andy@falconair.com.sg>
Sent: Wednesday, March 20, 2019 4:57 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Subject: [External] RE: CLMOMVC000003625 : GBE1652L CLAIMING TP AGAINST GBA9617H (GAIC) DOA 12/03/2019

Dear Kelvyna,

As per telephone conversation with you
Kindly assign LKK for this case

Regards
Andy

From: ANDY [<mailto:andy@falconair.com.sg>]
Sent: Tuesday, March 19, 2019 10:37 AM
To: 'general.claims@sg.gaig.com' <general.claims@sg.gaig.com>
Cc: 'Falcon-Air Pandan' <pandan@falconair.com.sg>
Subject: GBE1652L CLAIMING TP AGAINST GBA9617H (GAIC) DOA 12/03/2019

Dear Sir / Madam,

Please refer to attached GIA report and estimate of the above mentioned GBE1652L CLAIMING TP AGAINST GBA9617H (GAIC) DOA 12/03/2019
Please advise liability & kindly arrange the survey.
Vehicle not in.
Attached documents for your perusal

Best Regards

Andy

Falcon-Air Auto Services Pte Ltd

Add : No. 8 Pandan Loop (Blk K / Blk 1) Singapore 128226 Tel No : +65 6779 5665

Fax No : +65 6779 1110

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Shiau Chan (LKKAUTO)

From: ANDY <andy@falconair.com.sg>
Sent: Tuesday, 6 August 2019 8:32 AM
To: Rasul (LKKAUTO)
Subject: RE: GBE1652L FINALISE

Sir

Amount confirmed

Thanks
Andy

-----Original Message-----

From: Rasul (LKKAUTO) [mailto:Rasul@lkkauto.com]
Sent: Monday, August 05, 2019 4:59 PM
To: ANDY <andy@falconair.com.sg>
Subject: RE: GBE1652L FINALISE

Hi Andy,

Finalised amount is \$ 6,886.60 / 7 days Kindly confirm

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

-----Original Message-----

From: ANDY [mailto:andy@falconair.com.sg]
Sent: Monday, 5 August, 2019 12:46 PM
To: Rasul (LKKAUTO)
Cc: Admin A
Subject: GBE1652L FINALISE

Sir

Please confirm finalise P/P \$6,926.60 7 days

Regards
Andy
Tel # 67795665

Your message is ready to be sent with the following file or link attachments:

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 25 March 2019 2:21 PM
To: 'Ngian, Kelvyna'; assignments
Cc: SUR
Subject: RE: TP survey - CLMOMVC000003625 : GBE1652L CLAIMING TP AGAINST GBA9617H (GAIC) DOA 12/03/2019
Attachments: CSGAI19005146R1qd3.pdf

Dear Kelvyna,

Enclosed herewith preliminary advice of GBE 1652L.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 21 March 2019 11:24 AM
To: 'Ngian, Kelvyna' <Kelvyna.Ngian@sg.gaig.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: TP survey - CLMOMVC000003625 : GBE1652L CLAIMING TP AGAINST GBA9617H (GAIC) DOA 12/03/2019

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle not in the workshop, repairer will arrange.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ngian, Kelvyna [<mailto:Kelvyna.Ngian@sg.gaig.com>]
Sent: Wednesday, 20 March 2019 5:02 PM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>
Subject: TP survey - CLMOMVC000003625 : GBE1652L CLAIMING TP AGAINST GBA9617H (GAIC) DOA 12/03/2019

Hi team

TP survey please.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Claim No. : CLMOMVC000003625

Date: 25th March 2019

Our Ref: CS/GAI19005146/R1qd3

The Motor Claims Department
Great American Insurance Company

Attn: Kelvyna

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. GBE 1652L.


We thank you for the instruction on 20/03/2019.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 22/03/2019 at the premises of M/s FALCON AIR AUTO and have the following to report:-

Workshop Estimate Amount	: S\$ <u>8,968.20</u> .
Revised Estimate Amount	: S\$ <u>7,459.40</u> .
"Check" Items Amount	: S\$ <u>660.00</u> .
Market Value	: S\$ <u>-</u> .
Salvage Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages consistent.

Recommend repair days: 7 days

We have NOT authorise repair.

Yours faithfully

Rasul
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/03/2019 14:29
Date Of Accident	12/03/2019 16:45
Exact Location Of Accident	KJE SLIP ROAD EXIT TO BKE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE1652L
Insured/Policyholder	
Name Of Registered Owner	ACE ZAG SERVICES
Co Reg No	52890381K
Email Address	TERRENCELINMAOXIN@HOTMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-90123873

Vehicle Particulars

Manufacturer	SSANGYONG
Model	ACTYON SPORTS-2.0 D/CAB 2.0 AT AIRBAG 2WD (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5083188742-02
Cover Note Number	

Driver

Name of Driver	LIN MAOXIN, TERRENCE
NRIC No	S8525364F
Date Of Birth	04/09/1985
Occupation	OUTDOOR
Date Of Driving Pass	29/12/2005
Driving Experience	13 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97845242
Fax Number	
Contact Number	
Email Address	NOEMAIL

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

LIN MAOXIN TERRENCE

Approximate Age

Injuries Sustain

Injured person in which vehicle?

GBE1652L

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode



FALCON-AIR

ACE ZAG SERVICES
50 EAST COAST ROAD
ROXY SQUARE SINGAPORE (428769)
MR TEO

Attention : Motor Claim Department

Contact : 97845252

Estimate : ES003412

Date : 18/03/2019
Vehicle Num. : GBE1852L
Make/Model : SSANGYONG ACTYON SPORTS
Chassis/Eng# : KPADA1ETSFP225129
Accident Date : 12/03/2019
Claim No. :
Reference : TP NTUC VS GAIC
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	LIST ITEMS		
2.	1	TAILGATE <i>81</i>		2,200.00 1950
3.	2	TAILGATE LOCK <i>81 - X SUC</i>	161.00	322.00
4.	1	TAILGATE HINGE <i>? X SUC</i>	30.00	60.00
5.	1	TAILGATE CHROME HANDLE <i>SUC</i>		320.00
6.	1	TAILGATE LOGO <i>NE</i>		92.00
7.	1	TAILGATE EMBLEM SPORTS ACTYON <i>NE</i>		138.00
8.	1	TAILGATE EMBLEM SSANGYONG <i>NE</i>		84.00
9.	1	TAILGATE INNER PLASTIC BOARD <i>DE</i>		650.00 600
10.	1	RH TAILLAMP <i>CRA</i>		515.00
11.	1	REAR END PANEL <i>DE - X SUC</i>		440.00
12.	1	REAR BUMPER <i>DE</i>		1,750.00 1570
13.	1	REAR BUMPER REINFORCEMENT <i>81</i>		445.00
14.	1	REAR BUMPER REFLECTOR <i>CRA</i>		108.00
15.	1	FRONT BUMPER LOWER GRILLE CENTRE <i>CRA</i>		330.00
16.	1	TAILGATE TOP RUBBER PROTECTOR <i>DE</i>		220.00
17.	1	REAR BUMPER TOP RUBBER PROTECTOR <i>DE</i>		280.00
List Total S\$:				7,954.00
20.00% Discount S\$:				1,590.80
				6,363.20
1.	1	SPECIAL NETT ITEMS		
		70 KM/HR STICKER <i>NE</i>		10.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



ACE ZAG SERVICES
50 EAST COAST ROAD
ROXY SQUARE SINGAPORE (428769)
MR TEO

Attention : Motor Claim Department
Contact : 97845252

Estimate : ES003412

Date : 18/03/2019
Vehicle Num : GBE1652L
Make/Model : SSANGYONG ACTYON SPORTS
Chassis/Eng# : KPADA1ETSFP225129
Accident Date : 12/03/2019
Claim No :
Reference : TP NTUC VS GAIC
Policy No :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

2.	1	REVERSE SENSOR ? 14 /	200	250.00
3.	1	REAR NUMBER PLATE	50	45.00
Special Nett Total S\$:				305.00

LABOUR :
TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING
TO RUSTPROOF ON ACCIDENT DAMAGE AREAS
TO TRANSFER TAILGATE PARTS/MECHANISM
SPRAY PAINTING FRONT & REAR ACCIDENT DAMAGED AREAS
TO CUT/OUT REWELD REAR END PANEL. REPAIR FLOOR PANEL
REPAIR FRONT BUMPER, REINFORCEMENT INCLUDES
KNOCKING & REPLACEMENT OF PARTS

60	180.00
80	250.00
90	50.00
500	1,200.00
500	800.00
2,300.00	

Labour Total S\$:

2,300.00

Signature
25/3/19



E. & O.E.

Total S\$: 8,968.20

Resue
Hp 9001168

7 days

P/P

22/03/19 @ 1050

Resue before paint

for FALCON AIR AUTO SERVICES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER SINGAPORE 039190

Attention : Motor Claim Department
Contact : 68046003

Estimate : ES003412

Date : 08/07/2019
Vehicle Num. : GBE1652L
Make/Model : SSANGYONG ACTYON SPORTS
Chassis/Eng# : KPADA1ETSFP225129
Accident Date : 12/03/2019
Claim No. :
Reference : TP NTUC VS GAIC
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LIST ITEMS :		1,950.00
1.	1	TAILGATE	X	
2.	1	X TAILGATE LOCK X	X	
3.		X TAILGATE HINGE X		320.00
4.	1	TAILGATE CHROME HANDLE		92.00
5.	1	TAILGATE LOGO		138.00
6.	1	TAILGATE EMBLEM SPORTS ACTYON		84.00
7.	1	TAILGATE EMBLEM SSANGYONG		660.00 600
8.	1	TAILGATE INNER PLASTIC BOARD		515.00
9.	1	RH TAILLAMP	X	
10.	1	X REAR END PANEL X		1,570.00
11.	1	REAR BUMPER		445.00
12.	1	REAR BUMPER REINFORCEMENT		108.00
13.	1	REAR BUMPER REFLECTOR		330.00
14.	1	FRONT BUMPER LOWER GRILLE CENTRE		
		List TotalS\$:	6152	6,202.00
		20.00% Discount S\$:	208	1,240.40
			4921.60	4,961.60
		SPECIAL NETT ITEMS :		
1.	1	70 KM/HR STICKER		10.00

CONTINUE / ...

GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER SINGAPORE 039190

Attention : Motor Claim Department

Contact : 68046003

Estimate : ES003412

Date : 08/07/2019
Vehicle Num. : GBE1652L
Make/Model : SSANGYONG ACTYON SPORTS
Chassis/Eng# : KPADA1ETSFP225129
Accident Date : 12/03/2019
Claim No. :
Reference : TP NTUC VS GAIC
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
				200.00
2.	1	REVERSE SENSOR		45.00
3.	1	REAR NUMBER PLATE		100.00
4.	1	TAILGATE TOP RUBBER PROTECTOR		100.00
5.	1	REAR BUMPER TOP RUBBER PROTECTOR		
				<u>455.00</u>
		Special Nett Total S\$:		
		LABOUR :		60.00
		TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING		
		TO RUSTPROOF ON ACCIDENT DAMAGE AREAS X		50.00
		TO TRANSFER TAILGATE PARTS/MECHANISM		900.00
		SPRAY PAINTING FRONT & REAR ACCIDENT DAMAGED AREAS		
		TO CUT/OUT REWELD REAR END PANEL, REPAIR FLOOR PANEL		
		REPAIR FRONT BUMPER, REINFORCEMENT INCLUDES		500.00
		KNOCKING & REPLACEMENT OF PARTS		
				<u>1,510.00</u>
		Labour Total S\$:		

E. & O.E.

Total S\$: 6,926.60

FINAL

for FALCON AIR AUTO SERVICES PTE LTD

7 DAYS

4921.60

455.00

1510.00

6886.60

7 days

P/P



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI19005146/R1qd3s2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 07-08-2019



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBQ 9617H	Veh. Inspected	GBE 1652L
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000003625	Excess (\$)	0.00
Assign From	KELVYNA NGIAN	Assign Date	20/03/2019

2. Vehicle Particulars & Condition

Make & Model	SSANGYONG ACTYON SP 2.0	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KPADA1ETSFP225129	Colour	BLACK
Odometer	233465	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/75 R16C	FIRENZA	6 mm
L/H Front Tyre	225/75 R16C	FIRENZA	6 mm
R/H Rear Tyre	225/75 R16C	FIRENZA	6 mm
L/H Rear Tyre	225/75 R16C	FIRENZA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/03/2019	Inspection Date	22/03/2019
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 8 PANDAN LOOP SINGAPORE 128226		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 1652L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER LOWER GRILLE CENTRE	* CHECK, VERIFY FURTHER	330.00	-
1	TAILGATE	BENT	2,200.00	1,950.00
2	TAILGATE LOCK @ \$161.00	SERVICEABLE	322.00	-
2	TAILGATE HINGE @ \$30.00	SERVICEABLE	60.00	-
1	TAILGATE CHROME HANDLE	SCRATCHED	320.00	320.00
1	TAILGATE LOGO	NECESSARY	92.00	92.00
1	TAILGATE EMBLEM SPORTS ACTYON	NECESSARY	138.00	138.00
1	TAILGATE EMBLEM SSANGYONG	NECESSARY	84.00	84.00
1	TAILGATE INNER PLASTIC BOARD	DEFORMED	650.00	600.00
1	RH TAILLAMP	CRACKED	515.00	515.00
1	REAR END PANEL	SERVICEABLE	440.00	-
1	REAR BUMPER	DEFORMED	1,750.00	1,570.00
1	REAR BUMPER REINFORCEMENT	BENT	445.00	445.00
1	REAR BUMPER REFLECTOR	CRACKED	108.00	108.00
	LESS 20% DISCOUNT		-1,490.80	-1,164.40
			5,963.20	4,657.60
1	TAILGATE TOP RUBBER PROTECTOR (SN)	DEFORMED	220.00	100.00
1	REAR BUMPER TOP RUBBER PROTECTOR (SN)	DEFORMED	280.00	100.00
	LESS 20% DISCOUNT		-100.00	-
			400.00	200.00
SPECIAL NETT ITEMS				
1	70KM/H STICKER (SN)	NECESSARY	10.00	10.00
1	REVERSE SENSOR (SN)	NOT WORKING	250.00	200.00
1	REAR NUMBER PLATE (SN)	SCRATCHED	45.00	45.00
			305.00	255.00
LABOUR				
	TO REMOVE / REPLACE REVERSE SENSOR & CHECK WIRING.		100.00	60.00

Report Ref No. CS/GAI19005146/R1qd3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RUSTPROOFING ON ACCIDENT DAMAGE AREAS.	NOT NECESSARY	150.00	-
	TO TRANSFER TAILGATE PARTS / MECHANISM.		50.00	50.00
	SPRAY PAINTING FRONT & REAR ACCIDENT DAMAGED AREAS.		1,200.00	900.00
	TO CUT / OUT REWELD REAR END PANEL, REPAIR FLOOR PANEL REPAIR FRONT BUMPER, REINFORCEMENT INCLUDES KNOCKING & REPLACEMENT OF PARTS.		800.00	500.00
			2,300.00	1,510.00
	GRAND TOTAL		8,968.20	6,622.60
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$264.00 NETT)			6,622.60

Report Ref No. CS/GAI19005146/R1qd3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.