

Instructions

ASS. REC. BY

MI Veyor

REF CS3/CT1 1900 5144 / GC d302

part of instruction

ASSIGNMENT (Office)

From (Person)

Chong Boon Sen

of

CT1

Estimated Cost

Date/Time:

19/3/19 @ 2.54pm

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EYA / INW / MY / CS

To Inspect Vehicle No:

SKK 8314D

Insured:

GBH 8494P

at Workshop m/s

88 Motorz

Tel:

98111555

of

25 Kaki Bukit Rd 4 # 05-34

Policy No:

DMCVEN18318918000

Claim No:

SNM19D201193C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

15/3/19

CA / REV / REP. / REV 24 HRS

22/3/19

H.O.D. Endorsement

Date/Time:

Person Contacted:

Bryan

Vehicle IN ☒ OUT

Date/Time	Action/Instruction (X) Estimate
	SKK 8314D - X
	GBH 8494P - X
	Dismantle: 25/3/2019.

REF: CTE

ASSIGNMENT

From: Date: 22/3/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKK8314D

at Workshop m/s 88 Motorz

of 25 kaki Bukit Rd 4 #05-34

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

	
N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKK8314D Yr Regn: Dec / 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Camry 2.4 C.C. 2362

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 166963

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR053BK4007036787

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 215/60 R16

R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I. 22-03-19

Survey held at w/s

Des. of Damages: Frt - Rear / O/S / N/S / U/C / Rooftop or 4230pm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$4000 - \$5000

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format: PRQ

Lump Sum / I.B.I: (\$)

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

150

150

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 May 2019		22 May 2019 17:07 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:									
Main Claimant: 88 RENTAL PTE LTD, Co. Reg. No.: 201538190R									
Vehicle Reg. No.: SKK8314D		Date of Loss: 15/03/2019 05:00 - :59							
Claim Type: TP / SNM19D201193C02		Policy/Cover Note No.: DMCVSN18318918000							
Vehicle Reg. No. (Insured): GBH8494P		Policy No. (Claimant): 99994482							
		Excess: S\$0.00							
Repairer: 88 Motorz (sg) Pte Ltd (HQ) 25 Kaki Bukit Road 4 Synergy @ KB #05-34, 417800 Kaki Bukit - Tel: 82200338									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 31/05/2019]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 19 March 2019 2:54 PM
To: Nur Ardiilah Ramli; Charles Hoon
Cc: 88motorz@gmail.com; Jean; assignments
Subject: RE: [our ref: AP/2019/000903] - CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 15 MARCH 2019 AT ABOUT 05:45HRS INVOLVING MOTOR VEHICLES NO(S). SKK8314D AND GBH8494P ALONG AIRPORT BOULEVARD (SNM19D201193)
Attachments: ltr to 3P & China Taiping - (18 Mar 2019).pdf; SKK8314D (1) (1).pdf

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir,

We refer to your email.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Nur Ardiilah Ramli [mailto:ardiilah@apl.com.sg]
Sent: Tuesday, 19 March, 2019 2:43 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Charles Hoon <charles@apl.com.sg>
Cc: 88motorz@gmail.com; Jean <jean@apl.com.sg>
Subject: RE: [our ref: AP/2019/000903] - CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 15 MARCH 2019 AT

Nivitha (LKK Auto)

From: Charles Hoon <charles@aplp.com.sg>
Sent: Wednesday, 20 March 2019 2:42 PM
To: Chong Boon Sen
Cc: 88motorz@gmail.com; assignments; Nur Ardiilah Ramli
Subject: RE: [our ref: AP/2019/000903] - CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 15 MARCH 2019 AT ABOUT 05:45HRS INVOLVING MOTOR VEHICLES NO(S). SKK8314D AND GBH8494P ALONG AIRPORT BOULEVARD (SNM19D201193)

Dear Sir,

Our Client's vehicle can be inspected at:

88 Motorz Pte Ltd
25 Kaki Bukit Rd 4, #05-34
Synergy@KB, Singapore 417800
Contact Person: Bryan (98111555)

Please note that our clients' vehicle will only be available for pre-repair survey within the next two (2) working days. Our clients shall proceed to repair their vehicle thereafter without further notice or reference to you.

All our clients' rights are reserved.

Please note our new office address as of 1st March 2019.

*50 Chin Swee Road,
#07-01 Thong Chai Building, Singapore 169874
Tel no.: 6955 8899
Office mobile no.: 9171 4767
Fax no.: 6900 9899*

Regards,

Charles Hoon

AP Law Practice
50 Chin Swee Road #07-01 Thong Chai Building S169874
T: 6955 8899 F: 6900 9899 E: charles@aplp.com.sg
Singapore UEN No.: 53380739E

This email transmission is confidential and intended only for the addressee(s). It may contain information which is privileged as between solicitor and client or protected by litigation privilege. If you are not the intended recipient, please delete this message and all attachments and inform us by return email. No part of this message should be disclosed to any party, copied or used for any purpose. Thank you for your co-operation.

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 19 March 2019 2:54 PM
To: Nur Ardiilah Ramli <ardiilah@aplp.com.sg>; Charles Hoon <charles@aplp.com.sg>
Cc: 88motorz@gmail.com; Jean <jean@aplp.com.sg>; assignments <assignments@lkkauto.com>
Subject: RE: [our ref: AP/2019/000903] - CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 15 MARCH 2019 AT ABOUT 05:45HRS INVOLVING MOTOR VEHICLES NO(S). SKK8314D AND GBH8494P ALONG AIRPORT BOULEVARD (SNM19D201193)

**WITHOUT PREJUDICE
SAVE AS TO COSTS**

ABOUT 05:45HRS INVOLVING MOTOR VEHICLES NO(S). SKK8314D AND GBH8494P ALONG AIRPORT BOULEVARD (SNM19D201193)

WITHOUT PREJUDICE

Dear Sir,

We refer to your email of even date.

Our clients do not agree to your list of surveyors.

We are instructed to propose the use of one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

- a) Alan Cheong
- b) TT Rajan
- c) Oh Han Cheong
- d) Andrew How
- e) Dave Ho Joo Koong
- f) Sincere Appraiser
- g) Seah Kwang Boon
- h) L H Teo
- i) Mr Willy Goh
- j) Nicky Seah
- k) Jayson Liaw

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors.

Please note our new office address as of 1st March 2019.

**50 Chin Swee Road,
#07-01 Thong Chai Building, Singapore 169874
Tel no.: 6955 8899
Office mobile no.: 9171 4767
Fax no.: 6900 9899**

Ardiilah

Secretary to Mr Charles Hoon

AP Law Practice

50 Chin Swee Road #07-01 Thong Chai Building, Singapore 169874

T: 6955 8899 F: 6900 9899 E: ardiilah@aplp.com.sg

Singapore UEN No.: 53380739E

=====

This email transmission is confidential and intended only for the addressee(s). It may contain information which is privileged as between solicitor and client or protected by litigation privilege. If you are not the intended recipient, please delete this message and all attachments and inform us by return email. No part of this message should be disclosed to any party, copied or used for any purpose. Thank you for your co-operation.

=====

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Sent: Tuesday, 19 March 2019 2:41 PM

To: Charles Hoon <charles@aplp.com.sg>

Cc: Nur Ardiilah Ramli <ardiilah@aplp.com.sg>; 88motorz@gmail.com

Subject: RE: [our ref: AP/2019/000903] - CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 15 MARCH 2019 AT ABOUT 05:45HRS INVOLVING MOTOR VEHICLES NO(S). SKK8314D AND GBH8494P ALONG AIRPORT BOULEVARD (SNM19D201193)

Without Prejudice

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Charles Hoon [<mailto:charles@aplp.com.sg>]

Sent: Monday, 18 March 2019 9:46 AM

To: Claims Dept of China Taiping Insurance <e-claims@sg.cntaiping.com>; Claims Dept of CTI
<claimsdept@sg.cntaiping.com>

Cc: Nur Ardiilah Ramli <ardiilah@aplp.com.sg>; 88 MOTORZ <88motorz@gmail.com>

Subject: [our ref: AP/2019/000903] - CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 15 MARCH 2019 AT ABOUT 05:45HRS INVOLVING MOTOR VEHICLES NO(S). SKK8314D AND GBH8494P ALONG AIRPORT BOULEVARD

Dear Sirs,

Please find attached, our letter of even date.

Please note our new office address as of 1st March 2019.

**50 Chin Swee Road,
#07-01 Thong Chai Building, Singapore 169874
Tel no.: 6955 8899
Office mobile no.: 9171 4767
Fax no.: 6900 9899**

Regards,

Charles Hoon

AP Law Practice

50 Chin Swee Road #07-01 Thong Chai Building S169874

T: 6955 8899 F: 6900 9899 E: charles@aplp.com.sg

Singapore UEN No.: 53380739E

This email transmission is confidential and intended only for the addressee(s). It may contain information which is privileged as between solicitor and client or protected by litigation privilege. If you are not the intended recipient, please delete this message and all attachments and inform us by return email. No part of this message should be disclosed to any party, copied or used for any purpose. Thank you for your co-operation.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	8190R
Vehicle Details	
Vehicle No.:	SKK8314D
Vehicle to be Exported:	No
Intended Deregistration Date:	22 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.4 AUTO ABS AIRBAG
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	2AZE152246
Chassis No.:	MR053BK4007036787
Maximum Power Output:	123.0 kW (164 bhp)
Open Market Value:	\$29,264.00
Original Registration Date:	22 Dec 2009
First Registration Date:	22 Dec 2009
Transfer Count:	3
Actual ARF Paid:	\$29,264.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Dec 2019
PARF Rebate Amount:	\$14,632.00
Intended COE Rebate Details	
COE Expiry Date:	21 Dec 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$20,200.00
COE Rebate Amount:	\$1,145.00
Total Rebate Amount:	\$15,777.00

The information contained herein is correct as at 22 May 2019

OK

MSME19034911 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 15/03/2019 16:48
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/03/2019 16:48
Date Of Accident	15/03/2019 05:45
Exact Location Of Accident	AIRPORT BOULEVARD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKK8314D
Insured/Policyholder	
Name Of Registered Owner	88 RENTAL PTE LTD
Co Reg No	201538190R
Email Address	88MOTORZ@GMAIL.COM
Mobile Phone No	
Alternative Phone No	Office-98111555

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	99994482
Cover Note Number	

Driver

Name of Driver	TAN SWEE SAN
NRIC No	S1761966G
Date Of Birth	05/08/1966
Occupation	OUTDOOR
Date Of Driving Pass	25/02/1988
Driving Experience	31 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98576644

Fax Number

Contact Number

EMail Address

NOEMAIL

Address

BLK 251 SERANGOON CENTRAL DRIVE #04-11

Postcode

550251

Was driver an employee of the Insured's Company

NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle

-
-
-

Insurance Company of Driver's Own Vehicle

-
-
-**General Information of the Accident**

Type Of Accident

COLLISION - U-TURN

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

SERANGOON NEIGHBOURHOOD POLICE CENTRE

Police Station Address

ROAD: 50 SERANGOON AVE 2 #01-02 , **POSTCODE:** 556129 , **COUNTRY:** SINGAPORE

Police Station Contact

TEL NO: 1800-4880999 - **FAX NO:** 64883561

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS DRIVING ALONG AIRPORT BOULEVARD MAKING AN U-TURN TO AIRPORT TERMINAL 2. IT WAS A TRAFFIC JUNCTION. WHEN THE TRAFFIC LIGHT TURNED GREEN, I PROCEED TO MAKE AN U-TURN. SUDDENLY, VEHICLE B FROM OPPOSITE TRAFFIC DID NOT STOP UPON RED LIGHT AND COLLIDED ONTO MY VEHICLE. I AM MAKING THIS REPORT FOR INSURANCE CLAIM PURPOSE.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBH8494P

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE B

Vehicle Category

COMMERCIAL VEHICLE

5/22/2019

E-FILE

Name of Driver

SAUM BIN SALLEH

NRIC/Passport Number

Contact Number

84291281

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

ANNOUNCEMENT




Journal of Management Education, Vol. 30, No. 6
Copyright © 2006 Sage Publications

1. James Earl Ray
 2. James Earl Ray
 3. James Earl Ray
 4. James Earl Ray
 5. James Earl Ray
 6. James Earl Ray
 7. James Earl Ray
 8. James Earl Ray
 9. James Earl Ray
 10. James Earl Ray
 11. James Earl Ray
 12. James Earl Ray
 13. James Earl Ray
 14. James Earl Ray
 15. James Earl Ray
 16. James Earl Ray
 17. James Earl Ray
 18. James Earl Ray
 19. James Earl Ray
 20. James Earl Ray
 21. James Earl Ray
 22. James Earl Ray
 23. James Earl Ray
 24. James Earl Ray
 25. James Earl Ray
 26. James Earl Ray
 27. James Earl Ray
 28. James Earl Ray
 29. James Earl Ray
 30. James Earl Ray
 31. James Earl Ray
 32. James Earl Ray
 33. James Earl Ray
 34. James Earl Ray
 35. James Earl Ray
 36. James Earl Ray
 37. James Earl Ray
 38. James Earl Ray
 39. James Earl Ray
 40. James Earl Ray
 41. James Earl Ray
 42. James Earl Ray
 43. James Earl Ray
 44. James Earl Ray
 45. James Earl Ray
 46. James Earl Ray
 47. James Earl Ray
 48. James Earl Ray
 49. James Earl Ray
 50. James Earl Ray
 51. James Earl Ray
 52. James Earl Ray
 53. James Earl Ray
 54. James Earl Ray
 55. James Earl Ray
 56. James Earl Ray
 57. James Earl Ray
 58. James Earl Ray
 59. James Earl Ray
 60. James Earl Ray
 61. James Earl Ray
 62. James Earl Ray
 63. James Earl Ray
 64. James Earl Ray
 65. James Earl Ray
 66. James Earl Ray
 67. James Earl Ray
 68. James Earl Ray
 69. James Earl Ray
 70. James Earl Ray
 71. James Earl Ray
 72. James Earl Ray
 73. James Earl Ray
 74. James Earl Ray
 75. James Earl Ray
 76. James Earl Ray
 77. James Earl Ray
 78. James Earl Ray
 79. James Earl Ray
 80. James Earl Ray
 81. James Earl Ray
 82. James Earl Ray
 83. James Earl Ray
 84. James Earl Ray
 85. James Earl Ray
 86. James Earl Ray
 87. James Earl Ray
 88. James Earl Ray
 89. James Earl Ray
 90. James Earl Ray
 91. James Earl Ray
 92. James Earl Ray
 93. James Earl Ray
 94. James Earl Ray
 95. James Earl Ray
 96. James Earl Ray
 97. James Earl Ray
 98. James Earl Ray
 99. James Earl Ray
 100. James Earl Ray

\mathbb{R}^n 上のベクトル場 X の \mathbb{R}^n 上の積分曲線 γ は、 $\gamma'(t) = X(\gamma(t))$ となる。

Sketch Plan #2

SKETCH PLAN



A-SKK8314D
B-GBH8494P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING ALONG AIRPORT BOULEVARD, MAKING
A UTURN TO AIRPORT ~~FE~~ TERMINAL 2. IT WAS A
TRAFFIC JUNCTION. WHEN THE TRAFFIC LIGHT TURNED GREEN,
I PROCEED TO MAKE A UTURN. SUDDENLY, VEHICLE B
FROM OPPOSITE TRAFFIC DID NOT STOP UPON RED LIGHT AND
COLLIDED ONTO MY VEHICLE. I AM MAKING THIS REPORT FOR
INSURANCE CLAIM PURPOSES.

DECLARATION

I/We declare that the particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #3

CONFIDENTIAL

Annex E

NOTICE OF COMPLIANCE

This is to confirm that Tan Swee San, HP:98576644 


NRIC/FIN S1761966G, has reported to the Police a non-injury traffic accident which occurred at Airport Boulevard towards Terminal 2 Boulevard on 15/03/2019 at 0545HRS involving the following vehicles:

SKK8314D – Complainant's vehicle
GBH8494P – Defendant's vehicle

- 2 If this accident was reported to the Police within 24 hours of its occurrence, Then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Rank/Name of Issuing Officer: SGT(2) Muhammad Alif Ridhwan

Date: 15/03/2019 Time: 0625hrs

S/D Ref: 14 

Police Post/Unit: Serangoon NPC
Serangoon NPC
No: 50 Serangoon Ave 2
#01-02 Singapore 556129
Tel: 1800 488 0000

Original – to be issued to informant
Duplicate – to be submitted to Traffic Police

CONFIDENTIAL

Version as of 15 Jan 2002



Sketch Plan #4
































...CLAIM SUBFOLDER...(Pending for Survey Report)















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 May 2019		22 May 2019 17:07 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	88 RENTAL PTE LTD , Co. Reg. No.: 201538190R								
Vehicle Reg. No.:	SKK8314D	Date of Loss:	15/03/2019 05:00 - :59 [110 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201193C02	Policy/Cover Note No.:	DMCVSN18318918000						
Vehicle Reg. No. (Insured):	GBH8494P	Policy No. (Claimant):	99994482						
		Excess:	S\$0.00						
Repairer:	88 Motorz (sg) Pte Ltd (HQ) 25 Kaki Bukit Road 4 Synergy @ KB #05-34, 417800 Kaki Bukit - Tel: 82200338								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 31/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKK8314D (SNM19D201193C02)
[GBH8494P]
TP
88 RENTAL PTE LTD
Mar 15 2019 5:00AM
[-]
88 Motorz (sg) Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	15/03/19 16:53	Accident Statement	 Load HTML	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	15/03/19 16:53	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	15/03/19 16:53	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	15/03/19 16:53	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	15/03/19 16:53	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	15/03/19 16:53	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	15/03/19 16:53	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	15/03/19 16:53	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	15/03/19 16:53	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/05/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
2	22/05/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
3	22/05/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
4	22/05/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
5	22/05/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
6	22/05/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
7	22/05/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
8	22/05/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
9	22/05/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
10	22/05/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
11	22/05/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
12	22/05/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
13	22/05/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
14	22/05/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
15	22/05/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
16	22/05/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
17	22/05/19 17:38	General View	 Load JPG	<input checked="" type="checkbox"/>
18	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
19	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
20	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
21	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
22	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
23	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
24	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
25	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	22/05/19 17:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/05/19 17:08	pri contact	Load PDF	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	15/03/19 16:52	Sketch Plan [Linked Accident Report Documents]		Load TIF	
2	15/03/19 16:52	Sketch Plan #2 [Linked Accident Report Documents]		Load TIF	
3	15/03/19 16:52	Sketch Plan #3 [Linked Accident Report Documents]		Load TIF	
4	15/03/19 16:52	Sketch Plan #4 [Linked Accident Report Documents]		Load TIF	
5	15/03/19 16:52	Sketch Plan #5 [Linked Accident Report Documents]		Load TIF	
6	15/03/19 16:52	Sketch Plan #6 [Linked Accident Report Documents]		Load TIF	

Linked Accident Report Documents

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	15/03/19 16:53	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	15/03/19 16:53	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	15/03/19 16:53	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	15/03/19 16:53	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	15/03/19 16:53	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	15/03/19 16:53	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	15/03/19 16:53	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	15/03/19 16:53	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	15/03/19 16:53	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	15/03/19 16:52	Sketch Plan		Load TIF	
2	15/03/19 16:52	Sketch Plan #2		Load TIF	
3	15/03/19 16:52	Sketch Plan #3		Load TIF	
4	15/03/19 16:52	Sketch Plan #4		Load TIF	
5	15/03/19 16:52	Sketch Plan #5		Load TIF	
6	15/03/19 16:52	Sketch Plan #6		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19005149/GCD3E2

Date: 24/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN18318918000

Claimant Vehicle
No : SKK8314DInsured Vehicle
No : GBH8494P

Date of Loss: 15/03/2019

Nature of Claim: TP

Claim
No: SNM19D201193C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKK8314D**

Make & Model: TOYOTA CAMRY, 2.4 (A)

Reg. Date: 22/12/2009 (Man. Year: 2009)

Colour: Silver

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 2AZE152246

Chassis No: MR053BK4007036787

Odometer: 166963 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 22/05/2019

Date Inspected: 22/03/2019 Inspected At:

 88 Motorz (sg) Pte Ltd (HQ)
 25 Kaki Bukit Road 4 Synergy @ KB #05-34
 Singapore 417800

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2019)
Parts:	143	TOYOTA CAMRY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKK8314D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >