## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO: SHA 4114D

DATE 21/3/2019 9:59

 $A \times A$ 

MAKE :

ODEL	: HYUNDAI SONATA  Parts Description/ Labour	Type	Uni	it Price	Amount	
Qty		1 2 7 2			\$	1,151.80
	Bonnet		\$	87.50	\$	175.00
	Bonnet Hinge (LH/RH)				\$	120.90
	Bonnet Moulding	4			\$	232.80
	Bonnet Insulator				\$	10.00
	Bonnet Insulator Clips				\$	282.10
	Radiator Grille				\$	108.90
	Radiator Grille U Moulding				\$	538.80
	Front Bumper Cover				\$	136.30
	Front Bumper Sponge				\$	504.10
	Front Bumper Reinforcement		\$	17.60	\$	35.20
	Front Bumper Grille (LH/RH)		\$	22.40	\$	44.80
	Front Bumper Bracket Top (LH/RH)		\$	29.20	\$	58.40
	Front Bumper Protector (LH/RH)		\$	20.10	\$	40.20
	Front Bumper Bracket (LH/RH)		3	20.10	\$	1,023.00
	Headlamp Support Panel Assy		0	797.90	\$	1,595.80
	Headlamp (LH/RH)		\$	797.90	\$	814.80
	Radiator				\$	651.30
	Radiator Fan Blade, Cowling, Motor Assy				\$	6.20
	Radiator Bracket				200	45.40
	Radiator Hose Upper				\$	45.4
	Radiator Hose Lower				\$	46.0
	Radiator Expansion Tank				\$	83.1
	Horn Unit (RH)				\$	
	Horn Wire			#02.00	\$	150.0
	Front Fender (LH/RH)		\$	593.00	\$	1,186.0
	Front Fender Shield (LH/RH)		\$	86.00	\$	172.0
	Front Fender Retainer		280		\$	9.2
	Air Cleaner Assy				\$	254.3
	Air Duct				\$	197.5
	Air Cleaner Body				\$	101.8
	Aircon Condenser				\$	1,089.9
	Battery Tray				\$	53.0
	Front Chasis Member (LH/RH)		\$	1,219.80	\$	2,439.6
	Engine Under Cover				\$	328.7
	Engine Crossmember				\$	2,143.7
	ECU Bracket				\$	78.3
	ECU Unit				\$	4,028.3
	Oil Cooler - Tube Assy-P/Stg				\$	256.0
	Inter Cooler				\$	771.5
NO	Inter Cooler Mounting (2 PCS)				\$	24.8
Larry N9	Hose B To Inter Cooler				\$	220.1
	Hose C To Inter Cooler Inlet				\$	108.5
	Pipe To Inter Cooler				\$	160.0
	Pipe To Inter Cooler Outlet				\$	234.3
	Controller (PWN)				\$	495.

Qty	Parts Description/ Labour	Type	Unit Price		Amount	
	Wiring-Front			\$	1,879.00	
				6	24 122 60	+
	SUB TOTAL				24,132.60	- 1
	LESS 20%			\$	4,826.52 <b>19,306.08</b>	_
	DISCOUNTED TOTAL			3	19,300.08	+
	Front Number Plate			\$	25.00	N
	Front No Plate Trim Cover			\$	30.00	N
	New Battery			\$	207.00	N
				\$	262.00	+
	Labour Charge					
	Panel Beating			\$	1,200.00	
	Spray Painting Charge			\$	1,200.00	
	Wiring Charge			\$	50.00	
	Tuff Kote			\$	50.00	
	Towing Charge Front Chassis Alignment Charge			\$	60.00 400.00	
	Remove/Refix Aircon & Refill Gas			\$	150.00	
	Remove/Remy Ancon & Remi Gas			Φ	130.00	
	TOTAL LABOUR			\$	3,110.00	-
	ESTIMATE TOTAL			\$	22,678.08	
	1.1.1111					
	Kahri Mas					
	Reconnell to Scrap  whecomodized to Report					
	1/1 -1/3/19 14/54					
	1/2//					
	1 11 to Scrap					
	Recoher					
N9	121 le Report					
10 M	wh elon notice					
	This is an initial estimate based on a visual inspection of the	ahava vahi	ala Tha Gual namain	anant	-211	1

## COMFORTDELGRO ENGINEERING PTE LTD

VEHICLE NO: SHA 4114D

DATE 21/3/2019 10:02

MAKE

MODEL : HYUNDAI SONATA

Qty		Type			
	Parts Description/ Labour Boot Lid			\$	1,349.50
	Boot Lid Lock Upper			\$	132.10
	Boot Lid Lock Lower			\$	30.30
	Boot Lid Sonata Plate			\$	43.60
	Boot Lid Hyundai Plate			\$	24.20
	Boot Lid 'H' Emblem			\$	26.10
	Boot Lid CRDI Plate			\$	22.70
. 1	Rear Bumper			\$	578.40
	Rear Bumper Reinforcement			\$	483.30
	Rear Bumper Clip			\$	22.00
	Rear Bumper Bracket (LH/RH)		\$ 49.00	\$	98.00
	Rear Bumper Sponge			\$	137.40
	Rear Bumper Under Cover			\$	185.80
	Rear Bumper Protector (LH/RH)		\$ 38.00	\$	76.00
	Rear Panel			\$	391.80
	Rear Panel Garnish			\$	95.80
	Total Tallet Salation				
	SUB TOTAL			\$	3,697.00
	LESS 20%			\$	739.40
	DISCOUNTED TOTAL			\$	2,957.60
	Boot Lid Comfort Logo & Tel No. Sticker			\$	30.00
	Rear Bumper Reverse Sensor			\$	135.70
	Rear Bumper Rubber Mat			\$	50.00
				\$	215.70
	Labour Charge Panel Beating			\$	800.00
	Spray Painting Charge			\$	900.00
	Wiring Charge			\$	30.00
	Tuff Kote			\$	50.00
	Remove/Refix Reverse Sensor			\$	120.00
	TOTAL LABOUR			\$	1,900.00
Larry NG	TOTALEABOUR			-	2,500.00
Larry.	ESTIMATE TOTAL			\$	5,073.30
	This is an initial estimate based on a visual inspection of the be prepared after the vehicle is surveyed by a motor Surveyed.				

Page 1 of 1



member of COMFORIDELGRO

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701 Meinline +85 6383 8280 Facsimile +85 6280 9755

Service Centres
205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 50869
58 Sin Ming Drive Singapore 50869
58 Sin Ming Drive Singapore 50869
58 Sin Ming Drive Singapore 575717
7 Sungel Kadut Way Singapore 728791
24 Sanako Loop Singapore 758156





## JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

	N FOR BREAKDOWN 7 19				
Date: 20/03/9 Time Received: 1400  New SPARK Kakis Name of Customer: M5 Manna  Contact No.: 65508570  Vehicle No.: SHA 41140	3. Vehicle Type:  Private  Private  Fleet  STK (Boon Lay)  5. Nature of Service:	PL)	4. Type of Towing:  Normal Tow  King Dolly  Flat Bed  Crane-up  6. Parts Replaced/Remarks:		
Make/Model/Colour: H/Sonuta	Jumpstart Recovery Change Tyre /		Walahaa		
. Preferred Workshop:  Braddell Loyang Sin Ming Sungei Kadut Senoko Komoco (UBI / Leng Kee) Others:	Pandan Ubi Cycle & Carriage (PD)	8. Vehicle Tow - In Smoky Ext Overheatin Brake Faul Starting Pr Accident Return Tay	naust		
0. Odometer Reading :  Fuel Level : F 1/4 1/2 3/4  Job Attended  12. Tow Truck / Recovery Van : VRS D QA  Name of Driver : Vehicle No. : Yes	4 E	K aulty ot tested	#: Cracked X: Dented /: Scatched O: Missin		
Time Dispatch  Time of Arrival  Time Completed:  Cash Invoice Details (if applicable)	30		Signature of Customer		
13. Cash Invoice No. :					
Customer Acknowledgement  a. I have been advised to remove all valuable items in my versash cards, spectacles, pen, etc. b. I understand that any items left behind are at my own risk c. Surcharge: Towing fee will be levied if the customer decided.	Land SDARK Car CareTM will not be I	neld liable for such losse he repairs in SPARK Car	es. Care <sup>TM</sup> .		
Date  14. WORKSHOP	Time	Signat	ture of Customer		
Name of Attending Staff/Guard Da	ate & Time of Arrival	Signature o	of Attending Staff/Guard WORKSHOP		