

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19005155/AKA3Q2

Date: 30/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : FZ656A **Insured Vehicle No :** SLF1936U

Date of Loss: 11/02/2019 **Nature of Claim:** TP **Claim No:** 1554141412SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FZ656A		
Make & Model:	HONDA CB400SF, 399cc	Engine No:	NC23E2064041
Reg. Date:	01/04/2005 (Man. Year: 2004)	Chassis No:	JH2NC39914M020036
Colour:	White	Odometer:	135306 km
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/60R17	Rear Tyre Size:	160/60R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,380.00	1,440.00	940.00	39.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	260.00	230.00	30.00	11.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,640.00	1,670.00	970.00	36.74
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	2,640.00	1,300.00	1,340.00	50.76
+ GST 7.00/7.00% (S\$)	184.80	91.00	93.80	50.76
Nett Amount (S\$)	2,824.80	1,391.00	1,433.80	50.76
+ Loss of Use (4.0 x S\$20.00/day) (S\$)		80.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		1,478.49		
Global Sum Settlement (S\$)		1,478.00		

INSPECTION

Date of Assignment: 21/03/2019

Date Inspected: 27/03/2019 Inspected At:

UNIQUE MOTORSPORTS- 1 KAKI
BUKIT AVE 6 #02-54
Repairer: ComfortDelGro Engineering
Pte Ltd (Ubi)

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CUSTOMISED CRASH BAR	Bent	850.00 FS	*700.00 FS
2	1		*CUSTOMISED REAR CRASH BAR-KLEFT	Bent	320.00 FS	*250.00 FS
3	1		*REAR SADDLE BAG-LEFT	Not Necessary	720.00 FS	*- FS
4	1		*SADDLE BAG COVER-LEFT	Deformed	370.00 FS	*370.00 FS
5	2		*3M REFLECTIVE STICKER	Necessary	120.00 FS	*120.00 FS
					Total Parts (S\$)	2,380.00 1,440.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REPLACE DAMAGE PARTS	New	200.00	200.00
2	TRANSPORTATION FOR DELIVER BOX FOR APPLYING STICKERS	New	60.00	30.00
Gross Labour Cost (\$\$)			260.00	230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >