



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Repair Estimates

SLK 1780 A

Not Authorized
Repair by paint

Parts	(a) Cost / List Price Items	\$	2,812.90
	Plus/Less 25%	\$	703.23
	Total of Cost / List	\$	2,109.68
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	200.00
Total Parts Cost		\$	2,309.68
Labour		\$	1,620.00
Total		\$	3,929.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / Not Required

(d) Excess

(e) Signature of surveyor

Date:

21/3/19

Parts

No. : SLK 1780 A
Model : TOYOTA PRIUS
No : JTDKB3FU903540072

Submit By : Carmen Lim
Year Manufacture : 2016
Engine No. :
Cost / List

	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
	Reverse sensor	1	\$200.00	S.N	X
	Rear bumper	1	\$497.50		X
	Rear bumper clip	1	\$40.00		X
	Rear bumper side retainer LH	1	\$112.70		X
	Rear bumper side retainer RH	1	\$112.70		X
	Rear bumper lower garnish centre	1	\$582.60		✓
	Rear bumper lower garnish LH	1	\$149.70		X
	Rear bumper lower garnish RH	1	\$149.70		X
	Rear bumper tow cover	1	\$31.70		✓
	Tail end panel	1	\$596.60		X
	Tail end panel garnish	1	\$151.60		X
	Tail end panel garnish clip	10	\$35.00		✓
	Boot weatherstrip	1	\$353.10		X
4					
5					
6					
7					
8					
9					
0					
1					
2					
3					

If any of the quoted parts are recommended to be repaired, then an additional labour charge
e charged accordingly under supplementary.



Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Vehicle No. : SLK 1780 A Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2016

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.