From (Person)	Chong Boon		CTI (Office)		ate/Time: 21	morch. 19	2.54
To Inspect Ve	thicle No. SJ	5898Y	Bill to: MV / CS		YP 541		
of / Kati Policy No:	Butit Avenue DMCVSN	6 \$ 02-11	Claim No:				
Sum Insured: Make of Veh: (Client's Record			Excess:_	1	0.0.A. 19.	3. 2019	
CA / REV	REP. / REV 241	HRS Person Cont	acted: ST	Ve	H.O.D. Enderso	ment.	
Date/Time	Action/Instruction SJJ 5302 YP 591 E	Y- ×	linate.				
8/4/19	Adrian a	oficeal 10	\$ 15000	(Parl III	Lich II	110 %	

REEL

ASS, REC. BY

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adi Assigned	Adj Rpt	Ad) Sub	mitted	Ins Auth'ed	Status	
Main	25 Mar 2019		25 Mar 2019 09:37 Edit Adj Rpt					Pending Report Cancel Ca	for Survey
	Main	Re	ference		Claim Details		Documer	nts	Show All
CLAIM SU	BFOLDER DE	TAILS				[Creat	ed by insurer]		
Insured:									
Main Claimant:	TAM LEE	CHIN, ID: 5756	4322E						
Vehicle Reg No.:	SJJ5898	BY			Date of Loss:	19/03/2	2019 16:00 - :59		
Claim Type:	m Type: TP / SNM19D201263C02 Policy/Cover Note No.: DMCV		DMCVSN30776618000						
Vehicle Reg No. (Insured):	YP591E				Policy No. (Claimant):	GA1080	74		
					Excess:	5\$0.00			
Repairer:	Jec Autor	notive (HQ) 1 KA	KI BUKIT AVENU	JE 6, #02-1	1 AUTOBAY, 4178	383 Kaki i	Bukit - Tel: 6509 6	585	
Handling Insurer:	China Tai	ping Insurance	(Singapore) Pt	e. Ltd. (HQ) - Tel: 6389 611	11 [Har	ndled by Chong B	oon Sen]	
Claimant's Insurer:	MODEL DOZDANA	rance Pte Ltd (H							V-7/1-1-1-1
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Handled by	ADRIAN	LING] [Final	Rpt due 03	3/04/2019]
ASSOCIAT	ED MAIL RE	CEIVED						View All	ompose Case Ma
There are n	o mail for this	case.							
ALL ASSO	CIATED TAS	sks⊟				View	All Search Tasks	Create Nev	Task Complet
Due Date	e Priority	Type Task	Group Sub	ject Har	ndler Assign	ned By	Completed O	n Creat	ed On Done

Nivitha (LKK Auto)

From:

Chong Boon Sen <booksen.chong@sg.cntaiping.com>

Sent:

Thursday, 21 March 2019 2:38 PM

To:

bonnie kwok assignments

Subject:

RE: (OUR REF: SNM19D201263-YP591E) Urgent: Pre-Repair Inspection: Your Vehicle: YP 591 E; JEC's Vehicle: SJJ 5898 Y; ACCIDENT INVOLVING SJJ 5898 Y & YP 591 E

ON 19 March 2019

Without prejudice

Dear Sir,

We will appoint LKK.

Dear LKK,

Pls pri.

Regards,

Chong Boon Sen

Claims Executive Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909 Co. Reg. No. 200208384E

DID: 63896171 Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: bonnie kwok [mailto:litigation@bonniekwok.com]

Sent: Thursday, 21 March, 2019 2:17 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: (OUR REF: SNM19D201263-YP591E) Urgent: Pre-Repair Inspection: Your Vehicle: YP 591 E; JEC's

Vehicle: SJJ 5898 Y; ACCIDENT INVOLVING SJJ 5898 Y & YP 591 E ON 19 March 2019

Dear Sirs,

Our client agrees to Adrian Ling as the Single Joint Expert (SJE).

Please let us have his report in due course.

Kindly request for the SJE to contact the repairers, M/s JEC Auto Service at 9232 7457 to make the necessary arrangements.

Regards,

BONNIE KWOK LLC

Advocates & Solicitors 101A Upper Cross Street #08-12 People's Park Centre Singapore 058358

TEL: 6536 6026 FAX: 6536 2279

email: litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Thu, 21 Mar 2019 at 13:41, Chong Boon Sen

boonsen.chong@sg.cntaiping.com wrote:

Without Prejudice

Dear Sir.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN
OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

HENRY NG	
----------	--

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sq.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Claims Dept of CTI

Sent: Wednesday, March 20, 2019 11:15 AM

To: Angie Foo

Subject: FW: Urgent: Pre-Repair Inspection: Your Vehicle: YP 591 E; JEC's Vehicle: SJJ 5898 Y; ACCIDENT INVOLVING

SJJ 5898 Y & YP 591 E ON 19 March 2019

From: bonnie kwok [mailto:litigation@bonniekwok.com]

Sent: Wednesday, 20 March 2019 11:14 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: Urgent: Pre-Repair Inspection: Your Vehicle: YP 591 E; JEC's Vehicle: SJJ 5898 Y; ACCIDENT INVOLVING SJJ

5898 Y & YP 591 E ON 19 March 2019

Urgent

Dear Sirs.

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle no. SJJ 5898 Y at M/s JEC Auto Service, 1 Kaki Bukit Avenue 6 #02-11 Autobay Singapore 417883.

Regards,

ST

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email: litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC	
Owner ID:	98071	
White distance in the second		
Vehicle No.:	SJJ5898Y	
Vehicle to be Exported:	Yes	
Intended Deregistration Date:	21 Mar 2019	
Vehicle Make:	HONDA	
Vehicle Model:	FIT 1.3G A	
Primary Colour:	Pink	
Manufacturing Year:	2008	
Engine No.:	L13A4034184	
Chassis No.:	GE61030276	
Maximum Power Output:	73.0 kW (97 bhp)	
Open Market Value:	\$13,186,00	
Original Registration Date:	19 Sep 2008	
First Registration Date:	19 Sep 2008	
Transfer Count:	3	
Actual ARF Paid:	\$10,930.00	
Interigan PARE Remate Descrip		
PARF Eligibility:	Forfeited	
PARF Eligibility Expiry Date:	210000	
PARF Rebate Amount:	\$0.00	
Internet Controller partie		
COE Expiry Date:	18 Sep 2028	
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	10	
PQP Paid:	\$32,339.00	
COE Rebate Amount:	\$30,701.00	
Total Rebate Amount:	\$30,701.00	

The information contained herein is correct as at 21 Mar 2019



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report helpo made excelleble

aforesaid.	to the report being made available	
	ACCIDENT STATEMENT	
Date Of Report	20/03/2019 09:54	
Date Of Accident	19/03/2019 16:00	
Exact Location Of Accident	ALONG PAYA LEBAR TWDS UPPER PAYA LABER	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	П
Vehicle Registration Number	SJJ5898Y	
Insured/Policyholder		
Name Of Registered Owner	TAN POH LIN	
NRIC No	S1129807I	
Email Address	NOEMAIL	

Mobile Phone No (LOCAL) +65-92746278 Alternative Phone No. OFFICE-92746278

Vehicle Particulars

Manufacturer HONDA Model FIT

Exact Purpose for which vehicle was being used at PRIVATE USE time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

If No, Please state action to be taken THIRD PARTY Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

NO

Type Of Coverage COMPREHENSIVE Fleet Policy

Policy Number 5103953532

Cover Note Number

Driver

Name of Driver TAN POH LIN NRIC No S11298071 Date Of Birth 15/01/1955 Occupation INDOOR Date Of Driving Pass 11/04/1986

Driving Experience 32 YEARS AND 11 MONTHS

Gender FEMALE

Mobile Number +65-92746278

Fax Number

Contact Number OFFICE-92746278

EMail Address NOEMAIL Address

2 GUAN SOON AVE

Postcode

489574

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

YP591E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

PERIYAKARUPPAN DURAI

NRIC/Passport Number

F7791774T

Contact Number

90274404

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJF7898E

Vehicle Make/Model/Colour Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

PRIVATE CAR TAN LEE CHIN S7564322E

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material
 facts may allow insurance companies to repudiate policy liability.
- The Issue and acceptance of this Form by insurance companies is not an admission of policy flability on the part of the insurance companies.
- 5. Any faise reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurence Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or desiling with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (II) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (IV) administering my claims (Including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

a material results.

(if driver

Oriver's Signature (if driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signatura Name:

NRIC/FIN No.:

DESCRIBE CIRCUMSTANCE		Vehicle A: SJJE B=VP50 C:SJF7
I deel	an impact from beh	and couse my
vehicle (A) hi-		Them After I checked,
ît was a	chain collision.	
DECLARATION NWe declare the foregoing part	culars are true in every respect.	Show
olicyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

with Stewart and St.

JEC AUTO SERVICE

1 Kaki Bukit Ave 6 #02-11 Autobay, Singapore 417883

Hp: 9232 7457@Ah Xian Tel: 6509 6585 Fax: 6509 6584

Email: jecautoservice@yahoo.com.sg

TP Chin.

Verox.

Vehicle No.: SJJ 5898 Y Owner:

TAN POH LIN

Accident Date:

19/3/2019

Model: Honda Fit

Qty	Description	A	amt S(\$)
	•	-	
1	Front bonnet P. Started	\$	716:90 579
2	Front bonnet hinges	5	77.00 K
1	Front bonnet insulator AH MA	5	134.50 ₹
1	Front bonnet lock De-yc	5	105.00
1	Front bonnet rubber	5	28.60 ₹
2	Front headlamps Could	\$	1,433.80
2 2 1	Front headlamp lower brackets Culled	5	07.20 57.60
1	Front bumper Distarted	5	680.90 523 4
1	Front bumper centre grille	5	118.50
1	Front bumper reinforcement	5	310:00 245
2	Front bumper side retainers	5	57.20
1	Front bumper tow hook cover Missing	5	28.50
2 2	Front fenders	5	1,143.00 -
2	Front fender brackets He-	5	93.60 /
2	Front fender inner shields Hen	S	243.20
1	Front support panel Beot	S	589.50
1	Front brace panel New	5	146.90 ×
2	Homs Man	5	173.00 +
1	Air con condenser Best	5	855:90 762.81
1	Air con discharge pipe 2	5	385.00
1	Air con liquid pipe	5	186.50 ±
1	Air con suction pipe	5	296.50-
1	Air con electric fan care	5	585.00
1	Radiator Best	5	1,437.60 1137.20
1	Radiator electric fan Cocc	5	585.00
1	Radiator spare tank & Me Me	5	89.60 ×
1	Radiator top hose	5	38.60 ×
2	Radiator top mountings > ~	S	37.00 →
1	Air intake duct	9	48.60 ₹
1	Exhaust inlet manifold The ~	5	322.30 ₺
1	A A STATE OF THE S		115 10 #
1	Rear windscreen glass Shattered	5	1.240.60 11805
1	Rear windscreen inner scal	,	198.20 7340
1	Rear tailgate Delete		966.00 845-60
2	Rear tailgate dampers Bert	\$	
2	21600 (TO) (-) 1310 (1010 (1010 (1010)) (TO) (1010) (TO)	\$	263.00
1	Rear tailgate inner trim board	5	137.40
-1	Rear tailgate inner trim board	5	254.50
1	Rear tangate inner lock.	5	183.50
1	Rear tailgate logo MM	5	56.00 28
1	Rear tailgate outer garnish Cul-C	\$	190.60 113/10
		\$	14,650.30

			5	14,650.30
	List Items		1000	
1	Rear tailgate rubber Lt		5	154.10
1	D . II . DETER LI AND		5	48.50
2	Rear tailgate rumber plate lamp		5	97.20 X
1	Rear tailgate outer key set pren-		5	195.80 ℃
1	Rear tailgate inner pull pocker set re-		5	85.60×
1	Rear wiper arm Lt		5	68.50
1	Rear wiper arm cover (and d		5	18.50
1	Rear wiper motor Do od		5	435.60 253
2			5	1.05220 57
2	Rear taillamp panels RH Buckled		5	876.40 146
1	Rear end panel Dished		5	558.40 450 0
1	Rear end panel innergrantish 90		5	213.40 60.60
1	Rear bumper Distilled		5	660.90 453 70
2	Rear bumper brackets He M		5	65.40 4
2	Rear bumper side retainers 146		5	61.00
1	Rear bumper tow hook cover (MCE)			38.50 13 30
1	Rear bumper tow hook bracket		4	216.50~
1	Rear floor panel Distated		4	965.00 737
1	Rear floor board & L		5	280.40
ıi.	Rear spare tyre tool sponge, trave Lund		6	289.50
1	Rear exhaust silencer		č	580.70
2	Rear exhaust mountings M		e e	57.00 ×
1	Rear exhaust heat shield compled	1530370	2	105.90
2	Rear fenders RH Sucked	10000 00	e	2788.005.688.20
2	Rear fender air gates yet m	177579	e	91.20
2	Rear fender top inner trim garnishes		4	379.20 ×
2	Rear fender lower inner trim garpishes och 2		e e	571-20 A42.80
2	Rear fender inner shields RH Wood		e e	9720 4860
2	Rear fender inner trim boards Reported		g.	671.20
31	Rear door -R/H Zy		e e	780.00
1	Rear door rubber Ate Mu		9	86.90 +
	Kear door rubber //FE 1940		5	26,330.20
	Less 20%		2	5,266.04
	6400 21/10		5	21,064.16
			*	21,004.10
	Special Nett Items			
1	Front bonnet insulator clip (1 set) AL ~		5	35.00 /
1	Front grille assy Culled		S	350.00
1	Front bumper clip (1 set) NG		\$	50.00-≥ ⊃
1	Front number plate with holder Dod		\$	50.00
2	Front fender inner shield clips (2 set) put -		5	70.00 K
1	Rear windscreen scalant NC		\$	80.00 60
1	Rear wiper motor ## ~	1220	5	40.00 #
1	Rear bumper clip (1 set)	1300	\$	£5.00° 3 €
1	Rear number plate with holder Bad		\$	5 0:00 3 ∪
1	Rear reverse sensor (1 set) Dond		5	350.00 ₹30
1	Rear reverse camera Dege		5	480.00-330
1	Rear floor panel insulator New		5	150.00
2	Rear fender quarter glass scalants XXV PW		\$	200-60 4-0
			5	1,950.00

	Labour Charges			
1	To check wiring and reset headlampe focusing.		5	80:00 30
2	To remove, replaced damaged lamps and check up rear wiring.		5	80.08 3 O
3	To remove and refit inner garnashes,		5	180:00 /50
4	To remove and refit rear reverse sensor and camera.		5	150.00100
5	To transfer boot lid mechanism and wiring assembly		S	120.00 80
6	To remove and refit fuel tank assembly with all attachments.		5	150.00 80
7	To remove, refit air-con condenser, will gas & conduct leakage test		5	180.00 120
8	To remove and refit rear windscreen glass.		5	180.00-120
9	To remove, refit and replace exhaust silencer and mountings.		S	180:00 8 2
10	To apply underconting.	. 0	5	309:00 /30
11	Panel beating, remove and replacing above parts.	190	5	2,500:00 2300
12	To respray painting.		5	2490.00 2000.
			5	6.470.00

ESTIMATE PARTS AND LABOUR TOTAL S

29,484.16

total: 18752.56. 4/s: 15k

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display camaged pan(s) during resurvey
- . Parts prices are subject to confirmation
- . Third party survey is on a "Wimout Prejudice" basis
- . No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

AIM SUB	OLDER TRA	CKING								
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj	Submitted	Ins Auth'ed	Status		
Main	25 Mar 2019		25 Mar 2019 09:37 Edit Adj Rpt	S\$15,000.00 Edit Estimates	1	5,000.00 ew Rpt		Pending fo Report Cancel Cas	14	
	Main	R	eference	Claim D	etails		Documents		Show All	
CLAIM SU	BFOLDER DE	TAILS				[Created	by insurer]			
Insured:	-, 1D: -									
Main Claimant:	TAM LEE	TAM LEE CHIN, ID: \$7564322E								
Vehicle Reg No.:	SJJ5898	SJJ5898Y					9 16:00 - :59 hs From LTA Reg !	Date (Man Yr)]		
Claim Type:	TP / SNI	TP / SNM19D201263C02				DMCVSN30776618000				
Vehicle Reg No. (Insured):	YP591E	YP591E				GA108074				
				Excess	1	5\$0.00				
Repairer:	Jec Autor	notive (HQ) 1 KA	KI BUKIT AVENUE 6	, #02-11 AUTOBA	Y, 4178	83 Kaki Buki	t - Tel: 6509 658	5		
landling	China Tai	ping Insurance	(Singapore) Pte. L	td. (HQ) - Tel: 63	89 6111	1 [Handles	by Chong Boon	Sen]		
Claimant's Insurer:	AXA Insu	rance Pte Ltd (H	(Q) - Tel: 6338 7288	5						
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [Hand	ed by A	DRIAN LIN	G] [Final Rp	t due 03/04/2	2019]	
ASSOCIAT	ED MAIL RE	CEIVED					Vie	w All Compo	se Case Mail	
There are n	o mail for this	case.								
ALL ASSO	CIATED TAS	xs∃			-	View All S	Search Tasks C	reate New Task	Complete	
Due Date	Priority	Type Task	Group Subjec	t Handler	Assign		Completed On	Created O		

Claim Documents

*SJJ5898Y (SNM19D201263C02)
[YP591E]
TP
TAM LEE CHIN
Mar 19 2019 4:00PM
[-]
Jec Automotive

Ass	essment Reports		1 per	page 🔽	~
No	Finalized On	Ah Lim Motor Company (AMK)	- Contraction of the Contraction	Thumbnall	and the second
1	20/03/19 17:20	Accident Statement	0	Load HTM	
Pho	otos/Images		3 per	page V	V
No.	Finalized On	Ah Lim Motor Company (AMK)	2 per	Thumbnail	-
1	20/03/19 15:16	Accident Photo [Linked Accident Report Documents]	0	Load JPG	120
2	20/03/19 15:16	Accident Photo [Linked Accident Report Documents]	0	Load 3PG	50
3	20/03/19 15:16	Accident Photo [Linked Accident Report Documents]	0	Load JPG	Ø
4	20/03/19 15:16	Accident Photo [Linked Accident Report Documents]	0	Load JPG	S Z
5	20/03/19 15:16	Accident Photo [Linked Accident Report Documents]	0	Load JPG	Ø
6	20/03/19 15:16	Accident Photo [Linked Accident Report Documents]	0	Load JPG	Ø
7	20/03/19 15:16	Accident Photo [Uniked Accident Report Documents]	0	Load JPG	$\overline{\mathbf{A}}$
8	20/03/19 15:16	Accident Photo [Linked Accident Report Documents]	0	Load JPG	₩
9	20/03/19 15:16	Accident Photo [Linked Accident Report Documents]	0	Load JPG	☑
10	20/03/19 15:16	Accident Photo [Linked Accident Report Documents]	0	Load JPG	☑
11	20/03/19 15:16	Accident Photo [Limked Accident Report Documents]	0	Load JPG	V
12	20/03/19 15:16	Accident Photo [Linked Accident Report Documents]	0	Load 3PG	V
13	20/03/19 15:16	Accident Photo [Linked Accident Report Documents]	0	Load JPG	Ø
14	20/03/19 15:16	Accident Photo [Linked Accident Report Documents]	0	Load 3PG	Ø
15	20/03/19 15:16	Accident Photo [Linked Accident Report Documents]	0	Load 3PG	Ø
16	20/03/19 15:16	Accident Photo [Linked Accident Report Documents]	0	Load JPG	Ø
17	20/03/19 15:16	Accident Photo [Linked Accident Report Documents]	0	Load 3PG	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	08/04/19 10:06	General View	0	Load JPG	V
2	08/04/19 10:06	General View	0	Load JPG	3
3	08/04/19 10:06	General View	0	Load JPG	V
4	08/04/19 10:06	General View	0	Load JPG	1
5	08/04/19 10:06	General View	0	Load JPG	$\overline{\mathbf{A}}$
6	08/04/19 10:06	General View	0	Load JPG	20
7	08/04/19 10:06	General View	0	Load 3PG	3
8	08/04/19 10:06	General View	0	Load JPG	V
9	08/04/19 10:06	General View	0	Load 3PG	
10	08/04/19 10:06	General View	Ð	Load JPG	V

	essment Reports		per la contracta de la contrac	~ 2
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbn Load JP	
11	08/04/19 10:06	General View		- 14
12	08/04/19 10:06	General View	1 Load JP	-
13	08/04/19 10:06	General View	1 Load JP	
14	08/04/19 10:06	General View	■ Load JP	
15	08/04/19 10:06	General View	■ Load JP	G E
16	08/04/19 10:06	General View	■ Load JP	6 5
17	08/04/19 10:06	General View	Load JP	G 5
18	08/04/19 10:06	General View	D Load JP	G E
19	08/04/19 10:06	General View	Load 3P	6 5
20	08/04/19 10:06	General View	Load JP	G E
21	08/04/19 10:06	General View	■ Load JP	G 5
22	08/04/19 10:06	General View	£ Load 3P	G 5
23	08/04/19 10:06	General View	■ Load 3P	G 5
24	08/04/19 10:06	General View	D Load JP	
25	08/04/19 10:06	General View	D Load JP	-
26	08/04/19 10:06	General View	O Load JP	-
27	08/04/19 10:06	General View	O Load JP	
28	08/04/19 10:06	General View	D Load 3P	-
29	08/04/19 10:06	General View	O Load JP	
30	08/04/19 10:06	General View		_
	W 200 W 20 W 20 W 20 W 20 W 20 W 20 W 2		10 Load JP	
31	08/04/19 10:06	General View	D Load JP	_
32	08/04/19 10:06	General View	1 Lbed JP	-
33	08/04/19 10:06	General View	1 Load JP	
34:	08/04/19 10:06	General View	1 Load 3P	
35	08/04/19 10:06	General View	1 Load JP	- Indian
36	08/04/19 10:06	General View	1 Load JP	6 B
37	08/04/19 10:06	General View	■ Load JP	
38	08/04/19 10:06	General View	■ Load 3P	G 5
19	08/04/19 10:06	General View	■ Load JP	G S
40	08/04/19 10:06	General View	■ Load JP	G E
11	08/04/19 10:06	General View	■ Load 3Pd	G E
12	08/04/19 10:06	General View	£ Load JPI	G E
13	08/04/19 10:06	General View	£ Load 3P	G 5
14	08/04/19 10:06	General View	Load 3PG	G G
15	08/04/19 10:06	General View	■ Load JPI	g E
6	08/04/19 10:06	General View	■ Load JP	- 44
7	08/04/19 10:06	General View	O Load 3PG	gar
8	08/04/19 10:06	General View	■ Load 3P0	
19	08/04/19 10:06	General View	O Load JPG	- 1
0	08/04/19 10:06	General View	■ Load 3PG	per
1	08/04/19 10:06	General View	Load 3PG	-
2	08/04/19 10:06	General View	■ Load 3PG	-
3	08/04/19 10:06	General View	Load JPC	
4	08/04/19 10:06	General View	O Load JPC	
5	08/04/19 10:06	General View		
6	winds of branching of	Contract Tables	0 Load 3PC	_
	08/04/19 10:06	General View	D Load JPC	
7	08/04/19 10:06	General View	Load JPC	
8	08/04/19 10:06	General View	Load 3PG	_
9	08/04/19 10:06	General View	■ Load 3PC	3

-	essment Reports		1 per page	
Nα	Finalized On	Ah Lim Motor Company (AMK)	Thumbna	-
51	08/04/19 10:06	General View	1 Load 3PC	142
12	08/04/19 10:06	General View	S Load 3PC	-
3	08/04/19 10:06	General View	€ Load JP6	-
4	08/04/19 10:06	General View	■ Load 3PG	3
55	08/04/19 10:06	General View	■ Load 3PG	5 5
56.	08/04/19 10:06	General View	■ Load 3PG	5
57:	08/04/19 10:06	General View	■ Load 3PC	i 5
58	08/04/19 10:06	General View	1 Load 3PC	5 5
59	08/04/19 10:06	General View	● Load JPG	5 5
70	08/04/19 10:06	General View	■ Load JPC	5 5
71	08/04/19 10:06	General View	■ Load 3PG	5 5
72	08/04/19 10:06	General View	■ Load 3PG	400
73	08/04/19 10:06	General View	1 Load 3PC	-
74	08/04/19 10:06	General View	1 Load JPG	
75	08/04/19 10:06	General View	O Load JPG	
76	08/04/19 10:06	General View	Load JPG	-
77	08/04/19 10:06	General View	S Load JPC	
78		General View	D Load 3PG	
	08/04/19 10:06	CONTRACTOR		_
79	08/04/19 10:06	General View	■ Load JPC	_
80	08/04/19 10:06	General View	1 Load JPC	-
31	08/04/19 10:06	General View	1 Lbad JPC	
52	08/04/19 10:06	General View	1 Load 3PC	-
83	08/04/19 10:06	General View	1 Load 3PC	-
84	08/04/19 10:06	General View	3 Load 3PC	-
85	08/04/19 10:06	Reinspection Photo	■ Load JPC	-
86	08/04/19 10:06	Reinspection Photo	Load JPC	5 5
87	08/04/19 10:06	Reinspection Photo	Eoad 3PG	5 5
88	08/04/19 10:06	Reinspection Photo	■ Load JPC	5 E
89	08/04/19 10:06	Reinspection Photo	■ Load 3PG	5
90	08/04/19 10:06	Reinspection Photo	■ Load 3PG	5
91	08/04/19 10:06	Reinspection Photo	■ Load 3PC	i 5
92	08/04/19 10:06	Reinspection Photo	■ Load JPC	
93	08/04/19 10:06	Reinspection Photo	■ Load 3PG	<u> </u>
94	08/04/19 10:06	Reinspection Photo	■ Load 3PG	
95	08/04/19 10:06	Reinspection Photo	■ Load 3PG	-
96	08/04/19 10:06	Reinspection Photo	■ Load 3PG	-
27	08/04/19 10:06	Reinspection Photo	Load JPG	-
8	08/04/19 10:06	Reinspection Photo	■ Load JPG	
99	08/04/19 10:06	Reinspection Photo	■ Load 3PG	
00	08/04/19 10:06	Reinspection Photo	■ Load 3PG	-
101	08/04/19 10:06	Reinspection Photo	D Load 3PG	
02	08/04/19 10:06	Reinspection Photo	B Load JPG	-
	and the state of t	anner Chen, annual Co		-
04	08/04/19 10:06	Reinspection Photo		_
104	08/04/19 10:06	Reinspection Photo	Load JPG Load JPG	_
05	08/04/19 10:06	Reinspection Photo	Load JPG	-
06	08/04/19 10:06	Reinspection Photo	1 Load JPG	_
107	08/04/19 10:06	Reinspection Photo	€ Load JPG	-
108	08/04/19 10:06	Reinspection Photo	1 Load JP6	-
09	08/04/19 10:06	Reinspection Photo	■ Load JPG	1

-	essment Reports		1 per page	
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbna	il Prin
111	08/04/19 10:06	Reinspection Photo	€ Load JPG	135.0
112	08/04/19 10:06	Reinspection Photo	■ Load JPG	1
113	08/04/19 10:06	Reinspection Photo	■ Load 3PG	V
114	08/04/19 10:06	Reinspection Photo	Load JPG	V
115	08/04/19 10:06	Reinspection Photo	Load 3PG	100
116	08/04/19 10:06	Reinspection Photo	Exad JPG	V
117	08/04/19 10:06	Reinspection Photo	Load JPG	12
118	08/04/19 10:06	Reinspection Photo	 Load JPG 	V
119	08/04/19 10:06	Reinspection Photo	 Load JPG 	52
120	08/04/19 10:06	Reinspection Photo	Load JPG	V
121	08/04/19 10:06	Reinspection Photo	■ Load JPG	V
122	08/04/19 10:06	Reinspection Photo	Load JPG	8
123	08/04/19 10:06	Reinspection Photo	Load JPG	V
124	08/04/19 10:06	Reinspection Photo	Load 3PG	V
125	08/04/19 10:06	Reinspection Photo	Load JPG	V
126	08/04/19 10:06	Reinspection Photo	Load JPG	3
127	08/04/19 10:06	Reinspection Photo	Load 3PG	4
128	08/04/19 10:06	Reinspection Photo	Example 1 Load 3PG	V
129	08/04/19 10:06	Reinspection Photo	Load JPG	V
130	08/04/19 10:06	Reinspection Photo	■ Load 3PG	V
131	08/04/19 10:06	Reinspection Photo	■ Load 3PG	V
132	08/04/19 10:06	Reinspection Photo	Load JPG	82
133	08/04/19 10:06	Reinspection Photo	■ Load 3PG	V
134	08/04/19 10:06	Reinspection Photo	Load 3PG	1
135	08/04/19 10:06	Reinspection Photo	■ Load 3PG	V
136	08/04/19 10:06	Reinspection Photo	■ Load 3PG	1
137	08/04/19 10:06	Reinspection Photo	■ Load 3PG	3
138	08/04/19 10:06	Reinspection Photo	■ Load 3PG	V
139	08/04/19 10:06	Reinspection Photo	Load JPG	12
140	08/04/19 10:06	Reinspection Photo	■ Load JPG	V
141	08/04/19 10:06	Reinspection Photo	■ Load JPG	V
142	08/04/19 10:06	Reinspection Photo	■ Load JPG	V
143	08/04/19 10:06	Reinspection Photo	Load 3PG	Ø
144	08/04/19 10:06	Reinspection Photo	■ Load JPG	W
145	08/04/19 10:06	Reinspection Photo	■ Load 3PG	V
146	08/04/19 10:06	Reinspection Photo	■ Load 3PG	2
147	08/04/19 10:06	Reinspection Photo	■ Load 3PG	V
148	08/04/19 10:06	Reinspection Photo	■ Load JPG	V
149	08/04/19 10:06	Reinspection Photo	● Load 3PG	V
150	08/04/19 10:06	Reinspection Photo	● Load 3PG	V
151	08/04/19 10:06	Reinspection Photo	■ Load 3PG	3
152	08/04/19 10:06	Reinspection Photo	Load 3PG	V
153	08/04/19 10:06	Reinspection Photo	Load 3PG	2
154	08/04/19 10:06	Reinspection Photo	Load JPG Load JPG	3
155	08/04/19 10:06	Reinspection Photo	D Load 3PG	(A)
156	08/04/19 10:06	Reinspection Photo	■ Load JPG	(X)
	CONTRACTOR OF STREET		O Load JPG	A
157	08/04/19 10:06	Reinspection Photo	■ Load JPG	<u>A</u>
158	08/04/19 10:06	Reinspection Photo	Load JPG	₹.
159	08/04/19 10:06	Reinspection Photo Reinspection Photo	O Load JPG	₩.

Merimen e-Claims Page 5 of 7

TO VOLUME STATE OF THE STATE OF THE STATE OF		1 per page	×	1
No Finalized On	Ah Lim Motor Company (AMK)	Thum	-	- British
161 08/04/19 10:06	Reinspection Photo	€ Load	JPG :	V
162 08/04/19 10:06	Reinspection Photo	€ Load	JPG	V
163 08/04/19 10:06	Reinspection Photo	€ Load	JPG	V
164 08/04/19 10:06	Reinspection Photo	⑤ Load	JPG	V
165 08/04/19 10:06	Reinspection Photo	■ Load	JPG	12
166 08/04/19 10:06	Reinspection Photo	€ Load	IPG	V
167 08/04/19 10:06	Reinspection Photo	O Load	JPG	V
168 08/04/19 10:06	Reinspection Photo	O Load	JPG	2
169 08/04/19 10:06	Reinspection Photo	O Load	JPG	V
170 08/04/19 10:06	Reinspection Photo	1 Load	JPG	V
171 08/04/19 10:06	Reinspection Photo	O Load	JPG	V
172 08/04/19 10:06	Reinspection Photo	■ Load	-	V
173 08/04/19 10:06	Reinspection Photo	O Load		V
174 08/04/19 10:06	Reinspection Photo	D Load		V
	Manufacture and April	3 Load	V-12-1	V
	Reinspection Photo		-	V
176 08/04/19 10:06	Reinspection Photo	1		
177 08/04/19 10:06	Reinspection Photo	O Load		N.
178 08/04/19 10:06	Reinspection Photo	0 Load		V
179 08/04/19 10:06	Reinspection Photo	■ Load	-	V
180 08/04/19 10:06	Reinspection Photo	1 Load		V
181 08/04/19 10:06	Reinspection Photo	1 Load		1
182 08/04/19 10:06	Reinspection Photo	1 Load	JPG	V
183 08/04/19 10:06	Reinspection Photo	1 Load	JPG	4
184 08/04/19 10:06	Reinspection Photo	■ Load	JPG	W
185 08/04/19 10:06	Reinspection Photo	1 Load	3PG	V
186 08/04/19 10:06	Reinspection Photo	1 Load	JPG	1
187 08/04/19 10:06	Reinspection Photo	1 Load	JPG.	V
188 08/04/19 10:06	Reinspection Photo	■ Load	JPG .	V
189 08/04/19 10:06	Reinspection Photo	U Load	JPG .	12
190 08/04/19 10:06	Reinspection Photo	1 Load	JPG	V
191 08/04/19 10:06	Reinspection Photo	1 Load	JPG.	V
192 08/04/19 10:06	Reinspection Photo	1 Load	JPG	V
193 08/04/19 10:06	Reinspection Photo	1 Load	JPG	V
194 08/04/19 10:06	Reinspection Photo	■ Load	JPG	V
95 08/04/19 10:06	Reinspection Photo	D Load	JPG	V
196 08/04/19 10:06	Reinspection Photo	O Load	JPG	V
97 08/04/19 10:06	Reinspection Photo	O Load		V
98 08/04/19 10:06	Reinspection Photo	■ Load		V
99 08/04/19 10:06	Reinspection Photo	O Load		V
00 08/04/19 10:06	Reinspection Photo	□ Load	0.11	V
01 08/04/19 10:06	Reinspection Photo	O Load		V
02 08/04/19 10:06	Reinspection Photo	O Load		V
03 08/04/19 10:06	Reinspection Photo	O Load	17 64	2
04 08/04/19 10:06	Reinspection Photo	3 Load	-	EZ.
05 08/04/19 10:06	Reinspection Photo			Z.
06 08/04/19 10:06				-
	Reinspection Photo	O Load	-00% J	2
07 08/04/19 10:06	Reinspection Photo	€ Load	115.45	V
08 08/04/19 10:06	Reinspection Photo	0 Load	_	EZ.
09 08/04/19 10:06	Reinspection Photo Reinspection Photo	O Load	JPG JPG	V

Ass	essment Reports		1 per	page V	1
No	Finalized On	Ah Lim Motor Company (AMK)	- F. F.	Thumbnail	-
211	08/04/19 10:06	Reinspection Photo	0	Load JPG	V
212	08/04/19 10:06	Reinspection Photo	0	Load JPG	V
213	08/04/19 10:06	Reinspection Photo	0	Load JPG	N
214	08/04/19 10:06	Reinspection Photo	0	Load 3PG	V
215	08/04/19 10:06	Reinspection Photo	0	Load JPG	[2]
216	08/04/19 10:06	Reinspection Photo	0	Load JPG	V
217	08/04/19 10:06	Reinspection Photo	0	Load JPG	V
218	08/04/19 10:07	Reinspection Photo	0	Load JPG	3
219	08/04/19 10:07	Reinspection Photo	0	Load JPG	S
220	08/04/19 10:07	Reinspection Photo	0	Load 3PG	V
221	08/04/19 10:07	Reinspection Photo	0	Load 3PG	V
222	08/04/19 10:07	Reinspection Photo	0	Load 3PG	3
223	08/04/19 10:07	Reinspection Photo	0	Load JPG	V
Doc	umentation		I per s	age 🔽	W
No:	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	25/03/19 09:37	PRI LIST	0	Load PDF	
No	Finalized On	Ah Lim Motor Company (AMK)		Thumbnall	Print
1	20/03/19 17:20	Sketch Plan [Linked Accident Report Documents]	0	Load TIF	

Linked Accident Report Documents

			View View in E	rowser V
Ass	essment Reports		1 per page	V
No	Finalized On	Ah Lim Motor Company (AMK)	Thumb	nail Print
1	20/03/19 17:20	Accident Statement	Load H	TM
Pho	otos/Images		3 per page	~ V
No	Finalized On	Ah Lim Motor Company (AMK)	Thumb	nail Print
1	20/03/19 15:16	Accident Photo	■ Load 3	G 🔽
2	20/03/19 15:16	Accident Photo	■ Load 3	G Z
3	20/03/19 15:16	Accident Photo	1 Load 3	G 🗹
4	20/03/19 15:16	Accident Photo	iond 3	eg 🗹
5	20/03/19 15:16	Accident Photo	■ Load 3	G V
6	20/03/19 15:16	Accident Photo	1 Load 3	G W
7	20/03/19 15:16	Accident Photo	1 Load J	G Z
8	20/03/19 15:16	Accident Photo	■ Load 3	G 🔽
9	20/03/19 15:16	Accident Photo	■ Load 3	G 😡
10	20/03/19 15:16	Accident Photo	■ Load 3	G 🗹
11	20/03/19 15:16	Accident Photo	■ Load Ji	6 2
12	20/03/19 15:16	Accident Photo	■ Load 3	NG 😨
13	20/03/19 15:16	Accident Photo	■ Load 3	G 🗹
14	20/03/19 15:16	Accident Photo	■ Load 3	G 😿
15	20/03/19 15:16	Accident Photo	■ Load 3	G 🔽
16	20/03/19 15:16	Accident Photo	■ Load 3	G 😡
17	20/03/19 15:16	Accident Photo	① Load 3	rg ☑
Doc	cumentation		1 per page	<u> </u>
No	Finalized On	Ah Lim Motor Company (AMK)	1,7,0310,000	nail Print
1	20/03/19 17:20	Sketch Plan	Load T]F

Merimen e-Claims Page 7 of 7

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25. Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI19005163/AVD3Q2

Date:

10/04/2019

REFERENCE

Handling Insurer:

China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No:

DMCVSN30776618000

Claimant Vehicle

No:

SJJ5898Y

No:

Insured Vehicle YP591E

Date of Loss:

19/03/2019

Nature of Claim: TP

Claim No:

SNM19D201263C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJJ5898Y

Make & Model:

MITSUBISHI LANCER, 1.6 (A) 19/09/2008 (Man. Year: 2008)

Engine No:

L13A4034184

Reg. Date: Colour:

Chassis No: Odometer:

GE61030276 68069 km

Engine Capacity:

1339 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

205/50 R16

Rear Tyre Size:

205/50 R16

Front Left Side: Front Right Side: West Lake 6 mm West Lake 6 mm Rear Left Side: Rear Right Side:

West Lake 6 mm West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,014.16	13,562.96	9,451.20	41.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,470.00	5,190.00	1,280.00	19.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,484.16	18,752.96	10,731.20	36.40
Approved Total (Overridden) (S\$)		15,000.00		
Nett Amount (S\$)	29,484.16	15,000.00	14,484.16	49.13

INSPECTION

Date of Assignment:

25/03/2019

Date Inspected:

21/03/2019 Inspected At:

Jec Automotive (HQ)

1 KAKI BUKIT AVENUE 6, #02-11

AUTOBAY

Singapore 417883

Estimated Period of Repair:

18.0 days

Adjuster Report Page 2 of 5

Adjuster: ADRIAN LING Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Reference

REPAIR DETAILS

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Apr 2019)

Parts: 143 MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJJ5898Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Distorted	716.90 FL	*579.00 FL
2	1		*FRONT BONNET HINGES	Not Necessary	77.00 FL	*-FL
3	1		*FRONT BONNET INSULATOR	Not Necessary	134.50 FL	*-FL
4	1		*FRONT BONNET LOCK	Damaged	105.00 FL	*105.00 FL
5	1		*FRONT BONNET RUBBER	Not Necessary	28.60 FL	*-FL
6	2		*FRONT HEADLAMPS	Cracked	1,433.80 FL	*1,433.80 FL
7	2		*FRONT HEADLAMP LOWER BRACKETS	Cracked	97.20 FL	*57.60 FL
8	1		*FRONT BUMPER	Distorted	680,90 FL	*523.40 FL
9	1		*FRONT BUMPER CENTRE GRILLE	Deformed	118.50 FL	*118.50 FL
10	1		*FRONT BUMPER REINFORCEMENT	Bent	310.50 FL	*245.00 FL
11	2		*FRONT BUMPER SIDE RETAINERS	Necessary	57.20FL	*57.20 FL
12	1		*FRONT BUMPER TOW HOOK COVER	Missing	28.50 FL	*28.50 FL
13	2		*FRONT FENDERS	Repair	1,143.00 FL	*-FL
14	2		*FRONT FENDER BRACKETS	Not Necessary	93.60 FL	*-FL
15	2		*FRONT FENDER INNER SHIELDS	Not Necessary	243.20 FL	*-FL
16	1		*FRONT SUPPORT PANEL	Bent	589.50 FL	*589.50 FL
17	1		*FRONT BRACE PANEL	Not Necessary	146,90 FL	*-FL
18	2		*HORNS	Not Necessary	173.00 FL	*-FL
19	1		*AIR CON CONDENSER	Bent	855.90 FL	*762.80 FL
20	1		*AIR CON DISCHARGE PIPE	Not Necessary	385.00 FL	*-FL
21	1		*AIR CON LIQUID PIPE	Not Necessary	186.50 FL	*-FL
22	1		*AIR CON SUCTION PIPE	Not Necessary	296.50 FL	*-FL
23	1		*AIR CON ELECTRIC FAN	Cracked	585.00 FL	*585.00 FL
24	1		*RADIATOR	Bent	1,437.60 FL	*1,137.20 FL
25	1		*RADIATOR ELECTRIC FAN	Cracked	585.00 FL	*585.00 FL
26	1		*RADIATOR SPARE TANK	Not Necessary	89.60 FL	*-FL
27	1		*RADIATOR TOP HOSE	Not Necessary	38.60 FL	*-FL
28	2		*RADIATOR TOP MOUNTINGS	Not Necessary	37.00 FL	*-FL
29	1		*AIR INTAKE DUCT	Not Necessary	48.60 FL	*-FL
30	1		*EXHAUST INLET MANIFOLD	Not Necessary	322.30 FL	*-FL
31	1		*FRONT WIPER TANK	Not Necessary	115.10FL	*-FL
32	1		*REAR WINDSCREEN GLASS	Shattered	1,240.60 FL	*1,180.50 FL
33	1		*REAR WINDSCREEN INNER SEAL	Necessary	198.20 FL	*73.40 FL
34	1		*REAR TAILGATE	Distorted	966.00 FL	*849.60 FL
35	2		*REAR TAILGATE DAMPERS	Bent	263.00 FL	*263.00 FL
36	2		*REAR TAILGATE HINGES	Not Necessary	137.40 FL	*-FL
37	1		*REAR TAILGATE INNER TRIM BOARD	Cracked	254.50 FL	*254.50 FL
38	1		*REAR TAILGATE INNER LOCK	Damaged	183.50 FL	*183.50 FL
39	1		*REAR TAILGATE LOGO	Necessary	56.00 FL	*28.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR TAILGATE OUTER GARNISH	Cracked	190.60 FL	*110.10 FL
1	1		*REAR TAILGATE RUBBER	Cut	154.10FL	*154.10 FL
2	1		*REAR TAILGATE FIT EMBLEM	Necessary	48.50 FL	*48.50 FL
3	2		*REAR TAILGATE NUMBER PLATE LAMPS	Not Necessary	97.20 FL	*-FL
14	1		*SET REAR TAILGATE OUTER KEY	Not Necessary	195.80 FL	*-FL
5	1		*REAR TAILGATE INNER PULL POCKET	Not Necessary	85.60 FL	*-FL
6	1		*REAR WIPER ARM	Cut	68.50 FL	*68.50 FL
17	1		*REAR WIPER ARM COVER	Cracked	18.50 FL	*18.50 FL
48	1		*REAR WIPER MOTOR	Damaged	435.60 FL	*295.00 FL
19	2		*REAR TAILLAMPS	Cracked	1,052.20 FL	*571.00 FL
50	1		*REAR TAILLAMP PANELS	O/S Buckled	876.40 FL	*146.00 FL
51	1		*REAR END PANEL	Distorted	553.40 FL	*450.10 FL
52	1		*REAR END PANEL INNER GARNISH	Deformed	213.40 FL	*60.80 FL
53	1		*REAR BUMPER	Distorted	660.90 FL	*493.70 FL
54	2		*REAR BUMPER BRACKETS	Not Necessary	65.40 FL	*-FL
55	2		*REAR BUMPER SIDE RETAINERS	Necessary	61.00 FL	*61.00 FL
56	1		*REAR BUMPER TOW HOOK COVER	Missing	38.50 FL	*13.30 FL
57	1		*REAR BUMPER TOW HOOK BRACKET	Not Necessary	216.50 FL	*-FL
58	1		*REAR FLOOR PANEL	Distorted	965.00 FL	*737.00 FL
59	1			Deformed	280.40 FL	*280.40 FL
60	1		*REAR FLOOR BOARD *REAR SPARE TYRE TOOL SPONGE TRAY	Cracked	289.50 FL	*289.50 FL
-	-			- CI CONCO		
61	1		*REAR EXHAUST SILENCER	Bent	580.70 FL	*580.70 FL
52	2		*REAR EXHAUST MOUNTINGS	Not Necessary	57.00 FL	*-FL
53	1		*REAR EXHAUST HEAT SHIELD	Crumpled	105.90 FL	*105.90 FL
54	1		*REAR FENDERS	O/S Buckled	1,783.00 FL	*688.20 FL
65	2		*REAR FENDER AIR GATES	Not Necessary	91.20 FL	*-FL
66	2		*REAR FENDER TOP INNER TRIM GARNISHES	Not Necessary	379.20 FL	*-FL
37	2		*REAR FENDER LOWER INNER TRIM GARNISHES	Deformed	671.20FL	*442.80 FL
88	1		*REAR FENDER INNER SHIELDS	O/S Deformed	97.20 FL	*48.60 FL
69	2		*REAR FENDER INNER TRIM BOARDS	Repeated	671.20 FL	*-FL
70	1		*REAR DOOR-R/H	Repair	780.00 FL	*-FL
71	1		*REAR DOOR RUBBER	Not Necessary	86.90 FL	*-FL
72	1		*SET FRONT BONNET INSULATOR CLIP	Not Necessary	35.00 FS	*-FS
73	1		*FRONT GRILLE ASSY	Cracked	350.00 FS	*350.00 FS
74	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
75	1		*FRONT NUMBER PLATE WITH HOLDER	Damaged	50.00 FS	*50.00 FS
76	2		*SET FRONT FENDER INNER SHIELD CLIPS	Not Necessary	70.00FS	*-F8
77	1		*REAR WINDSCREEN SEALANT	Necessary	80.00FS	
78	1		*REAR WIPER MOTOR	Not Necessary	40.00FS	
79	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	
80	1		*REAR NUMBER PLATE WITH HOLDER	Bent	50.00 FS	
81	1		*SET REAR REVERSE SENSOR	Damaged	350.00 FS	
82			*REAR REVERSE CAMERA	Damaged	480.00 FS	
33			*REAR FLOOR PANEL INSULATOR	Necessary	150.00 FS	
84			*REAR FENDER QUARTER GLASS SEALANTS	O/S Necessary	200.00 FS	
	I.	nad Callan	Nett. L=ListItemDisc	O/S Necessary	200.0013	40.0013
-619	incriise	peri o-opo	TYPE C-LIMITETIONS	Sub Total (S\$)	28,280.20	16,623.70
			- List Item Discount on L Items			3,060.74
			- List item Discount on L Items	25.00/20.00 /0 (00)	2,500,01	a,aaa, s

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	30.00
2	TO REMOVE, REPLACED DAMAGED LAMP AND CHECK UP REAR WIRING	New	80.00	30.00
3	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	150.00
4	TO REMOVE AND REFIT REAR REVERSE SENSOR AND CAMERA	New	150.00	100.00
5	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY	New	120.00	80.00
6	TO REMOVE AND REFIT FUEL TANK ASSEMBLY WITH ALL ATTACHMENTS	New	150.00	80.00
7	TO REMOVE, REFIT AIR-CON CONDENSER, REFILL GAS & CONDUCT LEAKAGE TEST	New	180.00	120.00
8	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
9	TO REMOVE, REFIT AND REPLACE EXHAUST SILENCER AN MOUNTINGS	D New	150.00	80.00
10	TO APPLY UNDERCOATING	New	300.00	100.00
11	PANEL BEATING ,REMOVE AND REPLACING ABOVE PARTS	8 New	2,500.00	2,300.00
12	TO RESPRAY PAINTING	New	2,400.00	2,000.00
	Gross Labo	ur Cost (S\$)	6,470.00	5,190.00

Report was unsubmitted during this print-out.