

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 25 Mar 2019

Preliminary Advice

Vehicle No	: SKR319G	Accident Date	: 15/03/2019
Make	: LOTUS ELISE	Policy No.	: DMPCSN1836771800
Assignment Date	: 21/03/2019	Excess	: S\$4,000.00
Date of Inspection	: 22/03/2019	Est. Duration of Repair	: 6.00
Inspection At	: EUROSPO RTS AUTO PTE LTD (HQ) 24 LENG KEE ROAD #01-03 SINGAPORE 159096		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	57,940.50
Revised Amount	:S\$	52,350.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	52,350.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	190,000.00
COE / PARF Rebate	:S\$	85,605.00
Salvage Value	:S\$	
Margin for Repair	:S\$	104,395.00

Brake System	: In Order
Steering System	: In Order
Tyre Condition (Front)	: 6/6 mm
Tyre Condition (Rear)	: 6/6 mm

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :