

ASS. REC. BY:

REF: CS/MSG19005168/KSD 302

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Vimala D/o Raja Sengul of MSZ 9

Date/Time: 21.3.19 12:46 p.m.

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SKK 8773L

Insured:

at Workshop m/s Optima Werkz Pte Ltd

Tel: 6484 9919

of 9A Serangoon North Ave 5

Policy No: 22629631

Claim No: 587902

Sum Insured:

Excess: \$500.00

Make of Veh:

(Client's Record)

D.O.A. 15.3.2019

CA (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 22.3.19 9.14 a.m.

Person Contacted: Sharon

Vehicle IN/OUT

Date/Time	Action/Instruction
	Estimate (✓) SKK 8773L - X
25/03/19	@ 16:27 p.m. revised PA to Vimala's via memo.
25/03/19	@ 16:27 p.m. mandate requested authorize repair to Vimala's via memo.
27/03/19	@ 17:17 p.m. mandate approved by Chen How
27/03/19	@ 17:59 p.m. revert authorize repair to Lily via email.

REF: MSIG

ASSIGNMENT

From:

Date: 22.3.2019

Estimated Cost:

(OD) TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKK 8773L

at Workshop n/s: Optima Works Pte Ltd
of 9A Serangoon North Ave 5

Insured

Policy No

Claims No

Sum Insured

Excess \$500.00

(Client's Record)

Make of Veh: To check on the market value and rebate
if the vehicle is economical to repair.

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$65k

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 08 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / (REV) / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No

SKK 8773L Yr Regn 01 / 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

M. A, E250 CGI cc 1796

Colour

M. Blue A/C: Insured / Std / NI / NA

Sp. Reading

50044 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD 207 44 72F 042759

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size

F:

R:

245/30 R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal

7 mm

R/Bal

7 mm

L/Bal

7 mm

L/Bal

7 mm

D.O.A.

15/3/19

D.O.I

22/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

repair limit 14k HS

17/04/19

Confirmed HS \$14k @ 8 days with Kenneth
(\$6,913.73 Red - 33%)

18/4/2019

RECEIVED 22 APR 2019

Date/Time: File Pass to?

22/04/19

1)

Type

Date/Time: File Return to?

2)



Prell. Report



Final Report

Days Of Repair:

8

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



West-end (\$)

Survey Fee:

200

Transportation:

) \$ + RS \$

) Photos

) Others

10

TOTAL

210

Report Format :

Lump Sum / L.B.E / S

14,000/- HS

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Mar 2019		21 Mar 2019 16:46 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	KOEN PETER RENE CARDON, ID: S2718831A			[Created by insurer]					
Vehicle Reg. No.:	SKK8773L	Date of Loss:	15/03/2019 08:00 - :59 [98 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 587902	Policy/Cover Note No.:	28629631 (Comprehensive) Coverage: 07/07/2018 - 06/07/2019						
		Excess:	S\$500.00						
Repairer:	Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5, 554500 Serangoon - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmaia D/O Raja Singam - 65942471]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/03/2019]								
Driver/Custodian:	JAMIYANPERJEE MUNKHBAYAR (47 / Female), NRIC: S7160171D, Tel: +6597848280 Email: NOEMAIL								
Adj Asg. Remarks:	Please revert. No estimate yet. Surveyor to check on the market value and rebate if the vehicle is economical to repair. Vehicle is at the workshop now - 9A Serangoon North Ave. Please call Lily Loi at 64811522 to arrange for the survey appointment.								
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
View All Compose Case Mail									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8831A
Vehicle Details	
Vehicle No.:	SKK8773L
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Mar 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E250 CGI A
Primary Colour:	Blue
Manufacturing Year:	2010
Engine No.:	27186030052170
Chassis No.:	WDD2074472F042759
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$59,256.00
Original Registration Date:	07 Jan 2011
First Registration Date:	07 Jan 2011
Transfer Count:	3
Actual ARF Paid:	\$59,256.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Jan 2021
PARF Rebate Amount:	\$32,590.00
Intended COE Rebate Details	
COE Expiry Date:	06 Jan 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$49,890.00
COE Rebate Amount:	\$8,651.00
Total Rebate Amount:	\$41,241.00

The information contained herein is correct as at 16 Mar 2019

OK

Shirley Hiew (LKK Auto)

From: puitheng.chong@ow.sg
Sent: Thursday, 18 April 2019 5:29 PM
To: 'Shirley Hiew (LKK Auto)'
Cc: sharon@ow.sg; hockkong.ong@ow.sg; 'SUR'; Lily.Loi@ow.sg; 'angela.tan'; 'Kenneth Kong (LKKAuto)'
Subject: RE: SKK 8773L OD (MSIG) DOA 15 MARCH 2019

Hi Shirley,

OD CLAIMS – SKK8773L MERCEDES BENZ E250 15 MARCH 2019

Confirmed final limit repair amount @ \$14,000.00 (lump sum) before GST.

Thank you very much.

Best Regards,

Chong Pui Theng (Ms.)

Estimator, Motor Claims Department

D: +65 6481 1522 | F: +65 6481 1011

OPTIMA WERKZ PTE. LTD.

Head office: 8 Kung Chong Road Singapore 159143

Branch: 9A Serangoon North Ave 5 Singapore 554500

Branch: 551 Upp Thomson Road Singapore 574415

Tel: (+65) 6472 1313

Tel: (+65) 6484 9919

Tel: (+65) 6452 8888

Fax: (+65) 6472 2112

Fax: (+65) 6481 1011

Fax: (+65) 6452 9223

www.ow.sg | www.facebook.com/OptimaWerkz

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, you must not copy, distribute or use it for any purpose, nor disclose its contents to any other person.

Please notify the sender if you receive this email in error, and delete the email and its content immediately after which.

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent: Thursday, 18 April 2019 11:33 AM

To: puitheng.chong@ow.sg

Cc: sharon@ow.sg; hockkong.ong@ow.sg; SUR <sur@lkkauto.com>; Lily.Loi@ow.sg; 'angela.tan' <angela.tan@ow.sg>; Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>

Subject: RE: SKK 8773L OD (MSIG) DOA 15 MARCH 2019

Dear Pui Theng,

Please confirm final fig \$ 14,000.00 (lump sum) @ 8 days of repairs before excess \$ 500/- & GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 27 March 2019 7:59 PM
To: puitheng.chong@ow.sg; Lily.Loi@ow.sg
Cc: sharon@ow.sg; hockkong.ong@ow.sg; SUR
Subject: RE: SKK 8773L OD (MSIG) DOA 15 MARCH 2019
Attachments: RE: Own Damage Claim - SKK8773L DOA: 15/03/19 (MSIG) (85.6 KB)

Dear Pui Theng/Lily,

As instructed by our client, please proceed at repair cost not exceeding \$14,000.00 (inclusive supplementary) to repair the insured vehicle **SKK 8773L (Excess \$ 500/-)** on lump sum basis.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Please refer to the attachment.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Wednesday, 27 March 2019 7:47 PM
To: puitheng.chong@ow.sg
Cc: sharon@ow.sg; hockkong.ong@ow.sg; Lily.Loi@ow.sg; SUR <sur@lkkauto.com>
Subject: SKK 8773L OD (MSIG) DOA 15 MARCH 2019

Hi Pui Theng,

Kindly check the repair cost limit whether you are able to repair the vehicle not exceeding \$ 14,000.00 on lump sum basis.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From: Vimimala D/O Raja Singam <vimimala_rajasingam@sg.msig-asia.com>
Sent: Wednesday, 27 March 2019 5:27 PM
To: Lily.loi@ow.sg
Cc: sharon@ow.sg; angela.tan@ow.sg; puiheng.chong@ow.sg; hockkong.ong@ow.sg; audrey.lim@ow.sg; SUR; assignments
Subject: RE: Own Damage Claim - SKK8773L DOA: 15/03/19 (MSIG)
Importance: High

Hi Lily,

Thank you for the acceptance of our limit repair amount of not exceeding \$14,000(including check & supplementary items) before excess of \$500.00.

You may proceed to start immediate repair.

Regards,

Mala (Ms)

Senior Admin Officer, Claims Services (Motor)

Direct line +65 6594 2471 | Direct fax +65 6225 7402 | vimimala_rajasingam@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us on :    

A member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

From: Lily.loi@ow.sg [mailto:Lily.loi@ow.sg]
Sent: Wednesday, 27 March 2019 5:14 PM
To: Vimimala D/O Raja Singam <vimimala_rajasingam@sg.msig-asia.com>
Cc: sharon@ow.sg; angela.tan@ow.sg; puiheng.chong@ow.sg; hockkong.ong@ow.sg; audrey.lim@ow.sg
Subject: RE: Own Damage Claim - SKK8773L DOA: 15/03/19 (MSIG)

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Vimimala,

Kindly authorise us to repair this vehicle.
Thank you

--

Best Regards,

Lily Loi (Ms.)

Claims Executive, Motor Claims Department

D: +65 6481 1522 | F: +65 6481 1011

OPTIMA WERKZ PTE. LTD.

Head office: 6 Kung Chong Road Singapore 159143

Branch: 9A Serangoon North Ave 5 Singapore 554500

Branch: 551 Upp Thomson Road Singapore 574415

Tel: (+65) 6472 1313

Tel: (+65) 6484 9919

Tel: (+65) 6452 8888

Fax: (+65) 6472 2112

Fax: (+65) 6481 1011

Fax: (+65) 6452 9223

www.ow.sg | www.facebook.com/OptimaWerkz

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, you must not copy, distribute or use it for any purpose, nor disclose its contents to any other person.

Please notify the sender if you receive this email in error, and delete the email and its content immediately after which.

From: Lily.loi@ow.sg <Lily.loi@ow.sg>

Sent: Wednesday, 27 March, 2019 5:10 PM

To: 'Vimmala D/O Raja Singam' <vimmala_rajasigam@sg.msig-asia.com>

Cc: 'sharon@ow.sg' <sharon@ow.sg>; 'angela.tan@ow.sg' <angela.tan@ow.sg>; 'puitheng.chong@ow.sg' <puitheng.chong@ow.sg>; 'hockkong.ong@ow.sg' <hockkong.ong@ow.sg>; 'audrey.lim@ow.sg' <audrey.lim@ow.sg>

Subject: RE: Own Damage Claim - SKK8773L DOA: 15/03/19 (MSIG)

Dear Vimmala,

We accept your offer \$14,000 LS repair.

Thank you.

--
Best Regards,

Lily Loi (Ms.)

Claims Executive, Motor Claims Department

D: +65 6481 1522 | F: +65 6481 1011

OPTIMA WERKZ PTE. LTD.

Head office: 6 Kung Chong Road Singapore 159143

Branch: 9A Serangoon North Ave 5 Singapore 554500

Branch: 551 Upp Thomson Road Singapore 574415

Tel: (+65) 6472 1313

Tel: (+65) 6484 9919

Tel: (+65) 6452 8888

Fax: (+65) 6472 2112

Fax: (+65) 6481 1011

Fax: (+65) 6452 9223

www.ow.sg | www.facebook.com/OptimaWerkz

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, you must not copy, distribute or use it for any purpose, nor disclose its contents to any other person.

Please notify the sender if you receive this email in error, and delete the email and its content immediately after which.

From: Vimmala D/O Raja Singam <vimmala_rajasigam@sg.msig-asia.com>

Sent: Wednesday, 27 March, 2019 10:03 AM

To: Lily.loi@ow.sg

Cc: sharon@ow.sg; angela.tan@ow.sg; puitheng.chong@ow.sg; hockkong.ong@ow.sg

Subject: FW: Own Damage Claim - SKK8773L DOA: 15/03/19 (MSIG)

Importance: High

Our claim no: 587902

Hi Lily,

We refer to the above accident.

We reviewed our limit repair amount with our management.

We can only offer our limit repair amount not exceeding \$14,000.00 including check and supplementary items before excess of \$500.00

Kindly let us know your acceptance before we update our insured on the status of the claim.

Thank you.

Regards,

Mala (Ms)

Senior Admin Officer, Claims Services (Motor)

Direct line +65 6594 2471 | Direct fax +65 6225 7402 | vimmala_rajasingam@sg.msiga.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65

6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msiga.com.sg/> | Follow us on :    

A member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

From: Motor Survey

Sent: Thursday, 21 March 2019 3:15 PM

To: Vimmala D/O Raja Singam <vimmala_rajasingam@sg.msiga.com>

Subject: FW: Own Damage Claim - SKK8773L DOA: 15/03/19 (MSIG)

Fyna. Tks.

Best Regards

Winnie Chua

Admin Officer, Claims Services (Motor)

Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msiga.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msiga.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Agnes Lee

Sent: Thursday, 21 March 2019 3:05 PM

To: Motor Survey <motorsurvey@sg.msiga.com>

Subject: FW: Own Damage Claim - SKK8773L DOA: 15/03/19 (MSIG)

From: Lily.loi@ow.sg <Lily.loi@ow.sg>

Sent: Thursday, 21 March 2019 2:32 PM

To: Claims <claims@sg.msig-asia.com>

Cc: 'Sharon Ten' <sharon@ow.sg>; angela.tan@ow.sg; puitheng.chong@ow.sg; hockkong.ong@ow.sg

Subject: Own Damage Claim - SKK8773L DOA: 15/03/19 (MSIG)

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Officer,

Please arrange PRI at 9A Serangoon North Ave

Estimate provided here.

Thank you

--

Best Regards,

Lily Loi (Ms)

Claims Executive, Motor Claims Department

D: +65 6481 1522 | F: +65 6481 1011

OPTIMA WERKZ PTE LTD

Head office: 6 Kung Chong Road Singapore 159143

T: +65 6472 1313

F: +65 6472 2112

Branch : 9A Serangoon North Ave 5 Singapore 554500

T: +65 6484 9919

F: +65 6481 1011

Branch : 551 Upp Thomson Road Singapore 574415

T: +65 6452 6868

F: +65 6452 9223

www.ow.sg

www.facebook.com/optimawerkz

View Received Message

This mail is associated with :

***SKK8773L (587902)**
OD
Mar 15 2019 8:00AM
[KOEN PETER RENE CARDON]
Optima Werkz Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 27/03/2019 17:17 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$14000.00) - SKK8773L - Claim Handler: Vimmala D/O Raja Singam

Approved:14000.00:Repair Limit at \$14000, including supplementary. Lump sum allowed.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimimala D/O Raja Singam

Date: 17 Apr 2019

Preliminary Advice

Vehicle No	: SKK8773L	Accident Date	: 15/03/2019
Make	: MERCEDES-BENZ E250	Policy No.	: 28629631
Assignment Date	: 21/03/2019	Excess	: S\$500.00
Date of Inspection	: 22/03/2019	Est. Duration of Repair	: 8 days
Inspection At	: Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5 Singapore 554500		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,913.73
Revised Amount	:S\$	15,283.86
Check Items (Estimated)	:S\$	0.00
Total	:S\$	15,283.86
Lump Sum Repair	:S\$	14,000.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	65,000.00
COE / PARF Rebate	:S\$	41,241.00
Salvage Value	:S\$	
Margin for Repair	:S\$	23,759.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimmala D/O Raja Singam

Date: 25 Mar 2019

Preliminary Advice

Vehicle No	: SKK8773L	Accident Date	: 15/03/2019
Make	: MERCEDES-BENZ E250	Policy No.	: 28629631
Assignment Date	: 21/03/2019	Excess	: S\$500.00
Date of Inspection	: 22/03/2019	Est. Duration of Repair	: 8 days
Inspection At	: Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5 Singapore 554500		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,913.73
Revised Amount	:S\$	16,356.33
Check Items (Estimated)	:S\$	3,773.15
Total	:S\$	20,129.48

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	65,000.00
COE / PARF Rebate	:S\$	41,241.00
Salvage Value	:S\$	
Margin for Repair	:S\$	23,759.00

Remarks

- (X) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/03/2019 16:17
Date Of Accident	15/03/2019 08:45
Exact Location Of Accident	FARRER ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKK8773L
Insured/Policyholder	
Name Of Registered Owner	KOEN PETER RENE CARDON
NRIC No	S2718831A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96238608
Alternative Phone No	OTHERS-96238608

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E250
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B 28629631 QMY
Cover Note Number	

Driver

Name of Driver	JAMIYANPERJLEE MUNKHBAYAR
NRIC No	S7160171D
Date Of Birth	11/08/1971
Occupation	INDOOR
Date Of Driving Pass	06/10/2008
Driving Experience	10 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97848280
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	255 ARCADIA ROAD #14-23
Postcode	289850
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TUYA CARDON GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGK5725T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHC4705M

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLT7432T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Individual Statement

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE	SKK. 8773L	ACCIDENT DATE & TIME	15 March 2019 3:45pm
CONTACT NUMBER	97848280	E-MAIL ADDRESS	cardonfamily888@gmail.com
LOCATION	Outside Farrer MRT. Near Bus Station		
I was driving and front car sudden stopped I didn't break in time and hit front car. Later realise that its 3 other cars involved. I'm the last car. I didn't know exactly what and why 2 other cars hit each other.			
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION			
Please state:			
☒ Claim Own Policy ☐ Claim Third Party ☐ Claim OD/TP at other workshop ☐ Reporting Only			

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Date : 20.03.2019
 Vehicle No: SKK8773L
 Model: MERCEDES BENZ E250
 Chassis: WDD2074472F042759 - 2010
 Reg.Year: 2011
 Policy No: B 28629631 QMY
 Date of Accident: 15.03.2019

TO MOTOR CLAIM DEPT
 MSIG INSURANCE (S) PTE LTD
 16 RAFFLES QUEY #24-01
 HONG LEONG BUILDING
 SINGAPORE 048581

Not Authorised
11 Days @?
Recovery After Rain
Ex @ 500k
8 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT WINDSCREEN PILAR RUBBER RH <i>CM</i>	1		
2	FRONT WINDSCREEN PILAR RUBBER LH <i>CM</i>	1		
3	FRONT BONNET <i>B</i>	1		
4	FRONT BONNET INSULATOR <i>Return</i>	1		
5	FRONT BONNET EMBLEM <i>Net</i>	1		
6	FRONT BONNET LOCK RH <i>B1/D1</i>	1		
7	FRONT BONNET LOCK STRIKER RH <i>D1</i>	1		
8	FRONT BONNET LOCK LH <i>D1</i>	1		
9	FRONT BONNET HINGE RH <i>?</i>	1		
10	FRONT BONNET HINGE LH <i>?</i>	1		
11	FRONT BONNET CENTRE LOCK <i>D1</i>	1		
12	FRONT BONNET LOCK PULL HANDLE <i>A1</i>	1		
13	FRONT BONNET STOPPER ASSY RH <i>A1</i>	1		
14	FRONT BONNET STOPPER ASSY LH <i>A1</i>	1		
15	FRONT BONNET SPRING ASSY RH <i>A1</i>	1		
16	FRONT BONNET SPRING ASSY LH <i>A1</i>	1		
17	FRONT GRILLE <i>B</i>	1		
18	FRONT GRILLE EMBLEM <i>me</i>	1		
19	FRONT GRILLE EMBLEM BASE <i>B</i>	1		
20	FRONT GRILLE RETAINER BRACKET <i>B</i>	1		
21	FRONT BUMPER <i>CM</i>	1		
22	FRONT BUMPER FIXING COVER (TOW HOOK) <i>A1</i>	1		
23	FRONT BUMPER PARKING SENSOR RH <i>?</i>	2		
24	FRONT BUMPER PARKING SENSOR RING <i>me</i>	6		
25	FRONT BUMPER "LED" FOG LAMP LH <i>?</i>	1		
26	FRONT BUMPER NUMBER PLATE GARNISH <i>?</i>	1		
27	FRONT BUMPER LOWER GRILLE <i>CM</i>	1		
28	FRONT BUMPER INNER RETAINER RH <i>D1</i>	1		
29	FRONT BUMPER INNER RETAINER LH <i>D1</i>	1		
30	FRONT BUMPER ABSORBER (INNER SPONGE) <i>CM</i>	1		
31	FRONT BUMPER ABSORBER (INNER SPONGE) RH <i>?</i>	1		
32	FRONT BUMPER ABSORBER (INNER SPONGE) LH <i>?</i>	1		
33	FRONT BUMPER REINFORCEMENT <i>B</i>	1		
34	FRONT BUMPER INNER LOWER BRACKET <i>?</i>	1		

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

5A Serangoon North Ave 5 Singapore 554300
 Tel: (+65) 6484 9919 Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 8868 Fax: (+65) 6452 9223



Date : 20.03.2019
 Vehicle No: SKK8773L
 Model: MERCEDES BENZ E250
 Chassis: WDD2074472F042759 - 2010
 Reg.Year: 2011
 Policy No: B 28629631 QMY
 Date of Accident: 15.03.2019

TO MOTOR CLAIM DEPT
 MSIG INSURANCE (S) PTE LTD
 16 RAFFLES QUEY #24-01
 HONG LEONG BUILDING
 SINGAPORE 048581

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
35	FRONT BUMPER INNER LOWER BRACKET RH ?	1		
36	FRONT BUMPER INNER LOWER BRACKET LH ?	1		
37	FRONT HEADLAMP RH B ₂	1		
38	FRONT HEADLAMP RUBBER RH A ₁	1		
39	FRONT HEADLAMP UPPER PANEL RH B ₁	1		
40	FRONT HEADLAMP LH M ₃ C ₁ M	1		
41	FRONT HEADLAMP UPPER PANEL LH B ₁	1		
42	FRONT FENDER RH B ₁ / C ₁ M	1		
43	FRONT FENDER EMBLEM 'BLUE EFFICIENCY' RH M ₂	1		
44	FRONT FENDER OUTER MOULDING RH M ₂	1		
45	FRONT FENDER RETAINER RH ?	1		
46	FRONT FENDER LH B ₁ / C ₁ M	1		
47	FRONT FENDER EMBLEM 'BLUE EFFICIENCY' LH M ₂	1		
48	FRONT FENDER OUTER MOULDING LH M ₂	1		
49	FRONT FENDER RETAINER LH ?	1		
50	FRONT AIR DUCT C ₁ M	1		
51	FRONT AIR CLEANER HOSE C ₁ M	1		
52	FRONT UPPER PANEL B ₁	1		
53	FRONT UPPER PANEL COVERING C ₁ M	1		
54	FRONT UPPER PANEL COVERING GARNISH C ₁ M	1		
55	FRONT UPPER PANEL COVERING "HEAT LABEL" STICKER M ₂	1		
56	FRONT UPPER PANEL COVERING "AIR COND LABEL" STICKER M ₂	1		
57	FRONT STAY PANEL B ₁	1		
58	FRONT PANEL CENTRE MEMBER ?	1		
59	FRONT PANEL SUPPORT MEMBER RH ?	1		
60	FRONT PANEL SUPPORT MEMBER LH ?	1		
61	FRONT AIRCON CONDENSER B ₁ / P ₂	1		
62	FRONT AIRCON CONDENSER PRESSURE PIPE ?	1		
63	FRONT AIRCON CONDENSER INLET PIPE ?	1		
64	FRONT AIRCON CONDENSER OUTLET PIPE ?	1		
65	FRONT RADIATOR ?	1		
66	FRONT RADIATOR STOPPER BRACKET ASSY RH/LH ?	2		

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554300
 Tel: (+65) 6484 9919 Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 8868 Fax: (+65) 6452 9223



Date : 20.03.2019
 Vehicle No: SKK8773L
 Model: MERCEDES BENZ E250
 Chassis: WDD2074472F042759 - 2010
 Reg.Year: 2011
 Policy No: B 28629631 QMY
 Date of Accident: 15.03.2019

TO MOTOR CLAIM DEPT
 MSIG INSURANCE (S) PTE LTD
 16 RAFFLES QUEY #24-01
 HONG LEONG BUILDING
 SINGAPORE 048581

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
67	FRONT RADIATOR SUPPORT PANEL RH <i>B₁</i>	1		
68	FRONT RADIATOR SUPPORT PANEL LH <i>B₁</i>	1		
69	FRONT RADIATOR GUIDE COVER ASSY <i>CMA</i>	1		
70	FRONT RADIATOR FAN ASSY <i>?</i>	1		
71	FRONT RADIATOR UPPER HOSE <i>?</i>	1		
72	FRONT RADIATOR SPARE TANK HOSE <i>?</i>	1		
73	FRONT RADIATOR LOWER COVER <i>?</i>	1		
74	FRONT POWER STEERING COOLING PIPE <i>B₁</i>	1		
75	FRONT POWER STEERING RESEVOIR OIL TANK <i>CMA</i>	1		
76	FRONT POWER STEERING RESEVOIR OIL TANK HOSE	1		
77	FRONT ENGINE UNDER COVER <i>Sm</i>	1		
			SUB TOTAL	\$0.00
			COST +15%	\$0.00
			PARTS TOTAL	\$0.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET INSULATOR CLIPS <i>Me</i>	1 SET		\$80.00
2	FRONT GRILLE CLIPS <i>Me</i>	1		\$50.00
3	FRONT UPPER PANEL COVERING CLIPS <i>Me</i>	1		\$40.00
4	FRONT BUMPER CLIPS <i>Me</i>	1 SET		\$60.00
5	FRONT FENDER INNER LINER CLIPS <i>Me</i>	2 SET	\$45.00	\$90.00
6	FRONT RADIATOR COOLANT <i>Me</i>	1		\$100.00
7	FRONT POWER STEERING OIL <i>Me</i>	1		\$100.00
8	FRONT NUMBER PLATE WITH CASING <i>B₁</i>	1		\$60.00
			S/N TOTAL	\$580.00

Date : 20.03.2019
Vehicle No: SKK8773L
Model: MERCEDES BENZ E250
Chassis: WDD2074472F042759 - 2010
Reg.Year: 2011
Policy No: B 28629631 QMY
Date of Accident: 15.03.2019

TO MOTOR CLAIM DEPT
MSIG INSURANCE (S) PTE LTD
16 RAFFLES QUEY #24-01
HONG LEONG BUILDING
SINGAPORE 048581

ESTIMATE

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE/REFIX & REPAIR FRONT ACCIDENT PORTION & ETC

800
\$1,300.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS

1200
\$1,400.00

TO TUFF KOTE / ANTI-RUST

12 \$80.00 *X*

TO DISMANTLE & REFIX/REPLACED FRONT BUMPER PARKING SENSOR

\$60.00 *✓*

TO REMOVE & REFIX/REPLACED AIRCON SYSTEM, VACUUM WITH FLUSHING/REFILL
AIRCON GAS/OIL

\$100.00 *✓*

TO REMOVE & REFIX/REPLACED RADIATOR WITH HIGH PRESSURE TEST

\$100.00 *60*

TO REMOVE & REFIX/REPLACE POWER STEERING RESEVOIR OIL TANK, POWER STEERING
COOLING PIPE & ETC

60
\$100.00

TO CHECK WIRING, REPLACE LAMP & FOCUS HEADLAMP

30
\$80.00

TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD

120
\$180.00

LABOUR TOTAL \$3,400.00

ONG TOTAL \$3,980.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 8868 Fax: (+65) 6452 9223



Date : 20.03.2019
Vehicle No: SKK8773L
Model: MERCEDES BENZ E250
Chassis: WDD2074472F042759 - 2010
Reg. Year: 2011
Policy No: B 28629631 QMY
Date of Accident: 15.03.2019

TO MOTOR CLAIM DEPT
MSIG INSURANCE (S) PTE LTD
16 RAFFLES QUEY #24-01
HONG LEONG BUILDING
SINGAPORE 048581

11/4/19
Not Author
11/4/19
Recovery After Paint
Ex \$500

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT WINDSCREEN PILAR RUBBER RH <i>CM</i>	1		\$20.00
2	FRONT WINDSCREEN PILAR RUBBER LH <i>CM</i>	1		\$20.00
3	FRONT BONNET <i>B</i>	1		\$1,550.00
4	FRONT BONNET INSULATOR <i>Reform</i>	1		\$150.00
5	FRONT BONNET EMBLEM <i>Re</i>	1		\$38.00
6	FRONT BONNET LOCK RH <i>B1/D1</i>	1		\$55.00
7	FRONT BONNET LOCK STRIKER RH <i>D1</i>	1		\$22.00
8	FRONT BONNET LOCK LH <i>D1</i>	1		\$55.00
9	FRONT BONNET HINGE RH <i>D1</i> <i>(2)</i>	1		\$110.00
10	FRONT BONNET HINGE LH <i>D1</i> <i>(2)</i>	1		\$110.00
11	FRONT BONNET CENTRE LOCK <i>D1</i>	1		\$475.00
12	FRONT BONNET LOCK PULL HANDLE <i>D1</i>	1		
13	FRONT BONNET STOPPER ASSY RH <i>D1</i>	1		
14	FRONT BONNET STOPPER ASSY LH <i>D1</i>	1		
15	FRONT BONNET SPRING ASSY RH <i>D1</i>	1		\$19.00
16	FRONT BONNET SPRING ASSY LH <i>D1</i>	1		\$19.00
17	FRONT GRILLE <i>B</i>	1		\$440.00
18	FRONT GRILLE EMBLEM <i>Re</i>	1		\$64.00
19	FRONT GRILLE EMBLEM BASE <i>B</i>	1		\$12.00
20	FRONT GRILLE RETAINER BRACKET <i>B</i>	1		\$40.00
21	FRONT BUMPER <i>CR</i>	1		\$1,151.20
22	FRONT BUMPER FIXING COVER (TOW HOOK) <i>Re</i>	1		\$40.00
23	FRONT BUMPER PARKING SENSOR RH <i>Sh</i> <i>(2)</i>	2	\$150.00	\$300.00
24	FRONT BUMPER PARKING SENSOR RING <i>Re</i>	6	\$5.00	\$30.00
25	FRONT BUMPER "LED" FOG LAMP LH <i>(2)</i>	1		\$280.00
26	FRONT BUMPER NUMBER PLATE GARNISH <i>(2)</i>	1		\$90.00
27	FRONT BUMPER LOWER GRILLE <i>CR</i>	1		\$130.00
28	FRONT BUMPER INNER RETAINER RH <i>D1</i>	1		\$15.00
29	FRONT BUMPER INNER RETAINER LH <i>D1</i>	1		\$15.00
30	FRONT BUMPER ABSORBER (INNER SPONGE) <i>CM</i>	1		\$148.00
31	FRONT BUMPER ABSORBER (INNER SPONGE) RH <i>(2)</i>	1		\$34.00
32	FRONT BUMPER ABSORBER (INNER SPONGE) LH <i>(2)</i>	1		\$34.00
33	FRONT BUMPER REINFORCEMENT <i>B</i>	1		\$170.00
34	FRONT BUMPER INNER LOWER BRACKET <i>(2)</i>	1		\$155.00

Date : 20.03.2019
 Vehicle No: SKK8773L
 Model: MERCEDES BENZ E250
 Chassis: WDD2074472F042759 - 2010
 Reg. Year: 2011
 Policy No: B 28629631 QMY
 Date of Accident: 15.03.2019

TO MOTOR CLAIM DEPT
 MSIG INSURANCE (S) PTE LTD
 16 RAFFLES QUEY #24-01
 HONG LEONG BUILDING
 SINGAPORE 048581

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
35	FRONT BUMPER INNER LOWER BRACKET RH	1		20.00
36	FRONT BUMPER INNER LOWER BRACKET LH	1		20.00
37	FRONT HEADLAMP RH	1		1800.00
38	FRONT HEADLAMP RUBBER RH	1		-
39	FRONT HEADLAMP UPPER PANEL RH	1		160.00
40	FRONT HEADLAMP LH	1		1800.00
41	FRONT HEADLAMP UPPER PANEL LH	1		160.00
42	FRONT FENDER RH	1		555.00
43	FRONT FENDER EMBLEM 'BLUE EFFICIENCY' RH	1		57.00
44	FRONT FENDER OUTER MOULDING RH	1		23.00
45	FRONT FENDER RETAINER RH	1		10.00
46	FRONT FENDER LH	1		555.00
47	FRONT FENDER EMBLEM 'BLUE EFFICIENCY' LH	1		27.00
48	FRONT FENDER OUTER MOULDING LH	1		23.00
49	FRONT FENDER RETAINER LH	1		10.00
50	FRONT AIR DUCT	1		31.00
51	FRONT AIR CLEANER HOSE	1		170.00
52	FRONT UPPER PANEL	1		79.00
53	FRONT UPPER PANEL COVERING	1		77.00
54	FRONT UPPER PANEL COVERING GARNISH	1		6.00
55	FRONT UPPER PANEL COVERING "HEAT LABEL" STICKER	1		15.00
56	FRONT UPPER PANEL COVERING "AIR COND LABEL" STICKER	1		15.00
57	FRONT STAY PANEL	1		22.00
58	FRONT PANEL CENTRE MEMBER	1		50.00
59	FRONT PANEL SUPPORT MEMBER RH	1		60.00
60	FRONT PANEL SUPPORT MEMBER LH	1		60.00
61	FRONT AIRCON CONDENSER	1		680.00
62	FRONT AIRCON CONDENSER PRESSURE PIPE	1		180.00
63	FRONT AIRCON CONDENSER INLET PIPE	1		290.00
64	FRONT AIRCON CONDENSER OUTLET PIPE	1		-
65	FRONT RADIATOR	1		475.00
66	FRONT RADIATOR STOPPER BRACKET ASSY RH/LH	2		112.00

Date : 20.03.2019
 Vehicle No: SKK8773L
 Model: MERCEDES BENZ E250
 Chassis: WDD2074472F042759 - 2010
 Reg.Year: 2011
 Policy No: B 28629631 QMY
 Date of Accident: 15.03.2019

TO MOTOR CLAIM DEPT
 MSIG INSURANCE (S) PTE LTD
 16 RAFFLES QUEY #24-01
 HONG LEONG BUILDING
 SINGAPORE 048581

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
67	FRONT RADIATOR SUPPORT PANEL RH <i>B₁</i>	1		<i>160.00</i>
68	FRONT RADIATOR SUPPORT PANEL LH <i>B₁</i>	1		<i>160.00</i>
69	FRONT RADIATOR GUIDE COVER ASSY <i>CM</i>	1		<i>441.00</i>
70	FRONT RADIATOR FAN ASSY <i>?</i>	1		<i>CM 440.00</i>
71	FRONT RADIATOR UPPER HOSE <i>?</i>	1		<i>Pu 460.00</i>
72	FRONT RADIATOR SPARE TANK HOSE <i>?</i>	1		<i>Sm 430.00</i>
73	FRONT RADIATOR LOWER COVER <i>?</i>	1		<i>Sm 98.00</i>
74	FRONT POWER STEERING COOLING PIPE <i>B₁</i>	1		<i>430.00</i>
75	FRONT POWER STEERING RESEVOIR OIL TANK <i>CM</i>	1		<i>485.00</i>
76	FRONT POWER STEERING RESEVOIR OIL TANK HOSE	1		<i>Sm 65.00</i>
77	FRONT ENGINE UNDER COVER <i>Sm</i>	1		<i>435.00</i>
			SUB TOTAL	<i>4,610.20</i>
			COST +15%	<i>+ 691.53</i>
			PARTS TOTAL	<i>5,301.73</i>

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET INSULATOR CLIPS <i>Mc</i>	1 SET		\$80.00
2	FRONT GRILLE CLIPS <i>Mc</i>	1		\$50.00
3	FRONT UPPER PANEL COVERING CLIPS <i>Mc</i>	1		\$40.00
4	FRONT BUMPER CLIPS <i>Mc</i>	1 SET		\$60.00
5	FRONT FENDER INNER LINER CLIPS <i>Mc</i>	2 SET	\$45.00	\$90.00
6	FRONT RADIATOR COOLANT <i>Mc</i>	1		\$100.00
7	FRONT POWER STEERING OIL <i>Mc</i>	1		\$100.00
8	FRONT NUMBER PLATE WITH CASING <i>B₁</i>	1		\$60.00
			S/N TOTAL	\$580.00

Date : 20.03.2019
Vehicle No: SKK8773L
Model: MERCEDES BENZ E250
Chassis: WDD2074472F042759 - 2010
Reg. Year: 2011
Policy No: B 28629631 QMY
Date of Accident: 15.03.2019

TO MOTOR CLAIM DEPT
MSIG INSURANCE (S) PTE LTD
16 RAFFLES QUEY #24-01
HONG LEONG BUILDING
SINGAPORE 048581

ESTIMATE

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE/REFIX & REPAIR FRONT ACCIDENT PORTION & ETC	800 \$1,300.00
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS	1200 \$1,400.00
TO TUFF KOTE / ANTI-RUST	12 \$80.00 X
TO DISMANTLE & REFIX/REPLACED FRONT BUMPER PARKING SENSOR	\$60.00 ✓
TO REMOVE & REFIX/REPLACED AIRCON SYSTEM, VACUUM WITH FLUSHING/REFILL AIRCON GAS/OIL	\$100.00 ✓
TO REMOVE & REFIX/REPLACED RADIATOR WITH HIGH PRESSURE TEST	\$100.00 600
TO REMOVE & REFIX/REPLACE POWER STEERING RESEVOIR OIL TANK, POWER STEERING COOLING PIPE & ETC	600 \$100.00
TO CHECK WIRING, REPLACE LAMP & FOCUS HEADLAMP	300 \$80.00
TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD	1200 \$180.00
LABOUR TOTAL	\$3,400.00

ONG

TOTAL

30,913.13

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Cheng Road Singapore 159143
Tel: (+65) 6472 1313 / Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 / Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 374415
Tel: (+65) 6452 4868 / Fax: (+65) 6452 9223



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Mar 2019		21 Mar 2019 16:46 Edit Adj Rpt	S\$14,000.00 Edit Estimates	S\$14,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KOEN PETER RENE CARDON , ID: S2718831A								
Vehicle Reg. No.:	SKK8773L	Date of Loss:	15/03/2019 08:00 - :59 [98 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 587902	Policy/Cover Note No.:	28629631 (Comprehensive) Coverage: 07/07/2018 - 06/07/2019						
		Excess:	S\$500.00						
Repairer:	Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5, 554500 Serangoon - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 20/04/2019]								
Driver/Custodian:	JAMIYANPERJLEE MUNKHBAYAR (47 / Female) , NRIC: S7160171D, Tel: +6597848280 Email: NOEMAIL								
Adj Asg. Remarks:	Please revert. No estimate yet. Surveyor to check on the market value and rebate if the vehicle is economical to repair. Vehicle is at the workshop now - 9A Serangoon North Ave. Please call Lily Loi at 64811522 to arrange for the survey appointment.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• MSIG_SG (27/03/2019): Alert - Adj Mandate Approved (S\$14000.00) - SKK8773L - Claim Handler: Vimmala D/...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKK8773L (587902)
 OD
 Mar 15 2019 8:00AM
 [KOEN PETER RENE CARDON]
 Optima Werkz Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print	
1	15/03/19 16:42	Accident Statement	 Load HTM	☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	25/03/19 16:27	Adjuster Immediate Advice	 Load HTM	☒	
2	17/04/19 14:45	Adjuster Immediate Advice	 Load HTM	☒	
Photos/Images				3 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print	
1	15/03/19 16:34	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒	
2	15/03/19 16:34	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒	
3	15/03/19 16:34	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒	
4	15/03/19 16:34	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒	
5	15/03/19 16:34	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒	
6	15/03/19 16:34	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒	
7	15/03/19 16:34	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒	
8	15/03/19 16:34	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒	
9	15/03/19 16:34	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒	
10	15/03/19 16:34	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒	
11	15/03/19 16:34	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒	
12	15/03/19 16:34	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒	
13	15/03/19 16:34	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒	
14	15/03/19 16:34	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒	
15	15/03/19 16:34	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒	
16	15/03/19 16:34	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒	
17	15/03/19 16:34	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒	
18	15/03/19 16:39	Identification Card [Linked Accident Report Documents]	 Load JPG	☒	
19	15/03/19 16:39	Driving License [Linked Accident Report Documents]	 Load JPG	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	25/03/19 14:19	General View	 Load JPG	☒	
2	25/03/19 14:19	General View	 Load JPG	☒	
3	25/03/19 14:19	General View	 Load JPG	☒	
4	25/03/19 14:19	General View	 Load JPG	☒	
5	25/03/19 14:19	General View	 Load JPG	☒	
6	25/03/19 14:19	General View	 Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
7	25/03/19 14:19	General View	 Load JPG	☒
8	25/03/19 14:19	General View	 Load JPG	☒
9	25/03/19 14:19	General View	 Load JPG	☒
10	25/03/19 14:19	General View	 Load JPG	☒
11	25/03/19 14:19	General View	 Load JPG	☒
12	25/03/19 14:19	General View	 Load JPG	☒
13	25/03/19 14:19	General View	 Load JPG	☒
14	25/03/19 14:19	General View	 Load JPG	☒
15	25/03/19 14:19	General View	 Load JPG	☒
16	25/03/19 14:19	General View	 Load JPG	☒
17	25/03/19 14:19	General View	 Load JPG	☒
18	25/03/19 14:19	General View	 Load JPG	☒
19	25/03/19 14:19	General View	 Load JPG	☒
20	25/03/19 14:19	General View	 Load JPG	☒
21	25/03/19 14:19	General View	 Load JPG	☒
22	25/03/19 14:19	General View	 Load JPG	☒
23	25/03/19 14:19	General View	 Load JPG	☒
24	25/03/19 14:19	General View	 Load JPG	☒
25	25/03/19 14:19	General View	 Load JPG	☒
26	25/03/19 14:19	General View	 Load JPG	☒
27	25/03/19 14:19	General View	 Load JPG	☒
28	25/03/19 14:19	General View	 Load JPG	☒
29	25/03/19 14:19	General View	 Load JPG	☒
30	25/03/19 14:19	General View	 Load JPG	☒
31	25/03/19 14:19	General View	 Load JPG	☒
32	25/03/19 14:19	General View	 Load JPG	☒
33	25/03/19 14:19	General View	 Load JPG	☒
34	25/03/19 14:19	General View	 Load JPG	☒
35	25/03/19 14:19	General View	 Load JPG	☒
36	25/03/19 14:19	General View	 Load JPG	☒
37	25/03/19 14:19	Odometer Reading	 Load JPG	☒
38	25/03/19 14:19	General View	 Load JPG	☒
39	25/03/19 14:19	Chassis Number	 Load JPG	☒
40	25/03/19 14:19	General View	 Load JPG	☒
41	25/03/19 14:19	General View	 Load JPG	☒
42	25/03/19 14:19	General View	 Load JPG	☒
43	25/03/19 14:19	General View	 Load JPG	☒
44	25/03/19 14:19	General View	 Load JPG	☒
45	25/03/19 14:19	General View	 Load JPG	☒
46	25/03/19 14:19	General View	 Load JPG	☒
47	17/04/19 12:13	Reinspection Photo	 Load JPG	☒
48	17/04/19 12:13	Reinspection Photo	 Load JPG	☒
49	17/04/19 12:13	Reinspection Photo	 Load JPG	☒
50	17/04/19 12:13	Reinspection Photo	 Load JPG	☒
51	17/04/19 12:13	Reinspection Photo	 Load JPG	☒
52	17/04/19 12:13	Reinspection Photo	 Load JPG	☒
53	17/04/19 12:13	Reinspection Photo	 Load JPG	☒
54	17/04/19 12:13	Reinspection Photo	 Load JPG	☒
55	17/04/19 12:13	Reinspection Photo	 Load JPG	☒
56	17/04/19 12:13	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
57	17/04/19 12:13	Reinspection Photo		☒
58	17/04/19 12:13	Reinspection Photo		☒
59	17/04/19 12:13	Reinspection Photo		☒
60	17/04/19 12:13	Reinspection Photo		☒
61	17/04/19 12:13	Reinspection Photo		☒
62	17/04/19 12:13	Reinspection Photo		☒
63	17/04/19 12:13	Reinspection Photo		☒
64	17/04/19 12:13	Reinspection Photo		☒
65	17/04/19 12:13	Reinspection Photo		☒
66	17/04/19 12:13	Reinspection Photo		☒
67	17/04/19 12:13	Reinspection Photo		☒
68	17/04/19 12:13	Reinspection Photo		☒
69	17/04/19 12:13	Reinspection Photo		☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/03/19 14:12	PARF/COE rebate detail		
2	21/03/19 14:12	Email to surveyor to check on the market value		
3	21/03/19 15:26	Email from repairer to arrange for survey-No estimate yet		
4	21/03/19 15:30	SG carmart		
5	22/04/19 15:01	Final repair bill+DV		
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	15/03/19 16:39	Accident Sketch Plan [Linked Accident Report Documents]		☒
2	15/03/19 16:39	Individual Statement [Linked Accident Report Documents]		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/03/19 14:17	ESTIMATE.pdf		
2	25/03/19 14:17	SKK 8773L GIA.pdf		
3	17/04/19 14:41	ESTIMATE MARKED.pdf		

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	15/03/19 16:42	Accident Statement		
Photos/Images			3 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	15/03/19 16:34	Accident Photo		☒
2	15/03/19 16:34	Accident Photo		☒
3	15/03/19 16:34	Accident Photo		☒
4	15/03/19 16:34	Accident Photo		☒
5	15/03/19 16:34	Accident Photo		☒
6	15/03/19 16:34	Accident Photo		☒
7	15/03/19 16:34	Accident Photo		☒
8	15/03/19 16:34	Accident Photo		☒
9	15/03/19 16:34	Accident Photo		☒
10	15/03/19 16:34	Accident Photo		☒
11	15/03/19 16:34	Accident Photo		☒
12	15/03/19 16:34	Accident Photo		☒
13	15/03/19 16:34	Accident Photo		☒
14	15/03/19 16:34	Accident Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
15	15/03/19 16:34	Accident Photo	 Load JPG	☒
16	15/03/19 16:34	Accident Photo	 Load JPG	☒
17	15/03/19 16:34	Accident Photo	 Load JPG	☒
18	15/03/19 16:39	Identification Card	 Load JPG	☒
19	15/03/19 16:39	Driving License	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	15/03/19 16:39	Accident Sketch Plan	 Load JPG	☒
2	15/03/19 16:39	Individual Statement	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19005168/KSD3E2

Date: 23/04/2019

REFERENCE

Insured/Claimant: KOEN PETER RENE CARDON

Policy No: 28629631

Date of Loss: 15/03/2019

Nature of Claim: OD

Claim No: 587902

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKK8773L

Make & Model: MERCEDES-BENZ E250, 1.8 (A)

Engine No: 27186030052170

Reg. Date: 07/01/2011 (Man. Year: 2010)

Chassis No: WDD2074472F042759

Colour: Metallic Blue

Odometer: 50044 km

Engine Capacity: 1796 cc

Market Value/New Car Price: S\$65,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/30Z R20

Rear Tyre Size: 245/30Z R20

Front Left Side: Continental 7 mm

Rear Left Side: Continental 7 mm

Front Right Side: Continental 7 mm

Rear Right Side: Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,933.73	16,674.83	1,258.90	7.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	2,430.00	970.00	28.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,333.73	19,104.83	2,228.90	10.45
Approved Total (Overridden) (S\$)		14,000.00		
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	20,833.73	13,500.00	7,333.73	35.20
+ GST 7.00/7.00% (S\$)	1,458.36	945.00	513.36	35.20
Nett Amount (S\$)	22,292.09	14,445.00	7,847.09	35.20

INSPECTION

Date of Assignment: 21/03/2019

Date Inspected: 22/03/2019 Inspected At:

Optima Werkz Pte Ltd (HQ)
9A Serangoon North Ave 5
Singapore 554500

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Apr 2019)
Parts:	143	MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKK8773L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN PILLAR RUBBER RH (WCP)	Cracked	20.00 F	*20.00 F
2	1		*FRONT WINDSCREEN PILLAR RUBBER LH (WCP)	Cracked	20.00 F	*20.00 F
3	1		*FRONT BONNET (WCP)	Bent	1,550.00 F	*1,550.00 F
4	1		*FRONT BONNET INSULATOR (WCP)	Deformed	150.00 F	*150.00 F
5	1		*FRONT BONNET EMBLEM (WCP)	Dented	38.00 F	*38.00 F
6	1		*FRONT BONNET LOCK RH (WCP)	Bent / Distorted	55.00 F	*55.00 F
7	1		*FRONT BONNET LOCK STRIKER RH (WCP)	Distorted	22.00 F	*22.00 F
8	1		*FRONT BONNET LOCK LH (WCP)	Distorted	55.00 F	*55.00 F
9	1		*FRONT BONNET HINGE RH (WCP)	Distorted	110.00 F	*110.00 F
10	1		*FRONT BONNET HINGE LH (WCP)	Distorted	110.00 F	*110.00 F
11	1		*FRONT BONNET CENTRE LOCK } (WCP)	Distorted	475.00 F	*475.00 F
12	1		*FRONT BONNET LOCK PULL HANDLE } (WCP)	Missing	0.00 F	*- F
13	1		*FRONT BONNET STOPPER ASSY RH } (WCP)	Missing	0.00 F	*- F
14	1		*FRONT BONNET STOPPER ASSY LH } (WCP)	Missing	0.00 F	*- F
15	1		*FRONT BONNET SPRING ASSY RH (WCP)	Missing	19.00 F	*19.00 F
16	1		*FRONT BONNET SPRING ASSY LH (WCP)	Missing	19.00 F	*19.00 F
17	1		*FRONT GRILLE (WCP)	Broken	440.00 F	*440.00 F
18	1		*FRONT GRILLE EMBLEM (WCP)	Necessary	69.00 F	*69.00 F
19	1		*FRONT GRILLE EMBLEM BASE (WCP)	Broken	42.00 F	*42.00 F
20	1		*FRONT GRILLE RETAINER BRACKET (WCP)	Bent	80.00 F	*80.00 F
21	1		*FRONT BUMPER (WCP)	Cracked	1,151.20 F	*1,151.20 F
22	1		*FRONT BUMPER FIXING COVER (TOW HOOK) (WCP)	Missing	40.00 F	*40.00 F
23	2		*FRONT BUMPER PARKING SENSOR RH (WCP)	Shorted	300.00 F	*300.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
24	6		*FRONT BUMPER PARKING SENSOR RING (WCP)	Necessary	30.00 F	*30.00 F
25	1		*FRONT BUMPER LED FOG LAMP LH (WCP)	Mtg Cracked	280.00 F	*280.00 F
26	1		*FRONT BUMPER NUMBER PLATE GARNISH (WCP)	Serviceable	90.00 F	*- F
27	1		*FRONT BUMPER LOWER GRILLE (WCP)	Cracked	130.00 F	*130.00 F
28	1		*FRONT BUMPER INNER RETAINER RH (WCP)	Distorted	15.00 F	*15.00 F
29	1		*FRONT BUMPER INNER RETAINER LH (WCP)	Distorted	15.00 F	*15.00 F
30	1		*FRONT BUMPER ABSOBER (INNER SPONGE) (WCP)	Cracked	168.00 F	*168.00 F
31	1		*FRONT BUMPER ABSOBER (INNER SPONGE) RH (WCP)	Serviceable	38.00 F	*- F
32	1		*FRONT BUMPER ABSOBER (INNER SPONGE) LH (WCP)	Serviceable	38.00 F	*- F
33	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	190.00 F	*190.00 F
34	1		*FRONT BUMPER INNER LOWER BRACKET (WCP)	Distorted	135.00 F	*135.00 F
35	1		*FRONT BUMPER INNER LOWER BRACKET RH (WCP)	Repair	20.00 F	*- F
36	1		*FRONT BUMPER INNER LOWER BRACKET LH (WCP)	Repair	20.00 F	*- F
37	1		*FRONT HEADLAMP RH (WCP)	Broken	1,800.00 F	*1,800.00 F
38	1		*FRONT HEADLAMP UPPER PANEL RH (WCP)	Bent	160.00 F	*160.00 F
39	1		*FRONT HEADLAMP LH (WCP)	Mtg Cracked	1,800.00 F	*1,800.00 F
40	1		*FRONT HEADLAMP UPPER PANEL LH (WCP)	Bent	160.00 F	*160.00 F
41	1		*FRONT FENDER RH (WCP)	Bent / Cracked	555.00 F	*555.00 F
42	1		*FRONT FENDER EMBLEM BLUE EFFIENCY RH (WCP)	Necessary	37.00 F	*37.00 F
43	1		*FRONT FENDER OUTER MOULDING RH (WCP)	Necessary	23.00 F	*23.00 F
44	1		*FRONT FENDER RETAINER RH (WCP)	Serviceable	10.00 F	*- F
45	1		*FRONT FENDER LH (WCP)	Bent / Cracked	555.00 F	*555.00 F
46	1		*FRONT FENDER EMBLEM BLUE EFFIENCY LH (WCP)	Necessary	37.00 F	*37.00 F
47	1		*FRONT FENDER OUTER MOULDING LH (WCP)	Necessary	23.00 F	*23.00 F
48	1		*FRONT FENDER RETAINER LH (WCP)	Serviceable	10.00 F	*- F
49	1		*FRONT AIR DUCT (WCP)	Cracked	31.00 F	*31.00 F
50	1		*FRONT AIR CLEANER HOSE (WCP)	Cracked	170.00 F	*170.00 F
51	1		*FRONT UPPER PANEL (WCP)	Bent	79.00 F	*79.00 F
52	1		*FRONT UPPER PANEL COVERING (WCP)	Cracked	77.00 F	*77.00 F
53	1		*FRONT UPPER PANEL COVERING GARNISH (WCP)	Cracked	6.00 F	*6.00 F
54	1		*FRONT UPPER PANEL COVERING HEAT LABEL STICKER (WCP)	Necessary	15.00 F	*15.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	1		*FRONT UPPER PANEL COVERING AIR COND LABEL STICKER (WCP)	Necessary	15.00 F	*15.00 F
56	1		*FRONT STAY PANEL (WCP)	Bent	22.00 F	*22.00 F
57	1		*FRONT PANEL CENTRE MEMBER (WCP)	Repair	50.00 F	*- F
58	1		*FRONT PANEL SUPPORT MEMBER RH (WCP)	Repair	60.00 F	*- F
59	1		*FRONT PANEL SUPPORT MEMBER LH (WCP)	Repair	60.00 F	*- F
60	1		*FRONT AIRCON CONDENSER (WCP)	Bent / Punctured	680.00 F	*680.00 F
61	1		*FRONT AIRCON CONDENSER PRESSURE PIPE (WCP)	Dented	180.00 F	*180.00 F
62	1		*FRONT AIRCON CONDENSER INLET PIPE (WCP)	Serviceable	230.00 F	*- F
63	1		*FRONT RADIATOR (WCP)	Bent	435.00 F	*435.00 F
64	2		*FRONT RADIATOR STOPPER BRACKET ASSY RH / LH (WCP)	Serviceable	42.00 F	*- F
65	1		*FRONT RADIATOR SUPPORT PANEL RH (WCP)	Bent	160.00 F	*160.00 F
66	1		*FRONT RADIATOR SUPPORT PANEL LH (WCP)	Bent	160.00 F	*160.00 F
67	1		*FRONT RADIATOR GUIDE COVER ASSY (WCP)	Cracked	41.00 F	*41.00 F
68	1		*FRONT RADIATOR FAN ASSY (WCP)	Cracked	780.00 F	*780.00 F
69	1		*FRONT RADIATOR SPARE TANK HOSE (WCP)	Serviceable	30.00 F	*- F
70	1		*FRONT RADIATOR LOWER COVER (WCP)	Serviceable	98.00 F	*- F
71	1		*FRONT POWER STEERING COOLING PIPE (WCP)	Bent	230.00 F	*230.00 F
72	1		*FRONT POWER STEERING RESEVOIR OIL TANK (WCP)	Cracked	85.00 F	*85.00 F
73	1		*FRONT POWER STEERING RESEVOIR OIL TANK HOSE (WCP)	Serviceable	65.00 F	*- F
74	1		*FRONT ENGINE UNDER COVER (WCP)	Serviceable	125.00 F	*- F
75	1		*SET FRONT BONNET INSULATOR CLIPS	Necessary	80.00 FS	*80.00 FS
76	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*50.00 FS
77	1		*FRONT UPPER PANEL COVERING CLIPS	Necessary	40.00 FS	*40.00 FS
78	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS
79	2		*SET FRONT FENDER INNER LINER CLIPS	Necessary	90.00 FS	*90.00 FS
80	1		*FRONT RADIATOR COOLANT	Necessary	100.00 FS	*40.00 FS
81	1		*FRONT POWER STEERING OIL	Necessary	100.00 FS	*50.00 FS
82	1		*FRONT NUMBER PLATE WITH CASING	Bent	60.00 FS	*45.00 FS
83	1		*FRONT RADIATOR UPPER HOSE (WCP)	Punctured	60.00 F	*60.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	15,670.20	14,559.20
+ Margin on L,N Items 15.00/15.00% (S\$)	2,263.53	2,115.63
Total Parts (S\$)	17,933.73	16,674.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE / REFIX & REPAIR FRONT ACCIDENT PORTION & ETC	New	1,300.00	800.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS	New	1,400.00	1,200.00
3	TO TUFF KOTE / ANTI-RUST	New	80.00	0.00
4	TO DISMANTLE & REFIX REPLACED FRONT BUMPER PARKING SENSOR	New	60.00	60.00
5	TO REMOVE & REFIX / REPLACED AIRCON SYSTEM, VACUUM WITH FLUSHING / REFILL AIRCON GAS / OIL	New	100.00	100.00
6	TO REMOVE & REFIX / REPLACED RADIATOR WITH HIGH PRESSURE TEST	New	100.00	60.00
7	TO REMOVE & REFIX / REPLACE POWER STEERING RESEVOIR OIL TANK, POWER STEERING COOLING PIPE & ETC	New	100.00	60.00
8	TO CHECK WIRING, REPLACE LAMP & FOCUS HEADLAMP	New	80.00	30.00
9	TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD	New	180.00	120.00
Gross Labour Cost (S\$)			3,400.00	2,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >