

ASS. REC. BY:

Surveyor: Adnan

REF: CS/CTI19005169/ Asd3

Special Instruction:

ASSIGNMENT (Office)

From (Person): Elaine Cheong of CTI Date/Time: 21.3.19 15.38 pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMD 3865 B Insured: PZ1298A

at Workshop m/s SK Automobile Pte LTD Tel: 67895155

of 23 Kaki Bukit Arzu 4, #103-01

Policy No: DMB1SN16537718022 Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 19.3.19
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP" H.O.D. Endorsement:

Date/Time: 22.2.19 9.18 a.m Person Contacted: Hui Lee Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (✓)	INSP: 8 Kaki Bukit Ave 4 #10846
	SMD 3865 B -		
	PZ 1298A - MGA / AIG 19005066/4		D.O.A. - 19/3/2019

REF: C71

ASSIGNMENT

From:

Date: 22.3.19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SMD3865D

at Workshop no: SK Automobile Pte LTD

of 8 Kaki Bukit Ave 4 # 0646

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days:

Res.: Yes or No

Lum Sum:

%

J Val: Yes or No

CA / REV / REP. / 24 HRS

"WP"

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMD 3865D.

Yr Regn: 2018 / August.

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes Benz B180 cc 1595

Colour:

Red.

A/C: Insured / Std / NI / NA

Sp. Reading:

11324.

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD2462422J489090

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/55R16.

R: 205/55R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

06

mm

R/Bal:

06

mm

L/Bal:

06

mm

L/Bal:

06

mm

D.O.A.

D.O.I.

22/03/19

Survey held at

S.K.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time:

Action / Instruction

TP Claim.

23/04/19 Confirmed HS ~~\$\$\$~~ \$16,400/- @ 13 days with Admin
(\$16,047.50 Rev 50%)

RECEIVED 23 APR 2019

Date/Time: File Pass Y/N

1)

23/04/19
T.Y.P.S.

Date/Time: File Return Y/N

2)

Report Format:

Lump Sum / I.B.I. (\$) :

☐

: Prel. Report

☒

: Final Report

Days Of Repair:

13

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

) 2 + RS)

) Photos

) Other

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Week-end (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Mar 2019 15:32		21 Mar 2019 15:38 Assign				New Assignment Cancel Case

MainReferenceClaim DetailsDocumentsShow All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

LIM CHIN YONG TRANSPORT PTE LTD, Co. Reg. No.: 201115637H

Main Claimant:

LAU CHEE WEE, DAVID (LIU ZHIWEI), ID: S7918993F

Vehicle Reg. No.:

SMD3865B

Date of Loss:

19/03/2019 17:00 - :59
[7 Months and 2 Days From LTA Reg Date (Man Yr)]

Claim Type:

TP

Policy/Cover Note No.:

DMB1SN16537718022 (TP, Fire & Theft)
Coverage: 01/11/2018 - 31/10/2019

Vehicle Reg. No. (Insured):

PZ1298A

Policy No. (Claimant):

1800096821

Excess:

S\$1,000.00

Repairer:

SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre, 415933 Kaki Bukit - Tel: 67895155

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]

Claimant's Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/04/2019]

Driver/Custodian (Insured):

MUHAMMAD FABBLY BIN MOHD NAZIR (/ Male) , NRIC: S7930102G Email:

Adj Asg. Remarks:

to assign Adrian Ling to conduct PRS. Thank you

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Miss Hing.

115899
53367

22/3/2019



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Car Removal Toyota Vios 1.5A



2.0M52 & Low Interest Rate
Finance 2 Years Warranty
\$1500 Down Monthly from 1400
GV Credit Pte Ltd. [Learn More](#)

PRIME MOTOR & LEASING
SINGAPORE'S LONG CREDIT ENTERPRISES PTE. LTD. GROUP OF COMPANIES
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

Sort by Date Posted 20 results/page

3 vehicles

mercedes b180

Advanced Search

Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection mercedes b180	Any	Any	2018	Any	Any	Any	Available
	Mercedes-Benz B-Class B180 Style	\$115,899	\$10,710 /yr	17-Aug-2018	1,595 cc	3,750 km	Hatchback Available
Value For Money, Great Saving, Brand New Condition, With New Car Smell, Latest Facelifted Model. Have Not Gone For First Servicing Yet, Under C&C Warranty, Mileage Only 3750km. Look No Further, Hatch...							
Posted: 17-Mar-2019 Tags: 2018 Mercedes-Benz B180, 2018 mercedes-benz b180, Mercedes-Benz B180, mercedes-benz b180, Mercedes-Benz, B180, b180, Used Mercedes-Benz							
	Mercedes-Benz B-Class B180 Style	\$116,000	\$10,590 /yr	11-Oct-2018	1,595 cc	4,300 km	Hatchback Available
1 Owner Unit! Car Still Under C&C Warranty And Servicing! Showroom Condition! Lunar Blue Metallic Exterior Against Premium White Vianen Leather Interior, Very Well Kept By Her Fussy Owner. Clean, Neat...							
Car Buyers Automotive Pte Ltd							
Posted: 15-Mar-2019 Tags: 2018 Mercedes-Benz B180, 2018 mercedes-benz b180, Mercedes-Benz B180, mercedes-benz b180, Mercedes-Benz, B180, b180, Used Mercedes-Benz							
	Mercedes-Benz B-Class B180 Style	\$109,800	\$10,810 /yr	11-Jun-2018	1,595 cc	7,813 km	Hatchback Available
8882 Car Plate To Go Along, Latest Facelifted Model, Fully C&C Service Unit! C&C Warranty Low Mileage, Almost Brand New! Almost Unused Black Interior! Classy Silver Exterior, Attractive Trade In/ Fle...							
Posted: 01-Mar-2019 Tags: 2018 Mercedes-Benz B180, 2018 mercedes-benz b180, Mercedes-Benz B180, mercedes-benz b180, Mercedes-Benz, B180, b180, Used Mercedes-Benz							

Save this search criteria, to get email alerts whenever a match is found.

Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used mercedes b180, mercedes b180 Singapore, used mercedes b180 Singapore, used mercedes b180, used vehicles Singapore or even buy used mercedes b180 Singapore.

We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no insurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us Careers Contact Us Sitemap Terms of Service Privacy Policy Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.

MHA419037068 / National Assessment Centre Services - Bukit Merah
 ENTRY DATE & TIME: 20/03/2019 16:18
 SUBMITTED BY: ROSLI BIN ABDUL WAHAB

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/03/2019 16:16
Date Of Accident	19/03/2019 17:00
Exact Location Of Accident	WOODLANDS RD TWRDS MANDAI JUNC WITH STAGMONT RING
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD3865B
Insured/Policyholder	
Name Of Registered Owner	LAU CHEE WEE, DAVID (LIU ZHIWEI)
NRIC No	S7918993F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98463932
Alternative Phone No	OTHERS-98463932
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	B180-1.6 STYLE (R16 LED) (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800096821
Cover Note Number	
Driver	
Name of Driver	LAU CHEE WEE, DAVID (LIU ZHIWEI)
NRIC No	S7918993F
Date Of Birth	29/06/1979
Occupation	INDOOR
Date Of Driving Pass	21/05/1999
Driving Experience	19 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98463932
Fax Number	
Contact Number	OTHERS-98463932
Email Address	NOEMAIL

Address 79 YISHUN AVENUE 11
#06-22
Postcode 768862
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1 NAME: : LAU SZE TONG, HAYLEE
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PZ1298A
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the Insurer, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Content under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to being about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Name:
Date/Time:

Accident Sketch Plan

SKETCH PLAN



(A) SMO 3865 B.

(B) PZ 1295 A

WOODBANE ROAD TUNDS. MONDRI
 TUNDS. WIND STATION? LINE

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 19 MAR 2019 @ 17:00H. I WAS DRIVING ALONG
 WOODBANE ROAD WHEN I STOPPED AT THE TRAFFIC LIGHT
 SUDDENLY VEHICLE B COLLIDED INTO MY REAR

DECLARATION

I/We declare the foregoing particulars are true in every respect.

David
 Policyholder's Signature
 Date & Time:

David
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

on 20/03/2019
 Reporting Centre Person's Signature
 Name: *Rashid*
 Date/Time/No.:

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO	: CHINA TAIPING	DATE	: 21-Mar-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SMD3865B
ADDRESS	:	MODEL	: MERCEDES B180
TEL. NO.	:	CHASSIS NO	: WDD2462422J489090
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Replaced</i>	1	\$ 1,959.00	\$ 1,959.00
2	TAILGATE WEATHERSTRIP <i>ct</i>	1	\$ 259.00	\$ 259.00
3	TAILGATE INNER TRIM BOARD <i>Replaced</i>	1	\$ 587.00	\$ 587.00
4	TAILGATE INNER TRIM SIDE GARNISH <i>ct</i>	2	\$ 258.00	\$ 516.00
5	TAILGATE TOP LOCK <i>Replaced</i>	1	\$ 321.00	\$ 321.00
6	TAILGATE LAMP <i>Replaced</i>	2	\$ 412.00	\$ 824.00
7	TAILGATE LOGO <i>Replaced</i>	1	\$ 63.00	\$ 63.00
8	TAILGATE EMBLEM 'B180'	1	\$ 85.00	\$ 85.00
9	TAILGATE CHROME MOULDING <i>Replaced</i>	1	\$ 312.00	\$ 312.00
10	TAILGATE WINDSCREEN GLASS <i>Shattered</i>	1	\$ 1,128.00	\$ 1,128.00
11	TAILGATE WINDSCREEN MOULDING <i>Replaced</i>	1	\$ 198.00	\$ 198.00
12	TAILGATE WIPER MOTOR <i>Replaced</i>	1	\$ 689.00	\$ 689.00
13	TAILGATE WIPER ARM <i>ct</i>	1	\$ 198.00	\$ 198.00
14	REAR BUMPER <i>Replaced</i>	1	\$ 1,768.00	\$ 1,768.00
15	REAR BUMPER LOWER <i>ct</i>	1	\$ 589.00	\$ 589.00
16	REAR BUMPER TOP CHROME <i>Replaced</i>	1	\$ 351.00	\$ 351.00
17	REAR BUMPER SIDE RETAINER <i>Replaced</i>	2	\$ 82.00	\$ 164.00
18	REAR BUMPER TOW HOOK COVER <i>Replaced</i>	1	\$ 60.00	\$ 60.00
19	REAR BUMPER CENTRE BRACKET <i>Replaced</i>	1	\$ 321.00	\$ 321.00
20	REAR BUMPER REINFORCEMENT <i>Replaced</i>	1	\$ 598.00	\$ 598.00

21	TAIL LAMP <i>cracked.</i>	2	\$ 598.00	\$ 1,196.00	✓
22	TAIL LAMP LOWER GARNISH <i>new</i>	2	\$ 198.00	\$ 396.00	x.
23	TAIL LAMP PANEL <i>dented</i>	2	\$ 289.00	\$ 578.00	✓
24	REAR FENDER <i>Buckeed.</i>	2	\$ 1,359.00	\$ 2,718.00	✓
25	REAR FENDER QUARTER GLASS MOULDING <i>new</i>	2	\$ 415.00	\$ 830.00	x
26	REAR FENDER INNER TRIM <i>cracked</i>	2	\$ 689.00	\$ 1,378.00	← 1169.
27	REAR FENDER INNER TRIM (TOP) <i>new</i>	2	\$ 511.00	\$ 1,022.00	x.
28	REAR FENDER INNER COWLING <i>new</i>	2	\$ 219.00	\$ 438.00	x
29	REAR END PANEL <i>dented</i>	1	\$ 965.00	\$ 965.00	✓
30	REAR END PANEL TOP GARNISH <i>Rehnd</i>	1	\$ 550.00	\$ 550.00	← 221
31	REAR FLOOR PANEL <i>2yr</i>	1	\$ 1,548.00	\$ 1,548.00	+
32	REAR FLOOR PANEL TOP BOARD <i>Rehnd</i>	1	\$ 543.00	\$ 543.00	✓
33	REAR EXHAUST PIPE <i>new</i>	1	\$ 1,356.00	\$ 1,356.00	+
34	REAR EXHAUST MOUNTING <i>new</i>	2	\$ 58.00	\$ 116.00	x
35	REAR EXHAUST EXHAUST INSULATOR <i>new</i>	1	\$ 476.00	\$ 476.00	x
36	REVERSE SENSOR WIRE HARNESS <i>new</i>	1	\$ 431.00	\$ 431.00	x
37	REVERSE SENSOR <i>2 pieces dyd</i>	4	\$ 341.00	\$ 1,364.00	← 520.

17444
15699.60

TOTAL PRICE \$ 26,895.00
LESS 10% \$ 2,689.50
SUB TOTAL PRICE \$ 24,205.50

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR BUMPER CLIP <i>new</i>	10	\$ 6.50	\$ 65.00	30
2	TAILGATE INNER TRIM CLIP <i>new</i>	10	\$ 6.50	\$ 65.00	30.
3	TAILGATE SPOILER <i>new</i>	1	\$ 1,200.00	\$ 1,200.00	x
4	TAILGATE WINDSCREEN WIPER BLADE <i>lot</i>	1	\$ 50.00	\$ 50.00	30.
5	TAIL LAMP CLIP <i>new</i>	4	\$ 6.50	\$ 26.00	✓
6	TAILGATE WINDSCREEN INNER SEAL <i>3mm</i>	1	\$ 80.00	\$ 80.00	50
7	TAILGATE WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00	30
8	TAILGATE TINTED GLASS <i>new</i>	1	\$ 500.00	\$ 500.00	250.
9	REAR FENDER QUARTER GLASS SEALANT <i>new</i>	2	\$ 80.00	\$ 160.00	60.
10	REAR FENDER INNER COWLING CLIP <i>new</i>	12	\$ 6.50	\$ 78.00	x
11	REAR FENDER INNER TRIM CLIP <i>new</i>	12	\$ 6.50	\$ 78.00	60
12	REAR END PANEL TOP GARNISH CLIP <i>new</i>	8	\$ 6.50	\$ 52.00	10
13	REAR END PANEL INNER TRIM CLIP <i>new</i>	12	\$ 6.50	\$ 78.00	x
14	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60.

Rear bumper \$1000
dyd 480

500 480
300

TOTAL \$ 2,662.00

1096

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	TO PANEL BEAT, WELD, CUT, KNOCK STRAIGHTEN, ADJUST GRAZE, JOIN	\$ 2,200.00	1800	
2	TO PUTTY, SPRAY PAINT, POLISH, WAX AFFECTED PARTS AND PANELS	\$ 1,800.00	1400.	

3	TUFF COAT	\$	250.00	100	
4	WIRING CHECK	\$	150.00	30	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$	550.00	80	
6	REMOVE AND REFIX REAR WINDSCREEN GLASS	\$	120.00	✓	
7	REMOVE AND REFIX REAR FENDER QUARTER GLASS 2PCS	\$	200.00	120	
8	CONDUCT WATER LEAKAGE TEST	\$	80.00	x	
9	TRANSFER BOOTLID MECHANISM	\$	80.00	✓	
10	REMOVE AND REFIX REAR EXHAUST PIPE	\$	150.00	x	

TOTAL \$ **5,580.00** 3730

ESTIMATE REPORT

TOTAL PARTS COST : \$ 26,867.50
TOTAL LABOUR COST : \$ 5,580.00
TOTAL REPAIR COST : \$ 32,447.50

APPROVED DETAILS

EXCESS :
NO. OF DAYS :
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Adrian L
H/s 22/03/19.

13 Days.

total: 2051560

H/S 16.4K. ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Mar 2019 15:32		21 Mar 2019 15:38 Edit Adj Rpt	S\$16,400.00 Edit Estimates	S\$16,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LIM CHIN YONG TRANSPORT PTE LTD , Co. Reg. No.: 201115637H								
Main Claimant:	LAU CHEE WEE, DAVID (LIU ZHIWEI) , ID: S7918993F								
Vehicle Reg. No.:	SMD3865B	Date of Loss:	19/03/2019 17:00 - :59 [7 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	DMB1SN16537718022 (TP, Fire & Theft) Coverage: 01/11/2018 - 31/10/2019						
Vehicle Reg. No. (Insured):	PZ1298A	Policy No. (Claimant):	1800096821						
		Excess:	S\$1,000.00						
Repairer:	SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre, 415933 Kaki Bukit - Tel: 67895155								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 01/04/2019]								
Driver/Customer (Insured):	MUHAMMAD FABBLY BIN MOHD NAZIR (/ Male) , NRIC: S7930102G Email:								
Adj. Remarks:	to assign Adrian Ling to conduct PRS. Thank you								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMD3865B

[PZ1298A]

TP

LAU CHEE WEE, DAVID (LIU ZHIWEI)

Mar 19 2019 5:00PM

[LIM CHIN YONG TRANSPORT PTE LTD]

SK Automobile Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		☒	
No	Finalized On	National Assessment Centre Services (Bukit Merah)				Thumbnail		Print	
1	20/03/19 16:34	Accident Statement				 Load HTM		☒	
Photos/Images						3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	22/04/19 18:04	General View				 Load JPG		☒	
2	22/04/19 18:04	General View				 Load JPG		☒	
3	22/04/19 18:04	General View				 Load JPG		☒	
4	22/04/19 18:04	General View				 Load JPG		☒	
5	22/04/19 18:04	General View				 Load JPG		☒	
6	22/04/19 18:04	General View				 Load JPG		☒	
7	22/04/19 18:04	General View				 Load JPG		☒	
8	22/04/19 18:04	General View				 Load JPG		☒	
9	22/04/19 18:04	General View				 Load JPG		☒	
10	22/04/19 18:04	General View				 Load JPG		☒	
11	22/04/19 18:04	General View				 Load JPG		☒	
12	22/04/19 18:04	General View				 Load JPG		☒	
13	22/04/19 18:04	General View				 Load JPG		☒	
14	22/04/19 18:04	General View				 Load JPG		☒	
15	22/04/19 18:04	General View				 Load JPG		☒	
16	22/04/19 18:04	General View				 Load JPG		☒	
17	22/04/19 18:04	General View				 Load JPG		☒	
18	22/04/19 18:04	General View				 Load JPG		☒	
19	22/04/19 18:04	General View				 Load JPG		☒	
20	22/04/19 18:04	General View				 Load JPG		☒	
21	22/04/19 18:04	General View				 Load JPG		☒	
22	22/04/19 18:04	General View				 Load JPG		☒	
23	22/04/19 18:04	General View				 Load JPG		☒	
24	22/04/19 18:04	General View				 Load JPG		☒	
25	22/04/19 18:04	General View				 Load JPG		☒	
26	22/04/19 18:04	General View				 Load JPG		☒	
27	22/04/19 18:04	General View				 Load JPG		☒	
28	22/04/19 18:04	General View				 Load JPG		☒	
29	22/04/19 18:04	General View				 Load JPG		☒	
30	22/04/19 18:04	General View				 Load JPG		☒	
31	22/04/19 18:04	General View				 Load JPG		☒	
32	22/04/19 18:04	General View				 Load JPG		☒	
33	22/04/19 18:04	General View				 Load JPG		☒	
34	22/04/19 18:04	General View				 Load JPG		☒	

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
				☒
35	22/04/19 18:04	General View	 Load JPG	☒
36	22/04/19 18:04	General View	 Load JPG	☒
37	22/04/19 18:04	General View	 Load JPG	☒
38	22/04/19 18:04	General View	 Load JPG	☒
39	22/04/19 18:04	General View	 Load JPG	☒
40	22/04/19 18:04	General View	 Load JPG	☒
41	22/04/19 18:04	General View	 Load JPG	☒
42	22/04/19 18:04	General View	 Load JPG	☒
43	22/04/19 18:04	General View	 Load JPG	☒
44	22/04/19 18:04	General View	 Load JPG	☒
45	22/04/19 18:04	General View	 Load JPG	☒
46	22/04/19 18:04	General View	 Load JPG	☒
47	22/04/19 18:04	General View	 Load JPG	☒
48	22/04/19 18:04	General View	 Load JPG	☒
49	22/04/19 18:04	General View	 Load JPG	☒
50	22/04/19 18:04	General View	 Load JPG	☒
51	22/04/19 18:04	General View	 Load JPG	☒
52	22/04/19 18:04	General View	 Load JPG	☒
53	22/04/19 18:04	General View	 Load JPG	☒
54	22/04/19 18:04	General View	 Load JPG	☒
55	22/04/19 18:04	General View	 Load JPG	☒
56	22/04/19 18:04	General View	 Load JPG	☒
57	22/04/19 18:04	General View	 Load JPG	☒
58	22/04/19 18:04	General View	 Load JPG	☒
59	22/04/19 18:04	General View	 Load JPG	☒
60	22/04/19 18:04	Reinspection Photo	 Load JPG	☒
61	22/04/19 18:04	Reinspection Photo	 Load JPG	☒
62	22/04/19 18:04	Reinspection Photo	 Load JPG	☒
63	22/04/19 18:04	Reinspection Photo	 Load JPG	☒
64	22/04/19 18:04	Reinspection Photo	 Load JPG	☒
65	22/04/19 18:04	Reinspection Photo	 Load JPG	☒
66	22/04/19 18:04	Reinspection Photo	 Load JPG	☒
67	22/04/19 18:04	Reinspection Photo	 Load JPG	☒
68	22/04/19 18:04	Reinspection Photo	 Load JPG	☒
69	22/04/19 18:04	Reinspection Photo	 Load JPG	☒
70	22/04/19 18:04	Reinspection Photo	 Load JPG	☒
71	22/04/19 18:04	Reinspection Photo	 Load JPG	☒
72	22/04/19 18:04	Reinspection Photo	 Load JPG	☒
73	22/04/19 18:04	Reinspection Photo	 Load JPG	☒
74	22/04/19 18:04	Reinspection Photo	 Load JPG	☒
75	22/04/19 18:04	Reinspection Photo	 Load JPG	☒
76	22/04/19 18:04	Reinspection Photo	 Load JPG	☒
77	22/04/19 18:04	Reinspection Photo	 Load JPG	☒
78	22/04/19 18:04	Reinspection Photo	 Load JPG	☒
79	22/04/19 18:04	Reinspection Photo	 Load JPG	☒
80	22/04/19 18:04	Reinspection Photo	 Load JPG	☒
81	22/04/19 18:04	Reinspection Photo	 Load JPG	☒
82	22/04/19 18:04	Reinspection Photo	 Load JPG	☒
83	22/04/19 18:04	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
84	22/04/19 18:04	Reinspection Photo		☒
85	22/04/19 18:04	Reinspection Photo		☒
86	22/04/19 18:04	Reinspection Photo		☒
87	22/04/19 18:04	Reinspection Photo		☒
88	22/04/19 18:04	Reinspection Photo		☒
89	22/04/19 18:04	Reinspection Photo		☒
90	22/04/19 18:04	Reinspection Photo		☒
91	22/04/19 18:04	Reinspection Photo		☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/03/19 15:38	Insd gia report		☒
2	21/03/19 15:38	PRS		☒

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	20/03/19 16:34	Accident Statement		☒
Photos/Images			3 per page	☒
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	20/03/19 16:30	Accident Photo		☒
2	20/03/19 16:30	Accident Photo		☒
3	20/03/19 16:30	Accident Photo		☒
4	20/03/19 16:30	Accident Photo		☒
5	20/03/19 16:30	Accident Photo		☒
6	20/03/19 16:30	Accident Photo		☒
7	20/03/19 16:30	Accident Photo		☒
8	20/03/19 16:32	Identification Card		☒
9	20/03/19 16:32	Driving License		☒
Documentation			1 per page	☒
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	20/03/19 16:32	Accident Sketch Plan		☒
2	20/03/19 16:32	Accident Sketch Plan		☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19005169/ASD3Q2

Date: 13/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN16537718022

Claimant Vehicle No: SMD3865B

Insured Vehicle No: PZ1298A

Date of Loss: 19/03/2019

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMD3865B

Make & Model: MERCEDES-BENZ B180, 1.6 STYLE (R16 LED) (A) Engine No: 27091031691899

Reg. Date: 17/08/2018 (Man. Year: 2018)

Chassis No: WDD2462422J499090

Colour: Red

Odometer: 11324 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,347.50	16,795.60	10,551.90	38.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,580.00	3,730.00	1,850.00	33.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,927.50	20,525.60	12,401.90	37.66
Approved Total (Overridden) (S\$)		16,400.00		
(S\$)	32,927.50	16,400.00	16,527.50	50.19
+ GST 7.00/7.00% (S\$)	2,304.93	1,148.00	1,156.93	50.19
Nett Amount (S\$)	35,232.43	17,548.00	17,684.43	50.19

INSPECTION

Date of Assignment: 21/03/2019

Date Inspected: 22/03/2019 Inspected At:

8 KAKI BUKIT AVE 4 #08-46

Repairer:SK Automobile Pte Ltd (HQ)

Estimated Period of Repair: 13.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2019)
Parts: 144	MERCEDES-BENZ B180 1.6 STYLE (R16 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD3865B)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE	Distorted	1,959.00 FL	*1,790.00 FL
2	1	*TAILGATE WEATHERSTRIP	Cut	259.00 FL	*259.00 FL
3	1	*TAILGATE INNER TRIM BOARD	Deformed	587.00 FL	*587.00 FL
4	2	*TAILGATE INNER TRIM SIDE GARNISH	Cut	516.00 FL	*516.00 FL
5	1	*TAILGATE TOP LOCK	Damaged	321.00 FL	*321.00 FL
6	2	*TAILGATE LAMP	Cracked	824.00 FL	*824.00 FL
7	1	*TAILGATE LOGO	Necessary	63.00 FL	*63.00 FL
8	1	*TAILGATE EMBLEM B180	Necessary	85.00 FL	*85.00 FL
9	1	*TAILGATE CHROME MOULDING	Cracked	312.00 FL	*312.00 FL
10	1	*TAILGATE WINDSCREEN GLASS	Shattered	1,128.00 FL	*1,128.00 FL
11	1	*TAILGATE WINDSCREEN MOULDING	Necessary	198.00 FL	*198.00 FL
12	1	*TAILGATE WIPER MOTOR	Not Necessary	689.00 FL	*- FL
13	1	*TAILGATE WIPER ARM	Cut	198.00 FL	*198.00 FL
14	1	*REAR BUMPER	Deformed	1,768.00 FL	*1,429.00 FL
15	1	*REAR BUMPER LOWER	Cut	589.00 FL	*395.00 FL
16	1	*REAR BUMPER TOP CHROME	Necessary	351.00 FL	*351.00 FL
17	2	*REAR BUMPER SIDE RETAINER	Necessary	164.00 FL	*164.00 FL
18	1	*REAR BUMPER TOW HOOK COVER	Repair	60.00 FL	*- FL
19	1	*REAR BUMPER CENTRE BRACKET	Cracked	321.00 FL	*321.00 FL
20	1	*REAR BUMPER REINFORCEMENT	Bent	598.00 FL	*598.00 FL
21	2	*TAIL LAMP	Cracked	1,196.00 FL	*1,196.00 FL
22	2	*TAIL LAMP LOWER GARNISH	Not Necessary	396.00 FL	*- FL
23	2	*TAIL LAMP PANEL	Dented	578.00 FL	*578.00 FL
24	2	*REAR FENDER	Buckled	2,718.00 FL	*2,718.00 FL
25	2	*REAR FENDER QUARTER GLASS MOULDING	Not Necessary	830.00 FL	*- FL
26	2	*REAR FENDER INNER TRIM	Cracked	1,378.00 FL	*1,164.00 FL
27	2	*REAR FENDER INNER TRIM (TOP)	Not Necessary	1,022.00 FL	*- FL
28	2	*REAR FENDER INNER COWLING	Not Necessary	438.00 FL	*- FL
29	1	*REAR END PANEL	Dented	965.00 FL	*965.00 FL
30	1	*REAR END PANEL TOP GARNISH	Deformed	550.00 FL	*221.00 FL
31	1	*REAR FLOOR PANEL	Repair	1,548.00 FL	*- FL
32	1	*REAR FLOOR PANEL TOP BOARD	Deformed	543.00 FL	*543.00 FL
33	1	*REAR EXHAUST PIPE	Not Necessary	1,356.00 FL	*- FL
34	2	*REAR EXHAUST MOUNTING	Not Necessary	116.00 FL	*- FL
35	1	*REAR EXHAUST INSULATOR	Not Necessary	476.00 FL	*- FL
36	1	*REVERSE SENSOR WIRE HARNESS	Not Necessary	431.00 FL	*- FL
37	4	*REVERSE SENSOR	Damaged (2 PCS ONLY)	1,364.00 FL	*520.00 FL
38	10	*REAR BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
39	10	*TAILGATE INNER TRIM CLIP	Necessary	65.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*TAILGATE SPOILER	Not Necessary	1,200.00 FS	*- FS
41	1		*TAILGATE WINDSCREEN WIPER BLADE	Cut	50.00 FS	*30.00 FS
42	4		*TAIL LAMP CLIP	Necessary	26.00 FS	*26.00 FS
43	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	80.00 FS	*30.00 FS
44	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*30.00 FS
45	1		*TAILGATE TINTED GLASS	Necessary	500.00 FS	*250.00 FS
46	2		*REAR FENDER QUARTER GLASS SEALANT	Necessary	160.00 FS	*60.00 FS
47	12		*REAR FENDER INNER COWLING CLIP	Not Necessary	78.00 FS	*- FS
48	12		*REAR FENDER INNER TRIM CLIP	Necessary	78.00 FS	*60.00 FS
49	8		*REAR END PANEL TOP GARNISH CLIP	Necessary	52.00 FS	*10.00 FS
50	12		*REAR END PANEL INNER TRIM CLIP	Not Necessary	78.00 FS	*- FS
51	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
52	1		*REAR CAMERA	Damaged	480.00 FS	*480.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	30,037.00	18,540.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,689.50	1,744.40
Total Parts (\$\$)	27,347.50	16,795.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT,WELD ,CUT ,KNOCK STRAIGHTEN ,ADJUST GRAZE ,JOIN	New	2,200.00	1,800.00
2	TO PUTTY,SPRAY PAINT,POLISH,WAX AFFECTED PARTS AND PANELS	New	1,800.00	1,400.00
3	TUFF COAT	New	250.00	100.00
4	WIRING CHECK	New	150.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	550.00	80.00
6	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
7	REMOVE AND REFIX REAR FENDER QUARTER GLASS	New	200.00	120.00
8	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
9	TRANFER BOOTLID MECHANISM	New	80.00	80.00
10	REMOVE AND REFIX REAR EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (S\$)			5,580.00	3,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >