

ASS. REC. BY:

REF: CS/CTI 19005170 / kvd 302

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Elaine Cheong

of CTI

Date/Time: 21.3.2019 11.31 p.m

Estimated Cost:

Bill to:

GD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: skw 5079 P

Insured: GBE 285 L

at Workshop m/s Lai Huat (Mong Kae)

Tel: 64538110

of 160 sin ming drive # 04-01

Policy No: DM VCSN 3063681800

Claim No: SNM 19D 2012 71002 / 6

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 19.3.19

CA / REV / REP. / REV 24 HRS

"W"

H.O.D. Endorsement:

Date/Time: 22.3.19 9.17 am

Person Contacted:

Jenny

Vehicle IN / OUT

Date/Time	Action/Instruction	Estimate (✓)
	skw 5079 P - X	
	GBE 285 L - CS / EGI 1601 26451 K9H 3 C2	D.O.A - 4/7/2016
29/4/19	Final fig	\$ 3377.16 (Red 2372, 419) (No LS)

REF: CFI

ASSIGNMENT

From: _____ Date: 22/3/19

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SKW 5079P
at Workshop m/s: Lei Hwa (Mengkee)
of 160 Sin Ming Drive # 04-01

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Mrng

Veh No: SKW 5079P Yr Regn: 10, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Audi A3 c.c. 1395

Colour: M. Green A/C: Insured / Std / NI / NA

Sp. Reading: 27580 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU8888V6G1030350

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16
R: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No


Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 1.31% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Continental

Front R/Bal. 6 mm L/Bal. 6 mm D.O.A. 19/3/19

Rear R/Bal. 6 mm L/Bal. 6 mm D.O.I. 22/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
RECEIVED 06 MAY 2019	
	<i>[Signature]</i> 11/4/2019

Date/Time, File Pass to? : Preli. Report : Final Report

1) _____

Date/Time, File Return to? _____

2) 6/5 - typist

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Invs (\$) : Weekend (\$)

Survey Fee: _____

Transportation: _____

S + RS, SI _____

Photos _____

Others _____

TOTAL 220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Mar 2019 Sendback Est	21 Mar 2019 15:42 S\$2,955.80	21 Mar 2019 16:31 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS

Insured: --, ID: --

Main Claimant: **CHIA SIEW CHENG**, ID: S1403810H

Vehicle Reg. No.:	SKW5079P	Date of Loss:	19/03/2019 16:00 - :59 [40 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D201271C02/5	Policy/Cover Note No.:	DMCVSN3063681800 Coverage: 02/10/2018 - 01/10/2019
Vehicle Reg. No. (Insured):	GBE2185L	Policy No. (Claimant):	2100471849-02
		Excess:	S\$0.00

Repairer: **Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)** 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110

Handling Insurer: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111 ... [Handled by **Elaine Cheong**]

Claimant's Insurer: **AIG Asia Pacific Insurance Pte. Ltd. (SG)** - Tel: 65-6419-3000

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Final Rpt due 01/04/2019]

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



CERTIFICATE OF INSURANCE

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder : CHIA SIEW CHENG
Period of Insurance : 30 Oct 2018 To 29 Oct 2019
Engine No. : CZC287256
Chassis No. : WAUZZZ8V6G1030350

Vehicle No. : SKW5079P
Policy No. : 2100471849-02
Endorsement No. :
Issued Date : 13 Sep 2018

ABOUT THE COVER

Make/Model : AUDI A3 SEDAN 1.4 TFSI (AMBIENTE)
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2015
Insuring with COE/PARF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

CHIA SIEW CHENG - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/ AIG Authorised Repairers (For claims related repairs)
Any accident repairs to the Vehicle must be carried out by one of our Authorised Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Sole Agent's workshop.
For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, You may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125000

PREMIUM LEASING PTE LTD
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. Manile

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSCASB

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
GBE2185L	19 Mar 2019 / 16:25:00	Successful	C01	CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Previous

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/03/2019 17:32
Date Of Accident	19/03/2019 16:25
Exact Location Of Accident	JUNCTION OF UPPER THOMSON ROAD AND JALAN LEMBAH TH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW5079P
Insured/Policyholder	
Name Of Registered Owner	CHIA SIEW CHENG
NRIC No	S1403810H
Email Address	CHIASIEWCHENG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92996604
Alternative Phone No	OTHERS-92996604
Vehicle Particulars	
Manufacturer	AUDI
Model	A3 SEDAN 1.4 TFSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100471849-02
Cover Note Number	
Driver	
Name of Driver	CHIA SIEW CHENG
NRIC No	S1403810H
Date Of Birth	21/05/1960
Occupation	INDOOR
Date Of Driving Pass	16/06/1981
Driving Experience	37 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92996604
Fax Number	
Contact Number	OTHERS-92996604
EEmail Address	CHIASIEWCHENG@GMAIL.COM

Address 52 GARDENIA ROAD
SINGAPORE

Postcode 578842

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name THOMSON NPP 25 SIN MING ROAD

Police Station Address **ROAD: 25 SIN MING ROAD #01-180 , POSTCODE: 570025 , COUNTRY: SINGAPORE**

Police Station Contact **TEL NO: - FAX NO:**

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT: NOTICE OF REPORTING - S/D REF: ESD 29.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBE2185L

Vehicle Make/Model/Colour TOYOTA PICK UP BLUE

Details Of Properties C/O BENCO -OFFICE TEL: 68613060

Vehicle Category COMMERCIAL VEHICLE

Name of Driver CHEW BOON KEONG

NRIC/Passport Number G2460381X

Contact Number 84543036

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for Investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

23 MAR 2019

GT/AR/C/Photo/Plan/acc_03

Reporting Centre Personnel's Signature


Name: Poh Kwee Choo

NRIC/FIN No.: S6040583A

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1403810H



Name
CHIA SIEW CHENG
謝秀清
Race
CHINESE
Date of Birth **21-05-1960** Sex **F**
Country of Birth
SINGAPORE



Lai Huat (Meng Kee) Motor Pte Ltd

160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming
Autocity
575722

Claim Reference: 70344
Assessment number: 000164
Version: 1810
Date calculated: 03/21/2019 03:37 PM

Full Report
Registration: SKW 5079P
Printed: 21/03/2019 3:38 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	70344	Date of Incident:	2019-03-19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer: AUDI
Model: A3 SALOON (8VS)
Sub Model: AMBIENTE
Model Sheet Number: 00 5A 13
Registration: SKW 5079P
VIN number: WAUZZZ8V6G1030350
Odometer:

Model Specs

FROM 08/2015	R/ASPHERIC D/MIRROR	L/MIRROR CONVEX	BRILLIANCE PACKAGE
STOP-START SYSTEM	DEACTIVATED P/AIRBAG	FRONT BRAKE 288 X 25	AUTO AIR CON
FRONT SCREEN W/WEDGE	REAR PARKING SYSTEM	HEATED DOOR MIRRORS	ELEC FOLD DR MIRRORS
AUTO DIPPING MIRROR	8 SPEAKER	MMI RADIO STANDARD	XENON HEADLAMPS
MULTI FUNC S-WHEEL	HEATED WASHER JETS	HEADLAMP WASHERS	LIGHT-/RAIN SENSOR
EQUIP LEATH/IMIT LEA	STORAGE PACKAGE	AUTO DIPPING MIRROR	DRIVER INFO COLOUR
INTERIOR LAMP PACK	FRONT CENTRE ARMREST	EMISSION STD EURO 6+	HD COOLING
S-TRONIC 7-SPEED	INDEPENT RR SUSPENS	CRUISE CONTROL	TYRES 205/55 WR 16
PHONE SYS BLUETOOTH	GLASS OPTICS TRIM	1.4 LTR 92KW	TWO COAT METALLIC
PREPARE OFF VEHICLE			

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
55 90 19 00	R + R BOOTLID INCLUDES: R + R BOOTLID TRIM, ADJUST BOOTLID		9.0	37.80
55 90 55 50	RENEW BOOTLID (BOOTLID REMOVED) INCLUDES: R + R ALL PARTS		11.0	46.20
63 69 55 52	RENEW REAR BUMPER COVER		5.0	21.00

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming
Autocity
575722

Claim Reference: 70344
 Assessment number: 000164
 Version: 1810
 Date calculated: 21/03/2019 03:37 PM

Full Report
 Registration: SKW 5079P
 Printed: 21/03/2019 3:38 PM
 WU Price SGD

	(COVER REMOVED)			
	INCLUDES: R + R LOWER SPOILER AND SENSORS			
66 59 55 50	RENEW REAR LOWER BUMPER SPOILER		1.0	4.20
53 16 53 01	REMOVE PARTS REAR END CROSSMEMBER		9.0	37.80
	INCLUDES: REMOVE TAILLAMPS, BUMPER (IMPACT CARRIER), BUMPER COVER, LOCK CARRIER COVER, BOOT TRIMS, TAILGATE SEAL AND LOWER LOCK			
53 16 55 01	RENEW REAR END CROSSMEMBER		19.0	79.80
53 16 59 01	FIT PARTS REAR END CROSSMEMBER		11.0	46.20
	INCLUDES: FIT REMOVED PARTS, RENEW IF NECESSARY			
2711	DOES NOT INCLUDE: RENEW BUMPER COVER REAR PANEL REPAIR		20	30.0*
				126.00
	Labour Cost	Hrs	WU	
	Panel / Mechanical Labour	9.50	95.0	399.00
	Total of Labour			399.00

Paint

Paint Work		Time Basis 10WU/h		
Code	Description - TWO COAT METALLIC		WU	Price SGD
63 69 61 50	REAR COVER BUMPER NEW PART PAINTING S1 ✓		9.0	37.80
91 75 61 50	L/R INNER SENSOR NEW PART PAINTING S1 ✓		1.0	4.20
55 59 61 00	BOOTLID/TAILGATE NEW PART PAINTING S1 ✓		11.0	46.20
53 05 79 03	REAR PANEL REPAIR PAINT S3 ✓		9.0	37.80
91 75 79 52	L/R OUTER SENSOR SURFACE PAINTING S2 ✓		1.0	4.20
91 75 79 52	R/R OUTER SENSOR SURFACE PAINTING S2 ✓		1.0	4.20
91 75 79 52	R/R INNER SENSOR SURFACE PAINTING S2 ✓		1.0	4.20
51 01 71 13	PAINTING PREPARATION WORK NEW PART S1 METAL (PART/S FITTED) Δ X		19.0	79.80
51 01 71 93	PREPARATION FOR PAINT (PLASTIC PARTS) (ASSEMBLY OPERATION) Δ X		2.0	8.40
	Total Paint	Hrs	WU	Price SGD
		5.40	54.0	226.80

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming
Autocity
575722

Claim Reference: 70344
 Assessment number: 000164
 Version: 1810
 Date calculated: 03/21/2019 03:37 PM

Full Report
Registration: SKW 5079P
Printed: 21/03/2019 3:38 PM

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-09-02/23	Price SGD
2581	REAR COVER BUMPER	8V5 807 067 A		Bur ✓ ✓	600.00
		GRU			
2605	REAR BUMPER SPOILER	8V5 807 521 B		Ned ✓ ✓	120.00
2640	REAR BUMPER SUPPORT	8V5 807 309		R1 ✓ ?	200.00
2719	REAR PANEL C-MEMBER	8V5 813 307		Bur ✓ ?	160.00
2783	L/R INNER SENSOR	5Q0 919 275 B		M1 ✓ ✓	95.00
		GRU			
2931	BOOTLID/TAILGATE	8V5 827 025 F		B1 ✓ ✓	950.00
2951	BOOT/T.GATE MNTG SET	8V0 098 617 B		Bur ✗	0.00
3013	L/R BADGE	8P0 853 741	2ZZ	Ne ✓ ✓	35.00
3019	R/R BADGE	8X0 853 737 A		Ne ✓ ✓	40.00
		2ZZ			
3020	REAR BADGE	8V7 853 742	2ZZ	Ne ✓ ✓	50.00
					0.00
	Savings				0.00
	Subtotal				2,250.00
	Total				2,250.00

f: OEM Parts
 n: Non-OEM Parts
 u: Used parts

Extras

Code	Description	Price SGD
1000	CHK/ERASE FAULT CODE SN	✓ 80.00*
	Total Extras	80.00

*NOT Notified
 Primary Repair*

LKK Auto Consultants hence notify the Repairer of the following: *5 days*

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

**Lai Huat (Meng Kee) Motor Pte
Ltd**
**160 Sin Ming Drive, #04-01,
 #04-02 & #07-03, Sin Ming
 Autocity**
575722

Claim Reference: 70344
 Assessment number: 000164
 Version: 1810
 Date calculated: 03/21/2019 03:37 PM

Full Report
Registration: SKW 5079P
Printed: 21/03/2019 3:38 PM

Final Calculation

		SGD	SGD
Parts	2330	2,250.00	
Total Parts			2,250.00
Labour Time Base 10 WU/h			
Total 95.0 WU X 42.00 SGD/h	357	399.00	
Total of Labour			399.00
Total Of Extras			80.00
Paint Work Time Base 10 WU/h			
Labour Cost 54.0 WU X 42.00 SGD/h	510.16	226.80	
Total Paint Including Material			226.80
Repair Cost Excludes GST		2,749.16	2,955.80
GST (+7.0%)			206.91
Repair Cost Included GST			3,162.71

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming
Autocity
575722

Claim Reference: 70344
 Assessment number: 70344
 Version: 1810
 Date calculated: 04/05/2019 04:32 PM

Full Report
Registration: SKW 5079P
Printed: 05/04/2019 4:32 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	70344	Date of Incident:	2019-03-19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle
 Manufacturer: AUDI
 Model: A3 SALOON (8VS)
 Sub Model: AMBIENTE
 Model Sheet Number: 00 5A 13
 Registration: SKW 5079P
 VIN number: WAUZZZ8V6G1030350
 Odometer:

Model Specs			
FROM 08/2015	R/ASPHERIC D/MIRROR	L/MIRROR CONVEX	BRILLIANCE PACKAGE
STOP-START SYSTEM	DEACTIVATED P/AIRBAG	FRONT BRAKE 288 X 25	AUTO AIR CON
FRONT SCREEN W/WEDGE	REAR PARKING SYSTEM	HEATED DOOR MIRRORS	ELEC FOLD DR MIRRORS
AUTO DIPPING MIRROR	8 SPEAKER	MMI RADIO STANDARD	XENON HEADLAMPS
MULTI FUNC S-WHEEL	HEATED WASHER JETS	HEADLAMP WASHERS	LIGHT-/RAIN SENSOR
EQUIP LEATH/IMIT LEA	STORAGE PACKAGE	AUTO DIPPING MIRROR	DRIVER INFO COLOUR
INTERIOR LAMP PACK	FRONT CENTRE ARMREST	EMISSION STD EURO 6+	HD COOLING
S-TRONIC 7-SPEED	INDEPENT RR SUSPENS	CRUISE CONTROL	TYRES 205/55 WR 16
PHONE SYS BLUETOOTH	GLASS OPTICS TRIM	1.4 LTR 92KW	TWO COAT METALLIC
PREPARE OFF VEHICLE			

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
55 90 19 00	R + R BOOTLID INCLUDES: R + R BOOTLID TRIM, ADJUST BOOTLID		9.0	37.80
55 90 55 50	RENEW BOOTLID (BOOTLID REMOVED) INCLUDES: R + R ALL PARTS		11.0	46.20
63 69 55 52	RENEW REAR BUMPER COVER		5.0	21.00

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming
Autocity
575722

Claim Reference: 70344
 Assessment number: 70344
 Version: 1810
 Date calculated: 04/05/2019 04:32 PM

Full Report
 Registration: SKW 5079F
 Printed: 05/04/2019 4:32 PM
 WU Price SGD

		(COVER REMOVED)		
		INCLUDES: R + R LOWER SPOILER AND SENSORS		
66 59 55 50		RENEW REAR LOWER BUMPER SPOILER	1.0	4.20
53 16 53 01		REMOVE PARTS REAR END CROSSMEMBER	9.0	37.80
		INCLUDES: REMOVE TAILLAMPS, BUMPER (IMPACT CARRIER), BUMPER COVER, LOCK CARRIER COVER, BOOT TRIMS, TAILGATE SEAL AND LOWER LOCK		
53 16 55 01		RENEW REAR END CROSSMEMBER	19.0	79.80
53 16 59 01		FIT PARTS REAR END CROSSMEMBER	11.0	46.20
		INCLUDES: FIT REMOVED PARTS, RENEW IF NECESSARY		
2711		DOES NOT INCLUDE: RENEW BUMPER COVER REAR PANEL REPAIR	20.0*	84.00
		Labour Cost	Hrs	WU
		Panel / Mechanical Labour	8.50	85.0
		Total of Labour		357.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h	WU	Price SGD
Code	Description - TWO COAT METALLIC			
	BOOTLID/TAILGATE NEW PART PAINTING ✓		16.0	
	REAR COVER BUMPER NEW PART PAINT K1R ✓		13.0	
	L/R INNER SENSOR NEW PART PAINT K1R ✓		3.0	
	REAR PANEL REPAIR PAINTING <50% ✓		12.0	
	L/R OUTER SENSOR SURFACE PAINT PLAST. ✓		3.0	
	R/R OUTER SENSOR SURFACE PAINT PLAST. ✓		3.0	
	R/R INNER SENSOR SURFACE PAINT PLAST. ✓		3.0	

Paint Material Per Part

Code	Description	Price SGD
2931	BOOTLID/TAILGATE NEW PART PAINTING	44.38
2581	REAR COVER BUMPER NEW PART PAINT K1R	62.48
2783	L/R INNER SENSOR NEW PART PAINT K1R	0.48
2711	REAR PANEL REPAIR PAINTING <50%	15.50
2781	L/R OUTER SENSOR SURFACE PAINT PLAST.	0.37
2782	R/R OUTER SENSOR SURFACE PAINT PLAST.	0.37

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming
Autocity
575722

Claim Reference: 70344
 Assessment number: 70344
 Version: 1810
 Date calculated: 04/05/2019 04:32 PM

Full Report
Registration: SKW 5079P
Printed: 05/04/2019 4:32 PM

Total **2,330.00**

Extras

Code	Description	Price SGD
1000	CHK/ERASE FAULT CODE SN	80.00*
	Total Extras	80.00

Final Calculation

	SGD	SGD
Parts	2,330.00	
Total Parts		2,330.00
Labour Time Base 10 WU/h		
Total 85.0 WU X 42.00 SGD/h	357.00	
Total of Labour		357.00
Total Of Extras		80.00
Paint Work Time Base 10 WU/h		
Labour Cost 83.0 WU X 42.00 SGD/h	348.60	
Material Cost	161.56	
Total Paint Including Material		510.16
Repair Cost Excludes GST		3,277.16
GST (+7.0%)		229.40
Repair Cost Included GST		3,506.56

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming
Autocity
575722

Claim Reference: 70344
 Assessment number: 70344
 Version: 1810

Full Report
 Registration: SKW 5079F
 Printed: 05/04/2019 4:32 PM

Date calculated: 05/04/2019 04:32 PM

Code	Description	Price SGD
2784	R/R INNER SENSOR SURFACE PAINT PLAST.	0.37

Labour Cost - Paint

	Factor	Hrs	WU	Price SGD
	42.00 SGD/h			
	Time Paint		53.0	
	Preparation Main Work Metal	2.50	25.0	105.00
	Preparation Comp. Work Plastic	0.50	5.0	21.00
Total		10 WU/h	83.0	348.60

Material Cost - Paint

	Price SGD
New Part Painting	44.38
New Part Painting - Plastic K1R	62.97
Repair Painting	15.50
Surface Painting Plastic	1.11
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	161.56

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-09-02/23	Price SGD
2581	REAR COVER BUMPER	8V5 807 067 A			600.00
		GRU			
2605	REAR BUMPER SPOILER	8V5 807 521 B			120.00
2640	REAR BUMPER SUPPORT	8V5 807 309			200.00
2719	REAR PANEL C-MEMBER	8V5 813 307			160.00
2783	L/R INNER SENSOR	5Q0 919 275 B			95.00
		GRU			
2931	BOOTLID/TAILGATE	8V5 827 025 F			950.00
2951	BOOT/T.GATE MNTG SET	8V0 098 617 B			0.00
2985	BOOT LID TIP SWITCH	5N0 827 566 T	(CA)		80.00
3013	L/R BADGE	8P0 853 741	2ZZ		35.00
3019	R/R BADGE	8X0 853 737 A			40.00
		2ZZ			
3020	REAR BADGE	8V7 853 742	2ZZ		50.00
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				2,330.00
u: Used parts					

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Finalised

Claim Reference: 70344
Assessment number: 70344
Version: 1810
Date calculated: 11/04/2019 1:05 PM

Full Report
Registration: SKW 5079P
Printed: 29/04/2019 2:31 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	70344	Date of Incident:	19/03/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle
Manufacturer: AUDI
Model: A3 SALOON (8VS)
Sub Model: AMBIENTE
Model Sheet Number: 00 5A 13
Registration: SKW 5079P
VIN number: WAUZZZ8V6G1030350
Odometer:

Model Specs			
FROM 08/2015	R/ASPHERIC D/MIRROR	L/MIRROR CONVEX	BRILLIANCE PACKAGE
STOP-START SYSTEM	DEACTIVATED P/AIRBAG	FRONT BRAKE 288 X 25	AUTO AIR CON
FRONT SCREEN W/WEDGE	REAR PARKING SYSTEM	HEATED DOOR MIRRORS	ELEC FOLD DR MIRRORS
AUTO DIPPING MIRROR	8 SPEAKER	MMI RADIO STANDARD	XENON HEADLAMPS
MULTI FUNC S-WHEEL	HEATED WASHER JETS	HEADLAMP WASHERS	LIGHT-/RAIN SENSOR
EQUIP LEATH/IMIT LEA	STORAGE PACKAGE	AUTO DIPPING MIRROR	DRIVER INFO COLOUR
INTERIOR LAMP PACK	FRONT CENTRE ARMREST	EMISSION STD EURO 6+	HD COOLING
S-TRONIC 7-SPEED	INDEPENT RR SUSPENS	CRUISE CONTROL	TYRES 205/55 WR 16
PHONE SYS BLUETOOTH	GLASS OPTICS TRIM	1.4 LTR 92KW	TWO COAT METALLIC
PREPARE OFF VEHICLE			

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: 70344
 Assessment number: 70344
 Version: 1810
 Date calculated: 11/04/2019 1:05 PM

Full Report
Registration: SKW 5079P
Printed: 29/04/2019 2:31 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All
 Underbody



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
55 90 19 00	R + R BOOTLID INCLUDES: R + R BOOTLID TRIM, ADJUST BOOTLID		9.0	37.80
55 90 55 50	RENEW BOOTLID (BOOTLID REMOVED) INCLUDES: R + R ALL PARTS		11.0	46.20
63 69 55 52	RENEW REAR BUMPER COVER (COVER REMOVED) INCLUDES: R + R LOWER SPOILER AND SENSORS		5.0	21.00
66 59 55 50	RENEW REAR LOWER BUMPER SPOILER		1.0	4.20
53 16 53 01	REMOVE PARTS REAR END CROSSMEMBER INCLUDES: REMOVE TAILLAMPS, BUMPER (IMPACT CARRIER), BUMPER COVER, LOCK CARRIER COVER, BOOT TRIMS, TAILGATE SEAL AND LOWER LOCK		9.0	37.80

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: 70344
 Assessment number: 70344
 Version: 1810
 Date calculated: 11/04/2019 1:05 PM

Full Report
 Registration: SKW 5079P
 Printed: 29/04/2019 2:31 PM

Code	Description	WU	Price SGD
53 16 55 01	RENEW REAR END CROSSMEMBER	19.0	79.80
53 16 59 01	FIT PARTS REAR END CROSSMEMBER INCLUDES: FIT REMOVED PARTS, RENEW IF NECESSARY DOES NOT INCLUDE: RENEW BUMPER COVER	11.0	46.20
2711	REAR PANEL REPAIR	20.0*	84.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		8.50	85.0
Total of Labour			357.00

Paint

Code	Description - TWO COAT METALLIC	WU	Price SGD
	BOOTLID/TAILGATE NEW PART PAINTING	16.0	
	REAR COVER BUMPER NEW PART PAINT K1R	13.0	
	L/R INNER SENSOR NEW PART PAINT K1R	3.0	
	REAR PANEL REPAIR PAINTING <50%	12.0	
	L/R OUTER SENSOR SURFACE PAINT PLAST.	3.0	
	R/R OUTER SENSOR SURFACE PAINT PLAST.	3.0	
	R/R INNER SENSOR SURFACE PAINT PLAST.	3.0	

Paint Material Per Part

Code	Description	Price SGD
2931	BOOTLID/TAILGATE NEW PART PAINTING	44.38
2581	REAR COVER BUMPER NEW PART PAINT K1R	62.48
2783	L/R INNER SENSOR NEW PART PAINT K1R	0.49
2711	REAR PANEL REPAIR PAINTING <50%	15.50
2781	L/R OUTER SENSOR SURFACE PAINT PLAST.	0.37
2782	R/R OUTER SENSOR SURFACE PAINT PLAST.	0.37
2784	R/R INNER SENSOR SURFACE PAINT PLAST.	0.37

Labour Cost - Paint	Hrs	WU	Price SGD
Factor			42.00 SGD/h
Time Paint		53.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.50	5.0	21.00
Total	10 WU/h	83.0	348.60

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: 70344
 Assessment number: 70344
 Version: 1810
 Date calculated: 11/04/2019 1:05 PM

Full Report
Registration: SKW 5079P
Printed: 29/04/2019 2:31 PM

Material Cost - Paint	Price SGD
New Part Painting	44.38
New Part Painting - Plastic K1R	62.97
Repair Painting	15.50
Surface Painting Plastic	1.11
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	161.56

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-09-02/23	Price SGD
2581	REAR COVER BUMPER	8V5 807 067 A			600.00
		GRU			
2605	REAR BUMPER SPOILER	8V5 807 521 B			120.00
2640	REAR BUMPER SUPPORT	8V5 807 309			200.00
2719	REAR PANEL C-MEMBER	8V5 813 307			160.00
2783	L/R INNER SENSOR	5Q0 919 275 B			95.00
		GRU			
2931	BOOTLID/TAILGATE	8V5 827 025 F			950.00
2951	BOOT/T.GATE MNTG SET	8V0 098 617 B			0.00
2985	BOOT LID TIP SWITCH	5N0 827 566 T			80.00 (A)
3013	L/R BADGE	8P0 853 741	2ZZ		35.00
3019	R/R BADGE	8X0 853 737 A			40.00
		2ZZ			
3020	REAR BADGE	8V7 853 742	2ZZ		50.00
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				2,330.00
u: Used parts	Total				2,330.00

Extras

Code	Description	Price SGD
1000	CHK/ERASE FAULT CODE SN	80.00*
1001	SUNDRIES	100.00* (A)
	Total Extras	180.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: 70344
Assessment number: 70344
Version: 1810
Date calculated: 11/04/2019 1:05 PM

Full Report
Registration: SKW 5079P
Printed: 29/04/2019 2:31 PM

Final Calculation

	SGD	SGD
Parts	2,330.00	
Total Parts		2,330.00
Labour Time Base 10 WU/h		
Total 85.0 WU X 42.00 SGD/h	357.00	
Total of Labour		357.00
Total Of Extras		180.00
Paint Work Time Base 10 WU/h		
Labour Cost 83.0 WU X 42.00 SGD/h	348.60	
Material Cost	161.56	
Total Paint Including Material		510.16
Repair Cost Excludes GST		3,377.16
GST (+7.0%)		236.40
Repair Cost Included GST		3,613.56

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 29 April 2019 3:50 PM
To: Jenny Lim
Cc: SUR
Subject: RE: Finalisation - SKW 5079P / Audi A3

Dear Jenny,

WITHOUT PREJUDICE

Confirmed amount \$3377.16 @ 5 days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Lim <jenny.lim@laihuat.com.sg>
Sent: Saturday, 6 April 2019 11:34 AM
To: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>
Subject: Finalisation - SKW 5079P / Audi A3

Dear Sir

For your confirmation, please:

- Parts: \$2,330.00 (include supplementary)
- SN: \$ 80.00
- Sundry: \$ 100.00
- L&P: \$ 867.16
- Total: \$3,377.16 / 9 days**

Supporting document and photographs are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Mar 2019 Sendback Est	21 Mar 2019 15:42 S\$2,955.80	21 Mar 2019 16:31 Edit Adj Rpt	S\$3,377.16 Edit Estimates	S\$3,377.16 View Rpt		Pending for Survey Report Cancel Case
Supp #1	05 Apr 2019 16:21	05 Apr 2019 16:22 S\$180.00	05 Apr 2019 16:22			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS				
Insured:	--, ID: --			
Main Claimant:	CHIA SIEW CHENG , ID: S1403810H			
Vehicle Reg. No.:	SKW5079P	Date of Loss:	19/03/2019 16:00 - :59 [40 Months and 19 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM19D201271C02/5	Policy/Cover Note No.:	DMCVSN3063681800 Coverage: 02/10/2018 - 01/10/2019	
Vehicle Reg. No. (Insured):	GBE2185L	Policy No. (Claimant):	2100471849-02	
		Excess:	S\$0.00	
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]			
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 01/04/2019]			
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail
There are no mail for this case.				
ALL ASSOCIATED TASKS <input type="checkbox"/>				
			View All	Search Tasks
			Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject
				Handler
				Assigned By
				Completed On
				Created On
				Done?
No results.				

Claim Documents

SKW5079P (SNM19D201271C02/5)
[GBE2185L]
TP
CHIA SIEW CHENG
Mar 19 2019 4:00PM
[--]
Lai Huat (Meng Kee) Motor Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View <input type="button" value="View in Browser"/>
Assessment Reports				1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	20/03/19 16:16	Accident Statement	Load HTM	<input type="checkbox"/>
2	21/03/19 15:42	Repairer Estimates	Load HTM	<input type="checkbox"/>
3	05/04/19 16:22	Repairer Estimates Suppl. #1	Load HTM	<input type="checkbox"/>
Photos/Images				3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	21/03/19 14:04	Rear View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	21/03/19 14:04	Rear View Right	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	21/03/19 14:04	Rear View Left	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	21/03/19 14:04	Rear View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	21/03/19 14:04	Rear View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	21/03/19 14:04	Rear View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	21/03/19 14:04	Tyre size	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	21/03/19 14:04	Tyre - Continental	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	21/03/19 14:04	Odometer Reading	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	21/03/19 14:04	Chassis Number	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Documentation				1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	21/03/19 14:13	E-filed GIA report	Load PDF	<input type="checkbox"/>
2	21/03/19 14:13	Driver NRIC & Driving Licence	Load PDF	<input type="checkbox"/>
3	21/03/19 14:13	Certificate of Insurance	Load PDF	<input type="checkbox"/>
4	21/03/19 14:13	Enquire PARF / COE Rebate for Registered Vehicle	Load PDF	<input type="checkbox"/>
Relabel/Reorder				1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/04/19 15:53	General View	Load PDF	<input type="checkbox"/>
2	29/04/19 15:53	Reinspection Photo (1)	Load PDF	<input type="checkbox"/>
3	29/04/19 15:53	Reinspection Photo (2)	Load PDF	<input type="checkbox"/>
Supplementary				1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/05/19 10:52	Supplementary	Load PDF	<input type="checkbox"/>

Linked Accident Report Documents

				View <input type="button" value="View in Browser"/>
Assessment Reports				1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	20/03/19 16:16	Accident Statement	Load HTM	<input type="checkbox"/>
Photos/Images				3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	19/03/19 17:32	Accident Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	19/03/19 17:32	Accident Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
3	19/03/19 17:32	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	19/03/19 17:32	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	20/03/19 16:15	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	20/03/19 16:15	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	20/03/19 16:15	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	20/03/19 16:15	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	20/03/19 16:15	CHASSIS NUMBER	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	20/03/19 12:03	Sketch Plan	Load TIF	
2	20/03/19 12:04	NOTICE OF REPORTING	Load TIF	
3	20/03/19 12:04	CERTIFICATE OF INSURANCE	Load TIF	
4	20/03/19 12:04	DRIVER'S NRIC + DRIVING LICENCE	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19005170/KVD3E2

Date: 15/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSN3063681800	
Claimant Vehicle No: SKW5079P	Insured Vehicle No: GBE2185L	
Date of Loss: 19/03/2019	Nature of Claim: TP	Claim No: SNM19D201271C02/5

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW5079P	Engine No:	CZC287256
Make & Model:	AUDI A3, 1.4 TFSI AMBIENTE MY 15 (A)	Chassis No:	WAUZZZ8V6G1030350
Reg. Date:	30/10/2015 (Man. Year: 2015)	Odometer:	27580 km
Colour:	Metallic Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,330.00	2,330.00	0.00	0.00
Miscellaneous Items	180.00	180.00	0.00	0.00
Labour	399.00	357.00	42.00	10.53
Paintwork Labour	226.80	510.16	-283.36	-124.94
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,135.80	3,377.16	-241.36	-7.70
+ GST 7.00/7.00% (S\$)	219.51	236.40	-16.89	-7.69
Nett Amount (S\$)	3,355.31	3,613.56	-258.25	-7.70

INSPECTION

Date of Assignment:	21/03/2019 Present Location:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected:	22/03/2019 Inspected At:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2019)
Parts: 143	AUDI A3 1.4 TFSI AMBIENTE MY 15 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW5079P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*Spare Parts		2,250.00 F	*2,250.00 F	
Supplementary #1							
2	1		*BOOT LID TIP SWITCH	Dented	80.00 F	*80.00 F	
					Total Parts (S\$)	2,330.00	2,330.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	CHK/ERASE FAULT CODE	80.00	80.00
Supplementary #1				
2	1	SUNDRY PARTS (NECESSARY)	100.00	100.00
Sub Total (S\$)			180.00	180.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Total Paint including Material	New	226.80	510.16
Labour Items				
2	Total of Labour	New	399.00	357.00
Gross Labour Cost (S\$)			625.80	867.16

Report was unsubmitted during this print-out.

< END OF ESTIMATES >