

Huee Jie

REF: NTUC NS/INC19005175/Jq35v

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. MT/1036367

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No. SHF522 Yr Regn. 1 NOV/2017Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius C.C. 1798Colour: maroon A/C: Insured / Std / NI / NASp. Reading: 141725 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTDKB3FU403573478Gen. Cond: Good / Fair / Poor / BurntSteering: inorder / Jammed / Leaked / Burnt orBrake: inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 18/3/19 D.O.I. 19/3/19Survey held at SumitDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SHF522-X

SHB8950A-CC3/MCG/5016590/H11602

DIA: 30/9/15

SHB8950A

No policy paid.

Final Hg @ 2400.45, 4 days (Red 4600.69, 71%)

RECEIVED 24 APR 2019

Date/Time. File Pass to?

☐ : Preli. Report

Date/Time. File Return to?

☐ : Final ReportDays Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + PS: \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

# TP Claims against NTUC Income: Follow-Through Survey

Date : 23/04/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate
1	MT/1036367-002	SMRT TAXIS PTE LTD	SHF 52Z	SHB 8950A	18/03/2019	12:35	\$ 8,445.14
2	MT/1041496-001	SMRT TAXIS PTE LTD	SHC 4096L	SLM 2499X	13/03/2019	17:30	\$ 3,278.20

[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.

Date of Accident

16/03/2019 12:59

Vehicle No.(For Motor)

SGM6606L

Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5104270550		WONG KIA LING	S2504812A	GPC	drive CLASSIC	SGM6606L	SGM6606L	07/10/2018	06/10/2019

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	18/03/2019 14:43
Date Of Accident	18/03/2019 12:35
Exact Location Of Accident	TANGLIN ROAD (OUTSIDE TANGLIN MALL)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF52Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

### Driver

Name of Driver	POH KOK BENG
NRIC No	S0463567A
Date Of Birth	15/10/1944
Occupation	OUTDOOR
Date Of Driving Pass	12/11/1969
Driving Experience	49 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address: 11  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - HIRER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident SIDE SWIPE  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident


I WAS TRAVELLING ALONG TANGLIN ROAD (OUTSIDE TANGLIN MALL) TOWARDS ORCHARD ROAD. WHILE TRAVELLING STRAIGHT, I FELT AN IMPACT AT THE RIGHT PORTION OF MY TAXI. A VEHICLE SHB8950A FROM MY RIGHT HAD COLLIDED ONTO THE RIGHT PORTION OF MY TAXI.

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHB8950A  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category TAXI  
 Name of Driver LIM YAM KIAN SIMON  
 NRIC/Passport Number S1336719A  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

I/We declare the foregoing particulars are true in every respect.



Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*Ph* 18/3/19

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

*[Signature]* 18/3/2019

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	5369K

### Vehicle Details

Vehicle No.:	SHF52Z
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS101018
Chassis No.:	JTDKB3FU403573478
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	01 Nov 2017
First Registration Date:	01 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Oct 2025
PARF Rebate Amount:	\$3,750.00

### Intended COE Rebate Details

COE Expiry Date:	31 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$33,596.00
COE Rebate Amount:	\$27,748.00
Total Rebate Amount:	\$31,498.00

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Mar 2019

OK





## Case Details

Case Reference Number :

TAX/03/19/2083

Type of Repair : Accident Repair

Vehicle Registration Number : SHF52Z

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-6143-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 18/03/2019 04:35 AM

Vehicle Age(In Months) : 16

## Documents / Photographs

View Documents / Photographs

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

SMRT Recommendation												Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR, RH	1	1,243.90	1,243.90	25.00	932.93	Replace	1	0	Repair		
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	nec	
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL , RH	1	576.00	576.00	25.00	432.00	Replace	1	0	Repair		
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	25.00	618.60	Replace	1	618.60	Replace	Buc	
One Time Key In	Main			FILLER, RR BUMPER , RH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Give	un	
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	0	Repair		
One Time Key In	Main			CAP SUB-ASSY, WHEEL	1	175.80	175.80	25.00	131.85	Replace	1	131.85	Replace	scr	
One Time Key In	Main			WHEEL, DISC	1	1,555.10	1,555.10	25.00	1,166.32	Replace	0	0	Not Give	un	
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	un	
Total Spare Part Cost									3,936.29	Surveyor Total					870.45
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)					0
Final Spare Part Cost									3,936.29	Final Sur Total					870.45

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	845.00	800	
Total:			845.00	800.00	

Spray Cost Detail



S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR DOOR RH	378.00	200	
2	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	100	
3	Main	TO RESPRAY REAR FENDER RH	378.00	200	
4	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	0	
5	Main	TO RESPRAY REAR BUMPER	378.00	200	
6	Main	TO RESPRAY RIM	180.00	0	
Total:			1,674.00	700.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
3	Main	TO TRANSFER DOOR MECHANISM	120.00	0	
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
5	Main	TO REMOVE AND REFIT TYRE	120.00	0	
6	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30	
7	Main	TO WASH AND VACUUM	60.00	0	
8	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			820.00	70.00	

## Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,936.29	870.45

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Labour Cost	845.00	800.00
Total Spray Painting	1,674.00	700.00
Other	820.00	70.00
Overall Total	7,275.29	2,440.45
Lump Sum Repair Option		
Lump Sum Total	0.00	2,440.45
Surveyor Approved Amount		2,440.45
No of Repair Days*	5	4
Remarks		P/P REPAIR, PHOTO BEFORE PAINT.
Surveyor Name		Hwee Jie
Signature		 25/3/19.
Survey Date	19/03/2019	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer



Signature:

Date:

Shan Chen

Section A - Accident Details

Registration Number	SHF52Z
Case Reference Number	TAX/03/19/2083
Registration Date	1/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	POH KOCK BENG
Type of Accident	Head To Side
Accident Date and Time	18/3/2019 12:35 PM
Accident Reported Date and Time	18/3/2019 2:54 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100648
Special Instruction to ARC, if any	BP / NTUC - LKK
Prepared Date and Time	19/3/2019 11:40 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Right Side

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$800.00
Total Spray Cost	\$1,674.00	\$700.00
Total Spare Part Cost	\$3,936.29	\$870.45
Total Other Cost	\$820.00	\$70.00
<b>TOTAL COST</b>	<b>\$7,275.29</b>	<b>\$2,440.45 (P/P)</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Zhi Yang Phua	Hwee Jie (LKK) / NTUC
ARC / Surveyor Sign Off Date	19/03/2019 11:57 AM	19/03/2019 1:19 PM
Signature		
Remarks		P/P REPAIR, PHOTO BEFORE PAINT.

## Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1904-0008	Invoice Number	
Quotation Date	02.04.2019	Invoice Date	
Invoice Amount		Prepared Date	

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$845.00	\$800.00
Total Labour	\$845.00	\$800.00

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR DOOR RH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,674.00	\$700.00

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$820.00	\$70.00

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		6700347210	PANEL SUB-ASSY, REAR DOOR, RH	1.00	\$1,243.90	100.00	\$0.00	Replace	Repair
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		7585047910	MOULDING ASSY, BODY ROCKER PANEL, RH	1.00	\$576.00	100.00	\$0.00	Replace	Repair
		6160147150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$824.80	25.00	\$618.60	Replace	Replace
		5256547900	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given
		5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	100.00	\$0.00	Replace	Repair
		4260247180	CAP SUB-ASSY, WHEEL	1.00	\$175.80	25.00	\$131.85	Replace	Replace
		4261147450	WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given

			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given
Total					\$5,106.14		\$870.45		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

8505.14

870.45  
+ 800.00  
+ 770.00

---

2440.45



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19005175/Jqd3s2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 26-04-2019



Code: INC4

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 8950A	Veh. Inspected	SHF 52Z
Policy No.	5104270550	Coverage (\$)	0.00
Claim No.	MT/1036367-002	Excess (\$)	0.00
Assign From		Assign Date	19/03/2019

## 2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU403573478	Colour	MAROON
Odometer	141725	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	WEST LAKE	6 mm
L/H Front Tyre	195/65R15	WEST LAKE	6 mm
R/H Rear Tyre	195/65R15	WEST LAKE	6 mm
L/H Rear Tyre	195/65R15	WEST LAKE	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	18/03/2019	Inspection Date	19/03/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 52Z**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	PANEL SUB-ASSY, FENDER REAR RH (DISC 25%)	BUCKLED	824.80	618.60
1	CAP SUB-ASSY, WHEEL (DISC 25%)	SCRATCHED	175.80	131.85
2	PIXEL STICKER @ \$60.00 (SN)	NECESSARY	120.00	120.00
1	FILLER, RR BUMPER, RH	NOT NECESSARY	119.90	-
1	WHEEL, DISC	NOT NECESSARY	1,555.10	-
1	TYRE	NOT NECESSARY	126.74	-
1	PANEL SUB-ASSY, REAR DOOR, RH	TO REPAIR SEE LABOUR	1,243.90	-
1	MOULDING ASSY, BODY ROCKER PANEL, RH	TO REPAIR SEE LABOUR	576.00	-
1	COVER, RR BUMPER ASSY	TO REPAIR SEE LABOUR	423.90	-
			5,166.14	870.45
<b>LABOUR</b>				
	PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY, REAR DOOR, RH; MOULDING ASSY, BODY ROCKER PANEL, RH AND COVER, RR BUMPER ASSY.		845.00	800.00
	SPRAY PAINT.		1,674.00	700.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	20.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO TRANSFER DOOR MECHANISM.	NOT NECESSARY	120.00	-
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT TYRE.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)		120.00	30.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
			3,339.00	1,570.00
<b>GRAND TOTAL</b>			<b>8,505.14</b>	<b>2,440.45</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>2,440.45</b>

Report Ref No. NS/INC19005175/Jqd3s2



Report Ref No. NS/INC19005175/Jqd3s2

ONG HWEE JIE

Automotive Assessor

A handwritten signature in black ink, appearing to be "K.K. LAU".

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.