

18/02/19

INS. CASE OWNER:

CC 6/AIG1900

5177, A 10/15/19

LKK:

IDAC:

Surveyor:

Adnan

DOI:

ASSIGNMENT

11/11/19

Date / Time:

11/11/19

Registered in Merimen:

11/11/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKX 5197B

Name of Insured:

UM DEAN KHONG

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

10/11/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO. Driver Name / Age:

UM YAP RENH

Driver Tel No.:

(VL: YES / NO)

Claim No.:

2566475510505

Policy No.:

200442587

Make / Model:

MAZDA

Place of Accident:

HIGHTWAY 57 22

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLP 1A07B



INSRS:

WSP:

Tel:

Liability:

RMKS:

mg solution



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SLP 1A07B - P

SKX 5197B

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

9/11/19 - khongchng

10/7/19 - FILE PASS TO LSP TO UPS

Spoken to OIO, OI is his father OIO confirmed injury. OIO rear ended TP. Informed OIO on TP claim, agreed to settle and aware of NCO will be affected.

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: SS (days) Reduction: % Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: 8/7/19 Confirm with: Su Wany Email ☒ Call ☐

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27

Repair Cost: (w/ GST) SS 5885.00

Loss of Rental (LOR): SS (days)

Loss of Use (LOU): SS 560.00 (\$ 80 x 7 days)

Loss of Income (LOI): SS (\$ x days)

LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LO ☐ [Tick only one]

GIA/LTA Search SS 7.45

Medical: SS

Disbursement: SS (e.g. Tow/ Independent)

Legal Cost SS

Total: SS 6452.45 Global Sum SS: 6450.00

FINAL PAYMENT Date/Time: Confirm with: Email ☐ Call ☐

Payee 1: SS 6450.00 Name 1: mg solution pte ltd

Payee 2: (Strike if N.A.) SS Name 2:

Payee 3: (Strike if N.A.) SS Name 3:

COPY SENT 11/7/19

1) Claim status: Normal/Reject/Private Settle
2) Report Format: TP
3) Survey fee: \$320

11/7/19

ASS. REQ. BY:

REP:


Adrian

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLP1907B Yr Regn: 2017, May
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Elantra c.c. 1591
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 77116 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KMH7D841CMJ4964491

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/45R17R: 215/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm
D.O.A. _____	D.O.I. <u>21/03/19</u>

Survey held at MG SolutionDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP ATG.LS - \$5500 (Red \$9796.40 / 64%)mv:PV:Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: AIG	DATE	: 20/03/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLP1907B	Vic	
MODEL	: HYUNDAI ELANTRA 1.6 AT ABS D/AB 2WD 4DR		
CHASSIS NO		KMH084KMJ4464491	
<u>ACCIDENT DETAILS</u>		DATE	: 20-Mar-19
		TIME	: 07:35HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	BOOTLID <i>Dented</i>	1	\$ 1,788.20	\$ 1,788.20	-1602
2	BOOTLID LOGO <i>new</i>	1	\$ 58.60	\$ 58.60	-
3	BOOTLID EMBLEM 'ELANTRA' <i>new</i>	1	\$ 86.90	\$ 86.90	-
4	BOOTLID EMBLEM 'S' <i>new</i>	1	\$ 86.90	\$ 86.90	x
5	BOOTLID HINGE <i>new</i>	2	\$ 120.80	\$ 241.60	+
6	BOOTLID TOP LOCK <i>Dented</i>	1	\$ 211.00	\$ 211.00	✓
7	BOOTLID LOWER CATCH <i>new</i>	1	\$ 56.80	\$ 56.80	+
8	BOOTLID REFLECTOR <i>crushed</i>	2	\$ 340.00	\$ 680.00	-35870
9	BOOTLID WEATHER STRIP <i>new</i>	1	\$ 180.00	\$ 180.00	✓
10	REAR BUMPER <i>Dented</i>	1	\$ 680.00	\$ 680.00	-
11	REAR BUMPER LOWER LID <i>Dented</i>	1	\$ 480.00	\$ 480.00	-27260
12	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 78.00	\$ 156.00	-
13	REAR BUMPER REFLECTOR <i>LH crushed</i>	2	\$ 103.00	\$ 206.00	-102
14	REAR BUMPER REINFORCEMENT <i>Bent</i>	1	\$ 410.00	\$ 410.00	-328
15	REAR BUMPER REINFORCEMENT BRACKET <i>new Bent</i>	2	\$ 82.10	\$ 164.20	✓
16	REAR BUMPER SENSOR LOCK <i>Dented</i>	1	\$ 180.00	\$ 180.00	✓
17	REAR BUMPER SENSOR LOCK WIRE HARNESS <i>new</i>	1	\$ 233.00	\$ 233.00	+
18	TAILLAMP <i>new</i>	2	\$ 420.00	\$ 840.00	-769

19	TAILLAMP PANEL <i>Repr</i>	2	\$ 190.00	\$ 380.00	+
20	REAR FENDER <i>new</i>	2	\$ 1,530.50	\$ 3,061.00	+
21	REAR FENDER INNER TRIM <i>new</i>	2	\$ 230.00	\$ 460.00	+
22	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 190.00	\$ 190.00	+
23	REAR END PANEL <i>Dented</i>	1	\$ 499.30	\$ 499.30	✓
24	REAR END PANEL TOP GARNISH <i>Rehd.</i>	1	\$ 150.00	\$ 150.00	+
25	SPARE TYRE SPONGE <i>new</i>	1	\$ 216.00	\$ 216.00	+
26	REAR FLOOR PANEL <i>new</i>	1	\$ 910.00	\$ 910.00	+
27	REAR FLOOR PANEL TOP BOARD <i>Rehd</i>	1	\$ 260.00	\$ 260.00	✓

610930

TOTAL PRICE \$ 12,865.50

4887.44

LESS 20% \$ 2,573.10

SUB TOTAL PRICE \$ 10,292.40

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	f
2	REAR BUMPER CLIP(SET) <i>m</i>	1	\$ 20.00	\$ 20.00	✓
3	TAIL LAMP CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	-
4	TAIL LAMP PANEL SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
5	REAR FENDER INNER TRIM CLIPS(SET) <i>new</i>	1	\$ 22.00	\$ 22.00	x
6	REAR WINDSCREEN SEALANT <i>3 new</i>	1	\$ 120.00	\$ 120.00	+
7	REAR WINDSCREEN INNER SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	+
8	REAR END PANEL TOP GARNISH CLIPS(SET) <i>new</i>	1	\$ 22.00	\$ 22.00	10.
9	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	x
10	REVERSE SENSOR <i>Dangd</i>	1	\$ 220.00	\$ 220.00	200

250

TOTAL \$ 854.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL & REPLACING PANEL	\$ 1,800.00	800	
2	TO SPRAY PAINT AFFECTED AREAS	\$ 1,600.00	800	
3	TO APPLY RUST PROOFING & TUFF COAT	\$ 350.00	60	
4	WIRING CHECK	\$ 60.00	30	
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 100.00	50	
6	TRANSFER BOOTLID MECHANISM	\$ 80.00	60	

7	TO REMOVE AND REFIX REAR WINDSCREEN	\$ 160.00	X	
---	-------------------------------------	-----------	---	--

TOTAL \$ 4,150.00

1800

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,146.40

TOTAL LABOUR COST : \$ 4,150.00

TOTAL REPAIR COST : \$ 15,296.40

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian Ling
w/s 21/03/19
06 Days
Total: 6937.44
L/S: 5.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/alter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4, AAS Kaki Bukit Centre #02-03 Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

(GST Reg. No. 201427944N)

Date : 26/04/2019

Your Ref : SKX5197B

To : AIG ASIA PACIFIC INSURANCE PTE LTD

Attn : Motor Claims Department

Dear Sir/Mdm,

**RE: ACCIDENT INVOLVING VEHICLE SLP1907B & SKX5197B ON 20/03/2019 AT
SLIP ROAD FROM BISHAN ROAD TURNING LEFT INTO BISHAN STREET 22.**

We refer to the above matter.

Attached copies of the following for your kind perusal:

- 1) Proforma Bill No.198132 @ S\$5,885.00 (Inclusive Of 7% GST)
- 2) Loss of Use @ S\$1,400.00 (7 Days x S\$200)
- 3) LTA Search @ S\$7.45
- 4) Authorisation to Act
- 5) GIA Report

Hope the above is in order and kindly let us have your confirmation soon.

Tax invoice will be issue upon amount finalized.

Thank You.

Yours faithfully,



Sharon Chia

HP: 9188 6931

E-mail: mg3solution@gmail.com

Jia Le (LKK Auto)

From: MG Solution <mg3solution@gmail.com>
Sent: Friday, 5 July 2019 2:21 PM
To: Jia Le (LKK Auto)
Cc: Admin A; Vic (LKKAuto)
Subject: Re: 3rd Party Claim for Accident involving Vehicle SLP1907B & SKX5197B on 20/03/2019
Attachments: DV for SLP1907B.pdf

Your Ref: **SKX5197B**

Our Ref: **SLP1907B**

Dear Jia Le,

Please find attached **TAX INVOICE** for your kind onward action.

Best Regards,

Su Wong

MG SOLUTION PTE LTD

No 23 Kaki Bukit Avenue 4

AAS Kaki Bukit Centre

#02-03B Singapore 415933

Tel: 6243 1373 | Fax: 6243 1376

On Fri, Jul 5, 2019 at 1:57 PM Jia Le (LKK Auto) <JiaLe@lkkauto.com> wrote:
Without Prejudice

Dear Su,

Please duly sign the DV enclosed and return to us for our necessary action.

Thank you.

Best Regards,

Carlton Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: MG Solution [mailto:mg3solution@gmail.com]

Sent: Friday, 5 July 2019 1:12 PM

To: Jia Le (LKK Auto)

Cc: Admin A; Vic (LKKAuto)

Subject: Re: 3rd Party Claim for Accident involving Vehicle SLP1907B & SKX5197B on 20/03/2019

Your Ref: **SKX5197B**

Our Ref: **SLP1907B**

Dear Jia Le,

We refer to below, we are pleased to accept the offer and please find attached **TAX INVOICE** for your kind onward action.

Please look into the above claim and let us have your payment of **S\$6,450.00** soonest.

Provided always that this discharge of my claim for damages relating to the damage to my vehicle SLP1907B shall not prejudice or affect my further claim for general and special damages for my personal injuries sustained in the same accident on 20/03/2019.

Best Regards,

Su Wong

MG SOLUTION PTE LTD

No 23 Kaki Bukit Avenue 4

AAS Kaki Bukit Centre

#02-03B Singapore 415933

Tel: 6243 1373 | Fax: 6243 1376

On Fri, Jul 5, 2019 at 12:12 PM Jia Le (LKK Auto) <JiaLe@lkkauto.com> wrote:

WITHOUT PREJUDICE

Dear Sirs/Mdm,

ACCIDENT INVOLVING SKX 5197B & SLP 1907B ON 20/03/2019

We refer to the above matter.

We propose settlement at a global sum of **\$6,450.00(all-in)**.

Please confirm acceptance.

“Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.”

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: MG Solution [mailto:mg3solution@gmail.com]

Sent: Thursday, 13 June 2019 2:41 PM

To: Admin A; Jia Le (LKK Auto)

Cc: Vic (LKKAUTO)

Subject: Re: 3rd Party Claim for Accident involving Vehicle SLP1907B & SKX5197B on 20/03/2019

Your Ref: **SKX5197B**

Our Ref: **SLP1907B**

Dear Jia Le,

Please refer to below mentioned email, as we have sent out our LOD previously to your side on 26/04/2019.

We have not receive any offer from your side.

Resend LOD for your reference and hope to receive an offer from your side soon.

Best Regards,

Su Wong

MG SOLUTION PTE LTD

No 23 Kaki Bukit Avenue 4

AAS Kaki Bukit Centre

#02-03B Singapore 415933

Tel: 6243 1373 | Fax: 6243 1376

On Fri, Apr 26, 2019 at 1:45 PM MG Solution <mg3solution@gmail.com> wrote:

Your Ref: **SKX5197B**

Our Ref: **SLP1907B**

Dear Vic,

Please find attached our LOD for your onward action.

Please feel free to contact the under mentioned should you require any further information.

Your prompt action will be greatly appreciated.

Best Regards,

Su Wong

MG SOLUTION PTE LTD

No 23 Kaki Bukit Avenue 4

AAS Kaki Bukit Centre

#02-03B Singapore 415933

Tel: 6243 1373 | Fax: 6243 1376



Provided always that the discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect my further claim for general and special damages for my personal injuries sustained in the same accident.

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, HITACHI CAPITAL ASIA PACIFIC Pte Ltd ("the third party claimant")
of 111 Somerset Road #14-05-15 TripleOne Somerset S(238164) (address),
owner of SLP1907B (vehicle no.) hereby authorize
MG SOLUTION PTE LTD
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SLP1907B that was
damaged pursuant to the accident which occurred on 20/03/19 (date) along
Slip Road from Bishan Road turning Left into Bishan Street 22 (location)
involving vehicle no/s SKX 5197B ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 21 day of 03 (month) 20 19 (year)

HITACHI CAPITAL ASIA PACIFIC PTE. LTD.

KELVIN CHANG (MR)
Manager
Vehicle Solutions
Total Vehicle Solutions Department

Signed by "the third party claimant"



Signed by "the workshop"

MG SOLUTION PTE LTD
23 Kaki Bukit Ave 4 (South Wing) #02-03B
Vicom Inspection Centre, Singapore 415933
Tel: 6243 1373 Fax: 6243 1376
GST Reg. No. : 201427944N

MOTOR CLAIM DISCHARGE

INSURED: HITACHI CAPITAL ASIA PACIFIC PTE LTD
CAR/ LORRY/CYCLE: REG NO: SLP1907B POLICY NO: -
ACCIDENT CLAIM NO: -

I / We confirm that I / we have taken delivery of Car / Lorry / Motor Cycle
Registered No. SLP1907B from the repairers,
Messrs MG SOLUTION PTE LTD

And that all repairs necessary as a result of an accident in which the said vehicle was Involved on or
about the 20 day of 03 2019 have been completed to my / our satisfaction, and that
I / we have no further claim on the above company in Respect thereof.

HITACHI CAPITAL ASIA PACIFIC PTE. LTD.

KELVIN CHANG (MR)
Manager
Vehicle Solutions

Date: 21/03/2019 Signed Kelvin Chang Vehicle Solutions Department

Co's Stamp: 21/03/2019 - PR1 NRIC No: 24/03/2019 - Sunday

Vehicle In - 21/03/2019
Vehicle Out - 27/03/2019
Loan - 7 days x \$200
= \$1,400

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Mar 2019 Edit Reg		21 Mar 2019 00:00 Edit Adj Rpt	S\$5,500.00 Edit Estimates	S\$5,500.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Lim Dean Cheong, ID: S0081566G		
Main Claimant:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N		
Vehicle Reg. No.:	SLP1907B	Date of Loss:	20/03/2019 08:00 - :59 [21 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 2566475510SG	Policy/Cover Note No.:	2100442581 (Comprehensive) Coverage: 16/12/2018 - 15/12/2019
Vehicle Reg. No. (Insured):	SKX5197B	Policy No. (Claimant):	VPX/P1943020
		Excess:	
Repairer:	MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre, 415933 Kaki Bukit - Tel: 91886931		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 02/04/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MG Solution Pte Ltd

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
29	10/04/19 00:03	General View	 Load JPG	✓
30	10/04/19 00:03	General View	 Load JPG	✓
31	10/04/19 00:03	General View	 Load JPG	✓
32	10/04/19 00:03	General View	 Load JPG	✓
33	10/04/19 00:03	General View	 Load JPG	✓
34	10/04/19 00:03	General View	 Load JPG	✓
35	10/04/19 00:03	General View	 Load JPG	✓
36	10/04/19 00:03	General View	 Load JPG	✓
37	10/04/19 00:03	General View	 Load JPG	✓
38	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
39	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
40	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
41	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
42	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
43	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
44	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
45	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
46	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
47	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
48	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
49	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
50	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
51	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
52	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
53	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
54	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
55	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
56	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
57	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
58	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
59	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
60	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
61	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
62	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
63	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
64	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
65	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
66	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
67	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
68	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
69	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
70	10/04/19 00:04	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/03/19 09:53	TP GIA REPORT	 Load PDF	
2	09/04/19 16:05	Letter to OI	 Load PDF	
3	29/07/19 14:25	AUTHORISATION TO ACT	 Load PDF	
4	29/07/19 14:25	LTA SEARCH	 Load PDF	

Letters/Correspondences

1 per page ▼



No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
5	29/07/19 14:25	RELEASE VOUCHER		Load PDF	
6	29/07/19 14:25	WORKSHOP INVOICE		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKX5197B (Insd veh)	Model:	HYUNDAI ELANTRA 1.6 AD GLS
	SLP1907B (TP veh)		(A)
Date of Accident:	20/03/2019		

Global Sum Settlement	:	☒ [X] Yes	☐ [] No	
Repair Estimate	:	\$		16,367.15
Final Repair Cost	:	\$		6,450.00
Loss of Use	:	\$		7.00 days at \$80.00 per day
Rental (if any)	:	\$		days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (GLOBAL SUM)	:	\$		6,450.00

Is Third Party Workshop GIA Registered?		☐ [] YES	☒ [X] NO	(Kindly indicate below)
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability ____ 100 ____ (%)		
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: ____		
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown				
1)	MG Solution Pte Ltd	:	\$	6,450.00
2)		:	\$	
3)		:	\$	
4)		:	\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

29 Jul
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19005177/ADB3S2

Date: 29/07/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100442581
Claimant Vehicle No :	SLP1907B	Insured Vehicle No :	SKX5197B
Date of Loss:	20/03/2019	Nature of Claim:	TP
		Claim No:	2566475510SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP1907B		
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)		
Reg. Date:	29/05/2017 (Man. Year: 2017)	Engine No:	G4FGHU121309
Colour:	Grey	Chassis No:	KMHD841CMJU464491
Engine Capacity:	1591 cc	Odometer:	77116 km
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45R17	Rear Tyre Size:	215/45R17
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,146.40	5,137.44	6,008.96	53.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,150.00	1,800.00	2,350.00	56.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,296.40	6,937.44	8,358.96	54.65
Approved Total (Overridden) (S\$)		5,500.00		
(S\$)	15,296.40	5,500.00	9,796.40	64.04
+ GST 7.00/7.00% (S\$)	1,070.75	385.00	685.75	64.04
Nett Amount (S\$)	16,367.15	5,885.00	10,482.15	64.04
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,452.45		
Global Sum Settlement (S\$)		6,450.00		

INSPECTION

Date of Assignment: 21/03/2019

Date Inspected: 21/03/2019 Inspected At:

MG Solution Pte Ltd (HQ)
23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection
Centre
Singapore 415933

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	1,788.20 FL	*1,602.00 FL
2	1		*BOOTLID LOGO	Necessary	58.60 FL	*58.60 FL
3	1		*BOOTLID EMBLEM ELANTRA	Necessary	86.90 FL	*86.90 FL
4	1		*BOOTLID EMBLEM S	Not Necessary	86.90 FL	*- FL
5	2		*BOOTLID HINGE	Not Necessary	241.60 FL	*- FL
6	1		*BOOTLID TOP LOCK	Damaged	211.00 FL	*211.00 FL
7	1		*BOOTLID LOWER CATCH	Not Necessary	56.80 FL	*- FL
8	2		*BOOTLID REFLECTOR	Cracked	680.00 FL	*558.70 FL
9	1		*BOOTLID WEATHER STRIP	Cut	180.00 FL	*180.00 FL
10	1		*REAR BUMPER	Deformed	680.00 FL	*680.00 FL
11	1		*REAR BUMPER LOWER LID	Deformed	480.00 FL	*272.60 FL
12	2		*REAR BUMPER SIDE RETAINER	Necessary	156.00 FL	*156.00 FL
13	1		*REAR BUMPER REFLECTOR	N/s Cracked	206.00 FL	*103.00 FL
14	1		*REAR BUMPER REINFORCEMENT	Bent	410.00 FL	*328.00 FL
15	2		*REAR BUMPER REINFORCEMENT BRACKET	Bent	164.20 FL	*164.20 FL
16	1		*REAR BUMPER SENSOR LOCK	Damaged	180.00 FL	*180.00 FL
17	1		*REAR BUMPER SENSOR LOCK WIRE HARNESS	Not Necessary	233.00 FL	*- FL
18	2		*TAILLAMP	Cut	840.00 FL	*769.00 FL
19	2		*TAILLAMP PANEL	Repair	380.00 FL	*- FL
20	2		*REAR FENDER	Not Necessary	3,061.00 FL	*- FL
21	2		*REAR FENDER INNER TRIM	Not Necessary	460.00 FL	*- FL
22	1		*REAR WINDSCREEN MOULDING	Not Necessary	190.00 FL	*- FL
23	1		*REAR END PANEL	Dented	499.30 FL	*499.30 FL
24	1		*REAR END PANEL TOP GARNISH	Deformed	150.00 FL	*- FL
25	1		*SPARE TYRE SPONGE	Not Necessary	216.00 FL	*- FL
26	1		*REAR FLOOR PANEL	Not Necessary	910.00 FL	*- FL
27	1		*REAR FLOOR PANEL TOP BOARD	Deformed	260.00 FL	*260.00 FL
28	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
29	1		*SET REAR BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
30	1		*SET TAIL LAMP CLIP	Necessary	20.00 FS	*20.00 FS
31	1		*TAIL LAMP PANEL SEALANT	Not Necessary	80.00 FS	*- FS
32	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	22.00 FS	*- FS
33	1		*REAR WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
34	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	150.00 FS	*- FS
35	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	22.00 FS	*10.00 FS
36	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
37	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,719.50	6,359.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,573.10	1,221.86
Total Parts (\$\$)	11,146.40	5,137.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL & REPLACING PANEL.	New	1,800.00	800.00
2	TO SPRAY PAINT AFFECTED AREAS.	New	1,600.00	800.00
3	TO APPLY RUST PROOFING & TUFF COAT.	New	350.00	60.00
4	WIRING CHECK.	New	60.00	30.00
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.	New	100.00	50.00
6	TRANSFER BOOTLID MECHANISM.	New	80.00	60.00
7	TO REMOVE AND REFIX REAR WINDSCREEN.	New	160.00	0.00
Gross Labour Cost (S\$)			4,150.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >