



Steve (LKK)
8322 8813

Wn Mr. d 26/3/19
5 days 2.30pm
L/S
Ry AL say

VAG Singapore Pte Ltd
48 Toh Guan Road East
#05-123, Enterprise Hub
Singapore 608586

Repair Estimate

Tel: 6267 9916
Fax: 6267 9313
www.avantage.sg

Date : 22-Mar-2019

Vehicle Num : SJY8039L

Make/Model : VW GOLF GTI

Chassis No : WVWZZZ1KZAW421960

S/N	PARTS	QTY	PRICE	TOTAL
1	LH DOOR / DD	1	\$ 1,900.00	\$ 1,900.00
2	DOOR SEAL OUTER	1	\$ 105.00	\$ 105.00
3	LH DOOR HIGNE UPPER ?	1	\$ 100.00	\$ 100.00
4	LH DOOR HINGE LOWER ?	1	\$ 190.00	\$ 190.00
5	FRONT BUMPER X NN	1	\$ 1,000.00	\$ 1,000.00
6	LH FENDER / DD	1	\$ 380.00	\$ 380.00
7	FENDER GUIDE PIECE X ? NN	1	\$ 40.00	\$ 40.00
8	LH SIDESKIRT / RR	1	\$ 480.00	\$ 480.00
9	LH SIDESKIRT ADAPTOR / NEC	4	\$ 35.00	\$ 140.00
10	FRONT LH PANEL / DD	1	\$ 1,900.00	\$ 1,900.00
11	REAR LH QUARTER PANEL X R	1	\$ 1,500.00	\$ 1,500.00
12	REAR LH SIDE SKIRT PANEL / RR DD	1	\$ 780.00	\$ 780.00
13	FRONT LH RIM X / CHT	1	\$ 1,500.00	\$ 1,500.00
14	RIM CAP X NN	1	\$ 30.00	\$ 30.00
15	DOOR SEAL INNER ?	1	\$ 250.00	\$ 250.00
16	LH UNDERCARRIAGE LINING X NN	1	\$ 160.00	\$ 160.00
TOTAL PARTS				\$ 10,455.00
TOTAL AMOUNT				\$ 10,455.00
MISCELLANEOUS ITEM				
LABOUR				
1	To remove/refit/ panel beat of front bumper, LH fender, LH sideskirt, LH rear quarter panel, LH door.		\$ 1000 1200	\$ 1,700.00
2	To putty and spray paint of front bumper, LH fender, LH sideskirt, LH rear quarter panel, LH door and other affected area		\$ 1000	\$ 1,300.00
3	To diagnose and clearing of fault codes before and after repair		\$ 30	\$ 60.00
4	To conduct wheel alignment the following:		\$ 60	\$ 70.00
5	To remove and refit tyre.		\$ X	\$ 60.00
TOTAL				\$ 13,645.00
Acknowledged by Repairer				\$ 955.15
Signature:				GST 7%
Date:				GRAND TOTAL
				\$ 14,600.15