

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Stevi (LKK)
8322 8813WZ Prejudice 2/4/19 10.30 am
PIP
Ry bef spy
3 days**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SMG3659P

Chassis No : JHMRC1890JC206403

Model : ODYSSEY 2.4 EXV-S 18YM (EURO 6)

Owner's Name : HYPAC PACKAGING PTE LTD

Ins Policy No. :

Date of Accident : 20/3/2019

Document No. : SQT19001360

Date : 26. Mar 2019

Customer No. : WZA006

Svc Advisor : JACK NG

Engine No : K24W72402535

Date | Time : 26. Mar 2019 9:13:27 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:HYPAC PACKAGING PTE LTD OWNER INSURER:AVIVA LTD ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER:AXA INSURANCE TP VEH:SGC 2209 D						
04711-T6A-N13ZZ	FACE ASSY,FR.BUMPER x R	1	686.20	25	514.65	36.03	550.68
71151-T6A-N41	BASE,MID GRILLE P x	1	222.90	25	167.17	11.70	178.87
71152-T6A-N01	MOLDING,R.FR.MID GRILLE BPR x	1	60.80	25	45.60	3.19	48.79
71153-T6A-N01	MOLDING A,FR.MID GRILLE BPR x	1	178.40	25	133.80	9.37	143.17
71154-T6A-N01	MOLDING B,FR.MID GRILLE BPR x	1	162.20	25	121.65	8.52	130.17
71155-T6A-N01	MOLDING C,FR.MID GRILLE BPR x	1	60.80	25	45.60	3.19	48.79
71158-T6A-N01	MOLDING D,FR MID GRILLE BPR x	1	152.00	25	114.00	7.98	121.98
71159-T6A-N01	MOLDING C,L.FR.MID GR BPR x	1	60.80	25	45.60	3.19	48.79
71193-T6A-N01	SPACER,R.FR.BPR SLLE x	1	11.80	25	8.85	0.62	9.47
71198-T6A-N01	SPACER L,FR BPR SLLE x	1	11.80	25	8.85	0.62	9.47
91505-TM8-003	CLIP,BUMPER x	16	2.30	25	27.60	1.93	29.53
71112-T6A-901ZA	SPOILER ASSY,R.FR. x	1	79.00	25	59.25	4.15	63.40
71117-T6A-901ZA	SPOILER ASSY,L.FR. x	1	79.00	25	59.25	4.15	63.40
Sum Item					1351.87	94.64	1,446.51
BOSUN	SUNDRIES	1	100.00	20	100.00	7.00	107.00
BML011	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	380.00	280	380.00	26.60	406.60
BOMISC1	REMOVE & RE-INSTALL FRONT VIEW CAMARA (N)	1	450.00	/	450.00	31.50	481.50
BKBU01R	REMOVE & RENEW FR BUMPER.RENEW ALLA DAMAGE PARTS	1	2500.00	560	2500.00	175.00	2675.00

Printed on 26/3/2019 9:21:36 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SMG3659P
Chassis No : JHMRC1890JC206403
Model : ODYSSEY 2.4 EXV-S 18YM (EURO 6)
Owner's Name : HYPAC PACKAGING PTE LTD
Ins Policy No. :
Date of Accident : 20/3/2019

Document No. : SQT19001360
Date : 26. Mar 2019
Customer No. : WZA006
Svc Advisor : JACK NG
Engine No : K24W72402535
Date | Time : 26. Mar 2019 9:13:27 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	1500.00	450	1500.00	105.00	1605.00
Sum Labor					4930.00	345.10	5,275.10

Survey By

Date & Time

Excess

Status

Signature

Total Amount 6,281.87 439.74 6,721.61

Total (Inclusive of GST) 6,721.61

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 26/3/2019 9:21:36 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.