

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05945

Vehicle Insured : SJC5581Y
Accident Date : 19-Mar-2019

Date : 21-Mar-2019

Our Ref : 219044 (AXA) / JANICE

PAGE : 1

CHEW SIONG NGO
BLK 110D PUNGGOL FIELD
#07-600
Singapore 824110

*Not Authorized
C/Rep &?
Resurvey After Paint
6 days*

ESTIMATED COST OF REPAIR FOR TOYOTA ALTIS SLH4541U

1 pc boot lid
1 pc boot lid inner lock
1 pc boot lid rubber
2 pcs boot lid hinge
1 pc boot lid chrome moulding
2 pcs boot lid reflector
1 pc boot lid logo emblem
1 pc "TOYOTA" emblem
1 pc "COROLLA" emblem
1 pc "ALTIS" emblem
2 pcs tail lamp
1 pc end panel
1 pc end panel inner garnish
1 pc rear bumper
2 pcs rear bumper bracket
2 pcs rear bumper reflector
1 pc rear bumper inner sponge
2 pcs rear bumper side retainer

	Bu	754.30	✓
	BU	96.50	✓
	Dis 100	175.40	50% in @ 87.20
@ S\$ 60.20	R	120.40	X
	Bu	332.90	✓
@ S\$167.20		334.40	?
	BU	52.60	✓
	BU	49.90	✓
	BU	42.30	✓
	BU	44.10	✓
o/s cm	@ S\$281.90	563.80	✓
	Bu	552.20	✓
	Dis	185.30	✓
	BT 1/CM	482.10	✓
@ S\$ 82.80		165.60	?
@ S\$ 37.20	BU	74.40	X
	CM	117.50	✓
@ S\$ 72.70	d/d Dis	145.40	✓
		4,289.10	
Less 25% :		1,072.28	

1 pc rear parking sensor (set)

3,216.82
Shan 200.00 sn ✓

To putty and spray replaced parts

1,000.00 Shan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SJC5581Y

Page : 2

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

700

800.00

Total : S\$ 5,216.82
=====

Singapore Dollars Five Thousand Two Hundred and
Sixteen and Cents Eighty Two Only