

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SJC5581Y  
Accident Date : 19-Mar-2019

Our Ref : 219044 (AXA) / JANICE

CHEW SIONG NGO  
BLK 110D PUNGGOL FIELD  
#07-600  
Singapore 824110

No. : 05945

Date : 21-Mar-2019

PAGE : 1

## ESTIMATED COST OF REPAIR FOR TOYOTA ALTIS SLH4541U

|                                 |             |          |
|---------------------------------|-------------|----------|
| 1 pc boot lid                   |             | 754.30   |
| 1 pc boot lid inner lock        |             | 96.50    |
| 1 pc boot lid rubber            |             | 175.40   |
| 2 pcs boot lid hinge            | @ S\$ 60.20 | 120.40   |
| 1 pc boot lid chrome moulding   |             | 332.90   |
| 2 pcs boot lid reflector        | @ S\$167.20 | 334.40   |
| 1 pc boot lid logo emblem       |             | 52.60    |
| 1 pc "TOYOTA" emblem            |             | 49.90    |
| 1 pc "COROLLA" emblem           |             | 42.30    |
| 1 pc "ALTIS" emblem             |             | 44.10    |
| 2 pcs tail lamp                 | @ S\$281.90 | 563.80   |
| 1 pc end panel                  |             | 552.20   |
| 1 pc end panel inner garnish    |             | 185.30   |
| 1 pc rear bumper                |             | 482.10   |
| 2 pcs rear bumper bracket       | @ S\$ 82.80 | 165.60   |
| 2 pcs rear bumper reflector     | @ S\$ 37.20 | 74.40    |
| 1 pc rear bumper inner sponge   |             | 117.50   |
| 2 pcs rear bumper side retainer | @ S\$ 72.70 | 145.40   |
|                                 |             | -----    |
|                                 |             | 4,289.10 |
|                                 | Less 25% :  | 1,072.28 |
|                                 |             | -----    |

3,216.82

200.00 sn

1 pc rear parking sensor (set)

1,000.00

To putty and spray replaced parts

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SJC5581Y

Page : 2

To remove, cut-out damaged parts,  
panel beating, welding, align,  
refix and to renew above parts

800.00

Total : S\$ 5,216.82  
=====

Singapore Dollars Five Thousand Two Hundred and  
Sixteen and Cents Eighty Two Only

