

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7615A**AAD1903-138***Not Notion**Putty B& paint**81993.73*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHB 7615A

JTDKB3FU603077100

TOYOTA

PRIUS

17.3.2019

AXA

4/12/2018

PART**LIST**

1	1 PANEL SUB-ASSY, REAR DOOR, LH	\$	<i>R</i> 1,258.30 ✓
2	1 PANEL, QUARTER WHEEL HOUSE, OUTER LH	\$	<i>n</i> 290.50 X
3	1 REAR FENDER LH	\$	<i>n</i> 817.50 X

	\$	2,366.30
25%	\$	591.58
	\$	1,774.73

Special Nett

1	1 REAR DOOR STICKER 'TRANS-CAB'	\$	<i>n</i> 80.00 <i>6000</i>
---	---------------------------------	----	----------------------------

TOTAL \$ 80.00**TOTAL PARTS \$ 1,854.73****LABOUR**Putty And Spray Painting Of The Affected Portion. \$ 3,000.00 *4400*Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same \$ 3,000.00 *4000*To Rust-Proofing Of The Affected Areas. \$ 170.00 *300*

Trans-cab Auto Services Pte Ltd**AAD1903-138**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7615A

To transfer of Rear Door fittings, attachments and
perform water seepage test. \$ 170.00 *602*

To transfer of Rear Bumper fittings, attachments and
perform water seepage test. \$ *nn* 170.00 *X*

To transfer of Rear Fender fittings, attachments and
perform water seepage test. \$ 170.00 *601*

To check steering geometry and computer wheel
alignment \$ *nn* 220.00 *X*

TOTAL \$ 6,900.00

Over All Total \$ 10,529.45

(PART-BY-PART) Repair Days**~~10~~ DAYS***3 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: