

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9731Z

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

AAD1903-136*Not Notified**1/1 Sing & 6850.00**Book Value?***SHD 9731Z**

VF1ABL15AUC276093

RENAULT

LATITUDE

15.3.2019

AXA

4/12/2013

1	1	BUMPER COVER FRT
2	1	BUMPER SPOILER FRT
3	1	BUMPER ABSORBER FRT
4	1	BUMPER RETAINER FRT LH
5	1	BUMPER SUPPORT FRT
6	1	BUMPER RETAINER FRT RH
7	1	BUMPER SUPPORT FRT
8	1	BUMPER UNDERTRAY FRT
9	1	BUMPER GRILLE LOWER FRT
10	1	BUMPER FOG LAMP GRILLE LH
11	1	BUMPER FOG LAMP GRILLE RH
12	1	BUMPER BEAM FRT
13	1	TOW COVER FRT
14	1	RADIATOR GRILLE
15	1	RADIATOR GRILLE BADGE 'RENAULT'
16	1	RADIATOR GRILLE FRAME
17	1	FRAME FULL SUPPORT PANEL
18	1	FRAME FULL SUPPORT BRACKET
19	1	HEADLAMP LH
20	1	HEADLAMP RH
21	1	HEADLAMP PANEL FRT LH
22	1	HEADLAMP PANEL FRT RH
23	1	BONNET
24	1	BONNET INSULATOR
25	1	BONNET STRUT LH
26	1	BONNET STRUT RH
27	1	BONNET HINGE LH
28	1	BONNET HINGE RH

LIST

\$	<i>Bu</i>	1,259.42	✓
\$	<i>Div</i>	181.75	✓
\$		394.68	X NN
\$	<i>Div</i>	151.41	✓
\$	<i>Sn</i>	123.88	X
\$	<i>Div</i>	150.77	✓
\$	<i>Sn</i>	123.88	X
\$	<i>Sn</i>	472.83	X
\$	<i>CM</i>	266.80	✓
\$	<i>Sn</i>	207.21	X
\$	<i>Sn</i>	207.21	X
\$		914.08	X NN
\$	<i>Sn</i>	28.61	X
\$	<i>mgm</i>	1,707.78	✓
\$	<i>na</i>	225.36	✓
\$		1,353.75	X NN
\$	<i>CM</i>	615.90	✓
\$	<i>n</i>	89.79	X
\$	<i>mgm</i>	1,184.43	✓
\$	<i>mg CM</i>	1,184.43	✓
\$	<i>n</i>	152.15	X
\$	<i>n</i>	152.15	X
\$	<i>n</i>	1,941.63	X
\$	<i>Sn</i>	405.73	X
\$	<i>Sn</i>	88.61	X
\$	<i>Sn</i>	88.61	X
\$	<i>n</i>	348.31	X
\$	<i>n</i>	348.31	X

Trans-cab Auto Services Pte Ltd**AAD1903-136**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9731Z

29	1	BONNET CABLE COVER	\$	SL 161.03 X
30	1	BONNET SEAL OUTER	\$	SL 92.36 X
31	1	BONNET SEAL INNER	\$	SL 157.28 X
32	1	FENDER PANEL FRT RH	\$	Bu 783.83 ✓
33	1	WHEELARCH FRT RH	\$	SL 278.84
34	1	FENDER BRACKET LOWER RH	\$	SL 15.79
35	1	FENDER INSULATOR RH	\$	SL 130.84
36	1	DOOR PANEL FRT RH	\$	N 2,844.66
37	1	WIPER RESERVOIR	\$	SL 348.25
38	1	WIPER RESERVOIR NECK	\$	SL 136.11
39	1	WIPER RESERVOIR MOTOR	\$	SL 270.06
			TOTAL \$	19,588.52
			10% \$	1,958.85
			\$	17,629.67

Specical Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	na 52.00 ✓
2	1SET	BUMPER CLIP FRT	\$	na 66.00 ✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	na 12.00
4	1	BUMPER SUPPORT CLIP FRT LH	\$	na 10.50
5	1	BUMPER BRACKET CLIP FRT RH	\$	na 12.00
6	1	BUMPER SUPPORT CLIP FRT RH	\$	na 10.50
7	1	TOW COVER FRT	\$	SL 14.50
8	1SET	RADAIOR GRILLE SCREW	\$	na 16.00
9	1SET	BUMPER GRILLE LOWER CLIP	\$	na 69.00
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na 70.00
11	2	FRAME FULL SUPPORT PANEL NUT	\$	na 20.00
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na 30.00
21	1	Windscreen moulding	\$	na 100.00 ✓
22	1SET	Front licence plate with holder	\$	SL 80.00 X

TOTAL \$	562.50
TOTAL PARTS \$	18,192.17

Trans-cab Auto Services Pte Ltd**AAD1903-136**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9731Z

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	500
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00	X
Putty and spray painting of the affected portion.	\$	3,000.00	660
To rust-proofing of the affected areas.	\$	170.00	30
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	X NN
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	380.00	100
To replace, refix and top up coolant for radiator	\$	170.00	50
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	50

Trans-cab Auto Services Pte Ltd**AAD1903-136**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9731Z

To Transfer Of Fender Fittings, Attachments And
Perform Water Seepage Test.

\$ *nn* 170.00 X**TOTAL \$ 9,140.00****Over All Total \$ 27,332.17****(LUMP SUM) Repair Days ~~10 DAYS~~***7 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: