

HS170 Tony

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

22 MAR 2019

ESTIMATE

Page No. : 1 of 5

Estimate No. : b1 50559
Date Estimated : 21/03/2019
Prepared By : Gary Poh Chai Hoon

- ESTIMATE REPAIR FOR -
Shane Alexander Abucewicz Tan Yuan-
10E Bradell Hill
#04-17

singapore 579724

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLD6023G	VD45252	18/12/2018	M2 COUPE	0

DESCRIPTION

To replace rear bumper and lower trim and attachment
include knocking cause by the accident.

Painting rear bumper

To check electrical wiring systems and lightings at the
rear section for proper function.

Sundries.

VALUE
850 1,700.00

934 1,038.00

150 177.00

80 80.00

Total Labour 1: 2,995.00

DESCRIPTION

REAR BUMPER CARRIER ?
REAR BUMPER CENTRE GUIDE ?
REAR BUMPER LH SIDE GUIDE ?
REAR BUMPER RH SIDE GUIDE ?
Support, PDC ?
Support, PDC ?
REAR BUMPER TOWING EYE FLAP PRIMED X
REAR BUMPER TRIM PANEL (PDC) X
M PERFORMANCE REAR DIFFUSER X
DECOUPLING RING PDC TORQUE CONVERTE X
RR PDC SENSOR BLACK SAPPHIRE (475) ?

QTY	PRIC	VALUE
1	416.45	416.45
1	48.35	48.35
1	92.30	92.30
1	92.30	92.30
1	21.60	21.60
1	21.60	21.60
1	46.85	46.85
1	1,390.85	1,390.85
1	3,149.80	3,149.80
4	5.05	20.20
2	236.85	473.70

Total Parts : 5,774.00

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 50559		Page No. : 2 of 5
Date Estimated : 21/03/2019		
Prepared By : Gary Poh Chai Hoon		

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLD6023G	VD45252	18/12/2018	M2 COUPE	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Page No. _____ Claim No. _____

Date/Time 12/04/19 @ 1120 Excess \$S _____

Surveyor's Name RRM Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 3 days

Labour 1	:	2,995.00
Parts	:	5,774.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	613.83
Grand Total	:	9,382.83

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 50559
Date Estimated : 21/03/2019
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Shane Alexander Abucewicz Tan Yuan-Yu
10E Bradell Hill
#04-17

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

singapore 579724

REGN.NO.	CHASSIS NO.	REGN.DATE	MODEL	MILEAGE	
SLD6023G	VD45252	18/12/2018	M2 COUPE	0	
DESCRIPTION			ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachment include knocking out dents caused by the accident			850.00		850.00
To spray paint rear bumper			934.00		934.00
To check electrical wiring systems and lightings at the rear section for proper function			150.00		150.00
Sundries			80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER TRIM PANEL (PDC)	1,390.85	1.00		1,390.85
M PERFORMANCE REAR DIFFUSER	3,149.80	1.00		3,149.80

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	4,540.65
Total Labour & Parts :	6,554.65
Deduction for Excess :	
Total Repair Costs less Excess:	6,554.65
GST @7%:	458.83
Grand Total :	7,013.48