amkwok es/od res/ev	ASSIGNATION OF THE POPULATION	GNMEN AL I I I MY / CS OX	TH3/G+ T (Office) Sill to: A 01-52 Claim No: Excess:	Insured: Tel:_ \cdot \			1019
Safe Safe Blk 1 Kuli 390066	FCI 7000 Auto 1 Bukit	/MV/CS	# 01-52	Insured:Tel:	9111	CKP9697R 13103	
Safe Safe BIK 1 Kuk, 390066	FCI 7000 Auto 1 Bukit	0X	Claim No: _	Tel:_	9199	3103	
BIK 1 KUK, 390066	s Bukit	Ave l	Claim No: _	19575			
390066		Ave &	Claim No: _	19575	51717	06h	
					51717	06h	
REV 24 HRS			Excess:				
REV 24 HRS							
REV 24 HRS				D	O.A	18042018	
	wp r				H.O.D.)	Endorsement:	
12 12.04pm	Person Con	ntacted:		Ve	tricle (I	NOUT	
/Instruction (>	() Es	limate					
			111/14			Oct ITULE	
9199 - X		1010	4.4				
The second secon							
amin't LS.Q.	2550	and.	3 days	Red 19	150/	432)	
P	mentled	mentled	nentled	nentled	nentled	nentled	UPIR - X ·

RECEIVED 2 5 MAR 2019

morrow Xhl.	AIG		
	35	SIGNMENT	
rom Date:		Neh No SFG 70	00 X YARBER 31 Jul 20
istimated Cost		Type: MCas/ M.Cycle / Bus / Va	
DD TP WS TP RES (OD RES / EVA / II	NV / MV	Truck / Trailer or	
To inspect Vehicle No:		Make Volvo	560 TY = 1596
at Workshop m/s Cofe Au	ota	Colour Silver	A/G Insured / Std / NI / NA
Sale 110	*30	Sp.Reading 91958	
nsured		Eng/No:	
Policy Na.		CNO. YVIFS	48HBD 223334
Claims No.		Gen. Cond. Good Fair / Poor /	Burnt
Sum Insured Exce	55	Steering: In (rer / Jammed / Le	
(Client's Record)		Brake In Greet / Jammed / Le	
Make of Ven.		Modi. Nil / S/Rim / STO A/R	Rim or
			15/50ZRD
(Policy Condition)		R.	11
Remark: The veh had commenced its	N/S O/	BS / DUN / EXNOVA / GY / FS /	LIZA / (III) OHTSU / PIR / SUMI /
repair at the time of inspection	·	TOYO / YOKO or	
Ball or Market Value: STK	. 0	Front /	Rear
4 11	ent? : Yes or No	R/Bal. 0 mm	R/Bal. 6 mm
	ent? : Yes or No	L/Bal. 6 mm	L/Bal 6 mm
	es. Yes or No	D.O.A.	0.0.1. 22-04-
	Val.: Yes or No.	Survey held at	N/5 51
11		Des. of Damages Frt / Reary	O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS	Vehicle: IN / C		
Date Person Contacted		The U/C / Chassis frame	Body Structure affected due to collisio
Date / Time Action / Instruction			
27/4/18 SAPWIT DAK 1	eport		
	0 100 0010		
RECEIVE	3 0 APR 2010		
	THEO OF THE STREET		
Date-Time, File Pass to? : Preli. F	Report	Days Of Repair:	
Final F		Resurvey No. of Trip:	Survey Fee:
CatelTime File Return to 7	Сероп		Transcortance
	Add	Fee: Site Insp (\$]S+R33L
		Interview (S	Photos
Report Format :		Tech Invs (\$) C949
Trapation and the second		Weevend IS	

Celine Fong (LKKAuto)

From:

sam kwok <aplussam@yahoo.com.sg>

Sent:

Monday, 18 March 2019 3:01 PM

To: Cc: assignments sam kwok

Subject:

Resend car accident verification report in colour photo

Attachments:

CAR ACCIDENT REPORT IN COLOUR.pdf

Hi Celine,

We would like to resend you the car accident verification report with color photo, please let us know the can do verification again with the colour photo attached?

Warmest regards Sam Kwok

---- Forwarded Message -----

From: sam kwok <aplussam@yahoo.com.sg>

To: "assignments@lkkauto.com" <assignments@lkkauto.com>

Sent: Monday, 10 December 2018, 15:53 Subject: Resend 03 SFG 7000X Static Report

Hi Celine,

Please kindly assist us with this car accident verification, the reason is:-

- not agree on the settlement amount (\$7,413.60)
- Cost of repair (\$4,500) because the owner only spends \$150 for his own car. bumper respray
- cost of Ho See Kheong car rental fee \$1,400 ???

Car owner: HTUN STANLEY STEVEN

Driver: CAR: VINCENT LIU SKP 9697R

.....

Claim Person: HO SEE KHEONG

Car:

SFG7000X

Please refer to attachment for details.

Warmest regards Sam Kwok *Hp 82028688*

Celine Fong (LKKAuto)

From:

sam kwok <aplussam@yahoo.com.sg>

Sent:

Monday, 19 November 2018 10:04 AM

To: Cc:

assignments sam kwok

Subject:

Request Accident verification report

Attachments:

new doc 2018-11-19 09.50.05_20181119095130.pdf

Hi Celine.

Please kindly assist us on this car accident verification, the reason for are:-

- not agree the settlement amount (\$7,413.60)

- Cost of repair (\$4,500) because owner only spend \$150 for his own car. bumper respray

- cost of Ho See Kheong car rental fee \$1,400 ???

Car owner: HTUN STANLEY STEVEN

Driver:

VINCENT LIU

CAR:

SFG 7000X

Claim Person: HO SEE KHEONG

Please refer to attachment for details.

Warmest regards Sam Kwok Hp 82028688

Sent from Yahoo Mail for iPhone

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

TO SELECT THE RESERVE THE RESE	ACCIDENT STATEMENT
Date Of Report	16/10/2018 15:16
Date Of Accident	18/04/2018 23:00
Exact Location Of Accident	BRADDELL ROAD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SKP9697R
Insured/Policyholder	
Name Of Registered Owner	HTUN STANLEY STEVEN
NRIC No	G3053383L
Email Address	STANHTUN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98933385
Alternative Phone No	OTHERS-97707690
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	S400L-3.0 R19 LED (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100390066
Cover Note Number	
Driver	
Name of Driver	LIU BOWEN
NRIC No	S8875388G
Date Of Birth	01/04/1988
Occupation	INDOOR
Date Of Driving Pass	26/12/2012
Driving Experience	5 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97707690
Fax Number	
Contact Number	

ELFENLIED@ICLOUD.COM

Address

17 EWE BOON ROAD #11-01

SINGAPORE

Postcode

259325

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

FRIEND

Vehicle Registration Number of Driver's Own

Vehicle

.

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

RAINING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged?

000000

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SFG7000X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiete policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. Sy the ladgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Linderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use. disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured refricte(s) involved in this accident shall be collectively referred to as the "insurers") the insurers' lawyerylaw firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) corrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (by) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me. which could involve disclosure of certain personal data about one to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the Purposes")
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permutted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or Gsa to their third party service providers on agentating adding their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile daims lifetory for the purpose of fraud detection. investigation and management in present and all future claims.
- the information so collected under (d) above may be shared indiclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud. regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyheldege Signature

Oriver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

Sketch Plan #2

ETCH PLAN		Vehicle
	1 /2	A SKP 9697 B SFG 7000X
	1/28/	B 27 G 7000
	VA /	
		Legend
		M £
		Vehicle Motorcycle
SCRIBE CIRCUMSTANCES O	THE ACCIDENT	
Lt3 a Riving Night	I was asking to drive the (Car to work shop
	A 1 T a 's often do	Process Will MI // CORP.
n 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	the store STATILE 120 MT THE	164 111 12
See the Traffic lie	ht Clearly and start to	move the car and
touch Weeks Vehi	de B	
TO VENT MARKET		
DECLARATION		^
	culars are true in every respect. y have a fourteen (14) days clause whereby the claim against own p	solicy must be made within the stiguisted (insetraine
Please be advised that your insurer ma from the day of occurrence Knally che	ck your policy for more detail	NOV'
Z41	- A.	Reporting Chritze Personnel's Signature
Policyfolder's Signature	Oriver's Sentture (If driver is not the policyholder)	Name:
Date & Fime:	(If driver is not the posicyholder) Date & Time:	Name: PETWL

VISION LAW LLC

Advocates & Solicitors - Notary Public Commissioner for Quibs Agents for Trade Marks

(Incorporated with limited liability) Unique Entity Number: 200721148H

ERIC NO CHING BOON
RAYNEY WONG KENG LEONG
AUDREY WONG SU HISEN
PAGE AN TAL SAN
ANDALE DIG MUNIANON
SE DA PARAU
DIANE AND NIM MOI
RALE NIME AND NIM MOI
RALE NIME AND NIME AND SAN
CLASSES CHEONS YUMBUI
EDISON TAM CHITE U
SONG LIM WELLEL

YHEAD OFFICE 133 New Bridge Road #18-01/02 Chinatown Point Singapore 059413

Branch 490 Toa Payoh Lorong 6 #03-11 HDB Hub Singapore 310490

HEAD OFFICE

TEL. (65) 65342811 (Hunting) FAX (65) 65356802 (General) < (65) 65355902 (Litigation) E-mail: yvonnelim@visionlawlic.com

BRANCH

TEL . (65) 63580703 FAX : (65) 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - PLEASE REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref

: DA1-ylv-Ins-S121-106497-18-er

10 October 2018

17 Ewe Boon Road

HTUN STANLEY STEVEN

#11-01, Hallmark Residences

URGENT

AR-REGISTERED

BY POST ONLY

Singapore 259325 Dear Sir,

CLAIMANT : HO SEE KHEONG ACCIDENT INVOLVING SFG 7000 X & SKP 9697 R ON 18-APR-2018 AT SLIP ROAD AT BRADDELL **ROAD AT ABOUT 2305 HOURS**

We act for HO SEE KHEONG, the owner of motor vehicle no. SFG 7000 X.

We understand that you are the owner of motor vehicle SKP 9697 R at the material time of accident. Accordingly, we had submitted our client's claim to your insurers, AIG Asia Pacific Insurance Pte Ltd for their consideration.

We have now been informed by your insurers that they have repudiated liability as you have fail to comply with the terms and condition of the policy. A copy of their email dated 1 October 2018 is enclosed herewith for your information.

In view of the abovesaid, we have no alternative but to refer our client's claim to you.

Our client's claim for losses and damages are as follows:

1.	Costs of Repair	\$	4,500.00
2.	Rental fees	\$	1,400.00
3.	LTA/GIA/TP report/search fees	\$	40.00
4.	Survey report fees	\$	425.00
5.	Costs (with GST)	\$	963.00
6.	Incidentals (with GST)	5	85.60
٠.	TOTAL:-	\$	7,413.60

TAKE NOTICE that unless the said sum of \$7,413.60 is paid to us as solicitors for our client within ten (10) days from the date hereof, our instruction is to commence action against you for recovery of the same without any further notice to you.

DIANE ANG (HEAD OFFICE) Encl.

Yours faithfully/

cc: SFG 7000 X - By fax: 6386 7787 only

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.



SKP9697R Attention: VINCENT BENZ S400 97707690 Invoice Date 22 May 2018 Invoice Number 20180243 UEN/Co. Reg. No. 201614279E STK METAL & LEATHER PTE LTD 8 Kaki Bukit Ave 4 #03-30 Premier@Kaki Bukit Singapore 415875 HP:91237949 Tel:63860669

Description	Quantity	Unit Price	Amount SGD
RR &FRT BUMPER RESPRAY	1.00	150.00	150.00
		Subtotal	150.00
	INCLUDES	SALES GST 7%	0.00
		TOTAL SGD	150.00

Due Date: 22 May 2018

Received In Good Order & Condition Goods Sold Are Not Refundable/Return


*** Interest rate of 5% per month, calculated on a daily basis, is levied on payment for OVERDUE AMOUNT(s)/ACCOUNT(s) owing to STK METAL & LEATHER PTE LTD after SEVEN (7) DAYS from DATE OF INVOICE.

** Cheque should be crossed and make payable to "STK METAL & LEATHER PTE LTD".

Customer's Signature









Motor Vehicle Appraiser and Insurance Loss Adjuster No. 8 Kaki Bukit Ave 4 #06-21 Premier @ Kaki Bukit Singaore 415875 Handphone No.: +65 9146 1186 Email: united.appraisal@live.com.sg Business Registration Nos.: 200817301N

Our ref.: UAM18.04.10-AK-STP-SAF-SFG7000X

Date

: 26 Apr 2018

Ho See Kheong

WITHOUT PREJUDI	CE
Dear Sir,	
Re: Third Party Claim For Vehicle Registration No. SFG7000X	
We refer to your instruction to appraise the above-mentioned vehicle on 23 April 2018	
A static inspection was carried out and our report is enclosed for your perusal. The estimated cost of repair submitted by Messrs. Safe Auto for SGD 8,790.00 as per our attached schedule has been inspected thoroughly by us against the actual damages sustained on the above-mentioned vehicle and we recommend the replacement and rectification accordingly.	
Our revised quotation for the repair is SGD 5,137.06. In our opinion, it to be excessive Therefore, we recommend a contract lump-sum repair cost. This is more economical than to be the above-mentioned vehicle repaired on parts by/for parts basis. Invariably, the repairer has the prerogative/option for the recommended replacement parts to either be repaired or be replaced.	ave ne
We have negotiated with the repairer and they have agreed to repair the above-mentioned veh for SGD 4,500.00 NETT. Which, in our opinion is fair and reasonable.	icle
The repairer has agreed to undertake the repairs to your requirement at the recommended con lump-sum. However, we have not given any instruction and authorisation to the repairer to provide the repairs.	
Under normal circumstances, the entire repair of the damaged vehicle should be completed with a reasonable period of 3 (Three) days.	hin
We are reverting the matter to you for a decision, and enclosed is our vehicle inspection report appraisement schedule and invoice for services rendered.	,
Please do not hesitate to contact us if you have any queries on this matter.	
Yours faithfully, United Appraisal & Management Pte Ltd	
Ananda K. Biswas Marc Motor Vehicle Appraiser	

Encls.:

The information contained in these document may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you received this document by error, please contact us immediately to arrange for its return.

VEHICLE INSPECTION REPORT

To:

Ho See Kheong

Our ref.: UAM18.04.10-AK-STP-SAF-SFG7000X

Date : 26 Apr 2018

REFERENCE

Assign by	:	Ho See Kheong	Insured	:	To be advice
Assign on	:	23 Apr 2018	Policy no.	:	To be advice
Inspection on	:	23 Apr 2018	Claim no.	:	To be advice
Accident on	:	18 Apr 2018	Sum insured	:	To be advice
Workshop name	:	Safe Auto	Excess	:	Not applicable
Inspection at	:	1 Kaki Bukit Ave 6	3rd party Veh.		To be advice
		Kaki Bukit Autobay Blk C #01-52	3rd party ins.	:	To be advice
		Singapore 417883			

0.

PARTICULARS OF DAMAGED VEHICLE

Registration no.	: SFG7000X	Odometer	:	91958 km
Make / Model	: Volvo S60 T4	Chassis no.	:	YV1FS48HBD2233341
Regn. date	: 31 Jul 2013	Engine no.	:	B4164T1139738
Body colour	: Silver	Engine cap.	:	1596 cc

PRE-ACCIDENT CONDITION OF VEHICLE (STATIC CHECK ONLY)

Steering	:	In order	Paintwork	:	Good
Footbrake	:	In order	Undercarriage	:	Serviceable
Handbrake	:	In order	Gen. condition	:	Good


TYRE CONDITION ON VEHICLE

		Make	Size	Tread depth	Type of road wheel
Front N/S	:	Michelin	215/50ZR17	80%	Alloy
Front O/S	:	Bridgestone	215/50ZR17	80%	Alloy
Rear N/S	:	Michelin	215/50ZR17	80%	Alloy
Rear O/S	:	Michelin	215/50ZR17	80%	Alloy

NOTE: The above percentages represent the estimated remaining life of tyre threads.

^{*} Denotes damaged component/s

POINT OF IMPACT



SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT

The impact of the collision has damaged / affected the bootlid, rear bumper, reinforcement and etc...

Please refer to Annex A (Appraisement Schedule) for a detailed account of the damages and photographs taken.

Note: Reinspection vehicle on 24 Apr 2018 for repair in progress.

RECOMMENDATION

The estimate cost of repair submitted by Messrs

Safe Auto

as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. We have not authorised the repairs.

Our adjusted cost of repair is SGD 4,500.00 to carry out the repairs. Please refer to Annex A (Appraisement Schedule) for a detailed account of the cost estimates.

REMARKS

We have not authorised the repair. However, for information, under normal circumstances, the repair would takes approximately <u>3 (Three)</u> working days to complete.

In accordance to your instruction, we have **NOT AUTHORISED** the repair to the damaged vehicle and the survey was conducted strictly on a "WITHOUT PREJUDICE" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Appraisal Report, which includes evidence photographs.

Yours faithfully, United Appraisal & Management Pte Ltd

Ananda K. Biswas Marc Motor Vehicle Appraiser

APPRAISEMENT SCHEDULE

Annex A

Registration no.

: SFG7000X

Our reference : UAM18.04.10-AK-STP-SAF-SFG7000X

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
		LIST ITEMS			
1	1	Bootlid	Refer To Labour	2114.20	0.00
2	1	Bootlid emblm " VOLVO "	Necessary	107.00	107.00
3	1	Bootlid emblm " S60 "	Necessary	65.00	65.00
4	1	Bootlid emblem " T4 "	Necessary	62.00	62.00
5	1	Rear bumper	Deformed	1827.00	1827.00
6	1 set	Rear bumper clip	Necessary	50.00	₩050.00 h
7	2	Rear bumper side retainer @ SGD 109.40	Distorted	218.80	156 218.80
8	1	Rear bumper lower	Deformed	625.00	553625.00
9	1	Rear bumper reinforcement	Re-Used	381.00	0.00
10	1	Reverse sensor @ SGD 192.00	Mulfunction	768.00	768.00×
11	1	Reverse sensor holder @ SGD 18.00	Necessary	72.00	72.00
12	1	Reverse sensor seal @ SGD 8.00	Necessary	32.00	32.00
13	1 set	Reverse sensor angle bracket @ SGD 32.00	Necessary	128.00	128.00
				6450.00	3954.80
		Ī	Less 0% / 5%	0.00	197.74
				6450.00	3757.06
		SPECIAL NETT ITEMS			
1	1	Sundries	Necessary	60.00	40.00
				60.00	40.00
		TOTAL		6510.00	3797.06

APPRAISEMENT SCHEDULE

'Annex A

Registration no. : SFG7000X

Our reference

: UAM18.04.10-AK-STP-SAF-SFG7000X

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
		LABOUR & MISC CHARGES	Balance C/F	6510.00	3797.06
1		To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.		1000.00	500.00 ₹9 ○
2		To disconnect wire harness of electrical component to facilitate repairs, reconnect and check functions.		80.00	60.00 30
3		To apply undercoating on the accident repair and replaced panel for rust protection.		200.00	180.00
4		Supply spray paint material and necessary items to respray bootlid, rear bumper and other affected area / panel.		1000.00	600.00 400
		TOTAL		2280.00	1340.00
		Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment)		8790.00	5137.06 637.06
		Adjustment Parts and Labour Cost of Repair			4500.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

Ref: CS3/AIG18007413/Gtd3e2-1

HTUN STANLEY STEVEN 17 EWE BOON ROAD

#11-01 HALLMARK RESIDENCESSINGAPORE

Date: 25-03-2019



			Code: TP2	
1.		Policy Particul	ars :- THIRD PARTY CLA	AIM.
	Insured Veh.	SKP 9697R	Veh. Inspected	SFG 7000X
	Policy No.	2100390066	Coverage (\$)	0.00
	Claim No.	1957517170SG	Excess (\$)	0.00
	Assign From	SAM KWOK	Assign Date	18/03/2019
2.		Vehicle P	articulars & Condition	
	Make & Model	VOLVO S60 T4	c.c	1596
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	YV1FS48HBD2233341	Colour	SILVER
	Odometer	91958	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	215/50Z R17	MICHELIN	6 mm
	L/H Front Tyre	215/50Z R17	MICHELIN	6 mm
	R/H Rear Tyre	215/50Z R17	MICHELIN	6 mm
	L/H Rear Tyre	215/50Z R17	MICHELIN	6 mm
4.		Descr	iption of Damages	能力能够,他不会一生 。"
	THE VEHICLE SU	STAINED DAMAGES AT THE	REAR PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Gen	eral Information	
	Accident Date	18/04/2018	Inspection Date	23/04/2018
	Survey held at	SAFE AUTO		
		1 KAKI BUKIT AVE 6 #01-52 AUTOBAY KAKI BU SINGAPORE 417883	КІТ	
5a.	CHARLES IN		Remarks	似 以图记忆思图[]
	A)THE INSPECTION	ON WAS CONDUCTED ON A'CE TO YOUR INSTRUCTION	WITHOUT PREJUDICE" BA	ISIS.
5b.	IB)IN ACCORDANG		ate Days of Repair	ISED REPAIRS.
ob.	Tearus Tea	MAL PERIOD FOR REPAIR:	3 Working Da	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFG 7000X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID	NOT NECESSARY	2,114.20	-
1	BOOTLID EMBLEM "VOLVO"	NECESSARY	107.00	107.00
1	BOOTLID EMBLEM "S60"	NECESSARY	65.00	65.00
1	BOOTLID EMBLEM "T4"	NECESSARY	62.00	62.00
1	REAR BUMPER	CUT	1,827.00	1,512.00
1	SET REAR BUMPER CLIP	NECESSARY	50.00	40.00
2	REAR BUMPER SIDE RETAINER @\$109.40	DISTORTED	218.80	158.00
1	REAR BUMPER LOWER	CUT	625.00	553.00
1	REAR BUMPER REINFORCEMENT	REUSE	381.00	15
4	REVERSE SENSOR @\$192.00	NOT NECESSARY	768.00	
4	REVERSE SENSOR HOLDER @\$18.00	NECESSARY	72.00	72.00
4	REVERSE SENSOR SEAL @\$8.00	NECESSARY	32.00	32.00
4	SET REVERSE SENSOR ANGLE BRACKET @\$32.00	NOT NECESSARY	128.00	
	LESS 5% DISCOUNT		, , ,	-130.05
			6,450.00	2,470.95
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN)	NOT NECESSARY	60.00	
			60.00	5.
	LABOUR			
	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS.		1,000.00	300.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS.		80.00	30.00
	TO APPLY UNDERCOATING ON THE ACCIDENT REPAIR AND REPLACED PANEL FOR RUST PROTECTION.	NOT NECESSARY	200.00	
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY BOOTLID, REAR BUMPER AND OTHER AFFECTED AREA / PANEL.		1,000.00	400.00
			2,280.00	730.00

Report Ref No. CS3/AIG18007413/Gtd3e2-1



Page No.:2 of 2

GRAND TOTAL	8,790.00	3,200.95
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		2,550.00

Report Ref No. CS3/AIG18007413/Gtd3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

St. S.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.