

22/3/19
 Kenneth
 Eileen Lee
 FCS
 Date/Time: 2:56pm @ 22/3/19

CS/PC1 19005208/Ktd307

ASSIGNMENT (Office)

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No. SKT 6591K Insured SHD 6628J
 at Workshop no. Cheng Hoe Motor Tel. 6755 6142
 of Blk 1019 Xishun Ind. park A # 01374
 Policy No. Claim No. D19001964 MFSH
 Sum Insured Excess
 Make of Veh. D.O.A. 19/03/19
 (Client's Record)

CA / REV / REP. / REV 24 HRS 105
 Date/Time: 3:39pm @ 22/3/19 Person Contacted: Effreda Vehicle: IN / OUT

Date/Time	Action/Instruction () Estimate
	SKT 6591K - x
	SHD 6628J - x
28/3/19	Revised via Email preli advise.
28/3	82754.16 Confirm E Parts (bad \$ 847.78, 24%). no lump sum

ASS. REC. BY:

REF:

17021

Kennaeth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

1.131 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKT 6591K

Yr Regn:

06/15

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda City

c.c.

1497

Colour:

m. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

31117

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MRH 6MB6606 P000046

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

185/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

19/3/19

D.O.I.

22/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

RECEIVED 27 MAY 2019

24/5/2019

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

5

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Fees

Others

TOTAL

130

50

50 + 50

25

305

Report Format:

Lump Sum / I.B.I. (\$

TP

2254.16



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001964MFSH

Date: 28/3/2019

Our Ref: CS/FCI19005208/Ktd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKT 6591K

Please be informed that we had conducted the inspection of the abovementioned vehicle 22/3/2019 at the premises of M/s Cheng Hoe have the following to report: -

Workshop Estimate Amount	: S\$	<u>3,601.44</u>
Revised Estimate Amount	: S\$	<u>2,132.00</u>
"Check" Items Amount	: S\$	<u>1,181.28</u>
Market Value	: S\$	<u> </u>
LTA Reimbursement Value	: S\$	<u> </u>
Nett Value	: S\$	<u> </u>

Description of Damage:

The vehicle sustained damages at the
Rear n/s portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully
Kenneth
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	20-03-2019	Our Ref No. D19001964MFSH
Accident Date	19-03-2019	Claim Type. Third Party
Insured Vehicle	SHD6628J	Third Party Vehicle. SKT6591K
Survey Location	BLK 1019 YISHUN IND. PARK A #01-374	
Contact Person.	JUNE	
Contact No.	67556142/ 0	Fax No. 67557719
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHENG HOE MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 28 March 2019 10:26 AM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001964MFSH/1
Attachments: PRELI ADVISED SKT 6591K.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SKT 6591K**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 22 March 2019 3:10 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001964MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 22 March 2019 2:56 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001964MFSH/1

Dear Sir/Mdm,

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5460F
Vehicle Details	
Vehicle No.:	SKT6591K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	20 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	CITY 1.5 SV CVT
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	L15Z12702724
Chassis No.:	MRHGM6660GP000046
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$17,647.00
Original Registration Date:	18 Jun 2015
First Registration Date:	18 Jun 2015
Transfer Count:	0
Actual ARF Paid:	\$7,647.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jun 2025
PARF Rebate Amount:	\$5,735.00
Intended COE Rebate Details	
COE Expiry Date:	17 Jun 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$68,589.00
COE Rebate Amount:	\$42,823.00
Total Rebate Amount:	\$48,558.00

The information contained herein is correct as at 20 Mar 2019

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SKT6591K
 TP/FC

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department \ THE MOTOR

Estimate No: ES1991294/YISHUN

Date: 21 Mar 2019

Policy No: 18-MW005645-R03

Veh Reg No: SKT6591K

Make/Model: HONDA CITY 1.5 SV CVT

WS Ref: TP/FC/YS

Claim Type: Third Party

Accident Date: 19/03/2019

TP Veh Reg No: SHD6628J

Chassis No: MRHGM6660GP000046

Engine No: L15Z12702724

Reg. Date: 18/06/2015

Estimate Repair Cost to Vehicle No :SKT6591K

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	463.50	1 PC	463.50	✓
2 REAR BUMPER SIDE RETAINERS	14.90	2 PCS	29.80	✓
3 REAR BUMPER LH REFLECTOR	30.00	1 PC	30.00	X
4 REAR BUMPER CLIPS	3.90	6 PCS	23.40	✓
5 REAR BOOT	497.20	1 PC	497.20	✓
6 REAR BOOT LOGO	27.40	1 PC	27.40	✓
7 REAR BOOT EMBLEM (CITY)	21.40	1 PC	21.40	✓
8 REAR BOOT EMBLEM (I-VTEC)	19.80	1 PC	19.80	✓
9 REAR BOOT INNER LOCK	90.30	1 PC	90.30	X
10 REAR BOOT INNER RUBBER	76.10	1 PC	76.10	✓
11 REAR BOOT LH REFLECTOR	109.20	1 PC	109.20	✓
12 REAR CENTRE PANEL	323.90	1 PC	323.90	X
13 REAR CENTRE PANEL INNER TOP GARNISH	76.60	1 PC	76.60	✓
14 TAILLAMP LH	225.70	1 PC	225.70	✓
			2,014.30	
	Less 20%		402.86	1,611.44
Special Net				
15 REVERSE SENSOR (4 PCS)	280.00	1 SET	280.00	✓
			280.00	280.00
Labour				
16 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR BOOT & ATTACHMENT, CUT, WELD & RENEW REAR CENTRAL PANEL, KNOCK & REPAIR REAR SPARE TYRE COMPARTMENT & REALIGN THE SAME	800.00	1 LA	800.00	500
17 PUTTY & RESPRAY ON REAR BUMPER, REAR PANEL, REAR BOOT, REAR SPARE TYRE COMPARTMENT	850.00	1 LA	850.00	700
18 RUSTPROOFING	60.00	1 LA	60.00	300
			1,710.00	1,710.00

Total S\$ 3,601.44

Add GST @ 7% 252.10

Total Amount Payable S\$ 3,853.54

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19005208/Ktd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 28-05-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6628J	Veh. Inspected	SKT 6591K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001964MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	22/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CITY (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	MRHGM6660GP000046	Colour	METALLIC SILVER	
Odometer	51117	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	185/55 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	185/55 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	185/55 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/03/2019	Inspection Date	22/03/2019	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 6591K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BUCKLED	463.50	463.50
2	REAR BUMPER SIDE RETAINERS @\$14.90	N/S DISTORTED	29.80	14.90
1	REAR BUMPER LH REFLECTOR	SERVICEABLE	30.00	-
6	REAR BUMPER CLIPS @\$3.90	NECESSARY	23.40	23.40
1	REAR BOOT	BENT	497.20	497.20
1	REAR BOOT LOGO	NECESSARY	27.40	27.40
1	REAR BOOT EMBLEM (CITY)	NECESSARY	21.40	21.40
1	REAR BOOT EMBLEM (I-VTEC)	NECESSARY	19.80	19.80
1	REAR BOOT INNER LOCK	TO REPAIR SEE LABOUR	90.30	-
1	REAR BOOT INNER RUBBER	DISTORTED / DENTED	76.10	76.10
1	REAR BOOT LH REFLECTOR	DENTED / CUT	109.20	109.20
1	REAR CENTRE PANEL	TO REPAIR SEE LABOUR	323.90	-
1	REAR CENTRE PANEL INNER TOP GARNISH	MTG DISTORTED	76.60	76.60
1	TAILLAMP LH	CUT	225.70	225.70
	LESS 20% DISCOUNT		-402.86	-311.04
			1,611.44	1,244.16
<u>SPECIAL NETT ITEMS</u>				
1	SET REVERSE SENSOR (4 PCS)(SN)	SHORTED	280.00	280.00
			280.00	280.00
<u>LABOUR</u>				
	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR BOOT & ATTACHMENT, CUT, WELD & RENEW REAR CENTRAL PANEL, KNOCK & REPAIR REAR SPARE TYRE COMPARTMENT & REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR BOOT INNER LOCK AND REAR CENTRE PANEL.		800.00	500.00
	PUTTY & RESPRAY ON REAR BUMPER, REAR PANEL, REAR BOOT, REAR SPARE TYRE COMPARTMENT.		850.00	700.00

Report Ref No. CS/FC119005208/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RUSTPROOFING		60.00	30.00
			1,710.00	1,230.00
GRAND TOTAL			3,601.44	2,754.16
RECOMMENDED COST OF REPAIRS				2,754.16

Report Ref No. CS/FCI19005208/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.