


URGENT



ASS. REC. BY: Surveyor REF: CS3/FWD19002077/RI 03-1 of Instruction
From Person Rahul ASSIGNMENT (Office)
clara of FWD Date/Time: 22/03/2019
Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To inspect Vehicle No: SLG 6866A Insured: SKK 3165A
at Workshop in/s: T & B Motor Repairs Tel: 6458 0296
of Blk 160 Sin Ming Drive # 08-03

Policy No: PNPV2018-00011797 Claim No: 1201900003564
Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 30/01/2019
(Client's Record) 01/02/19 @ 10-11am
CA / REV / REP. / REV 24 HRS up H.O.D. Endorsement: _____

Date/Time: 10:49am 03/1/19 Person Contacted: judy Vehicle IN/OUT: IN

Date/Time	Action/Instruction (X) Estimate
	<u>SLG 6866A - X</u>
	<u>SKK 3165A - X</u>
	<u>Pending Gica Report.</u>
	<u>Part by Part \$4345.76 (Red: 2508.34, 36%) 5/4/2019</u>
	<u>6 Days.</u>

5/4 - file pass to typist.

RECEIVED 05 APR 2019

URGENT

URGENT

REF: FWD

PRS (Mettmen)

ASSIGNMENT

From: Date: 01/02/2019

Estimated Cost:

DD: ☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MY

To inspect Vehicle No: SLG 6866A

at Workshop no: T & B Motor Repairs

of 81k 160 Sin Ming Drive #08-03

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

10am-11am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

(IAC, Accident Report)

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repair:

4

days

Res: Yes or No

Lump Sum

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SLG 6866A

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover / ☐ Truck / ☐ Trailer or

Make: Honda vtr

Colour: Black

Sp Reading: 016837

Eng/No:

C/Nr: RA11202118

Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Mod: Nil / ☒ Rim / ☐ STD A/Rim or

Tyre Size: F: 215/50R16

R:

BS: ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI / ☐ TOYO / ☐ YOKO or

Front R/Bal: 6 mm

L/Bal: 6 mm

D.O.A: 30/01/19

Survey held at: T & B Motor

Des. of Damages: ☒ Front / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Rep. large 35K-4K

13/2/2019

Date/Time, File Pass to:

☐

Prel. Report

By:

☐

Final Report

Date/Time, File Return to:

By:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format:

PRS

Lump Sum / L.B. It: 15

Add Fee:

☐

Site Insp 15

☐

Interview 15

☐

Tech. Insp 15

☐

Workshop 15

1 x R 50

1 Hour

1 Hour

1

Total

Nivitha (LKK Auto)

From: clara.li@fwd.com
Sent: Friday, 22 March 2019 12:36 PM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: RE: [Paper Resurvey] - Traffic accident involving SLG 6866 A and SKK 3165 A (FWD // 1201900003564/CL)
Attachments: Survey Report.pdf

Hi LKK team,

Please refer to the attached survey report and assist with paper resurvey and let us have the report via email.

Thank you.

Regards,
Clara

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 7 February, 2019 9:38 AM
To: Motor Claims SG - SG Common
Cc: Clara Li Zirong - SGUser; Lionel Tan Tian Pei - SGUser
Subject: [Paper Resurvey] - Traffic accident involving SLG 6866 A and SKK 3165 A (FWD // PNPV2018-00011797)

Dear Josey,

Noted, with thanks.



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: motorclaims.sg@fwd.com [mailto:motorclaims.sg@fwd.com]
Sent: Thursday, 7 February 2019 9:30 AM
To: admin-d@lkkauto.com

Cc: clara.li@fwd.com; lionel.tan@fwd.com; motorclaims.sg@fwd.com

Subject: RE: Notice of Accident - Traffic accident involving SLG 6866 A and SKK 3165 A (FWD // PNPV2018-00011797) on 30 January 2019 at/along the CTE exit towards A.M.K Avenue 1; Our ref: LCH.my/SMTB-90113.19

Hi Nivitha,

We had uploaded insured's GIA in Merimen.

Please request for a copy of TP GIA from TP.

Thank you.

Kind Regards.

Josey Loh
Executive, Claims


FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872

E josey.loh@fwd.com

W fwd.com.sg



From: Admin-D (LKKAuto) [<mailto:admin-d@lkkauto.com>]

Sent: Thursday, 7 February, 2019 8:36 AM

To: Motor Claims SG - SG Common

Cc: Clara Li Zirong - SGUser; Lionel Tan Tian Pei - SGUser

Subject: RE: Notice of Accident - Traffic accident involving SLG 6866 A and SKK 3165 A (FWD // PNPV2018-00011797) on 30 January 2019 at/along the CTE exit towards A.M.K Avenue 1; Our ref: LCH.my/SMTB-90113.19

Dear Sir/Mdm,

Kindly assist to provide GIA Report for both Parties.



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315



From: motorclaims.sg@fwd.com [mailto:motorclaims.sg@fwd.com]

Sent: Wednesday, 30 January 2019 6:17 PM

To: assignments@lkkauto.com; sur@lkkauto.com

Subject: FW: Notice of Accident - Traffic accident involving SLG 6866 A and SKK 3165 A (FWD // PNPV2018-00011797) on 30 January 2019 at/along the CTE exit towards A.M.K Avenue 1; Our ref: LCH.my/SMTB-90113.19

PRI email below for your attention.

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]

Sent: Wednesday, January 30, 2019 5:25 PM

To: Motor Claims SG - SG Common

Subject: Re: Notice of Accident - Traffic accident involving SLG 6866 A and SKK 3165 A (FWD // PNPV2018-00011797) on 30 January 2019 at/along the CTE exit towards A.M.K Avenue 1; Our ref: LCH.my/SMTB-90113.19

Dear Sir / Madam,

We refer to the above matter and to your email of even date.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your list of appointed surveyors stated therein.

We are further instructed to append below our client's 10 proposed surveyors as follows:

- | | |
|--------------------------|-------------------------|
| 1) Jayson Liaw Leong San | 6) Hong Fook Choy |
| 2) Lee Kok Weng | 7) Andrew Aw |
| 3) Low Sar Huei | 8) Matthew Ng Yong Chin |
| 4) Patrick Ng Kong Beng | 9) Ong Poh Meng |
| 5) Leslie Lim | 10) Jackson Quek |

If you are not agreeable to our list of surveyors above, kindly appoint your surveyor to proceed with the pre-repair survey of our client's vehicle no. SLG 6866 A at our client's repairer workshop as follows:-

T & B Motor Repairs Services Pte Ltd
Blk 160 Sin Ming Drive #08-03
Sin Ming Auto City
Singapore 575722

Person to contact : Mr Tay (contact no. 6458 0296)

Thanks & regards,
Melody

CHEONGHOH LAW CORPORATION
Blk 53 Chin Swee Road #03-05 Singapore 160053
T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

On 30 Jan 2019, at 3:58 PM, motorclaims.sg@fwd.com wrote:

Without Prejudice

Dear Sir/ Madam

Please select one of our surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. VICOM LTD
5. APPRAISALS ASSOCIATES PTE LTD

If you are not agreeable to any of the above, we would proceed to appoint a surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We look forward to your reply.

Thank you.

Lionel

From: Cheonghoh Law [<mailto:mail@cheonghoh.sg>]
Sent: Wednesday, January 30, 2019 1:06 PM
To: Motor Claims SG - SG Common
Subject: Notice of Accident - Traffic accident involving SLG 6866 A and SKK 3165 A (your insured) on 30 January 2019 at/along the CTE exit towards A.M.K Avenue 1; Our ref: LCH.my/SMTB-90113.19

Dear Sir/ Madam,

Please see attached Notice of Accident for your attention and reply.

Thanks & regards,

Melody

CHEONGHOH LAW CORPORATION
Blk 53 Chin Swee Road #03-05 Singapore 160053
T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.


Messages and attachments are scanned for all viruses known. However, you are advised that you open any

attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189
Fax: 6315 3298, Mobile: 9061 0543

ACCIDENT VEHICLE INSPECTION REPORT

Report no : 29M0119.TB
Vehicle no : SLG6866A

1 REFERENCE

Date of inspection : 30 January 2019
Requested by : Jude Ng Jin Quan
Blk 475D Upper Serangoon Crescent
#14-557
Singapore 537475
Type of survey : Independent
Repairer : T & B Motor Repairs Services Pte Ltd
160 Sing Ming Drive #08-03 Sin Ming Auto City Singapore 575722
Date of accident : 30 January 2019

2 VEHICLE DATA

Make/model : Honda VEZEL 1.5X CVT
Chassis no : RU11202118
Engine no : L15B4402117
Date of registration : 27 September 2016
Engine capacity : 1496 cc
Colour : Black
Odometer reading : 016741 km

3 STATIC CONDITION CHECK

Steering : Serviceable
Foot brakes : Serviceable
Hand brakes : Serviceable
Paintwork : Good
General Condition : Good

4 TIRE CONDITION CHECK

	<u>RH/MAKE</u>	<u>LH/MAKE</u>	<u>SIZE</u>
Front tread	: 7 mm/Dunlop	7 mm/Dunlop	215/60R16
Rear tread	: 7 mm/Dunlop	7 mm/Dunlop	215/60R16

5 BRIEF DESCRIPTION OF DAMAGE

Rear bumper dented/deformed, rear end panel dented/bent, rear boot cover dented/bent, etc. Please see para. 8 of this report for more details.

6 REMARKS

This inspection is carried out on a "WITHOUT PREJUDICE" basis and I have not authorized any repairs.

7 RECOMMENDATION

Cost of repairs : \$6,854.10
No of days taken : Eight (8)

8 ASSESSMENT OF DAMAGE AND COSTS

Report no: 29M0119.TB
Vehicle no: SLG6866A

A SPARE PARTS

Description	Qty	Assessed Condition	Repairer's Amount	Revised Amount
1 Rear boot cover	1	dented/bent	1,048.90	1,048.90
2 Rear boot cover stay LH	1	serviceable	198.00	0.00
3 Rear boot cover stay RH	1	serviceable	198.00	0.00
4 Rear boot cover number plate garnish	1	reuse	1,076.00	0.00
5 Rear boot cover number plate garnish logo	1	not required	43.00	0.00
6 Rear boot cover reflector RH	1	reuse	264.00	0.00
7 Rear boot cover reflector LH	1	scraped	264.00	264.00 X m
8 Rear boot cover inner lock	1	bent/distorted	198.00	198.00
9 Rear boot weatherstrip	1	deformed	148.50	148.50
10 Rear end panel	1	dented/bent	415.00	415.00
11 Rear bumper	1	dented/deformed	849.30	849.30
12 Rear lamp LH	1	Casing & lens split	428.70	428.70 X m
13 Rear lamp RH	1	reuse	428.70	0.00
14 Rear bumper side garnish RH	1	edge warped/deformed	208.86	208.86 X m
15 Rear bumper side garnish LH	1	edge warped/deformed	208.86	208.86 X m
16 Rear bumper side garnish retainer RH	1	grip tabs fractured	17.50	17.50
17 Rear bumper side garnish retainer LH	1	grip tabs fractured	17.50	17.50
18 Rear bumper lower cover	1	reuse	195.00	0.00
19 Rear boot cover windscreen glass moulding	1	necessary	140.00	140.00
20 Rear end panel top garnish	1	reuse	92.30	0.00
Subtotal of the above			6,440.12	3,945.12
Discount			20% / 20%	1,288.02
Subtotal 1:			5,152.10	3,156.10
(Special nett)				
1 Rear boot windscreen sealant	1	necessary	120.00	120.00 60
2 Rear bumper clip set	1	necessary	80.00	80.00 40
3 Rear bumper lower cover clip set	1	necessary	60.00	60.00 30
4 Rear boot cover VEZEL emblem	1	necessary	43.00	43.00
5 Rear boot buzzer	1	broken	95.00	95.00
6 Rear boot cover top spoiler clip set	1	necessary	120.00	120.00 60
7 Rear floor board & end panel joint sealant	1	necessary	120.00	120.00 60
Subtotal 2:			638.00	638.00
Total cost of parts:			5,790.10	3,794.10

B LABOUR

1 Remove & refix rear boot windscreen glass.	160.00	120.00
2 Remove & refix rear boot reverse camera.	100.00	60.00 40
3 Supply & install one set of new rear bumper reverse sensors (shorted).	320.00	320.00 220
4 Check & repair wiring.	80.00	30.00
5 Spray anti-rust coating.	180.00	90.00 60
6 Spray paint on affected portions.	1,200.00	1,000.00 400

7	Remove & refix rear boot cover top spoiler and supply sealant.	180.00	120.00 60
---	--	--------	----------------------

Report no: 29M0119.TB
Vehicle no: SLG6866A

8	Remove & refix rear boot inner garnish & floorboard cover.	250.00	120.00 60
---	--	--------	----------------------

9	Remove & refix rear boot cover number plate garnish, spoiler, two rear bumper side garnishes, rear bumper, two rear fender and spray glass coating.	800.00	0.00
---	---	--------	------

10	Labour charge for repairing, replacing, adjusting, knocking and welding of damaged parts and panels.	1,800.00	1,200.00 100
----	--	----------	-------------------------

Total cost of labour:	5,070.00	3,060.00
-----------------------	----------	----------

Total cost of repair:	10,860.10	6,854.10
-----------------------	------------------	-----------------

9 CONCLUSION


The revised or adjusted cost of repairs to restore the vehicle is	\$6,854.10
---	------------

(a) The final cost of repair would be	\$6,854.10
---------------------------------------	-------------------

(b) The estimated number of days for the repairs would be	Eight (8)
(1 st Re-Inspection conducted on 12 th February 2019)	
(2 nd Re-Inspection conducted on 15 th February 2019)	
(Post Repair Inspection conducted on 19 th February 2019)	

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its pre-accident condition.

Yours faithfully



Liaw Leong San
Licensed Automotive Appraiser

Dated: 26 February 2019

2267.76

380.00

1690.00

4337.76

6 days

7/P

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Tel: 6315 1239, Fax: 6315 3298, Mobile: 9061 0543

Jude Ng Jin Quan
Blk 475D Upper Serangoon Crescent
#14-557
Singapore 537475

Invoice no:	POS029/19
Date:	26 February 2019
Report no:	29M0119.TB
Vehicle :	SLG6866A

INVOICE

No	Item Description	Qty	Unit Price	Total Amount(\$)
01	Being charges for the inspection of the accident vehicle, transport and photographs.			782.00
SGD(\$): Seven Hundred and Eighty-Two only			Payable Amount:	782.00

"Cheque should be crossed and made payable to "Pro-Option Services"

PRO-OPTION SERVICES



Authorised Signature

T & B MOTOR REPAIRS SERVICES PTE LTD

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

JUDE NG JIN QUAN

BLK 475D UPPER SERANGOON CRESCENT

#14-557 SINGAPORE 537475

Attention : Motor Claim Department

Final Repair Bill : TI001975

Date : 27/02/2019

Vehicle Num. : SLG6866A

Make/Model : HONDA VEZEL

Chassis/Eng# :

Accident Date : 30/01/2019

Claim No. :

Reference :

Policy No. : D18MPC001192

Amount S\$

FINAL REPAIRS

INCLUSIVE OF SUPPLYING PARTS AND LABOUR,
PANEL BEATING AND SPRAY PAINTING

6,854.10


SingDollars : Six Thousand Eight Hundred Fifty-Four & Cents Ten Only

E. & O.E.

Total S\$:

6,854.10

=====


for T & B MOTOR REPAIRS SERVICES PTE LTD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	30/01/2019 22:38
Date Of Accident	30/01/2019 06:50
Exact Location Of Accident	SLIP ROAD FROM CTE(CITY) INTO ANG MO KIO AVE 1
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKK3165A
Insured/Policyholder	
Name Of Registered Owner	TAN LAY KOON
NRIC No	S7917797J
Email Address	JOEYTANLK@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97994330
Alternative Phone No	OFFICE-97994330
Vehicle Particulars	
Manufacturer	KIA
Model	OPTIMA 2.0(A) SUNROOF
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00011797
Cover Note Number	
Driver	
Name of Driver	TAN LAY KOON
NRIC No	S7917797J
Date Of Birth	20/06/1979
Occupation	INDOOR
Date Of Driving Pass	16/07/1998
Driving Experience	20 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97994330
Fax Number	
Contact Number	OFFICE-97994330
EEmail Address	JOEYTANLK@HOTMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was coming from CTE(City) at the slip road of Ang Mo Kio Ave 1. I slow down my car but my car did not stop on time and bump onto the rear SLG6866A. Minor damages to my car front portion. No injuries were involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WILL UPLOAD TO MERIMEN ONCE INSURED SEND
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG6866A
Vehicle Make/Model/Colour	HONDA VEZEL 1.5X CVT
Details Of Properties	NA
Vehicle Category	PRIVATE CAR
Name of Driver	JUDE NG JIN QUAN
NRIC/Passport Number	S1658241G
Contact Number	97358688
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN**IMPORTANT NOTICE**

- 1 Please report correctly the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Authorized Driver.
- 3 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
- 7 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS

REPORTING OFFICER


Muhammad Faizal

Bin Pebila

Witnessed by Reporting Centre
Personnel

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Sketch Plan

Common Statement

ACCIDENT STATEMENT (2000 characters)

I was coming from CTE(City) at the slip road of Ang Mo Kio Ave 1. I slow down my car but my car did not stop on time and bump onto the rear SLG6866A. Minor damages to my car front portion. No injuries were involved.

Taxi Voucher No:

DECLARATION

/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MUHAMMAD FAIZAL BIN PABILA

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

30 January 2019 at 8:08 PM

Date/Time

30 January 2019 at 8:08 PM

Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo




Accident Photo




Accident Photo



Accident Photo







Identification Card

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7917797J



Name
TAN LAY KOON
(CHEN LIQUN)
陈 丽 群

Race
CHINESE

Date of birth
20-06-1979

Sex
F

Country of birth
SINGAPORE



Identification Card





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FWD SINGAPORE PTE LTD			Ref : CS3/FWD19002077/R1qd3e2-1	
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4SINGAPORE 038986			Date : 08-04-2019	
			Code : FWD	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKK 3165A	Veh. Inspected	SLG 6866A	
Policy No.	PNPV2018-00011797	Coverage (\$)	0.00	
Claim No.	1201900003584	Excess (\$)	0.00	
Assign From	CLARA LI	Assign Date	22/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU11202118	Colour	BLACK	
Odometer	16837	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/50 R16	DUNLOP	6 mm	
L/H Front Tyre	215/50 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/50 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/50 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/01/2019	Inspection Date	01/02/2019	
Survey held at	160 SIN MING DRIVE# 08-03			
Repairer	T & B MOTOR REPAIRS SERVICES PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 6866A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT COVER	DENTED / BENT	1,048.90	1,048.90
1	REAR BOOT COVER STAY LH	SERVICEABLE	198.00	-
1	REAR BOOT COVER STAY RH	SERVICEABLE	198.00	-
1	REAR BOOT COVER NUMBER PLATE GARNISH	REUSE	1,076.00	-
1	REAR BOOT COVER NUMBER PLATE GARNISH LOGO	NOT REQUIRED	43.00	-
1	REAR BOOT COVER REFLECTOR RH	REUSE	264.00	-
1	REAR BOOT COVER REFLECTOR LH	NOT NECESSARY	264.00	-
1	REAR BOOT COVER INNER LOCK	BENT / DISTORTED	198.00	198.00
1	REAR BOOT WEATHERSTRIP	DEFORMED	148.50	148.50
1	REAR END PANEL	DENTED / BENT	415.00	415.00
1	REAR BUMPER	DENTED / DEFORMED	849.30	849.30
1	REAR LAMP LH	NOT NECESSARY	428.70	-
1	REAR LAMP RH	REUSE	428.70	-
1	REAR BUMPER SIDE GARNISH RH	NOT NECESSARY	208.86	-
1	REAR BUMPER SIDE GARNISH LH	NOT NECESSARY	208.86	-
1	REAR BUMPER SIDE GARNISH RETAINER RH	GRIP TABS FRACTURED	17.50	17.50
1	REAR BUMPER SIDE GARNISH RETAINER LH	GRIP TABS FRACTURED	17.50	17.50
1	REAR BUMPER LOWER COVER	REUSE	195.00	-
1	REAR BOOT COVER WINDSCREEN GLASS MOULDING	NECESSARY	140.00	140.00
1	REAR END PANEL TOP GARNISH	REUSE	92.30	-
	LESS 20% DISCOUNT		-1,288.02	-566.94
			5,152.10	2,267.76
SPECIAL NETT ITEMS				
1	REAR BOOT WINDSCREEN SEALANT (SN)	NECESSARY	120.00	60.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	80.00	40.00
1	SET REAR BUMPER LOWER COVER CLIP (SN)	NECESSARY	60.00	30.00
1	REAR BOOT COVER VEZEL EMBLEM (SN)	NECESSARY	43.00	43.00
1	REAR BOOT BUZZER (SN)	BROKEN	95.00	95.00

Report Ref No. CS3/FWD19002077/R1qd3e2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR BOOT COVER TOP SPOILER CLIP (SN)	NECESSARY	120.00	60.00
1	REAR FLOOR BOARD & END PANEL JOINT SEALANT (SN)	NECESSARY	120.00	60.00
			638.00	388.00
	LABOUR			
	REMOVE & REFIX REAR BOOT WINDSCREEN GLASS.		160.00	120.00
	REMOVE & REFIX REAR BOOT REVERSE CAMERA.		100.00	40.00
	SUPPLY & INSTALL ONE SET OF NEW REAR BUMPER REVERSE SENSOR (SHORTED).		320.00	220.00
	CHECK & REPAIR WIRING.		80.00	30.00
	SPRAY ANTI-RUST COATING.		180.00	60.00
	SPRAY PAINT ON AFFECTED PORTIONS.		1,200.00	400.00
	REMOVE & REFIX REAR BOOT INNER GARNISH & FLOORBOARD COVER.		250.00	60.00
	REMOVE & REFIX REAR BOOT COVER NUMBER PLATE GARNISH, SPOILER, TWO REAR BUMPER SIDE GARNISHES, REAR BUMPER, TWO REAR FENDER AND SPRAY GLASS COATING.	NOT NECESSARY	800.00	-
	LABOUR CHARGE FOR REPAIRING, REPLACING, ADJUSTING, KNOCKING AND WELDING OF DAMAGED PARTS AND PANELS.		1,800.00	700.00
	REMOVE & REFIX REAR BOOT COVER TOP SPOILER AND SUPPLY SEALANT.		180.00	60.00
			5,070.00	1,690.00
GRAND TOTAL			10,860.10	4,345.76
RECOMMENDED COST OF REPAIRS				4,345.76

Report Ref No. CS3/FWD19002077/R1qd3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.