

22/03/2019

ASS. REC. BY:

REF: CS / FC119005225 / UV d3n2 Special Instruction:

Surveyor: MarcusASSIGNMENT (Office)

CWS

From (Person): Sithara of FCI Date/Time: 22.3.2019

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: P2 3388K Insured: SHC 72317at Workshop m/s Imperium Automotive Tel: 97489940of 25 Kaki Bukit Road 4 # 01-49Policy No: _____ Claim No: D19001950MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 19.3.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP"

H.O.D. Endorsement: _____

Date/Time: 22.3.2019 1.25p.m Person Contacted: Shawn Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	P2 3388K - NA/11/19005015 / 1/4	D.O.A - 19/3/2019
	SHC 72317 - X	
3/4/19	Email FCI informed pending est from repairer	
5/4/19	Email preli revised to FCI	

(05/11/13) wef

REF:

ASS. REC. BY: *Marcus*

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal.

L/Bal.

D.O.I.

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

5/4 - typist

Report Format:

Lump Sum / I.B.I. (\$

CWS

6000/-

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

8x15 = 120

170 + 120

50

50

60

450

MV: \$ 72K (EST) LTA: \$ 29,075 NV: \$ 42,925

RECEIVED 05 APR 2019

4/4/19 4/5 @ 6000 confirmed with shown. (Red 12,396.80, 67%)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19001950MFSH

Our ref: CS/FCI19005225/Uvd3

DATE: 5/4/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. PZ 3388K


We thank for your instruction on 2/4/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 2/4/2019 at the premises of M/s IMPERIUM AUTOMOTIVE

Workshop Estimate Amount	: S\$18,396.80
Revised Estimate Amount	: S\$6,000.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	20-03-2019	Our Ref No. D19001950MFSH
Accident Date	19-03-2019	Claim Type. Third Party
Insured Vehicle	SHC7231T	Third Party Vehicle. PZ3388K
Survey Location	25 KAKI BUKIT ROAD 4 #01-49 SYNERGY@KB	
Contact Person.	SHAWN TAN	
Contact No.	97489940/ 97489940	Fax No. 63467213
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

March 20
 V. NO.
 E. ✓
 Time: 1.25 p.m.

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	IMPERIUM AUTOMOTIVE	Attention. NIL
Cc : TP Solicitor	JUSEQUITY LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 5 April 2019 10:39 AM
To: 'CWS Motor Claims'
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001950MFSH/2, PZ 3388K
Attachments: PZ 3388K (PRELI REVISED).pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle PZ 3388K
Date of survey: 2/4/2019
Number of days : 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 3 April 2019 12:46 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001950MFSH/2, PZ 3388K

Dear Sir/Madam,

Please be informed that we have inspected the vehicle PZ 3388K on 2/4/2019

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 25 March 2019 8:00 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001950MFSH/2

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Friday, 22 March 2019 12:50 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19001950MFSH/2

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 3 April 2019 12:46 PM
To: 'CWS Motor Claims'
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001950MFSH/2, PZ 3388K

Dear Sir/Madam,

Please be informed that we have inspected the vehicle PZ 3388K on 2/4/2019

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 25 March 2019 8:00 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001950MFSH/2

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 22 March 2019 12:50 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001950MFSH/2

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	6016E
Vehicle Details	
Vehicle No.:	PZ3388K
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COASTER 19 SEATER
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	N04CTQ12570
Chassis No.:	JTGFC538503000335
Maximum Power Output:	-
Open Market Value:	\$68,174.00
Original Registration Date:	24 Sep 2008
First Registration Date:	24 Sep 2008
Transfer Count:	2
Actual ARF Paid:	\$3,409.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Sep 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$30,696.00
COE Rebate Amount:	\$29,075.00
Total Rebate Amount:	\$29,075.00

The information contained herein is correct as at 03 Apr 2019

OK

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-49 Synergy@KB, Singapore 417800

HP : 9748 9940 Shawn Tan Fax : 6346 7213

Email: shawn7530@hotmail.com

21 March 2019

Vehicle No.: PZ 3388 K

Model: Toyota Coaster Bus

QTY	DESCRIPTION	AMT S\$
<u>Nett Items</u>		
1	Rear panel -R/H	4,850.00
1	Rear panel glass moulding	180.00
1	Rear door -L/H	3,390.00
1	Rear door glass moulding	165.00
1	Rear door lock	255.00
1	Rear door hinge -lower	125.00
1	Rear door rubber	245.00
2	Rear taillamps	1,161.00
1	Rear end panel -lower	851.40
1	Rear bumper assy	1,909.40
1	Rear number plate lamp	85.00
		<u>13,216.80</u>
<u>Special Nett Items</u>		
1	Rear "80/90KM/J" sticker	40.00
1	Rear "HOTLINE SPAD" sticker	40.00
1	Rear panel glass sealant	120.00
1	Rear door glass sealant -L/H	120.00
2	Rear bumper brackets	370.00
1	Rear number with holder	50.00
1	Rear reverse camera	480.00
		<u>1,220.00</u>
<u>Labour Charges</u>		
1	To remove, replaced damaged lamps and check up rear wiring.	80.00
2	To remove and refit inner garnishes.	180.00
3	To remove and refit rear reverse sensor.	150.00
4	To remove and refit rear windscreen glass.	250.00
5	To apply tuff kote.	200.00
6	Panel beating.	1,600.00
7	To respray painting on the affected areas.	1,500.00
		<u>3,960.00</u>
Grand Total :		\$ 18,396.80

Customer to be notified
Following:
Respray painting
during resurvey
to confirmation
on "Without Prejudice" basis
to be resurveyed and
is subject to final approval from Ins

Acknowledged by Repairer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19005225/Uvd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 09-04-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7231T	Veh. Inspected	PZ 3388K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001950MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	22/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COASTER (M)	c.c	4009	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JTGFC538503000335	Colour	WHITE / YELLOW	
Odometer	468254	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/75 R17.5	MICHELIN	6 mm	
L/H Front Tyre	205/75 R17.5	MICHELIN	6 mm	
R/H Rear Tyre	205/75 R17.5 (D)	MICHELIN	6/6 mm	
L/H Rear Tyre	205/75 R17.5 (D)	MICHELIN	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/03/2019	Inspection Date	02/04/2019	
Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PZ 3388K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR PANEL-R/H	BADLY DENTED	4,850.00	4,650.00
1	REAR PANEL GLASS MOULDING	NECESSARY	180.00	180.00
1	REAR DOOR-L/H	TO REPAIR SEE LABOUR	3,390.00	-
1	REAR DOOR GLASS MOULDING	NOT NECESSARY	165.00	-
1	REAR DOOR LOCK	NOT NECESSARY	255.00	-
1	REAR DOOR HINGE-LOWER	NOT NECESSARY	125.00	-
1	REAR DOOR RUBBER	TORN	245.00	245.00
2	REAR TAILLAMPS	O/S CRACKED	1,161.00	580.50
1	REAR END PANEL-LOWER	TO REPAIR SEE LABOUR	851.40	-
1	REAR BUMPER ASSY	BENT	1,909.40	1,825.20
1	REAR NUMBER PLATE LAMP	NOT NECESSARY	85.00	-
	LESS 25% DISCOUNT		-	-1,870.18
			13,216.80	5,610.52
SPECIAL NETT ITEMS				
1	REAR "80/90KM/J" STICKER (SN)	NECESSARY	40.00	20.00
1	REAR "HOTLINE SPAD" STICKER (SN)	NECESSARY	40.00	20.00
1	REAR PANEL GLASS SEALANT (SN)	NOT NECESSARY	120.00	-
1	REAR DOOR GLASS SEALANT-L/H (SN)	NOT NECESSARY	120.00	-
2	REAR BUMPER BRACKETS (SN)	O/S BENT	370.00	150.00
1	REAR NUMBER WITH HOLDER (SN)	NOT NECESSARY	50.00	-
1	SET REAR REVERSE SENSOR (SN)	NOT NECESSARY	480.00	-
			1,220.00	190.00
LABOUR				
	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING.		80.00	30.00
	TO REMOVE AND REFIT INNER GARNISHES.	NOT NECESSARY	180.00	-
	TO REMOVE AND REFIT REAR REVERSE SENSOR.		150.00	50.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		250.00	100.00
	TO APPLY TUFF KOTE.		200.00	50.00

Report Ref No. CS/FCI19005225/Uvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR DOOR-L/H AND REAR END PANEL-LOWER. TO RESPRAY PAINTING ON THE AFFECTED AREAS.		1,600.00	600.00
			1,500.00	880.00
			3,960.00	1,710.00
GRAND TOTAL			18,396.80	7,510.52
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,000.00

Report Ref No. CS/FCI19005225/Uvd3n2

MARKET VALUE: \$72,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$29,075.00=NETT VALUE: \$42,925.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.