

TO :

ESTIMATE REPORT 1ST Quotation

FAX NO:

22/03/2019 10:55

JOB-NO: 50111499

Page 1 of 2

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
 ADDRESS: 383 SIN MING DRIVE
 SINGAPORE 575717 0

CONTACT: 65533880
 64739522

VEHICLE DETAILS

LICENSE NO: SHA8784T
 MAKE / MODEL: HYUNDAI / i40
 OWNER'S INSURER: MS First Capital Insurance Limited
 JOB-CODE: TP

TRANS: AUTO
 SA: Ding Auto User 2

CHASSIS: KMHLB41UMHU098304
 ENGINE: D4FDGU706871

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,200.00	600	0.00			1,200.00 Y
2 REMOVE & RE-FIX DOOR COMPONENT TO REPLACE NEW DOOR	1.00	160.00	50	0.00			160.00 Y
3 RUST PROOFING	1.00	80.00	30	0.00			80.00 Y
4 DIAGNOSTIC VEHICLE & CLEAR FAULT CODE & POWER WINDOW SYSTEM	1.00	230.00	30	0.00			230.00 Y
5 RESPRAY FRONT FENDER & SIDE MIRROR LHS	1.00	400.00		0.00			400.00 Y
6 RESPRAY FRONT DOOR & REAR DOOR LHS	1.00	450.00	400	0.00			450.00 Y
7 RESPRAY SIDE SKIRT & REAR FENDER & REAR BUMPER	1.00	650.00	600	0.00			650.00 Y
8 REMOVE & REFIT FRONT WHEEL CAP & TYRE & BALANCING	1.00	80.00	X	0.00			80.00 Y
TOTAL:		3,250.00		0.00			3,250.00
MATERIALS							
1 FRONT FENDER LHS	1.00	523.86	104.77	419.09	L		Y
2 FRONT FENDER INNER SHIELD LHS	1.00	175.00	35.00	140.00	L		Y
3 FRONT FENDER STAND GARNISH LHS	1.00	48.22	9.64	38.58	L		Y
4 FRONT WHEEL CAP LHS	1.00	265.22	53.04	212.18	L		Y
5 REPAIR A PILLAR LHS	1.00	0.00	0.00	0.00	L		Y
6 FRONT DOOR LHS	1.00	2,256.00	451.20	1,804.80	L		Y
7 FRONT DOOR WEATHERSTRIP	1.00	253.88	50.78	203.10	L		Y
8 FRONT DOOR LOCK ASSY LHS	1.00	290.80	58.16	232.64	L		Y
9 FRONT DOOR HINGE TOP LHS	1.00	39.00	7.80	31.20	L		Y
10 FRONT DOOR HINGE BOTTOM LHS	1.00	36.10	7.22	28.88	L		Y
11 FRONT DOOR CHECKER ASSY LHS	1.00	39.20	7.84	31.36	L		Y
12 FRONT DOOR WINDOW REGULATOR LHS	1.00	250.10	50.02	200.08	L		Y
13 REPAIR SIDE MIRROR LHS	1.00	0.00	0.00	0.00	L		Y
14 REPAIR REAR DOOR LHS	1.00	0.00	0.00	0.00	L		Y
15 REPAIR REAR FENDER LHS	1.00	0.00	0.00	0.00	L		Y
16 REPAIR B PILLAR LHS	1.00	0.00	0.00	0.00	L		Y
17 FRONT FENDER QTR GARNISH LHS	1.00	25.00	0.00	25.00	S		Y
18 FRONT FENDER INNER SHIELD CLIP SET LHS	1.00	35.00	0.00	35.00	S		Y
19 FRONT DOOR STICKER-COMFORTDELGRO LHS	1.00	160.00	0.00	160.00	S		Y
20 FRONT DOOR TRIM BOARD CLIP SET LHS	1.00	35.00	0.00	35.00	S		Y

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
21 REAR DOOR STICKER-BOOK NOW&APPS /	1/12/00	160.00	80	0.00	160.00	S	Y
STORE RHS		35.00	0.00	35.00	S	Y	
22 SIDE SKIRT CLIP SET	1.00	4,627.38	835.47	3,791.91			
TOTAL:		7,877.38	835.47	7,041.91			

TOTAL PARTS & LABOUR :

EXCESS/LOADING:\$ 0.00

No. Of Day:

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY:

SURVEYED BY:

CONTACT NO:

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: