

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBE1850G190304

**Estimate**

|                 |                                       |                    |                       |
|-----------------|---------------------------------------|--------------------|-----------------------|
| <b>Customer</b> |                                       | <b>Date:</b>       | 25-03-19              |
| <b>Name:</b>    | India International Insurance Pte Ltd | <b>Vehicle No:</b> | GBE1850G              |
| <b>Address</b>  | Motor Claims Department               | <b>Model/Make:</b> | Toyota Hiace          |
|                 | 64 Cecil Street #04-00 & #05-00       |                    | Van Turbo 5 DR Manual |
|                 | IOB Building                          |                    |                       |
|                 | Singapore 049711                      |                    |                       |

| Item No. | Descriptions Of Parts                                                     | Original Quotation / Estimation | Revised Quotation / Cost Of Repair |
|----------|---------------------------------------------------------------------------|---------------------------------|------------------------------------|
| 1        | Rear Lh Tail Lamp <i>scr</i>                                              | \$ 365.10                       |                                    |
| 2        | Bumper <i>cu7</i>                                                         | \$ 465.00                       |                                    |
| 3        | Bumper Clips 2 set <i>mu</i>                                              | \$ 48.00                        |                                    |
| 4        | Bumper Bracket <i>11</i>                                                  | \$ 39.10                        |                                    |
|          | To check all wiring & electrical component for proper function            | \$ 50.00                        |                                    |
|          | To putty & spray painting & including touch up paint on accident affected | \$ 600.00                       |                                    |
|          | Remove & reinstall Tailgate Glass to facilitate repairs                   | \$ 400.00                       |                                    |
|          | To apply Rust Proofing , reseal tuff-coating treatment on accident area   | \$ 50.00                        |                                    |

Total Parts &amp; Labour of estimate for damaged vehicle

\$ 2,017.20

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

*not Authorised*  
*hla*  
*h/s #1100*  
*23/3/19*  
*the phd after rep*  
*4 dy.*

*2-878/*  
*1008-57*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: