

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kwok Woon Choo

Date: 27 Mar 2019

Preliminary Advice

Vehicle No	: SJS4257G	Accident Date	: 26/02/2019
Make	: FORD S-MAX	Policy No.	: B28912568MCY
Assignment Date	: 25/03/2019	Excess	: S\$0.00
Date of Inspection	: 25/03/2019	Est. Duration of Repair	: -
Inspection At	: Shu Fatt Auto Works (HQ) Block 1009 Bukit Merah Lane 3, #01-90 Singapore 159723		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages engine compartment caught fire.

Repairer's Estimate (Gross)	:S\$	9,900.00
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	
Total	:S\$	TOTAL LOSS
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	16,000.00
COE / PARF Rebate	:S\$	11,362.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,638.00

Remarks

(X) The vehicle is not economical for repair. Vehicle recommended total loss. Pending investigation.

() The above survey was conducted on a 'without prejudice' basis.