

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
TEL: 6886 9097 FAX: 6841 9095 Email: focus.autopteltd@yahoo.com.sg
GST: 201004495R RCB NO: 201004495R

not Adjust
note
2/3 # 4200/
28/3/19
Whphl Alurap
Sdy.

M/S: Lonpac Insurance Bhd
100 Beach Road
#19-11 Shaw Tower
Singapore 189702

TEL: 6250 7388

FAX: 6296 2706

ATTN: Motor Claim Department

Your Ref No: SJX7944K

Claim Type: Third Party

Accident Date: 21-03-2019

TP Veh Reg No: SJN3576T

Estimate No: EST0000871

Date: 27 Mar 2019

Policy No: PNCV2019-00000022

Veh Reg No: SJX7944K

Make/Model: HYUNDAI AVANTE

Chassis No: KMHDU41BMAU019814

Engine No: G4FCAU848073

Reg. Date: 13-07-2010

Estimate Repair Cost for Vehicle No :SJX7944K

PAGE:1/2

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 Rear Boot	907.00	1 PC	907.00	X
2 Rear Boot Lock	108.50	1 PC	108.50	X
3 Rear Boot Lock Catch	28.60	1 PC	28.60	X
4 Rear Boot Rubber	68.50	1 PC	68.50	X
5 Rear Boot Hinge	60.50	2 PC	121.00	X
6 Rear Boot Emblem	28.50	1 PC	28.50	✓
7 Rear Boot Centre Logo	28.50	1 PC	28.50	✓
8 Rear Boot Reflector <i>ALS</i>	188.50	1 PC	188.50	—
9 Rear Fender <i>ALS</i>	1,603.00	1 PC	1,603.00	—
10 Rear Fender Inner Side Garnish <i>trim ALS</i>	245.00	1 PC	245.00	✓
11 Rear Fender Inner Side Garnish Clipse	5.50	4 PC	22.00	X
12 Rear Fender Dust Cover	42.00	1 PC	42.00	—
13 Rear Fender Air duct	58.20	1 PC	58.20	—
14 Rear Tail Lamp <i>ALS</i>	261.80	1 PC	261.80	—
15 Rear Bumper	480.50	1 PC	480.50	—
16 Rear Bumper Side Beam	32.00	1 PC	32.00	—
17 Rear Bumper Reinforcement	262.00	1 PC	262.00	—
18 Rear Bumper Reinforcement Bracket	68.00	1 PC	68.00	X
19 Rear Bumper Inner Sponge	<i>109.90</i> 122.00	1 PC	122.00	—
20 Rear Bumper Clip	5.50	6 PC	33.00	—
21 Rear Windscreen Moulding	<i>47.50</i> 70.20	1 PC	70.20	X
22 Rear End Panel	<i>493.80</i> 537.80	1 PC	537.80	—
23 Rear End Panel Top Garnish	<i>34.40</i> 58.50	1 PC	58.50	X
			5,375.10	
Less 20%			1,075.02	4,300.08
Special Net				
24 Rear Bumper Sensor	300.00	1 PC	300.00	200
25 Rear Windscreen Gum	80.00	1 PC	80.00	
			80.00	380.00
Labour				
26 Panel Beating	1,300.00	1 PC	1,300.00	1000
27 Check Wiring	60.00	1 PC	60.00	30

3866.70
3093.36

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6841 9095 Email: focus.autopteltd@yahoo.com.sg
GST:201004495R RCB NO:201004495R

M/S : Lonpac Insurance Bhd
100 Beach Road
#19-11 Shaw Tower
Singapore 189702

TEL: 6250 7388

FAX: 6296 2706

ATTN: Motor Claim Department

Your Ref No: SJX7944K

Claim Type: Third Party

Accident Date: 21-03-2019

TP Veh Reg No: SJN3576T

Estimate No: EST0000871

Date: 27 Mar 2019

Policy No: PNCV2019-00000022

Veh Reg No: SJX7944K

Make/Model: HYUNDAI AVANTE

Chassis No: KMH DU41BMAU019814

Engine No: G4FCAU848073

Reg. Date: 13-07-2010

Estimate Repair Cost for Vehicle No :SJX7944K

PAGE:2/2

Description	U/Price	Quantity	List Price S\$	Amount S\$
28 Rust Proofing	60.00	1 PC	60.00 ✓	
29 To remove & refit rear seat & up-hole-step	160.00	1 PCS	160.00 60	
30 To Remove & Refit Rear Windscreen	160.00	1 PC	160.00 X	
31 To Remove & Replace Bumper Sensor	80.00	1 PC	80.00 50	
32 Spray Painting	950.00	1 PC	950.00 800	
			2,770.00	2,770.00
			Total	S\$ 7,450.08

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND FOUR HUNDRED FIFTY AND CENTS EIGHT ONLY

5293.36

For FOCUS AUTO PTE LTD

Focus Auto Pte Ltd
No 1 Kaki Bukit Ave 6 Auto Bay
#02-50 Singapore 417883
AUTHORISED SIGNATURE
Tel: 65349595

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: