

7/10/2019

ASS. RES. BY:

REF: CS/CTI/1900527/19ad3⁸⁷

Special Instructions:

Surveyor:

Hwee Jie

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

25/3/2019 @ 11:24am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SGX 2227R

Insured:

GY 3554J

at Workshop n/a

Jee Autolution

Tel:

9677 5772

of

39 woodlands close #01-34/35

Policy No:

Claim No:

3NM19D201286

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21/03/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:07pm 28/3/19

Person Contacted:

ERIC

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SGX 2227-R - NA/CTI 19005191/h4

D.O.A - 21/3/2019

GY 3554J - NA/CTI 19005191/h4

D.O.A - 21/3/2019

27/3/19 @ 4.42pm Hwee Jie finalised with Abby is \$1000, 9 days.

CRed \$15732.99, 61%)


REF: CT1

NAME: Hwee Jie

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop n/s _____
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 9 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGX 2227 R Yr Regn: 16 Aug 2007
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Toyota wish G.C. 1794
Colour: Grey A/C: Insured / Std / NI / NA
Sp. Reading: 367888 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: 2NE100374013
Gen. Cond: 3 / Good / Fair / Poor / Burnt
Steering: 3 / In order / Jammed / Leaked / Burnt or
Brake: 3 / In order / Jammed / Leaked / Burnt or
Modl: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 215/45R17
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>21/3/19</u>	D.O.I. <u>25/3/19</u>
Survey held at <u>JEC Auto</u>	
Des. of Damages <u>(Frt)</u> / <u>Rear</u> / O/S / N/S / UIC / Rooflop or	

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
25/3/19	Waiting for estimate
	<u>Hwee Jie</u>
	<u>MV - \$53600</u>
	<u>PV - \$42750</u>
	<u>NV - \$10850</u>
	<u>PLS check parts prices</u>
	RECEIVED 03 MAY 2019
	<u>17/4</u>

Date/Time, File Pass to? ☐ : Preli. Report
1) 03/4 Hwee Jie ☐ : Final Report
Date/Time, File Return to?
2)
Report Format: MER-TP
Lump Sum / I.B.I. (\$) 10000
Days Of Repair: 9
Resurvey No. of Trip: 2
Survey Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)
Transportation: ☐ : \$ + PS. \$
Photos: ☐
Others: ☐
TOTAL

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 25 March 2019 11:24 AM
To: abbylim@jcngroup.com
Cc: assignments
Subject: RE: ***SPAM*** RE: ***SPAM*** RE: OUR REF: SNM19D201286- GY3554Y - PRS- ACCIDENT INVOLVING VEHICLES SGX 2227R & GY 3554J & SKA 8350B ALONG STILL ROAD ON 21/03/2019 AT ABOUT 1545 HOURS. (PRI)
Attachments: sgx2227r pri.pdf

Without Prejudice

Dear Sir,

We will appoint LKK.

Dear LKK,

Pls pri.

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

-----Original Message-----

From: abbylim@jcngroup.com [mailto:abbylim@jcngroup.com]
Sent: Monday, 25 March, 2019 11:22 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Re: ***SPAM*** RE: ***SPAM*** RE: OUR REF: SNM19D201286- GY3554Y - PRS-ACCIDENT INVOLVING VEHICLES SGX 2227R & GY 3554J & SKA 8350B ALONG STILL ROAD ON 21/03/2019 AT ABOUT 1545 HOURS. (PRI)

Hi Boon Sen,

Please arrange Adrian ling

Thank you.

On Mon, March 25, 2019 9:29 am, Chong Boon Sen wrote:

> Pls use excel.

>

>

> Adrian ling

> Kelvin ang

> See chew seng

> Mhd fadilah bin Osman

> Xing guo qiang

> Kenneth kong

> Simon ho

> Chua weijie

> Marcus chua

> Henry ng

>

>

> Regards,

> Chong Boon Sen

> Claims Executive

> Claims

>

>

> China Taiping Insurance (Singapore) Pte. Ltd.

> 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Co. Reg. No.

> 200208384E

> DID: 63896171

> Fax: 62247175

> Email: boonsen.chong@sg.cntaiping.com

> Website: www.sg.cntaiping.com

>

>

>

> Disclaimer :

> This message is confidential; its contents do not constitute a

> commitment by China Taiping Insurance (Singapore) Pte. Ltd. except

> where provided for in a written agreement between you and China

> Taiping Insurance

> (Singapore) Pte. Ltd. Any unauthorized disclosure, use or

> dissemination, either in whole or partial, is prohibited. If you are

> not the intended recipient of the message, please notify the sender immediately.

>

> -----Original Message-----

> From: abbylim@jcngroup.com [mailto:abbylim@jcngroup.com]

> Sent: Friday, 22 March, 2019 4:31 PM

> To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

> Subject: Re: ***SPAM*** RE: OUR REF: SNM19D201286- GY3554Y -

> PRS-ACCIDENT INVOLVING VEHICLES SGX 2227R & GY 3554J & SKA 8350B ALONG

> STILL ROAD ON

> 21/03/2019 AT ABOUT 1545 HOURS. (PRI)

>

>

> Hi Boon Sen,

>

> We refer to your email below.

>

>

> Please be informed that we are not able to download the list of surveyor.

>

>

> Please advise .

>

>

>

> On Fri, March 22, 2019 2:40 pm, Chong Boon Sen wrote:

>

>> Without Prejudice

>>

>>

>>

>> Dear Sir,

>>

>>

>>

>> We intend to conduct a pre-repair survey of the damage to your
>> client's vehicle jointly with your client/your motor workshop. We
>> propose to use one of the following motor surveyors to conduct the
>> joint pre-repair survey as a single joint expert.

>>

>>

>> Please let us know within two(2) working days whether you agree to
>> the appointment of any of these motor surveyors as a single joint
>> expert. You may select one of the listed motor surveyors and we will
>> bear the cost of the pre-repair survey carried out by the single joint expert.

>>

>>

>>

>> Regards,

>> Chong Boon Sen

>> Claims Executive

>> Claims

>>

>>

>>

>> China Taiping Insurance (Singapore) Pte. Ltd.

>> 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Co. Reg. No.

>> 200208384E

>> DID: 63896171

>> Fax: 62247175

>> Email: boonsen.chong@sg.cntaiping.com

>> Website: www.sg.cntaiping.com

>>

>>

>>

>>

>> Disclaimer :

>> This message is confidential; its contents do not constitute a
>> commitment by China Taiping Insurance (Singapore) Pte. Ltd. except
>> where provided for in a written agreement between you and China

>> Taiping Insurance
>> (Singapore) Pte. Ltd. Any unauthorized disclosure, use or
>> dissemination, either in whole or partial, is prohibited. If you are
>> not the intended recipient of the message, please notify the sender
>> immediately.
>>
>> -----Original Message
>>
>>
>>
>> -----Original Message-----
>> From: Claims Dept of CTI
>> Sent: Friday, 22 March, 2019 11:53 AM
>> To: Angie Foo
>> Subject: FW: ACCIDENT INVOLVING VEHICLES SGX 2227R & GY 3554J & SKA
>> 8350B ALONG STILL ROAD ON 21/03/2019 AT ABOUT 1545 HOURS. (PRI)
>> Importance: High
>>
>>
>>
>>
>> -----Original Message-----
>> From: abbylim@jcngroup.com [mailto:abbylim@jcngroup.com]
>> Sent: Friday, 22 March 2019 11:37 AM
>> To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
>> Subject: ACCIDENT INVOLVING VEHICLES SGX 2227R & GY 3554J & SKA 8350B
>> ALONG STILL ROAD ON 21/03/2019 AT ABOUT 1545 HOURS.
>> Importance: High
>>
>>
>>
>> HI Mdm /Sir,
>>
>>
>>
>> We refer to the above accident.
>>
>>
>>
>> Please find a copy of the Pre-repair-inspection letter attached.
>>
>>
>>
>> Kindly arrange the above soonest possible.
>>
>>
>>
>> Thank you.
>>
>>
>>
>> Regards
>>
>>

>>
>> Abby Lim
>> JCN Autolution Pte Ltd
>> EAST: 8 Kaki Bukit Avenue 4
>> #07-23,Premier @ Kaki Bukit
>> Singapore 415875
>> Tel:6881 1772

>>
>>
>>
>>
>>
>>
>>
>>
>>
>>

>> _ This email has been scanned by the Symantec Email Security.cloud
>> service. For more information please visit
>> <http://www.symanteccloud.com>

>>
>> _
>>
>>
>>
>>
>
>

> Regards

>
>
>

> Abby Lim
> JCN GROUP
> EAST: 8 Kaki Bukit Avenue 4
> #07-23,Premier @ Kaki Bukit
> Singapore 415875
> Tel:6881 1772

>
>

> North: 39 Woodlands Close
> #01-34/35, Mega @ Woodlands
> Singapore 737856
> Tel: 6278 1889

>
>
>
>
>

> This email has been scanned by the Symantec Email Security.cloud service.
> For more information please visit <http://www.symanteccloud.com>

>
>
>

Regards

Abby Lim

JCN GROUP

EAST: 8 Kaki Bukit Avenue 4
#07-23, Premier @ Kaki Bukit
Singapore 415875
Tel: 6881 1772

North: 39 Woodlands Close
#01-34/35, Mega @ Woodlands
Singapore 737856
Tel: 6278 1889

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



JCN AUTOLUTION PTE LTD

Company Reg No. 201813305W

Address: No 8, Kaki Bukit Ave 4, #07-23, Premier@ Kaki Bukit, Singapore 415875

☎ +65 6881 1772



sales@jcngroup.com

Date: 22nd March 2019

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00, Springleaf Tower
Singapore 079909
Attention: Motor Claims Department

BY EMAIL@ claimsdept@sg.cntaiping.com

Dear Sir/Madam

ACCIDENT INVOLVING VEHICLES SGX 2227R & GY 3554J & SKA 8350B ALONG STILL ROAD ON 21/03/2019 AT ABOUT 1545 HOURS.

1. We act for the Owner of Vehicle No. SGX 2227R, whose vehicle was damaged as a result of an accident with your Insured, the Driver of Vehicle No. GY 3554J on 21/103/2019
2. As a result of the accident, our client's vehicle has been damaged. Please kindly revert to us once you/Insurer have received this notice and a Pre-Repair Inspection will be arrange within the next 02 working days before we carry out any repairs to the mentioned vehicle.
3. If we do not receive any reply or instruction from you/Insurer within the stipulated timeline, our client/we shall proceed to repair the mentioned vehicle without further reference to you/Insurer.

Please kindly contact @ 9677 5772 Erik Chan should you require more information.

Venue for vehicle to be inspected as follows:

39 Woodlands Close
#01-34/35, Mega@ Woodlands
Singapore 737856

Yours faithfully,

Abby Lim
JCN AUTOLUTION PTE LTD

Shiau Chan (LKKAuto)

From: Hwee Jie (LKK Auto)
Sent: Thursday, 2 May 2019 4:42 PM
To: abbylim@jcgrp.com
Cc: Shiau Chan (LKKAuto)
Subject: RE: SGX 2227 FINALIZATION

Hi abby,

Finalized L/S \$10,000/- 9days of repair.

Best Regards,
Hwee Jie | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 9180 3151 | Email: Hweejie@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hwee Jie (LKK Auto)
Sent: Monday, 22 April, 2019 9:41 AM
To: abbylim@jcgrp.com
Cc: Shiau Chan (LKKAuto)
Subject: SGX 2227 FINALIZATION

Hi,

Finalized L/S \$12,200/- 9days of repair. As for this vehicle there is repair limit of \$10,000/-
Please let me know if you're agree with the amount so I can proceed with finalize, thank you.

Best Regards,
Hwee Jie | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 9180 3151 | Email: Hweejie@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

VEHICLE NO: 96X222TR

MAKE & MODEL : TOYOTA WISH 1.8A

DATE OF ACCIDENT	21 / 03 / 2019.	
TIME OF ACCIDENT	1545 AM/PM	
LOCATION OF ACCIDENT	STILL ROAD	
Exact Purpose use during accident		
NAME OF OWNER	CHUA SOO TIEN	
TELP NO	8161 0740	
NRIC	S7514772D	
CLAIM TYPE	OD / THIRD PARTY / Reporting Only	
PRIVATE HIRE	YES / NO ?	
INSURANCE CO.	SOMPO INSURANCE SINGAPORE PTE LTD	
TYPE OF CAVERAGE	Comprehensive / Third Party / Third Party Fire & Theft	
POLICY NO.	D18MTPV01012294	
NAME OF DRIVER	As above / If No:	
NRIC	Any passengers: /	
DATE OF BIRTH	08 / 05 / 1975	
OCCUPATION	Outdoor / Indoor	
DATE OF DRIVING PASS	05 / 02 / 1996	
GENDER	Male / Female	
CONTAC NO.	8161 0740 Office: Home:	
ADDRESS	4K 313B ANCHORVALE ROAD #12-108 (5+2313)	
DRIVER HAVE ANY OWN Vehicle	NO / If yes : Reg No:	
RELATIONSHIP	Employee / If No:	
WEATHER CONDITION	(Clear) / Raining / Other :	
ROAD SURFACE	(Dry) / Wet / Other :	
ANY INJURIES	No / If yes : Who?	
CONTAC NO.		
POLICE REPORT	(No) / If yes : Where?	
VEHICLE B NO.	GY3554J Any Passenger :	
NAME		
CONTACT NO.		
VEHICLE C NO.	SEA 8350B Any Passenger :	
VEHICLE D NO.	Any Passenger :	
VEHICLE E NO.	Any Passenger :	
VEHICLE F NO.	Any Passenger :	
ANY WITNESS		
WITNESS CONTACT NO.		
Have you been approach by unknown person soliciting (s) / offering accident claims assistance?	YES / NO	
PARTICULAR WORKSHOP		
TELP NO		
CONTACT PERSON		
FAX NO.		

SKETCH PLAN

VEH A SGX 2227R

VEH B CY 3554J

VEH C KA 8350B



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 21st March 2019 on 1545hrs. I was travelling along still road and stop ~~at~~ the traffic junction. Suddenly I felt a bang on the rear of my vehicle. Due to collision my veh A hit onto veh C.

DECLARATION

(We declare the foregoing particulars are true to best of our respect.)

Reporting Officer's Signature
Date & Time

Driver's Signature
(If driver is not the reporting officer)
Date & Time

Reporting Centre Person's Signature
Name
NAIC P/N/NO

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4772D
Vehicle Details	
Vehicle No.:	SGX2227R
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 A
Primary Colour:	Grey
Manufacturing Year:	2007
Engine No.:	1ZZ2939697
Chassis No.:	ZNE100374013
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$15,575.00
Original Registration Date:	16 Aug 2007
First Registration Date:	16 Aug 2007
Transfer Count:	2
Actual ARF Paid:	\$17,133.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Aug 2027
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$50,972.00
COE Rebate Amount:	\$42,750.00
Total Rebate Amount:	\$42,750.00

The information contained herein is correct as at 26 Mar 2019

OK

8-4



Posted: 14-Mar-2019 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A (COE till 10/2021) **\$17,838** **\$7,050 /yr** **06-Oct-2006** **1,794 cc** **-** **MPV** **Av**

100% In House Loan Available. View To Believe! Don't Miss, Call Today!

Posted: 23-Mar-2019 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A (COE till 10/2021) **\$19,800** **\$7,800 /yr** **09-Oct-2006** **1,794 cc** **152,586 km** **MPV** **Av**

LTA Rebate + Body = \$15.8K. Easy And Flexible In-House Loan Available, 1 Owner Only, 7 Seaters MPV, Sport Rims, Dark Blue In Colour, Service Regularly, Good For Short Term Drive.

Posted: 23-Mar-2019 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A (COE till 08/2021) **\$17,800** **\$7,310 /yr** **13-Oct-2006** **1,794 cc** **-** **MPV** **Av**

New Paint, New Leather Seats With Top Up. Just In. Engine, Gearbox, Aircon In Tip Top Condition. Cheapest In Market. Kindly Call For Viewing Advance. Rental Available Too.

Posted: 22-Mar-2019 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A (COE till 08/2021) **\$21,800** **\$8,950 /yr** **27-Oct-2006** **1,794 cc** **-** **MPV** **Av**

Superb Condition.Very Well Taken Care.Don't Miss It.Up To 100% Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrivalled Warranty Complete W...

Classic Credit Pte Ltd

Posted: 11-Feb-2019 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A (COE till 11/2026) **\$48,800** **\$6,370 /yr** **21-Nov-2006** **1,794 cc** **137,378 km** **MPV** **Av**

Depreciation At \$520 Monthly! 100% Safe Buy With Low Risk Involved. The Scrap Value Is Already \$44,000! Beautiful Condition Inside Out. Space, Reliability, Good Fuel Economy, Affordability, You Get All...

Posted: 06-Mar-2019 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A (COE till 11/2021) **\$19,800** **\$7,440 /yr** **22-Nov-2006** **1,794 cc** **158,377 km** **MPV** **Av**

LTA Rebate + Body = \$16.2K. Easy And Flexible In-House Loan Available, 7 Seaters MPV, Sport Rims, Silver In Colour, Service Regularly, Good For Short Term Drive.

Posted: 23-Mar-2019 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A (COE till 12/2021) **\$19,800** **\$7,300 /yr** **11-Dec-2006** **1,794 cc** **-** **MPV** **Av**

LTA Rebate + Body = \$16.2K. Easy And Flexible In-House Loan Available, 1 Owner Only, 7 Seaters MPV, Grey In Colour, Service Regularly, Good For Short Term Drive.

Posted: 24-Mar-2019 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A X Limited (COE till 12/2021) **\$20,800** **\$7,670 /yr** **11-Dec-2006** **1,794 cc** **128,000 km** **MPV** **Av**

Hi Loan Available! Gear Box, Engine And Undercarriage Still In Excellent Good Working Condition. Very Well Maintained! Guaranteed No Further Repair Needed. Warranty Will Be Provided. All Trade In Are ...

Creative Auto

Posted: 20-Mar-2019 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A X (COE till 05/2022) **\$23,800** **\$7,610 /yr** **12-May-2007** **1,794 cc** **156,008 km** **MPV** **Av**

New Arrival! Cheapest In Town! Genuine Price! Jet Black In Colour! (Rare Unit With Rear Aircon!) Pioneer Touchscreen DVD Player/ Reverse Camera/ I-Road V7 Front/Back Cam Recorder/ Top-mount Monitor/Up...

Posted: 24-Mar-2019 Tags: 2007 Toyota Wish, 2007 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

ta Wish 1.8A (COE till 02/28) **\$45,800** **\$4,950 /yr** **24-Jun-2008** **1,794 cc** **-** **MPV** **Av**

Compare

**JCN Autolution Pte Ltd**

COMPANY REG NO: 201813305W

8 Kaki Bukit Ave 4, #07-23, Premier @ Kaki Bukit,
Singapore 415878

+65 6881 1772 sales@jcngroup.com

ESTIMATE

CHUA SOO TIEN
BLK 313 B, ANCHORVALE ROAD, #12-108
Singapore 542313

Contact :

Code : C100045

Date in : 21/03/2019

Vehicle Num. : SGX2227R

Model : TOYOTA WISH 1.8 A

Chassis/Eng# : ZNE100374013/1ZZ2939697

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BONNET DO ✓	1	731.35	731.35
FRONT BONNET HINGE nux	2	171.10	342.20 X
FRONT BONNET INSULATOR MAT CLIPS rec ✓	11	12.40	136.40 20
FRONT BONNET MECHANISM LOCK SVC X	1	181.10	181.10 X
FRONT BONNET RUBBER GUIDE STOPPER nux	2	43.10	86.20 X
FRONT BONNET RUBBER WEATHER STRIP nux	1	171.25	171.25 X
FRONT BUMPER DEF ✓	1	481.10	481.10
FRONT BUMPER SIDE RETAINER L/R nux	2	171.10	342.20 X
FRONT CENTER BRACE PANEL Repair X	1	171.85	171.85 X
FRONT CENTER BRACE PANEL CLIP nux	1	12.90	12.90 X
FRONT GRILLE CRA ✓	1	231.35	231.35
FRONT GRILLE CLIPS nux	2	12.90	25.80 X
FRONT HEADLAMP L/R CRA ✓	2	972.85	1,945.70 1400
FRONT SUPPORT PANEL nux	1	972.10	972.10 X
REAR BUMPER DEF ✓	1	471.10	471.10
REAR BUMPER CORNER RETAINER L/R nux	2	131.25	262.50 X
REAR BUMPER IMPACT BRACKET DR BT-LH ✓	1 2	175.10	350.20 175.10

page 1



JCN Autolution Pte Ltd

COMPANY REG NO: 201813305W

8 Kaki Bukit Ave 4, #07-23, Premier @ Kaki Bukit,
Singapore 415875

+65 6881 1772 sales@jcngroup.com

REAR BUMPER SIDE RETAINER L/R	CRA ✓	2	171.15	342.30
REAR END PANEL	BUC ✓	1	581.10	581.10
REAR END PANEL INNER TOP GARNISH	CRA ✓	1	374.45	374.45
REAR EXHAUST PIPE	nnx	1	731.25	731.25 X
REAR EXHAUST PIPE RUBBER MOUNTING	nnx	1	61.10	61.10 X
REAR FENDER INNER SHIELD CLIPS	nnx	6	12.90	77.40 X
REAR FENDER INNER SHIELD L/R	nnx	2	182.10	364.20 X
REAR FENDER INNER TRIMBOARD (LOWER) L/R	nnx	2	374.45	748.90 X
REAR FENDER INNER TRIMBOARD (UPPER) L/R	CRA ✓	2	741.25	1,482.50 1350
REAR FENDER LH	BUC ✓	1	972.10	972.10 840
REAR FENDER WINDSCREEN GLASS RUBBER MOULDING	rec ✓	1	50.00	50.00
REAR TAILGATE	BUC ✓	1	1217.45	1,217.45
REAR TAILGATE 'LOGO' EMBLEM	rec ✓	1	61.10	61.10
REAR TAILGATE DAMPER L/R	nnx	2	372.10	744.20 X
REAR TAILGATE HINGE L/R	nnx	2	171.45	342.90 X
REAR TAILGATE INNER TRIMBOARD	CRA ✓	1	781.90	781.90
REAR TAILGATE INNER TRIMBOARD INNER HANDLE	nnx	1	121.10	121.10 X
REAR TAILGATE LOCK STRIKER	nnx	1	43.75	43.75 X
REAR TAILGATE MECHANISM LOCK	Jan ✓	1	561.60	561.60
REAR TAILGATE No. PLATE LAMP CHROME GARNISH	CRA ✓	1	374.45	374.45

page 2

**JCN Autolution Pte Ltd**

COMPANY REG NO: 201813302W

8 Kaki Bukit Ave 4, #07-23, Premier @ Kaki Bukit,
Singapore 415875

+65 6881 1772 sales@jcngroup.com

REAR TAILGATE No.PLATE LAMP CHROME GARNISH CLIPS	rec /	4	12.90	51.60	15
REAR TAILGATE No.PLATE LAMP L/R	nn x	2	121.25	242.50	x
REAR TAILGATE RUBBER GUIDE STOPPER	nn x	2	43.75	87.50	x
REAR TAILGATE RUBBER WEATHER STRIP	CUT /	1	371.85	371.85	
REAR TAILGATE WINDSCREEN GLASS	CRA /	1	972.45	972.45	
REAR TAILGATE WINDSCREEN GLASS RUBBER MOULDING	rec /	1	180.00	180.00	
REAR TAILGATE WIPER ARM	nn x	1	171.45	171.45	x
REAR TAILGATE WIPER ARM COVER	SLR /	1	121.10	121.10	
REAR TAILGATE WIPER MOTOR	SVC x	1	561.60	561.60	x
REAR TAILLAMP INNER PANEL L/R	DO-LH /	1 2	332.10	-664.20	332.10
REAR TAILLAMP L/R	CRA-LH SLR-RH /	2	561.60	1,123.20	
REAR TAILLAMP STAY CLIPS	rec /	4	12.90	51.60	15
REAR TRUNK PANEL	BVC /	1	972.10	972.10	
REAR TRUNK PANEL CARDBOARD COVER	} nn x	1	374.10	374.10	x
REAR TRUNK PANEL INNER GARNISH		1	381.90	381.90	x
REAR TRUNK PANEL UPHOLSTERY MAT		1	374.45	374.45	x
Subtotal before discount				23,650.65	
Percentage discount 25%				5,912.66	
Sub-total 1				17,737.99	
FRONT BUMPER CLIPS SET	rec	1	30.00	30.00	/

**JCN Autolution Pte Ltd**

COMPANY REG NO.: 201813302W

8 Kaki Bukit Ave 4, #07-23, Premier @ Kaki Bukit,
Singapore 415875

+65 6881 1772 sales@jcngroup.com

FRONT BUMPER No.PLATE (EMBOSS)	nn x	1	100.00	100.00	X
FRONT BUMPER No.PLATE GARNISH	nn x	1	50.00	50.00	X
REAR BUMPER CLIPS	nec	1	30.00	30.00	
REAR BUMPER REFLECTOR LAMP(Accessory)	CRA	1	350.00	350.00	150
REAR BUMPER REVERSE CAMERA SET	CRA	1	300.00	300.00	200
REAR BUMPER REVERSE SENSOR SET	Shorted	1	300.00	300.00	200
REAR FENDER WINDSCREEN GLASS SEALANT	nec	1	80.00	80.00	60
REAR TAILGATE No.PLATE	nn x	1	25.00	25.00	X
REAR TAILGATE INNER TRIMBOARD CLIPS SET	nec	1	30.00	30.00	15
REAR TAILGATE No.PLATE GARNISH	nn x	1	50.00	50.00	X
REAR TAILGATE WINDSCREEN GLASS SEALANT	nec	1	80.00	80.00	60
REAR TAILGATE WIPER BLADE	nn x	1	30.00	30.00	X
REAR TRUNK PANEL INSULATOR MAT	nn x	1	300.00	300.00	X
Subtotal before discount				1,755.00	
Percentage discount 0%				0.00	
Sub-total 2				1,755.00	
Parts-total				19,492.99	

LABOUR

Description	Price
TO PROVIDE TOWING CHARGE(3TRIPS),SCENE-WORKSHOP,WORKSHOP-REPORTING CENTRE,REPORTING CENTRE WORKSHOP	150.00 60
TO REMOVE,REINSTALL AIR-CON PARTS,VACUUMS,REFILL AIR-CON GAS.(TO FR)	180.00 X
TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING AND RESETING HEADLAMP FOCUSING.(TO FR)	120.00 20
TO DIAGNOSE,REPLACE AND/OR REPAIR TO RECTIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	100.00 40

**JCN Autolution Pte Ltd**

COMPANY REG NO: 201513258W

8 Kaki Bukit Ave 4, #07-23, Premier @ Kaki Bukit,
Singapore 415875

+65 6881 1772 sales@jcngroup.com

TO REFIX/RENEW REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING	150.00 30
TO REMOVE,REFIX/RENEW REVERSE CAMERA ASSY	100.00 30
TO REMOVE,REINSTALL REAR FENDER GLASS.(TO FR)	120.00 70
TO REMOVE,CHANGE REAR WINDSCREEN.	150.00 100
TO REMOVE,REINSTALL PETROL TANK(TO FR)	80.00 50
TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET(TO FR)	140.00 40
TO REMOVE REAR SEAT,DISMANTLE	120.00 30
TO TRANSFER TAILGATE/BOOTLID MECHANISM AND WIRING ASSY(TO FR)	100.00 50
TO RESPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	2,400.00 1600
TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	80.00 X
TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	2,000.00 1800
TO DISMANTLE,REPAIR AND RE-ALIGN REAR WIPER LINKAGE AND MOTOR ASSY TO PROPER FUNCTIONING	100.00 20
TO REMOVE/RENEW REAR BOOTLID OR TAILGATE SPOILER INCLUDING SEALANT	30.00 ✓
TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	120.00 30

Labour Total**6,240.00****Parts & Labour Total****25,732.99**

page 5

Total - \$12,200/-

Huee Jia - UKK

17/4/19

L/s 9days.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 May 2019		03 May 2019 15:29 Edit Adj Rpt	S\$10,000.00 Edit Estimates	S\$10,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	CHUA SOO TIEN		
Vehicle Reg. No.:	SGX2227R	Date of Loss:	21/03/2019 00:00 - :59 [139 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D201286C02	Policy/Cover Note No.:	DMCVSN16138819033
Vehicle Reg. No. (Insured):	GY3554J	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Jcn Autolotion Pte Ltd (HQ) 8 Kaki Bukit Ave 4 #07-23, Premier@ Kaki Bukit, 415875 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 14/05/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGX2227R (SNM19D201286C02)**
[GY3554J]
TP
CHUA SOO TIEN
Mar 21 2019 12:00AM
[-]
Jcn Autolution Pte Ltd

[Upload Documents](#) [Upload Photos](#) [Compose New Letter](#)

View [View in Browser](#) ▼

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/05/19 15:51	Odometer Reading	 Load JPG	✓
2	03/05/19 15:51	Chassis Number	 Load JPG	✓
3	03/05/19 15:51	General View	 Load JPG	✓
4	03/05/19 15:51	General View	 Load JPG	✓
5	03/05/19 15:51	General View	 Load JPG	✓
6	03/05/19 15:51	General View	 Load JPG	✓
7	03/05/19 15:51	General View	 Load JPG	✓
8	03/05/19 15:51	General View	 Load JPG	✓
9	03/05/19 15:51	General View	 Load JPG	✓
10	03/05/19 15:51	General View	 Load JPG	✓
11	03/05/19 15:51	General View	 Load JPG	✓
12	03/05/19 15:51	General View	 Load JPG	✓
13	03/05/19 15:51	General View	 Load JPG	✓
14	03/05/19 15:51	General View	 Load JPG	✓
15	03/05/19 15:51	General View	 Load JPG	✓
16	03/05/19 15:51	General View	 Load JPG	✓
17	03/05/19 15:51	General View	 Load JPG	✓
18	03/05/19 15:51	General View	 Load JPG	✓
19	03/05/19 15:51	General View	 Load JPG	✓
20	03/05/19 15:51	General View	 Load JPG	✓
21	03/05/19 15:51	General View	 Load JPG	✓
22	03/05/19 15:51	General View	 Load JPG	✓
23	03/05/19 15:51	General View	 Load JPG	✓
24	03/05/19 15:51	General View	 Load JPG	✓
25	03/05/19 15:51	General View	 Load JPG	✓
26	03/05/19 15:51	General View	 Load JPG	✓
27	03/05/19 15:51	General View	 Load JPG	✓
28	03/05/19 15:51	General View	 Load JPG	✓
29	03/05/19 15:51	General View	 Load JPG	✓
30	03/05/19 15:51	General View	 Load JPG	✓
31	03/05/19 15:51	General View	 Load JPG	✓
32	03/05/19 15:51	General View	 Load JPG	✓
33	03/05/19 15:51	General View	 Load JPG	✓
34	03/05/19 15:51	General View	 Load JPG	✓
35	03/05/19 15:51	General View	 Load JPG	✓

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	03/05/19 15:51	General View	 Load JPG	☒
37	03/05/19 15:51	General View	 Load JPG	☒
38	03/05/19 15:51	General View	 Load JPG	☒
39	03/05/19 15:51	General View	 Load JPG	☒
40	03/05/19 15:51	General View	 Load JPG	☒
41	03/05/19 15:51	General View	 Load JPG	☒
42	03/05/19 15:51	General View	 Load JPG	☒
43	03/05/19 15:51	General View	 Load JPG	☒
44	03/05/19 15:51	General View	 Load JPG	☒
45	03/05/19 15:51	General View	 Load JPG	☒
46	03/05/19 15:51	General View	 Load JPG	☒
47	03/05/19 15:51	General View	 Load JPG	☒
48	03/05/19 15:51	General View	 Load JPG	☒
49	03/05/19 15:51	General View	 Load JPG	☒
50	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
51	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
52	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
53	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
54	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
55	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
56	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
57	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
58	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
59	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
60	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
61	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
62	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
63	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
64	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
65	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
66	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
67	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
68	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
69	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
70	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
71	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
72	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
73	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
74	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
75	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
76	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
77	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
78	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
79	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
80	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
81	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
82	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
83	03/05/19 15:54	Reinspection Photo	Load JPG	☒

Photos/Images			3 per page ▾	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
85	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
86	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
87	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
88	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
89	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
90	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
91	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
92	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
93	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
94	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
95	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
96	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
97	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
98	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
99	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
100	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
101	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
102	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
103	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
104	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
105	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
106	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
107	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
108	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
109	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
110	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
111	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
112	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
113	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
114	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
115	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
116	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
117	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
118	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
119	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
120	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
121	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
122	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
123	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
124	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
125	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
126	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
127	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
128	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
129	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
130	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
131	03/05/19 15:54	Reinspection Photo	Load JPG	☒

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
132	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
133	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
134	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
135	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
136	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
137	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
138	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
139	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
140	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
141	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
142	03/05/19 15:54	Reinspection Photo	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/05/19 15:30	PRI CONTACT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119005271/JQD3S2

Date: 09/05/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN16138819033
Claimant Vehicle No :	SGX2227R	Insured Vehicle No :	GY3554J
Date of Loss:	21/03/2019	Nature of Claim:	TP
		Claim No:	SNM19D201286C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGX2227R	Engine No:	1ZZ2939697
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100374013
Reg. Date:	16/08/2007 (Man. Year: 2007)	Odometer:	367888 km
Colour:	Grey		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,492.99	11,355.36	8,137.63	41.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,240.00	4,000.00	2,240.00	35.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,732.99	15,355.36	10,377.63	40.33
Approved Total (Overridden) (S\$)		10,000.00		
Nett Amount (S\$)	25,732.99	10,000.00	15,732.99	61.14

INSPECTION

Date of Assignment:	03/05/2019		
Date Inspected:	25/03/2019	Inspected At:	39 WOODLAND CLOSE #01-34/35
Estimated Period of Repair:	9.0 days		Repairer: Jcn Autolution Pte Ltd

Adjuster: ONG HWEE JIE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2019)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGX2227R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	731.35 FL	*731.35 FL
2	2		*FRONT BONNET HINGE	Not Necessary	342.20 FL	*- FL
3	1		*FRONT BONNET INSULATOR MAT CLIPS @\$12.40 (11 PCS)	Necessary	136.40 FL	*20.00 FL
4	1		*FRONT BONNET MECHANISM LOCK	Serviceable	181.10 FL	*- FL
5	2		*FRONT BONNET RUBBER GUIDE STOPPER @\$43.10	Not Necessary	86.20 FL	*- FL
6	1		*FRONT BONNET RUBBER WEATHER STRIP	Not Necessary	171.25 FL	*- FL
7	1		*FRONT BUMPER	Deformed	481.10 FL	*481.10 FL
8	2		*FRONT BUMPER SIDE RETAINER L/R @\$171.10	Not Necessary	342.20 FL	*- FL
9	1		*FRONT CENTER BRACE PANEL	Repair	171.85 FL	*- FL
10	1		*FRONT CENTER BRACE PANEL CLIP	Not Necessary	12.90 FL	*- FL
11	1		*FRONT GRILLE	Cracked	231.35 FL	*231.35 FL
12	2		*FRONT GRILLE CLIPS @\$12.90	Not Necessary	25.80 FL	*- FL
13	2		*FRONT HEADLAMP L/R @\$972.85	Cracked	1,945.70 FL	*1,400.00 FL
14	1		*FRONT SUPPORT PANEL	Not Necessary	972.10 FL	*- FL
15	1		*REAR BUMPER	Deformed	471.10 FL	*471.10 FL
16	2		*REAR BUMPER CORNER RETAINER L/R @\$131.25	Not Necessary	262.50 FL	*- FL
17	2		*REAR BUMPER IMPACT BRACKET L/R @\$175.10	N/S Bent	350.20 FL	*175.10 FL
18	2		*REAR BUMPER SIDE RETAINER L/R @\$171.15	Cracked	342.30 FL	*342.30 FL
19	1		*REAR END PANEL	Buckled	581.10 FL	*581.10 FL
20	1		*REAR END PANEL INNER TOP GARNISH	Cracked	374.45 FL	*374.45 FL
21	1		*REAR EXHAUST PIPE	Not Necessary	731.25 FL	*- FL
22	1		*REAR EXHAUST PIPE RUBBER MOUNTING	Not Necessary	61.10 FL	*- FL
23	6		*REAR FENDER INNER SHIELD CLIPS @\$12.90	Not Necessary	77.40 FL	*- FL
24	2		*REAR FENDER INNER SHIELD L/R @\$182.10	Not Necessary	364.20 FL	*- FL
25	2		*REAR FENDER INNER TRIMBOARD (LOWER) L/R @\$374.45	Not Necessary	748.90 FL	*- FL
26	2		*REAR FENDER INNER TRIMBOARD (UPPER) L/R @\$741.25	Cracked	1,482.50 FL	*1,350.00 FL
27	1		*REAR FENDER LH	Buckled	972.10 FL	*840.00 FL
28	1		*REAR FENDER WINDSCREEN GLASS RUBBER MOULDING	Necessary	50.00 FL	*50.00 FL
29	1		*REAR TAILGATE	Buckled	1,217.45 FL	*1,217.45 FL
30	1		*REAR TAILGATE LOGO EMBLEM	Necessary	61.10 FL	*61.10 FL
31	2		*REAR TAILGATE DAMPER L/R @\$372.10	Not Necessary	744.20 FL	*- FL
32	2		*REAR TAILGATE HINGE L/R @\$171.45	Not Necessary	342.90 FL	*- FL
33	1		*REAR TAILGATE INNER TRIMBOARD	Cracked	781.90 FL	*781.90 FL
34	1		*REAR TAILGATE INNER TRIMBOARD INNER HANDLE	Not Necessary	121.10 FL	*- FL
35	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	43.75 FL	*- FL
36	1		*REAR TAILGATE MECHANISM LOCK	Jammed	561.60 FL	*561.60 FL
37	1		*REAR TAILGATE NO. PLATE LAMP CHROME GARNISH	Cracked	374.45 FL	*374.45 FL
38	4		*REAR TAILGATE NO. PLATE LAMP CHROME GARNISH CLIPS @\$12.90	Necessary	51.60 FL	*15.00 FL
39	2		*REAR TAILGATE NO. PLATE LAMP L/R @\$121.25	Not Necessary	242.50 FL	*- FL
40	2		*REAR TAILGATE RUBBER GUIDE STOPPER @\$43.75	Not Necessary	87.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*REAR TAILGATE RUBBER WEATHER STRIP	Cut	371.85 FL	*371.85 FL
42	1		*REAR TAILGATE WINDSCREEN GLASS	Cracked	972.45 FL	*972.45 FL
43	1		*REAR TAILGATE WINDSCREEN GLASS RUBBER MOULDING	Necessary	180.00 FL	*180.00 FL
44	1		*REAR TAILGATE WIPER ARM	Not Necessary	171.45 FL	*- FL
45	1		*REAR TAILGATE WIPER ARM COVER	Scratched	121.10 FL	*121.10 FL
46	1		*REAR TAILGATE WIPER MOTOR	Serviceable	561.60 FL	*- FL
47	2		*REAR TAILLAMP INNER PANEL L/R @\$332.10	N/S Dented	664.20 FL	*332.10 FL
48	2		*REAR TAILLAMP L/R @\$561.60	N/S Cracked / O/S Scratched	1,123.20 FL	*1,123.20 FL
49	4		*REAR TAILLAMP STAY CLIPS @\$12.90	Necessary	51.60 FL	*15.00 FL
50	1		*REAR TRUNK PANEL	Buckled	972.10 FL	*972.10 FL
51	1		*REAR TRUNK PANEL CARDBOARD COVER	Not Necessary	374.10 FL	*- FL
52	1		*REAR TRUNK PANEL INNER GARNISH	Not Necessary	381.90 FL	*- FL
53	1		*REAR TRUNK PANEL UPHOLSTERY MAT	Not Necessary	374.45 FL	*- FL
54	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
55	1		*FRONT BUMPER NO. PLATE (EMBOSS)	Not Necessary	100.00 FS	*- FS
56	1		*FRONT BUMPER NO. PLATE GARNISH	Not Necessary	50.00 FS	*- FS
57	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
58	1		*REAR BUMPER REFLECTOR LAMP (ACCESSORY)	Cracked	350.00 FS	*150.00 FS
59	1		*REAR BUMPER REVERSE CAMERA SET	Cracked	300.00 FS	*200.00 FS
60	1		*REAR BUMPER REVERSE SENSOR SET	Shorted	300.00 FS	*200.00 FS
61	1		*REAR FENDER WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*60.00 FS
62	1		*REAR TAILGATE NO. PLATE	Not Necessary	25.00 FS	*- FS
63	1		*REAR TAILGATE INNER TRIMBOARD CLIPS SET	Necessary	30.00 FS	*15.00 FS
64	1		*REAR TAILGATE NO. PLATE GARNISH	Not Necessary	50.00 FS	*- FS
65	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*60.00 FS
66	1		*REAR TAILGATE WIPER BLADE	Not Necessary	30.00 FS	*- FS
67	1		*REAR TRUNK PANEL INSULATOR MAT	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **25,405.65** **14,892.15**
 - List Item Discount on L Items 25.00/25.00% (S\$) 5,912.66 3,536.79

Total Parts (S\$) 19,492.99 11,355.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING CHARGE (3 TRIPS), SCENE-WORKSHOP, WORKSHOP-REPORTING CENTRE, REPORTING CENTRE-WORKSHOP.	New	150.00	60.00
2	TO REMOVE, REINSTALL AIR-CON PARTS, VACUUMS, REFILL AIR-CON GAS. (TO FR)	New	180.00	0.00
3	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING. (TO FR)	New	120.00	20.00
4	TO DIAGNOSE, REPLACE AND/OR REPAIR TO RECTIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	New	100.00	40.00
5	TO REFIX/RENEW REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING.	New	150.00	30.00
6	TO REMOVE, REFIX/RENEW REVERSE CAMERA ASSY.	New	100.00	30.00
7	TO REMOVE, REINSTALL REAR FENDER GLASS. (TO FR)	New	120.00	70.00
8	TO REMOVE, CHANGE REAR WINDSCREEN.	New	150.00	100.00
9	TO REMOVE, REINSTALL PETROL TANK. (TO FR)	New	80.00	50.00
10	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR).	New	140.00	40.00
11	TO REMOVE REAR SEAT, DISMANTLE.	New	120.00	30.00
12	TO TRANSFER TAILGATE/BOOTLID MECHANISM AND WIRING ASSY (TO FR).	New	100.00	50.00
13	TO RESPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.	New	2,400.00	1,600.00
14	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.	New	80.00	0.00
15	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	2,000.00	1,800.00
16	TO DISMANTLE, REPAIR AND RE-ALIGN REAR WIPER LINKAGE AND MOTOR ASSY TO PROPER FUNCTIONING	New	100.00	20.00
17	TO REMOVE/RENEW REAR BOOTLID OR TAILGATE SPOILER INCLUDING SEALANT.	New	30.00	30.00
18	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	New	120.00	30.00
Gross Labour Cost (\$\$)			6,240.00	4,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >