

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5760X**AAD1903-155***Not Authored**21 Rmp 8**Book Value?*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5760X

VF1ABL15AUC281647

RENAULT

LATITUDE

20.3.2019

AXA

26/6/2015

PART**LIST**

1	1 BUMPER COVER REAR	\$	<i>R₁</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>mi</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>cm</i> 113.47 ✓
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>D₁</i> 135.97 ✓
5	1 BUMPER RETAINER RH REAR	\$	<i>D₁</i> 44.99 ✓
6	1 BUMPER REFLECTOR RH	\$	<i>sn</i> 43.61 X
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>D₁</i> 135.97 ✓
8	1 BUMPER RETAINER LH REAR	\$	<i>D₁</i> 44.99 ✓
9	1 BUMPER REFLECTOR LH	\$	<i>cm</i> 43.61 ✓
10	1 BUMPER BEAM REAR	\$	<i>R₁</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R₁</i> 225.95 ✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>D₁</i> 225.95 ✓
13	1 BOOT REAR	\$	<i>R₁</i> 2,872.68 ✓
14	1 BOOT FINISHER	\$	<i>sn</i> 470.06 X
15	1 BOOT WHEATERSTRIP	\$	<i>D₁/L₁</i> 323.05 ✓
16	1 BOOT REFLECTOR LAMP LH	\$	<i>cm</i> 493.35 ✓
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Br</i> 493.35 ✓
18	1 BOOT BADGE 'RENAULT'	\$	<i>me</i> 225.36 ✓
19	1 BOOT BADGE	\$	<i>me</i> 225.36 ✓
20	1 BOOT STRUT LH	\$	<i>sn</i> 276.08 X
21	1 BOOT STRUT RH	\$	<i>sn</i> 276.08 X
22	1 BOOT HINGE LH	\$	<i>re</i> 367.84 X
23	1 BOOT HINGE RH	\$	<i>re</i> 367.84 X
24	1 BOOT INNER TRIM	\$	<i>Debum</i> 586.45 ✓
25	1 BOOT SWITCH	\$	<i>sn</i> 168.13 X
26	1 BOOT LOCK	\$	<i>re</i> 202.67 ✓
27	1 BOOT LOCK CATCH	\$	<i>re</i> 74.40 X
28	2 LICENCE PLATE LAMP	\$	<i>sn</i> 50.52 X
29	2 BOOT RUBBER PLUG	\$	<i>sn</i> 221.81 X

Trans-cab Auto Services Pte Ltd**AAD1903-155**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5760X

30	1 FENDER PANEL INNER TRIM REAR LH
31	1 FENDER PANEL REAR LH
32	1 WHEELARCH REAR LH
33	1 FENDER PANEL INNER TRIM REAR RH
34	1 FENDER PANEL REAR RH
35	1 WHEELARCH REAR RH
36	1 TAILLAMP RH
37	1 TAILLAMP PANEL RH
38	1 TAILLAMP LH
39	1 TAILLAMP PANEL LH
40	1 OUTER PANEL REAR (End Panel)
41	1 OUTER PANEL REAR (End Panel)TRIM
42	1 SPARE WHEEL PANEL (Luggage Floor Panel)
43	1 SPARE WHEEL PANEL TRIM
44	1 EXHAUST REAR
45	1 EXHAUST CAP REAR
46	1 FUEL FLAP L70Y
47	1 WHEEL HOUSING PANEL REAR LH
48	1 BUMPER COVER FRT
49	1 BUMPER SPOILER FRT
50	1 BUMPER ABSORBER FRT
51	1 BUMPER RETAINER FRT LH
52	1 BUMPER SUPPORT FRT
53	1 BUMPER RETAINER FRT RH
54	1 BUMPER SUPPORT FRT
55	1 BUMPER UNDERTRAY FRT
56	1 BUMPER GRILLE LOWER FRT
57	1 BUMPER FOG LAMP GRILLE LH
58	1 BUMPER FOG LAMP GRILLE RH
59	1 BUMPER BEAM FRT
60	1 TOW COVER FRT
61	1 RADIATOR GRILLE
62	1 RADIATOR GRILLE BADGE 'RENAULT'
63	1 RADIATOR GRILLE FRAME
64	1 FRAME FULL SUPPORT PANEL
65	1 FRAME FULL SUPPORT BRACKET
66	1 FRONT BRACE PANEL

\$	<i>Return</i>	671.45	✓
\$	<i>Bu</i>	3,299.13	✓
\$	<i>Sn</i>	543.47	X
\$	<i>Sn</i>	671.45	X
\$	<i>Bu</i>	3,299.13	✓
\$	<i>Sn</i>	543.47	X
\$	<i>CM</i>	552.55	✓
\$	<i>R</i>	986.70	X
\$	<i>Bu</i>	552.55	✓
\$	<i>R</i>	986.70	✓
\$	<i>R</i>	1,471.77	✓
\$	<i>nd</i>	404.56	✓
\$	<i>Bu</i>	2,189.88	✓
\$	<i>Return</i>	612.21	✓
\$	<i>R</i>	7,489.05	X
\$	<i>R</i>	230.49	X
\$	<i>Sn</i>	343.57	X
\$		4,682.09	?
\$	<i>Bu</i>	1,259.42	✓
\$	<i>Dis</i>	181.75	✓
\$	<i>CM</i>	394.68	✓
\$	<i>Dis</i>	151.41	✓
\$	<i>Sn</i>	123.88	X
\$	<i>Dis</i>	150.77	✓
\$	<i>Sn</i>	123.88	X
\$	<i>Sn</i>	472.83	X
\$	<i>Dis</i>	266.80	✓
\$	<i>Sn</i>	207.21	X
\$	<i>Sn</i>	207.21	X
\$		914.08	?
\$	<i>Sn</i>	28.61	X
\$	<i>mycm</i>	1,707.78	✓
\$	<i>R</i>	225.36	✓
\$	<i>CM</i>	1,353.75	✓
\$	<i>Sn</i>	615.90	X
\$	<i>R</i>	89.79	X
\$	<i>R</i>	177.22	X

Trans-cab Auto Services Pte Ltd**AAD1903-155**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5760X

67	1 HORN	\$	Sm 314.17
68	1 HORN BRACKET	\$	N 40.45
69	1 HEADLAMP LH	\$	Sm 1,184.43
70	1 HEADLAMP RH	\$	Sm 1,184.43
71	1 HEADLAMP PANEL FRT LH	\$	N 152.15
72	1 HEADLAMP PANEL FRT RH	\$	N 152.15
73	1 BONNET	\$	N 1,941.63
74	1 BONNET INSULATOR	\$	Sm 405.73
75	1 BONNET STRUT LH	\$	Sm 88.61
76	1 BONNET STRUT RH	\$	Sm 88.61
77	1 BONNET HINGE LH	\$	N 348.31
78	1 BONNET HINGE RH	\$	N 348.31
79	1 BONNET LOCK	\$	N 305.48
80	1 BONNET CABLE	\$	Sm 119.19
81	1 BONNET CABLE COVER	\$	Sm 161.03
82	1 BONNET SEAL OUTER	\$	Sm 92.36
83	1 BONNET SEAL INNER	\$	Sm 157.28
84	1 FENDER PANEL FRT LH	\$	N 783.83
85	1 WHEELARCH FRT LH	\$	Sm 278.84
86	1 FENDER BRACKET LOWER LH	\$	Sm 15.79
87	1 FENDER INSULATOR LH	\$	Sm 130.84
88	1 FENDER INSULATOR RH	\$	Sm 130.84
89	1 AIR CLEANER LOWER	\$	Sm 271.26
90	1 AIR CLEANER HOSE	\$	Sm 76.14
91	1 BASE BATTERY TRAY	\$	Sm 363.40
92	1 AIR CLEANER BOX	\$	Sm 464.20
93	1 TURBO DUCT	\$	Sm 1,027.80
94	1 A/C HEATER VALVE	\$	Sm 484.50
95	1 SUBFRAME OUTER FRT	\$	Sm 2,652.45
96	1 SUBFRAME BRACKET OUTER LH	\$	Sm 92.36
97	1 ENGINE UNDERTRAY	\$	Sm 564.98
98	1 A/C CONDENSER	\$	Sm 2,020.37
99	1 A/C CONDENSER GARNISH LH UPPER	\$	Sm 39.67
100	1 A/C CONDENSER GARNISH RH UPPER	\$	Sm 39.67
101	1 A/C CONDENSER GARNISH LH	\$	Sm 58.81
102	1 A/C CONDENSER GARNISH RH	\$	Sm 59.60
103	1 A/C PIPE CONDENSER TO COMPRESSOR	\$	Sm 208.39
104	1 A/C PIPE CONDENSER TO EXPENSION VALVE	\$	Sm 658.72

Trans-cab Auto Services Pte Ltd

AAD1903-155

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5760X

105	1 A/C PIPE COMPRESSOR	\$	334.29	}
106	1 A/C PIPE	\$	658.72	
107	1 A/C COMPRESSOR	\$	2,684.61	
108	1 AIR COOLER	\$	792.60	
109	1 AIR INTERCOOLER HOSE (LONG)	\$	1,014.13	
110	1 AIR INTERCOOLER HOSE (Short)	\$	375.14	
111	1 TRANSMISSION COOLER	\$	1,219.30	
112	1 TRANSMISSION COOLER PAD	\$	17.96	
113	1 RADIATOR	\$	1,202.20	
114	2 RADIATOR STUD UPPER	\$	14.41	
115	2 RADIATOR BUSH UPPER	\$	50.12	
116	2 RADIATOR MTG LOWER	\$	55.85	
117	1 RADIATOR FAN COWLING	\$	820.54	
118	1 RADIATOR FAN MOTOR LH	\$	967.36	
119	1 RADIATOR FAN MOTOR RH	\$	1,479.46	
120	1 RADIATOR TANK	\$	324.62	}
121	1 RADIATOR HOSE UPPER	\$	240.56	
122	1 RADIATOR HOSE LOWER	\$	491.18	
123	1 RADIATOR TANK HOSE	\$	61.18	

TOTAL	\$	79,857.93
10%	\$	7,985.79
	\$	71,872.13

Special Nett

1	1SET PARKING AID	\$	700.00	Short	Goosa
2	1SET REAR BUMPER CLIP	\$	66.00	na	—
3	1SET BUMPER BRACKET CTR CLIP	\$	33.00	na	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	na	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	20.00	na	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	na	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	20.00	na	X
8	1SET BUMPER LOWER REAR RIVET	\$	22.00	na	X
9	1SET BUMPER LOWER REAR CLIP	\$	66.00	na	—
10	1 EXHAUST MOUNTING REAR	\$	17.82	na	X
11	1SET BOOT FINISHER CLIP	\$	24.20	na	X
12	1 BOOT STICKER "Trans-cab"	\$	30.00	na	✓

Trans-cab Auto Services Pte Ltd

AAD1903-155

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5760X

13	1 BOOT STICKER "6555-3333"	\$	30.00	✓
14	1 BOOT INNER TRIM CLIP	\$	45.00	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	35.00	X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	35.00	X
17	1 FENDER INNER TRIM CLIP LH	\$	28.00	✓
18	1 FENDER INNER TRIM CLIP RH	\$	28.00	X
19	1 TAILLAMP CLIP RH	\$	5.00	✓
20	1 TAILLAMP CLIP LH	\$	5.00	✓
21	2 REAR WINDSCREEN SELANT	\$	80.00	40ea
22	1 WINDSCREEN MOULDING	\$	100.00	✓
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	30ea
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	385.00	X
25	1 SPARE TYRE	\$	330.00	X
26	1SET RADIATOR GRILLE FRAME CLIP	\$	52.00	X
27	1SET BUMPER CLIP FRT	\$	66.00	✓
28	1 BUMPER BRACKET CLIP FRT LH	\$	12.00	} X
29	1 BUMPER SUPPORT CLIP FRT LH	\$	10.50	
30	1 BUMPER BRACKET CLIP FRT RH	\$	12.00	
31	1 BUMPER SUPPORT CLIP FRT RH	\$	10.50	
32	1 TOW COVER FRT	\$	14.50	
33	1SET RADIATOR GRILLE SCREW	\$	16.00	
34	1SET BUMPER GRILLE LOWER CLIP	\$	69.00	
35	1SET FRAME FULL SUPPORT PANEL CLIP	\$	70.00	
36	2 FRAME FULL SUPPORT PANEL NUT	\$	20.00	}
37	2 FRAME FULL SUPPORT PANEL STUD	\$	30.00	
38	1 Windscreen moulding	\$	100.00	✓
39	1SET Front licence plate with holder	\$	80.00	45ea

TOTAL \$ 2,787.52

TOTAL PARTS \$ 74,659.65

LABOUR

Putty And Spray Painting Of The Affected Portion.

\$

6,000.00

17602

Trans-cab Auto Services Pte Ltd**AAD1903-155**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5760X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	2500/
To Rust-Proofing Of The Affected Areas.	\$	170.00	120/
To reinstall rear bumper parking sensor.	\$	170.00	60/
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60/
To repair and realign rear exhaust pipe.	\$	170.00	} 80/
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 100/
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	80/
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	120/
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	~ 380.00	X
Towing Fees.	\$	120.00	50/

Trans-cab Auto Services Pte Ltd**AAD1903-155**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5760X

To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i>	380.00	X
To rust-proofing of the affected areas.	\$	<i>Repair</i>	170.00	X
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	<i>↪</i>	380.00	X
To check steering geometry and computer wheel alignment	\$	<i>↪</i>	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>↪</i>	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	<i>401</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$		380.00	} <i>2501</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$		380.00	
To lift-up engine with gear box and refit.	\$	<i>nn</i>	440.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	<i>↪</i>	440.00	X
To remove and refit air bag system and reset.	\$	<i>↪</i>	480.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	<i>↪</i>	380.00	X
To vacuum, replace, refix and recharge air condenser	\$	<i>↪</i>	380.00	X
To replace, refix and top up coolant for radiator	\$	<i>↪</i>	170.00	X

Trans-cab Auto Services Pte Ltd**AAD1903-155**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5760X

To vacuum, replace, refix and recharge Air
Intercooler

\$ *nn* 170.00 X

To Transfer Of Fender Fittings, Attachments And
Perform Water Seepage Test.

\$ *nn* 170.00 X**TOTAL \$ 19,720.00****Over All Total \$ 94,379.65****(LUMP SUM)****Repair Days*****30 DAYS****20 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: