

HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075
Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X

Your Ref:
Our Ref : 0630/03/19
M/s : INDIA INTERNATIONAL INSURANCE P.LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
Attn : MOTOR CLAIM DEPARTMENT

Page: 1
Date: 20/03/2019

Dear Sir/Madam,

ACCIDENT REPAIR ON : SKQ6975C - QASHQAI 0
INSURED : BOLT CAR LEASING PTE LTD
DATE OF ACCIDENT : 15/03/2019
YOUR INSURED VEH NO: GBB7143R

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

		S\$	S\$	S\$
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN SEAL RUBBER <i>rec</i>	1 @	60.20	60.20
2	BOOT <i>dt</i>	1 @	2,936.80	2,936.80
3	BOOT LAMP <i>ca - RH</i>	<i>1pc</i> 2 @	215.90	431.80
4	BOOT NISSAN LOGO <i>rec</i>	1 @	59.70	59.70
5	BOOT NAME PLATE QASHQAI <i>rec</i>	1 @	87.00	87.00
6	BOOT NAME PLATE XTRONIC CVT <i>rec</i>	1 @	73.60	73.60
7	BOOT LOCK <i>dt</i>	1 @	116.70	116.70
8	BOOT WEATHERSTRIP <i>rec</i>	1 @	158.70	158.70
9	BOOT OUTER GARNISH <i>dt</i>	1 @	336.00	336.00
10	REAR BOOT HINGE RH/LH <i>X</i>	2 @	39.60	79.20
11	REAR BOOT ABSORBER RH/LH <i>X</i>	2 @	209.80	419.60
12	REAR END PANEL <i>repair</i>	1 @	482.60	482.60
13	END PANEL TRIM ?	1 @	63.50	63.50
14	REAR LAMP <i>X</i>	2 @	323.70	647.40
15	REAR BUMPER <i>dt</i>	1 @	717.00	717.00
16	REAR BUMPER REINFORCEMENT <i>dt</i>	1 @	619.20	619.20
17	REAR BUMPER SPONGE ?	1 @	126.40	126.40
18	REAR BUMPER REFLECTOR ?	1 @	55.00	55.00
19	REAR BUMPER SIDE RETAINER <i>X</i>	2 @	35.90	71.80
20	REAR BUMPER BRACKET <i>rec</i>	2 @	126.00	252.00
21	TOW COVER <i>mis</i>	1 @	26.80	26.80
Total				7,821.00
*SPECIAL NETT				
22	PARKING SENSOR 1 SET ?	1 @	320.00	320.00 220
23	WINDSCREEN SEALANT <i>rec</i>	1 @	60.00	60.00 40
24	REAR LICENCE PLATE WITH COVERING <i>su</i>	1 @	45.00	45.00 35

LABOUR CHARGES

1 CUT/WELD REAR END PANEL; REPLACE/

~~1,200.00~~ 600

HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075
Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X

Your Ref:
Our Ref : 0630/03/19

Page: 2
Date: 20/03/2019

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

	S\$	S\$	S\$
1 ALIGN NEW PARTS; REMOVE/REFIT ALL			
1 ATTACHMENT PARTS TO FACILITATE REPAIR			
2 TO REMOVE/REFIT REAR WINDSCREEN GLASS	180.00	120	
3 TO TRANSFER BOOT MECHANISM, SPOILER,	150.00	120	
3 REAR WIPER MOTOR ETC.		80	
4 REMOVE/REFIT REAR END PANEL LINING	150.00	60	
4 AND GARNISH TO FACILITATE REPAIR.			
5 SPRAY PAINT ON THE EFFECTED AREAS	1,000.00	600	
5 WITH 2K PAINT.		800	
6 CHECK ELECTRICAL WIRING	40.00		
7 CORROSION PROTECTION	200.00	80	

Nett Total Before GST

11,166.00

Yours faithfully,



(Workshop Manager)

Rasul
Hy 90010068
6 days

L/S

22/03/19 @ 1430

Resy after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: