

PSMO Form

# HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075  
Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X

Your Ref:   
Our Ref: 0630/03/19  
M/s: INDIA INTERNATIONAL INSURANCE P.LTD  
64 CECIL STREET  
#04/#05 IOB BUILDING  
SINGAPORE 049711  
Attn: NEWARK CLAIM DEPARTMENT

Page: 1  
Date: 20/03/2019

Work Order/Invoice

ACCIDENT REPAIR ON: SK06975C - QASHQAI 0 2014/Dec 32W F8A JIM  
INSURED: BOLT CAR LEASING PTE LTD  
DATE OF ACCIDENT: 15/03/2019  
YOUR INSURED VEH NO: CBH7143R

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

## REPLACEMENT OF PARTS

- 1 REAR WINDSCREEN SEAL RUBBER *rec*
- 2 BOOT *7+*
- 3 BOOT LAMP *CEA - RH*
- 4 BOOT HISSAN LOCK *rec*
- 5 BOOT NAME PLATE QASHQAI *rec*
- 6 BOOT NAME PLATE XTRONIC *CVT rec*
- 7 BOOT LOCK *BT*
- 8 BOOT WEATHERSTRIP *rec*
- 9 BOOT OUTER GAELISH *DE*
- 10 REAR BOOT HINGE RH/LH *X SVL*
- 11 REAR BOOT ABSORBER RH/LH *X SVL*
- 12 REAR END PANEL *repair BT*
- 13 END PANEL TRIM *?*
- 14 REAR LAMP *X SVL*
- 15 REAR BUMPER *DE*
- 16 REAR BUMPER REINFORCEMENT *BT*
- 17 REAR BUMPER SPONGE *? CEA*
- 18 REAR BUMPER REFLECTOR *? X SVL*
- 19 REAR BUMPER SIDE RETAINER *X SVL*
- 20 REAR BUMPER BRACKET *rec*
- 21 TOW COVER *M13*

|    | SS                    | SS       | SS |
|----|-----------------------|----------|----|
| 1  | 1 @ 60.20             | 60.20    |    |
| 2  | 1 @ 2,936.80          | 2,936.80 |    |
| 3  | 1 @ <del>435.80</del> | 431.80 X |    |
| 4  | 1 @ 59.70             | 59.70    |    |
| 5  | 1 @ 87.00             | 87.00    |    |
| 6  | 1 @ 73.50             | 73.50    |    |
| 7  | 1 @ 116.70            | 116.70   |    |
| 8  | 1 @ 158.70            | 158.70   |    |
| 9  | 1 @ 336.00            | 336.00   |    |
| 10 | 2 @ 39.60             | 79.20 X  |    |
| 11 | 2 @ 209.80            | 419.60 X |    |
| 12 | 1 @ 482.50            | 482.50   |    |
| 13 | 1 @ 63.50             | 63.50 X  |    |
| 14 | 2 @ 323.70            | 647.40 X |    |
| 15 | 1 @ 717.00            | 717.00   |    |
| 16 | 1 @ 619.20            | 619.20   |    |
| 17 | 1 @ 126.40            | 126.40   |    |
| 18 | 1 @ 55.00             | 55.00 X  |    |
| 19 | 2 @ 35.90             | 71.80 X  |    |
| 20 | 2 @ 126.00            | 252.00   |    |
| 21 | 1 @ 26.80             | 26.80    |    |

6268.60  
30%  
4388.02

Total

7,821.00

## \*SPECIAL NETT

- 22 PARKING SENSOR 1 SET *? rec*
- 23 WINDSCREEN SEALANT *rec*
- 24 REAR LICENCE PLATE WITH COVERING *SVL*

|            |        |
|------------|--------|
| 1 @ 320.00 | 320.00 |
| 1 @ 60.00  | 60.00  |
| 1 @ 45.00  | 45.00  |

220  
40  
35  
295

## LABOUR CHARGES

- 1 CUT/WELD REAR END PANEL; REPLACE/

1,200.00 600

Steve 2/4/19

Ref

# HIN LUNG WORKSHOP

814-1008 Bukit Merah Lane 3 #01-20, Singapore 150722. Tel: 65583000 Fax: 64760075  
 Website: [www.hinlung.com.sg](http://www.hinlung.com.sg) GST Regn. No: M2-0065859-X

Your Ref:  
 Our Ref : 0630/03/19

Page: 2  
 Date: 20/03/2019

ATTENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

|                                          | S\$ | S\$ | S\$       |
|------------------------------------------|-----|-----|-----------|
| 1. ALIGN NEW PARTS; REMOVE/REFIT ALL     |     |     |           |
| 1. ATTACHMENT PARTS TO FACILITATE REPAIR |     |     |           |
| 2. TO REMOVE/REFIT REAR WINDSCREEN GLASS |     |     |           |
| 3. TO TRANSFER BOOT MECHANISM, SPOILER,  |     |     |           |
| 3. REAR WIPER MOTOR ETC.                 |     |     |           |
| 4. REMOVE/REFIT REAR END PANEL LINING    |     |     |           |
| 4. AND GARNISH TO FACILITATE REPAIR...   |     |     |           |
| 5. SPRAY PAINT ON THE EFFECTED AREAS     |     |     |           |
| 5. WITH 2K PAINT                         |     |     |           |
| 6. CHECK ELECTRICAL WIRING               |     |     |           |
| 7. CORROSION PROTECTION                  |     |     |           |
| Nett Total Before GST                    |     |     | 11,166.00 |

150.00 ~~120~~  
 150.00 ~~120~~  
 80  
 150.00 60  
 1,000.00 ~~600~~  
 800  
 40.00  
 200.00 80

Yours faithfully,

*[Signature]*

(Workshop Manager)

*Rasul*

Hp 90010068

6 days

L/S

22/03/19 @ 1430

Rosy after repair

4388.02  
 295.00  
 1780.00  
 6463.02  
 20%  
 5170.41  
 43-5,150  
 6 days