

ASS. REC. BY:

REF: CS/SMO/1905283/TIV d372 Special Instruction:

Surveyor: Taufiqh ASSIGNMENT (Office)

From (Person): Hwang Shing Yi of SMO Date/Time: 25/3/19 @ 1:31pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKT 8684M Insured: YP 6298M

at Workshop m/s: Auto Wheels Tel: 9192 8963

of No. 1 Bukit Batok Crescent #02-40

Policy No: D18MTPCVE001573 Claim No: CMTDI 901488

Sum Insured: Excess:

Make of Veh: D.O.A. 22/03/2019

(Client's Record) 26/3/2019

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 2:11pm @ 28/3/19 Person Contacted: Louis Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	SKT 8684M-X
	YP 6298M-X
29/3/19	Send preli revised via merimen
4/4/19	LS \$5100 Confirmed by email (Red 828448, 6298)

Signature: Taufik


REF: SMO

ASSIGNMENT

From: Date: 26/3/19
Estimated Cost:
OD / (TP) WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SKT 8684M
at Workshop m/s: Auto wheels
of No. 1 Bukit Bontok Crescent # 02-40
Insured:
Policy No.
Claims No.
Sum Insured: Excess:

(Client's Record)
Make of Veh: Louis @ 9192 8963

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 457K.
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: days Res.: Yes or No
Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1up}
Date: Person Contacted: Vehicle: IN / OUT ^{Work}

Veh No: SKT 8684M Yr Regn: 2015, June
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Honda Legend cc: 1496
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 84549 T/Radio: Insured / Std / NI / NA
Eng/No:
C/No: BU11019457
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 215/60R16
R:
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front R/Bal: C mm Rear R/Bal: B mm
L/Bal: 6 mm L/Bal: 6 mm
D.O.A. D.O.I. 26/3/19 (1715)
Survey held at: Auto Wheels
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Table with 2 columns: Date / Time, Action / Instruction. Row 1: repair limit \$12K - to inform Louis. Includes a 'RECEIVED 04 APR 2019' stamp.

Summary section with checkboxes for 'Preliminary Report' and 'Final Report', 'Days Of Repair: 6', 'Resurvey No. of Trip: 1', 'Add Fee' options (Site Insp, Interview, Tech. Invs, Weekend), 'Survey Fee' breakdown (Transportation: 350, S+RS: 10, TOTAL: 360), and 'Report Format: merimen' and 'Lump Sum / I.B.I.: (\$ 5100p)'. Includes a signature box.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Hwang Shiang Yi	
Date: 29 Mar 2019	
<h3 style="margin: 0;">Preliminary Advice</h3>	

Insured Vehicle No : YP6298M	
TP Vehicle No : SKT8684M	Accident Date : 22/03/2019
Make : HONDA VEZEL	Assignment Date : 25/03/2019
Date of Inspection : 26/3/2019	Est. Duration of Repair : 6
Inspection At : AUTO WHEELS	

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,384.48
Revised Amount	:S\$	6,428.24
Check Items (Estimated)	:S\$	2,307.84
Total	:S\$	8,736.08
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- Other comments :The above survey was conducted on a 'Without Prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rot	Adj Submitted	Inc Auth'd	Status
Main	25 Mar 2019		25 Mar 2019 13:31 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIM SIANG HUAT PTE LTD , Co. Reg. No.: 199803003N		
Main Claimant:	SEAH CHOON HOW , ID: S1355653I		
Vehicle Reg. No.:	SKT8684M	Date of Loss:	22/03/2019 17:00 - :59
Claim Type:	TP / CMTD1901488	Policy/Cover Note No.:	D18MTPCVE001573 (Comprehensive)
Vehicle Reg. No. (Insured):	YP6298M	Policy No. (Claimant):	
		Excess:	
Repairer:	Auto Wheels Motorworks Pte Ltd (HQ) No.1 Bukit Batok Crescent, #02-40 WCEGA PLAZA, 658064 Bukit Batok - Tel: 97684247		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/04/2019]		
Adj Asg. Remarks:	WS: Louis Ong 91928963 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 4 April 2019 9:00 AM
To: 'louisongautowheels@yahoo.com'; Taufikh (LKKAuto)
Cc: SUR
Subject: RE: Finalize for vehicle SKT8684M lumpsum \$5,150.00 with 6 repair days.

Dear Louis,

Noted with thanks.

Kindly send Final invoice and all supporting documents to SOMPO INSURANCE

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Louis Ong <louisongautowheels@yahoo.com>
Sent: Thursday, 4 April 2019 8:57 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: Finalize for vehicle SKT8684M lumpsum \$5,150.00 with 6 repair days.

Hi Veron,

We accept the amount.

Thanks

Auto Wheels Motorworks PTE LTD
Louis Ong
91928963

On Thu, 4 Apr 2019 at 8:55, Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Louis,

WITHOUT PREJUDICE

Lump Sum \$5100 @ 6 working days.

Sundries Not Given.

Please check and confirm

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Louis Ong <louisongautowheels@yahoo.com>

Sent: Wednesday, 3 April 2019 5:33 PM

To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: Finalize for vehicle SKT8684M lumpsum \$5,150.00 with 6 repair days.

Hi,

The above attachment is the finalize and after paint.

Can help to finalize for vehicle SKT8684M lumpsum \$5,150.00 with 6 repair days.

No Supplementary.

Thanks

Auto Wheels Motorworks PTE LTD

Louis Ong

91928963

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
 Owner ID: 5653I

Vehicle Details

Vehicle No.: SKT8684M
 Vehicle to be Exported: No
 Intended Deregistration Date: 27 Mar 2019
 Vehicle Make: HONDA
 Vehicle Model: VEZEL 1.5X A
 Primary Colour: Silver
 Manufacturing Year: 2015
 Engine No.: L15B3519471
 Chassis No.: RU11019457
 Maximum Power Output: 96.0 kW (128 bhp)
 Open Market Value: \$18,764.00
 Original Registration Date: 25 Jun 2015
 First Registration Date: 25 Jun 2015
 Transfer Count: 0
 Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 24 Jun 2025
 PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 24 Jun 2025
 COE Category: A - Car up to 1600cc & 97kW (130bhp)
 COE Period(Years): 10
 QP Paid: \$66,000.00
 COE Rebate Amount: \$41,210.00
Total Rebate Amount: \$44,960.00

The information contained herein is correct as at 27 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/03/2019 12:29
Date Of Accident	22/03/2019 17:50
Exact Location Of Accident	PIE NEAR OLD POLICE ACADEMY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT8684M
Insured/Policyholder	
Name Of Registered Owner	SEAH CHOON HOW
NRIC No	S1355653I
Email Address	KHOR.JANIE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90016715
Alternative Phone No	HOME-90016715
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL 1.5X A
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00305164/02
Cover Note Number	
Driver	
Name of Driver	SEAH CHOON HOW
NRIC No	S1355653I
Date Of Birth	11/06/1959
Occupation	INDOOR
Date Of Driving Pass	17/03/1979
Driving Experience	40 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90016715
Fax Number	
Contact Number	HOME-90016715
EMail Address	KHOR.JANIE@GMAIL.COM

Address 61 CHOACHU KANG LOOP #01-04 SINGAPORE 689668
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle
 Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: WITH INSURED EXTRACTING
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP6298M
 Vehicle Make/Model/Colour ISUZU
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver SIHAIZAT BIN MAHMOOD
 NRIC/Passport Number S7127355E
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name SEAH CHOON HOW

Approximate Age

Injuries Sustain

Injured person in which vehicle? SKT8684M


Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- ① I was driving along V12 toward Changi Airport
- ② Just about reaching Thomson Rd exit and Bus filter into our lane causing the vehicles in front of me to slow down
- ③ I slow down as there are many cars on my right side lane.
- ④ Then I heard honking noise from vehicle behind me and next moment I was hit from the back

[Handwritten signature]

Important:

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a **FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE** within the stipulated time frame from the day of the occurrence.

<input type="checkbox"/>	- Reporting Only
<input type="checkbox"/>	- Claim OD
<input type="checkbox"/>	- Claim TP
<input checked="" type="checkbox"/>	- Claim OD/TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

[Handwritten signature]

Policyholder's signature
Date & Time 23/03/19
12:13 pm

[Handwritten signature]

Driver's Signature
(if driver not the policyholder)
Date & Time 23/03/19
12:13 pm

[Handwritten signature]

Reporting Centre Personnel's Signature
Name:
Nric/fin No.

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or Agents (including their lawyers/law firms, which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 23/03/19

12:13 pm



Driver's Signature

(If driver is not the policyholder)

Date & Time: 23/03/19

12:13 pm



Reporting Centre Personnel's Signature

Name

NGIC Ref No.:

AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: SOMPO INSURANCE

DATE: 3/23/2019

VEHICLE NO: SKT8684M

MODEL: HONDA VEZEL

YEAR: 2015

ACCIDENT DATE: 3/22/2019

CLAIM ADVISOR: LOUIS (91928963)

EMAIL: louisongautowheels@yahoo.com

ESTIMATE

DESCRIPTION	QTY	LIST PRICE
PARTS		
REAR WINDSCREEN	1	\$1,495.10 <i>can</i>
REAR WINDSCREEN MOULDING	1	\$105.40 <i>na</i>
TAILGATE	1	\$997.40 <i>bt</i>
TAILGATE OUTER GARNISH	1	\$297.60 <i>can</i>
TAILGATE LOCK	1	\$310.50 <i>bt</i>
TAILGATE SPOILER	1	\$764.40 <i>X an</i>
TAILGATE LAMP	2	\$798.40 <i>LH-na, RH-X an</i>
TAILGATE WIPER ARM	1	\$76.40 <i>na</i>
TAILGATE WIPER BLAZE	1	\$35.30 <i>mis</i>
TAILGATE WIPER MOTOR	1	\$376.10 <i>? X</i>
TAILGATE TRIM BOARD	1	\$453.10 <i>? X</i>
TAILGATE SIDE TRIM	2	\$598.20 <i>X X</i>
REAR NUMBER PLATE LAMP	2	\$288.40 <i>? X</i>
REAR EMBLEM	1	\$67.50 <i>na</i>
REAR LOGO - VEZEL	1	\$66.30 <i>na</i>
TAILLAMP	2	\$968.60 <i>LH-na, RH-X an</i>
TAILLAMP PANEL	2	REPAIR
REAR BUMPER	1	\$768.40 <i>de</i>
REAR CORNER BUMPER	2	\$564.10 <i>LH-de, RH-X an</i>
REAR BUMPER CLIPS	10	\$30.00 <i>na</i>
REAR BUMPER RETAINER	2	\$88.60 <i>LH-na RH-X an</i>
REAR BUMPER BRACKET	2	\$199.60 <i>? X an</i>

399.20

484.30

282.05

44.30

AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40.

WCEGA PLAZA SINGAPORE 658064

ATTN: SOMPO INSURANCE

DATE: 3/23/2019

VEHICLE NO: SKT8684M

MODEL: HONDA VEZEL

YEAR: 2015

ACCIDENT DATE: 3/22/2019

CLAIM ADVISOR: LOUIS (91928963)

EMAIL: louisongautowheels@yahoo.com

ESTIMATE

REAR BUMPER REFLECTOR	2	194.30	\$388.60	LH-err ✓, RH-err
END PANEL	1		\$678.30	? X RY
SPARE TYRE PANEL	1		REPAIR	
END PANEL TOP GARNISH	1		\$244.50	? X } not
REAR WEATHER STRIP	1		\$245.30	? X }
REAR SMART SENSOR	1		\$299.50	? X }

TOTAL:	\$11,205.60
DISCOUNT 20%:	\$2,241.12
	<u>\$8,964.48</u>

S/NET		PRICE
REVERSE SENSOR	1	\$250.00 200 qu ✓
REAR NUMBER PLATE	1	\$50.00 45 cut ✓
REAR END PANEL SEALANT	1	\$80.00 40? X nn
REAR WINDSCREEN SEALANT	1	\$80.00 new 60
		<u>\$460.00</u>

LABOUR		PRICE
LABOUR FOR FACILITATE REPAIR		\$1,800.00 700
TO RESPRAY TAILGATE		\$300.00 200
TO RESRAY REAR BUMPER & CORNER BUMPER		\$300.00 100
TO RESPRAY END PANEL		\$300.00 200
TO RESPRAY SPARE TYRE PANEL		\$300.00 X m.
TO CHECK AND RECONNECT ALL NECESSARY WIRING		\$50.00 30

AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: SOMPO INSURANCE

DATE: 3/23/2019
VEHICLE NO: SKT8684M
MODEL: HONDA VEZEL
YEAR: 2015
ACCIDENT DATE: 3/22/2019
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATE

TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR	\$200.00	60
TO REMOVE AND REFIT REVERSE SENSOR	\$100.00	30
TO REMOVE AND REFIT TAILGATE COMPONENT FOR FACILITATE REPAIR	\$200.00	60
TO REMOVE AND REFIT REAR WINDSCREEN	\$150.00	120
TO VACUUM AND CLEAN UP FRAGMENT GLASS	\$80.00	40
SUNDARIES	\$80.00	20
RUST PROOFING	\$100.00	40

TOTAL: \$3,960.00

TOTAL: \$13,384.48

7% GST: \$936.91

\$14,321.39

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To inspect damaged part(s) during resurvey
- Parts provided subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary survey should be resurveyed and is subject to final approval of Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Handwritten Signature]
29/3/19

Taufik 97495745
"wp"

26/3/19 @ 1745

Resurvey after repair

Taufik @ lkkandson

06 days

louisong

AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40
WCEGA PLAZA SINGAPORE 658064

ATTN: SOMPO INSURANCE

DATE: 3/23/2019
VEHICLE NO: SKT8684M
MODEL: HONDA VEZEL
YEAR: 2015
ACCIDENT DATE: 3/22/2019
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATE

DESCRIPTION	QTY	LIST PRICE
PARTS		
REAR WINDSCREEN	1	- \$1,495.10 <i>on</i>
REAR WINDSCREEN MOULDING	1	- \$105.40 <i>na</i>
TAILGATE	1	- \$997.40 <i>bt</i>
TAILGATE OUTER GARNISH	1	- \$297.60 <i>on</i>
TAILGATE LOCK	1	- \$310.50 <i>bt</i>
TAILGATE SPOILER	1	X \$764.40 X
TAILGATE LAMP	2	✓ (399.20) \$798.40 <i>LH-on, RH-X</i>
TAILGATE WIPER ARM	1	- \$76.40 <i>bro</i>
TAILGATE WIPER BLAZE	1	- \$35.30 <i>mi</i>
TAILGATE WIPER MOTOR	1	X \$376.10 ?
TAILGATE TRIM BOARD	1	X \$453.10 ?
TAILGATE SIDE TRIM	2	X \$598.20 X
REAR NUMBER PLATE LAMP	2	X \$288.40 ?
REAR EMBLEM	1	- \$67.50 <i>na</i>
REAR LOGO - VEZEL	1	- \$66.30 <i>na</i>
TAILLAMP	2	✓ (484.30) \$968.60 <i>LH-on, RH-X</i>
TAILLAMP PANEL	2	REPAIR
REAR BUMPER	1	- \$768.40 <i>de</i>
REAR CORNER BUMPER	2	✓ (282.05) \$564.10 <i>LH-de, RH-</i>
REAR BUMPER CLIPS	10	- \$30.00 <i>na</i>
REAR BUMPER RETAINER	2	✓ (44.30) \$88.60 <i>LH-na, RH-</i>
REAR BUMPER BRACKET	2	X \$199.60 ?

5,459.75

AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40
WCEGA PLAZA SINGAPORE 658064

ATTN: SOMPO INSURANCE

DATE: 3/23/2019
VEHICLE NO: SKT8684M
MODEL: HONDA VEZEL
YEAR: 2015
ACCIDENT DATE: 3/22/2019
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATE

REAR BUMPER: REFLECTOR
END PANEL
SPARE TYRE PANEL
END PANEL TOP GARNISH
REAR WEATHER STRIP
REAR SMART SENSOR

2	✓ (194.30)	\$388.60	LH corner, RH-X
1	Repair	\$678.30 ?	194.30
1		REPAIR	
1	x	\$244.50 ?	
1	x	\$245.30 ?	
1	x	\$299.50 ?	

TOTAL:	\$11,205.60
DISCOUNT 20%:	\$2,241.12
	<u>\$8,964.48</u>

5,654.05
20%
4,523.24

S/NET
REVERSE SENSOR
REAR NUMBER PLATE
REAR END PANEL SEALANT
REAR WINDSCREEN SEALANT

1
1
1
1

PRICE

-	\$250.00	200mm
-	\$50.00	45 cut
x	\$80.00	40 ?
-	\$80.00	new 60
	<u>\$460.00</u>	305

LABOUR

LABOUR FOR FACILITATE REPAIR
TO RESPRAY TAILGATE
TO RESRAY REAR BUMPER & CORNER BUMPER
TO RESPRAY END PANEL
TO RESPRAY SPARE TYRE PANEL
TO CHECK AND RECONNECT ALL NECESSARY WIRING

PRICE

\$1,800.00	700
\$300.00	200
\$300.00	100
\$300.00	200
\$300.00	x
\$50.00	30

AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40
WCEGA PLAZA SINGAPORE 658064

ATTN: SOMPO INSURANCE

DATE: 3/23/2019
VEHICLE NO: SKT8684M
MODEL: HONDA VEZEL
YEAR: 2015
ACCIDENT DATE: 3/22/2019
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATE

TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR	\$200.00	60
TO REMOVE AND REFIT REVERSE SENSOR	\$100.00	30
TO REMOVE AND REFIT TAILGATE COMPONENT FOR FACILITATE REPAIR	\$200.00	60
TO REMOVE AND REFIT REAR WINDSCREEN	\$150.00	120
TO VACUUM AND CLEAN UP FRAGMENT GLASS	\$80.00	40
SUNDARIES	\$80.00	20
RUST PROOFING	\$100.00	40

TOTAL: \$3,960.00

TOTAL: \$13,384.48 T: 6,428.24
7% GST: \$936.91
\$14,321.39 LS: 5,150

6 days.

Taufik 97495749
- WP
26/3/19 @ 1745
Busy after repair
taufik @ khairun
06 days
Luis

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19005283/T1VD3N2

Date: 04/04/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPCVE001573
Claimant Vehicle No :	SKT8684M	Insured Vehicle No :	YP6298M
Date of Loss:	22/03/2019	Nature of Claim:	TP
		Claim No:	CMTD1901488

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT8684M	Engine No:	L15B3519471
Make & Model:	HONDA VEZEL, 1.5 X (A)	Chassis No:	RU11019457
Reg. Date:	25/06/2015 (Man. Year: 2015)	Odometer:	84549 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,504.48	4,828.24	4,676.24	49.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,880.00	1,580.00	2,300.00	59.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,384.48	6,408.24	6,976.24	52.12
Approved Total (Overridden) (S\$)		5,100.00		
(S\$)	13,384.48	5,100.00	8,284.48	61.90
+ GST 7.00/7.00% (S\$)	936.91	357.00	579.91	61.90
Nett Amount (S\$)	14,321.39	5,457.00	8,864.39	61.90

INSPECTION

Date of Assignment:	25/03/2019	
Date Inspected:	26/03/2019 Inspected At:	Auto Wheels Motorworks Pte Ltd (HQ) No.1 Bukit Batok Crescent, #02-40 WCEGA PLAZA Singapore 658064
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2019)
Parts: M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKT8684M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Cracked	1,495.10 FL	*1,495.10 FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	105.40 FL	*105.40 FL
3	1		*TAILGATE	Bent	997.40 FL	*997.40 FL
4	1		*TAILGATE OUTER GARNISH	Cracked	297.60 FL	*297.60 FL
5	1		*TAILGATE LOCK	Bent	310.50 FL	*310.50 FL
6	1		*TAILGATE SPOILER	Not Necessary	764.40 FL	*- FL
7	1		*TAILGATE LAMP	N/s Cracked/O/s Not Necessary	798.40 FL	*399.20 FL
8	1		*TAILGATE WIPER ARM	Broken	76.40 FL	*76.40 FL
9	1		*TAILGATE WIPER BLADE	Missing	35.30 FL	*35.30 FL
10	1		*TAILGATE WIPER MOTOR	Not Necessary	376.10 FL	*- FL
11	1		*TAILGATE TRIM BOARD	Not Necessary	453.10 FL	*- FL
12	2		*TAILGATE SIDE TRIM	Not Necessary	598.20 FL	*- FL
13	2		*REAR NUMBER PLATE LAMP	Not Necessary	288.40 FL	*- FL
14	1		*REAR EMBLEM	Necessary	67.50 FL	*67.50 FL
15	1		*REAR LOGO-VEZEL	Necessary	66.30 FL	*66.30 FL
16	1		*TAILLAMP	N/s Cracked/O/s Not Necessary	968.60 FL	*484.30 FL
17	2		*TAILLAMP PANEL (NPA)	Repair	0.00 FL	*- FL
18	1		*REAR BUMPER	Deformed	768.40 FL	*768.40 FL
19	1		*REAR CORNER BUMPER	N/s Deformed/O/s Not Necessary	564.10 FL	*282.05 FL
20	10		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
21	1		*REAR BUMPER RETAINER	Ns Necessary/Os Not Necessary	88.60 FL	*44.30 FL
22	2		*REAR BUMPER BRACKET	Not Necessary	199.60 FL	*- FL
23	1		*REAR BUMPER REFLECTOR	N/s Cracked/O/s Not Necessary	388.60 FL	*194.30 FL
24	1		*END PANEL	Repair	678.30 FL	*- FL
25	1		*SPARE TYRE PANEL (NPA)	Repair	0.00 FL	*- FL
26	1		*END PANEL TOP GARNISH	Not Necessary	244.50 FL	*- FL
27	1		*REAR WEATHER STRIP	Not Necessary	245.30 FL	*- FL
28	1		*REAR SMART SENSOR	Not Necessary	299.50 FL	*- FL
29	1		*REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
30	1		*REAR NUMBER PLATE	Cut	50.00 FS	*45.00 FS
31	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
32	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
33	1		*SUNDARIES	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,745.60	5,959.05
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,241.12	1,130.81
Total Parts (\$\$)	9,504.48	4,828.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR FACILITATE REPAIR	New	1,800.00	700.00
2	TO RESPRAY TAILGATE	New	300.00	200.00
3	TO RESPRAY REAR BUMPER & CORNER BUMPER	New	300.00	100.00
4	TO RESPRAY END PANEL	New	300.00	200.00
5	TO RESPRAY SPARE TYRE PANEL	New	300.00	0.00
6	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	50.00	30.00
7	TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR	New	200.00	60.00
8	TO REMOVE AND REFIT REVERSE SENSOR	New	100.00	30.00
9	TO REMOVE AND REFIT TAILGATE COMPONENT FOR FACILITATE REPAIR	New	200.00	60.00
10	TO REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
11	TO VACUUM AND CLEAN UP FRAGMENT GLASS	New	80.00	40.00
12	RUST PROOFING	New	100.00	40.00
Gross Labour Cost (S\$)			3,880.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >