

INS. CASE OWNER:

CC 4/LPC 1900

5285 / Uea3m2

LKK:

IDAC:

## ASSIGNMENT

Survivor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: Ccs

Repair Cost: 43 SS\$6,600

( 6 days) Reduction: 50 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 14/6/19

Confirm with Mr Ng

Email ☐ Call ☒

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

SS\$6,600.00

00 REPR ENDED TP

Loss of Rental (LOR):

SS -

( days)

Loss of Use (LOU):

SS\$600.00

(\$100 x 6 days)

Loss of Income (LOI):

SS -

(\$ x days)

LOR only ☐LOU only ☒LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

SS\$8.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS\$7,208.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS\$7,208.00

Name 1:

Ng Lee Seng Auto Works

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

14/6/19

ASS. REC. BY: Marcus

## ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time Action / Instruction

Veh No:

Yr Regn:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$ )

☐ : Preli. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$ )☐ : Interview (\$ )☐ : Tech. Invs (\$ )☐ : Weekend (\$ )

Survey Fee:

Transportation:

) \$ + RS. \$ SI

) Photos

) Others

TOTAL

27/3/19 2/s 3yr. 10ml. coe until 28/1-2023  
 \$6600 confirmed with MR NH.  
 (RED. + 6.708.6) 50%



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 18/19/19/VC05/021565  
Our ref: CC4/LPC19005285/Uea3

Date: 28/03/2019

The Motor Claims Department  
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SFE 3688Z**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 25/03/2019 at the premises of M/s Ngee Seng Auto Works - Ubi and have the following to report:-

Workshop Estimate Amount	: S\$	13,308.62
Revised Estimate Amount	: S\$	6,600.00
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	6,600.00
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

**Description of Damage:**

The vehicle sustained damages at the  
Rear Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 6.0 days

Yours faithfully,

MARCUS CHUA  
Licensed Appraiser



## CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Toyota Mark

Price Range

Depreciation

&gt; 10 year

Vehicle Type



Submit

Advanced Search

[Home](#) » [Used Cars](#) » [Direct Owners](#) » [Toyota Mark X \(COE till 03/2022\)](#)

### Toyota Mark X (COE till 03/2022)

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)
[DIRECT OWNER](#)

#### Price

\$27,000

#### Depreciation

\$8,940 /yr

#### Reg Date

 03-Apr-2007  
(3yrs 6days COE left)

#### Mileage

165,000 km (13.8k /yr)

#### Manufactured

2006

#### Road Tax

\$2,158 /yr

#### Transmission

Auto

#### Dereg Value

\$15,201 as of today (change)

#### OMV

\$25,860

#### COE

\$25,174

#### ARF

\$28,446

#### Engine Cap

2,499 cc

#### Power

158.0 kW (211 bhp)

#### Curb Weight

1,500 kg

#### No. of Owners

2

#### Type of Vehicle

Luxury Sedan

#### Features

Tuned By Reputable Tuner, Stock And Healthy Engine, No Oil Leaks. View specs of the Toyota Mark X (2005-2011)

#### Accessories

New Pearl White Paintwork, No Cracked Dashboard (Original From Day 1). Boot Lip Spoiler, Grey Leather Seats, Black Leather Steering Wheel, 2 Owners Only.

#### Description

Wear And Tear Parts Replaced, One Of The Best Mark x In The Market, Lexus GS300 Brake Kit (Piston Overhauled) With New Remsa 650 Degree Brake Pads And Vetto Slotted Rotors, TC105N 17" Rims, New Original Absorber, Michelin PS4 225/50/17 Bought Less Than A Month. Viewing By Appointment. No Dealer Please.

#### Category

COE Car, Direct Owner Sale

#### Status

Available

#### Resources



#### Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)



#### Car Valuation - Free

Find out the market value of your existing car for free. [Get started](#)



Preferred Viewing Area

[Shortlist](#)
[Compare](#)
[Add note](#)
[Report Error](#)
[More Actions](#)

#### Seller Information

Contact Person(s)

Max

Contact No.

88581313

#### ESSENTIAL TRANSACTION FORMS

» Indemnity form

» Sales agreement

» Receipt

» Hand-over form

» Ownership Transfer


 GET HELP WITH  
PAPERWORK


sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agreement, and we'll help with **Car Loans, Insurance, Payments & Ownership Transfer**. FREE for all sgCarMart Advertised Vehicles.

[Upload your Sales Agreement](#)
[Read our 8 Step Guide for Direct Buyers & Sellers](#)

Posted on: 02-Feb-2019 | Last Updated on: 21-Mar-2019

[Compare](#)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	0556D

**Vehicle Details**

Vehicle No.:	SFE3688Z
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	MARK X 2.5 A
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	4GR0387848
Chassis No.:	GRX1203045397
Maximum Power Output:	158.0 kW (211 bhp)
Open Market Value:	\$25,013.00
Original Registration Date:	29 Jan 2008
First Registration Date:	29 Jan 2008
Transfer Count:	2
Actual ARF Paid:	\$27,515.00

**Intended PARF Rebate Details**

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

**Intended COE Rebate Details**

COE Expiry Date:	28 Jan 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$26,136.00
COE Rebate Amount:	\$20,079.00
<b>Total Rebate Amount:</b>	<b>\$20,079.00</b>

**Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 25 Mar 2019

OK

8437992



NRIC No. S2640556D



Nationality  
**JAPANESE**

Blood Group Date of issue  
A+ 28-01-2002 +

APT BLK 531 SERANGOON NORTH AVENUE 4-09-257  
SINGAPORE 550531

NRIC No: S2640556D Date: 15/02/2013 No: 7255806

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S2640556D



Name  
**FUKUSHIMA MITSUO**



Race  
**JAPANESE**

Date of Birth Sex  
05-02-1953 M


Country of Birth  
**JAPAN**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	PASS DATE
Class 2B	Motorcycles not exceeding 200 cc	30 May 1990
Class 1A	Motorcycles between 201 cc and 400 cc	30 May 1990
Class 2	Motorcycles exceeding 400 cc	30 May 1990
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	30 May 1990

NP 429A

Licence No: S2640556D



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S2640556D

Name  
**FUKUSHIMA MITSUO**



Birth Date: 05 Feb 1953

Issue Date: 22 Apr 2003







# NGEE SENG AUTO WORKS 誼盛摩哆

REGISTRATION NO: 52791500M

Blk. 3022A, Ubi Road 1, #01-50, Singapore 408716. Tel: 6841 2276 Fax: 6743 9006

ALL TYPES OF MOTOR REPAIRS SERVICES, SPRAY PAINTING & INSURANCE CLAIMS.

LONPAC INSURANCE BHD  
300, Beach Road  
The Concourse #17-04/07  
Singapore 199555

Estimate Repair Bill :TP19005  
Date :22/03/2019  
Ref No :SFE 3688Z  
Policy No. :  
Page :01

RE : VEHICLE NO. SFE 3688Z TOYOTA MARK X

Qty	Description	Unit Price	AMOUNT
1	REAR BOOTLID <i>bag/sac</i>		\$1,285.30
1	REAR BOOTLID LOCK <i>twi</i>		\$348.96
1	REAR BOOTLID EMBLEM TOYOTA LOGO <i>nei</i>		\$75.80
1	REAR BOOTLID EMBLEM MARK X <i>nei</i>		\$82.30
1	REAR BOOTLID EMBLEM 250G <i>nei</i>		\$85.20
1	REAR BOOTLID NUMBER PLATE GARNISH <i>cut/cue</i>		\$498.70
1	REAR BOOTLID WEATHERSTRIP <i>twi</i>		\$225.70
2	TAILLAMP RH/LH <i>nta cue</i>	\$752.40	\$1,504.80
1	REAR BUMPER <i>Dej</i>		\$1,563.80
2	REAR BUMPER TOW COVER <i>MS Tom</i>	\$68.50	\$137.00
2	REAR BUMPER EXHAUST COVER RH/LH <i>suc</i>	\$452.20	\$904.40
2	REAR BUMPER SIDE RETAINER RH/LH <i>sf</i>	\$156.40	\$312.80
2	REAR BUMPER BRACKET RH/LH <i>MS in</i>	\$265.60	\$531.20
1	REAR END PANEL <i>3-d 500</i>		\$652.50
1	REAR END PANEL TOP GARNISH <i>twi</i>		\$298.60
1	REAR SPARE TYRE PANEL <i>nei</i>		\$1,245.00
1	REAR TAILLAMP PANEL LH <i>bag</i>		\$325.40
1	REAR SPARE TYRE TOP COVER <i>twi</i>		\$306.40
2	REAR BUMPER LOWER COVER <i>nt</i>	\$120.40	\$240.80
2	REAR EXHAUST MOUNTING <i>1 x</i>	\$145.60	\$291.20
1	EXHAUST BOX <i>1 x</i>		\$1,298.30

SUB TOTAL \$12,214.16  
LESS 25% \$3,053.54  
TOTAL (1) \$9,160.62

## SPECIAL NETT ITEM

1	REAR BUMPER CLIPS (SET) <i>nei</i>	\$58.00
1	CAMERA <i>shd</i>	\$450.00
1	REAR NUMBER PLATE <i>su</i>	\$60.00
1	REVERSE SENSOR <i>shd</i>	\$350.00

TOTAL (2) \$918.00

## LABOUR

TO CHECK & RECTIFY WIRING SYSTEM	\$150.00
TO REMOVE & REFIT REVERSE SENSOR / CAMERA	\$180.00
TO RUST PROOF AFFECTED AREAS	\$120.00
TO REMOVE & REFIT REAR EXHAUST PIPE FOR REPAIR	\$180.00
TO PANEL BEATING	\$1,200.00
TO SPRAY PAINTING	\$1,400.00

TOTAL SPARE PARTS & LABOUR CHARGES

\$13,308.62

LKX Auto Centre hereby notify the Repairer of the following:

- To ensure the repair work is done in accordance with the relevant standards.
- To display damaged part(s) during repair.
- Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification is allowed.
- Supplementary work(s) must be authorised and is subject to final approval from insurance company.

Acknowledged by Repairer

Signature:

Date:

not Alvin  
heate  
4/5 \$6600/2  
6 day  
Take the Alvin  
25/3/19

P-7586.56  
5689.92

8287.92

## Nivitha (LKK Auto)

---

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Friday, 22 March 2019 4:26 PM  
**To:** assignments@lkkauto.com; Admin-D (LKKAuto)  
**Cc:** MT\_Claim\_SG  
**Subject:** Our Ref: 18/19/19/VC05/021565 [External General]  
**Attachments:** 22032019161420.pdf


11:01 am @ 28/3/19  
Mr Ng  
Vehicle In.

### Lonpac External - General

Dear Nivitha

Please refer to the attached and arrange Marcus Chua (as requested by workshop, Mr Ng) to conduct TP survey.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



*Lonpac External - General data is for internal / external use.*





# NGEE SENG AUTO WORKS 誼盛摩哆

REGISTRATION NO: 52791500M

Blk. 3022A, Ubi Road 1, #01-50, Singapore 408716. Tel: 6841 2276 Fax: 6743 9006  
ALL TYPES OF MOTOR REPAIRS SERVICES, SPRAY PAINTING & INSURANCE CLAIMS.

LONPAC INSURANCE BHD  
380, Beach Road #17-04  
The Concourse  
Singapore 199555

MV NG.

LKK  
Marius Amer

Your Ref : GW 4373 T  
Our Ref : SFE 3688 Z  
Date : 22-03-2019

Dear Sir / Mdm,

## NOTIFICATION OF ACCIDENT

ACCIDENT INVOLVING: GW 4373 T ALONG PAYA LEBAR ROAD  
AFTER AIRPORT ROAD JUNCTION ON 21-03-2019

We act for FUKUSHIMA MITSUO, in the accident above.

Please note that our client's motor vehicle SFE 3688 Z is now at the following workshop.

M/s Ngee Seng Auto Works  
Blk 3022A Ubi Road 1  
#01-50 Singapore 408716

Contact Person: Mr. Ng 96319168

PLEASE NOTE that if you fail to carry out pre-repair inspection or waive the pre-accident inspection within 2 days from the receipt of this Notice, our client may proceed to have his motor vehicle repaired.

Please give us written notice of the completion of pre-repair inspection or waivers as the cases may be to facilitate the repairs which can only commence after receipt of the written notice.

Yours faithfully



NGEE SENG AUTO WORKS

After motor

To: Mr. Ng

V: in

E: ✓

P: Mr. Ng

**Mei Kwan (LKKAUTO)**

---

**From:** Mei Kwan (LKKAUTO)  
**Sent:** Thursday, 28 March, 2019 9:43 PM  
**To:** GERALD POH WEE BIN  
**Cc:** MT\_Claim\_SG; Asher Sng (LKKAUTO); CS A Team; Admin A  
**Subject:** RE: Our Ref: 18/19/19/VC05/021565 [External General]  
**Attachments:** Preliminary Advice.pdf; TP ESTIMATE - MARKED.pdf  
  
**Categories:** HMK

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

LPC ref: 18/19/19/VC05/021565  
LKK REF: CC4/LPC19005285/Uea3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SFE 3688Z

- Estimated cost of repair
- Preliminary advice

We have not authorized repairs.

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Monday, 25 March, 2019 3:57 PM  
**To:** Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>  
**Cc:** MT\_Claim\_SG <mt\_claim@lonpac.com>  
**Subject:** RE: Our Ref: 18/19/19/VC05/021565 [External General]

**Lonpac External - General**

Dear Mei Kwan,

Attached copy of insured's GIA report for your attention.

Best Regards  
Gerald Poh  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555


**From:** ONG LI LI [<mailto:llong@lonpac.com>]  
**Sent:** Friday, 22 March 2019 4:26 PM  
**To:** [assignments@lkkauto.com](mailto:assignments@lkkauto.com); Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>  
**Subject:** Our Ref: 18/19/19/VC05/021565 [External General]

## Lonpac External - General

Dear Nivitha

Please refer to the attached and arrange Marcus Chua (as requested by workshop, Mr Ng) to conduct TP survey.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



*Lonpac External - General data is for internal / external use.*

---

This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19005285/Uda3n2

300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 19-06-2019



Code : LPC2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GW 4373T	Veh. Inspected	SFE 3688Z
Policy No.	Z18VC05001363	Coverage (\$)	0.00
Claim No.	18/19/19/VC05/021565	Excess (\$)	0.00
Assign From	GERALD	Assign Date	25/03/2019

## 2. Vehicle Particulars & Condition

Make & Model	TOYOTA MARK X (A)	c.c	2499
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	GRX1203045397	Colour	WHITE
Odometer	157286	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	224/45 R18	BRIDGESTONE	6 mm
L/H Front Tyre	224/45 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	224/45 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	224/45 R18	BRIDGESTONE	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

## 5. General Information

Accident Date	21/03/2019	Inspection Date	25/03/2019
Survey held at	NGEE SENG AUTO WORKS BLK. 3022A, UBI ROAD 1, #01-50 SINGAPORE 408716.		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFE 3688Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BOOTLID	BENT / BUCKLED	1,285.30	1,285.30
1	REAR BOOTLID LOCK	TWISTED	348.96	348.96
1	REAR BOOTLID EMBLEM TOYOTA LOGO	NECESSARY	75.80	75.80
1	REAR BOOTLID EMBLEM MARK X	NECESSARY	82.30	82.30
1	REAR BOOTLID EMBLEM 250G	NECESSARY	85.20	85.20
1	REAR BOOTLID NUMBER PLATE GARNISH	CUT / CRACKED	498.70	498.70
1	REAR BOOTLID WEATHERSTRIP	TWISTED	225.70	225.70
2	TAILLAMP RH/LH @\$752.40	CRACKED	1,504.80	1,504.80
1	REAR BUMPER	DISTORTED	1,563.80	1,250.00
2	REAR BUMPER TOW COVER @\$68.50	N/S TORN	137.00	68.50
2	REAR BUMPER EXHAUST COVER RH/LH @\$452.20	SERVICEABLE	904.40	-
2	REAR BUMPER SIDE RETAINER RH/LH @\$156.40	BENT	312.80	312.80
2	REAR BUMPER BRACKET RH/LH @\$265.60	N/S DENTED	531.20	265.60
1	REAR END PANEL	BADLY DENTED	652.50	652.50
1	REAR END PANEL TOP GARNISH	TWISTED	298.60	298.60
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	1,245.00	-
1	REAR TAILLAMP PANEL LH	BENT	325.40	325.40
1	REAR SPARE TYRE TOP COVER	TWISTED	306.40	306.40
2	REAR BUMPER LOWER COVER @\$120.40	NOT NECESSARY	240.80	-
2	REAR EXHAUST MOUNTING @\$145.60	NOT NECESSARY	291.20	-
1	EXHAUST BOX	NOT NECESSARY	1,298.30	-
	LESS 25% DISCOUNT		-3,053.54	-1,896.64
			9,160.62	5,689.92
<b>SPECIAL NETT ITEMS</b>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	58.00	58.00
1	CAMERA (SN)	SHORTED	450.00	300.00
1	REAR NUMBER PLATE (SN)	SERVICEABLE	60.00	-
1	REVERSE SENSOR (SN)	SHORTED	350.00	200.00
			918.00	558.00

Report Ref No. CC4/LPC19005285/Uda3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO CHECK & RECTIFY WIRING SYSTEM.		150.00	30.00
	TO REMOVE & REFIT REVERSE SENSOR /CAMERA.		180.00	50.00
	TO RUST PROOF AFFECTED AREAS.		120.00	60.00
	TO REMOVE & REFIT REAR EXHAUST PIPE FOR REPAIR.	NOT NECESSARY	180.00	-
	TO PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE PANEL .		1,200.00	800.00
	TO SPRAY PAINTING.		1,400.00	1,100.00
			3,230.00	2,040.00
	<b>GRAND TOTAL</b>		<b>13,308.62</b>	<b>8,287.92</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>6,600.00</b>

Report Ref No. CC4/LPC19005285/Uda3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.