



NGEE SENG AUTO WORKS 誼盛摩哆

REGISTRATION NO: 52791500M

Blk. 3022A, Ubi Road 1, #01-50, Singapore 408716. Tel: 6841 2276 Fax: 6743 9006

ALL TYPES OF MOTOR REPAIRS SERVICES, SPRAY PAINTING & INSURANCE CLAIMS.

LONPAC INSURANCE BHD
300, Beach Road
The Concourse #17-04/07
Singapore 199555

Estimate Repair Bill :TP19005
Date :22/03/2019
Ref No :SFE 3688Z
Policy No :
Page :01

RE : VEHICLE NO. SFE 3688Z TOYOTA MARK X

Qty	Description	Unit Price	AMOUNT
1	REAR BOOTLID <i>bag/sac</i>		\$1,285.30
1	REAR BOOTLID LOCK <i>twi</i>		\$348.96
1	REAR BOOTLID EMBLEM TOYOTA LOGO <i>ner</i>		\$75.80
1	REAR BOOTLID EMBLEM MARK X <i>ner</i>		\$82.30
1	REAR BOOTLID EMBLEM 250G <i>ner</i>		\$85.20
1	REAR BOOTLID NUMBER PLATE GARNISH <i>cur/cne</i>		\$498.70
1	REAR BOOTLID WEATHERSTRIP <i>twi</i>		\$225.70
2	TAILLAMP RH/LH <i>nta cne</i>	\$752.40	\$1,504.80
1	REAR BUMPER <i>Dis</i>		\$1,563.80
2	REAR BUMPER TOW COVER <i>nta 70m</i>	\$68.50	\$137.00
2	REAR BUMPER EXHAUST COVER RH/LH <i>src</i>	\$452.20	\$904.40
2	REAR BUMPER SIDE RETAINER RH/LH <i>bag</i>	\$156.40	\$312.80
2	REAR BUMPER BRACKET RH/LH <i>nta 70m</i>	\$265.60	\$531.20
1	REAR END PANEL <i>5-d 300</i>		\$652.50
1	REAR END PANEL TOP GARNISH <i>twi</i>		\$298.60
1	REAR SPARE TYRE PANEL <i>ner</i>		\$1,245.00
1	REAR TAILLAMP PANEL LH <i>bag</i>		\$325.40
1	REAR SPARE TYRE TOP COVER <i>twi</i>		\$306.40
2	REAR BUMPER LOWER COVER <i>nt</i>	\$120.40	\$240.80
2	REAR EXHAUST MOUNTING <i>nt</i>	\$145.60	\$291.20
1	EXHAUST BOX <i>nt</i>		\$1,298.30
SUB TOTAL			\$12,214.16
LESS 25%			\$3,053.54
TOTAL (1)			\$9,160.62

SPECIAL NETT ITEM

1	REAR BUMPER CLIPS (SET) <i>ner</i>	\$58.00
1	CAMERA <i>shd</i>	\$450.00
1	REAR NUMBER PLATE <i>src</i>	\$60.00
1	REVERSE SENSOR <i>shd</i>	\$350.00
TOTAL (2)		\$918.00

LABOUR

TO CHECK & RECTIFY WIRING SYSTEM	\$150.00
TO REMOVE & REFIT REVERSE SENSOR / CAMERA	\$180.00
TO RUST PROOF AFFECTED AREAS	\$120.00
TO REMOVE & REFIT REAR EXHAUST PIPE FOR REPAIR <i>nt</i>	\$180.00
TO PANEL BEATING	\$1,200.00
TO SPRAY PAINTING	\$1,400.00

TOTAL SPARE PARTS & LABOUR CHARGES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey *LABOUR CHARGES*
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*not Alvin
head
2/5 \$6600/2
6 day
Fok plb Atterage
25/3/19*

*1-7586.56
5689.92*

*ner
shd
src
shd
\$350.00
200*

*30
50
60
x
800
1100*

8287.92