

SW WERKZ PTE LTD

BLOCK 25 KAKI BUKIT ROAD 4 #03-65/67/68 SYNERGY @ KB Singapore 417800
 HP: 92712214 TEL: (65) 63844844 FAX: (65) 63834944

20th March 2019

SPRAYWERKS ENGINEERING PTE LTD
 25 KAKI BUKIT ROAD 54
 # 03-65/67/68 SYNERGY @KB
 Singapore 417800

Accident date: 18th MARCH 2019

Estimated repair cost for vehicle no: SLR3808E TOYOTA SIENTA 1.5 A

S/n	Qty	Items	U/price	Amount
1	2	Front head lamp	\$981.00	\$1,962.00
2	1	Front bumper		\$1,377.00
3	2	Front bumper side bracket	\$121.00	\$242.00
4	10	Front bumper clips	\$6.50	\$65.00
5	2	Front bumper fog lamp	\$285.00	\$570.00
6	1	Front bumper reinforcement		\$534.99
7	1	front bumper grille		\$285.00
8	1	front bumper lower garnish		\$385.10
9	1	Front grille		\$327.10
10	10	Front grille clips	\$6.00	\$60.00
11	1	Rear Boot Lid		\$1,150.00
12	2	Rear Boot Lid Hinges	\$187.70	\$375.40
13	1	Rear boot lid emble logo		\$74.10
14	1	Rear Boot Lid Inner Lock		\$349.10
15	1	Rear boot lid inner rubber		\$276.10
16	1	Rear Boot Lid center moulding		\$213.20
17	2	Rear Boot Lid center moulding side clips	\$8.50	\$17.00
18	1	Rear Boot Lid Number Plate		\$50.00
19	2	Rear Boot Lid Number Plate Lamp	\$135.10	\$270.20
20	1	Rear Boot Lid Inner Trim board		\$680.00
21	2	boot lid lamp	\$385.20	\$770.40
22	1	Rear boot lid windscreen seal		\$188.20
23	2	Rear tail lamp	\$640.10	\$1,280.20
24	4	Rear tail lamp clips	\$8.50	\$34.00
25	2	Rear tail lamp panel	\$320.00	\$640.00
26	1	Rear Bumper		\$825.00
27	2	Rear Bumper side reflector	\$88.00	\$176.00
28	2	Rear Bumper Side Bracket	\$55.60	\$111.20
29	1	Rear Bumper reverse sensor		\$350.00
30	2	Rear Bumper Bracket	\$68.40	\$136.80

31	8	Rear bumper clips	\$6.50	\$52.00
32	1	rear bumper lower cover		\$358.00
33	1	Rear End Panel outer		\$580.10
34	1	Rear End Panel inner		\$380.10
35	1	Rear End Panel Top Garnish		\$258.20
36	1	Rear spare tire lock		\$385.10
37	1	Rear floor panel top cover		\$380.00
38	1	Rear floor panel sealant		\$120.00

Subtotal :- \$16,288.59

labour charges

To Check Wiring System	\$60.00
Tuff Kote	\$150.00
To Remove & refix cushion	\$150.00
To Remove & refix rear exhaust	\$0.00
To Remove & refix rear windscreen	\$120.00
Gum	\$50.00
To Remove & refix reverse Sensor	\$100.00
Panel beating	\$1,400.00
Spray painting	\$1,400.00

Subtotal :- \$3,430.00

Total:- \$19,718.59