

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST: 201300201N

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY #07-16  
AIG BUILDING, SINGAPORE 079120  
TEL: 64193000 FAX: 68357416  
ATTN: Motor Claim Department

Estimate No: EST1900076  
Date: 20 Mar 2019  
Veh Reg No: SKW7600X  
Make/Model: HYUNDAI ELANTRA  
1.6AT ABS D/AB 2WD  
4DR  
Chasis No: KMHDH41CMGU655444  
Reg. Date: 16/11/2015  
Your Ref No: SMG2669S

Claim Type: Third Party  
Accident Date: 19/03/2019  
TP Veh Reg No: SMG2669S

Poh  
Kin.

## Estimate Repair Cost to Vehicle No :SKW7600X

| Quantity | Description                                | List Price          | Amount        |
|----------|--------------------------------------------|---------------------|---------------|
|          |                                            | SS                  | SS            |
|          | <b>List Price</b>                          |                     |               |
| 1        | 1 PC BOOT LID <i>Dented</i>                | <del>1,840.00</del> | <i>1,148.</i> |
| 2        | 1 PC BOOT LID RUBBER <i>new</i>            | 109.90              | <i>x</i>      |
| 3        | 1 PC BOOT LID LOCK <i>new</i>              | 134.60              | <i>x</i>      |
| 4        | 1 PC BOOT LID LOCK CHECKER <i>new</i>      | 32.40               | <i>x</i>      |
| 5        | 1 PC BOOT LID LAMP LH <i>new</i>           | 298.80              | <i>x</i>      |
| 6        | 1 PC BOOT LID LOGO                         | 41.60               | <i>✓</i>      |
| 7        | 1 PC BOOTLID "ELANTRA" EMBLEM <i>new</i>   | 38.40               | <i>✓</i>      |
| 8        | 1 PC BOOTLID "ELITE" EMBLEM                | 48.30               | <i>✓</i>      |
| 9        | 1 PC REAR BUMPER <i>delid</i>              | 489.40              | <i>✓</i>      |
| 10       | 1 PC REAR BUMPER REINFORCEMENT <i>Best</i> | 303.70              | <i>✓</i>      |
| 11       | 2 PCS REAR BUMPER BRACKET <i>RH Best</i>   | <del>80.20</del>    | <i>40.10</i>  |
| 12       | 2 PCS REAR BUMPER SIDE RETAINER <i>new</i> | 49.20               | <i>✓</i>      |
| 13       | 1 PC REAR LOWER BUMPER <i>delid</i>        | 280.10              | <i>✓</i>      |
| 14       | 1 PC REAR BUMPER REFLECTOR - RH <i>new</i> | 48.30               | <i>x</i>      |
| 15       | 1 PC TAIL LAMP - RH <i>new</i>             | 388.00              | <i>x</i>      |
| 16       | 1 PC TAIL LAMP LH <i>new</i>               | 388.00              | <i>x</i>      |
| 17       | 1 PC REAR PANEL <i>new</i>                 | 385.00              | <i>x</i>      |
| 18       | 1 PC REAR PANEL TRIM <i>delid</i>          | 83.40               | <i>✓</i>      |
| 19       | 1 PC BONNET <i>Buckled</i>                 | 1,361.90            | <i>✓</i>      |
| 20       | 1 PC BONNET RUBBER <i>new</i>              | 45.00               | <i>x</i>      |
| 21       | 1 PC HEADLAMP RH <i>delid</i>              | 1,756.46            | <i>✓</i>      |
| 22       | 1 PC FRT BUMPER <i>delid</i>               | 474.40              | <i>✓</i>      |
| 23       | 1 PC FRT BUMPER REINFORCEMENT <i>Best</i>  | 515.10              | <i>✓</i>      |
| 24       | 1 PC FRT BUMPER SPONGE <i>delid</i>        | 110.70              | <i>✓</i>      |
| 25       | 2 PCS FRT BUMPER BRACKET <i>new</i>        | 43.20               | <i>x</i>      |
| 26       | 2 PCS FRT BUMPER SIDE RETAINER <i>new</i>  | 24.00               | <i>✓</i>      |
| 27       | 1 PC FRT FOG LAMP RH <i>delid</i>          | 249.90              | <i>✓</i>      |
| 28       | 1 PC FRT FOG LAMP COVER RH <i>delid</i>    | 48.30               | <i>✓</i>      |
| 29       | 1 PC FRT BUMPER TOWING COVER <i>new</i>    | 18.00               | <i>x</i>      |

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY #07-16  
AIG BUILDING, SINGAPORE 079120  
TEL: 64193000 FAX: 68357416  
ATTN: Motor Claim Department

Estimate No: EST1900076  
Date: 20 Mar 2019  
Veh Reg No: SKW7600X  
Make/Model: HYUNDAI ELANTRA  
1.6AT ABS D/AB 2WD  
4DR  
Chasis No: KMHDH41CMGU655444  
Reg. Date: 16/11/2015  
Your Ref No: SMG2669S

Claim Type: Third Party  
Accident Date: 19/03/2019  
TP Veh Reg No: SMG2669S

## Estimate Repair Cost to Vehicle No :SKW7600X

| Quantity | Description                                                                                                   | List Price | Amount      |
|----------|---------------------------------------------------------------------------------------------------------------|------------|-------------|
|          |                                                                                                               | SS         | SS          |
| 30       | 1 PC FRT BUMPER GRILLE <i>Rehd</i>                                                                            | 285.70     | <i>2</i>    |
| 31       | 1 PC FRT GRILLE <i>amle</i>                                                                                   | 186.00     | <i>2</i>    |
| 32       | 1 PC FRT GRILLE LOGO <i>Re</i>                                                                                | 42.60      | <i>2</i>    |
|          |                                                                                                               | 10,200.56  |             |
|          | Less 20%                                                                                                      | 2,040.11   | 8,160.45    |
|          | <b>Special Net</b>                                                                                            |            |             |
| 33       | 1 SET REAR LOWER BUMPER CLIPS <i>ne</i>                                                                       | 48.00      | <i>30</i>   |
| 34       | 1 SET REAR BUMPER CLIPS <i>ne</i>                                                                             | 60.00      | <i>30</i>   |
| 35       | 1 SET REVERSE SNSOR <i>Dangd</i>                                                                              | 250.00     | <i>200.</i> |
| 36       | 1 SET REAR PANEL TRIM CLIPS <i>3 me ne</i>                                                                    | 48.00      | <i>+</i>    |
| 37       | 1 SET BONNET RUBBER CLIPS                                                                                     | 40.00      | <i>+</i>    |
| 38       | 1 SET FRT BUMPER CLIPS <i>ne</i>                                                                              | 60.00      | <i>30.</i>  |
| 39       | 1 SET FRTBUMPER GRILLE CLIPS <i>Ne ne</i>                                                                     | 48.00      | <i>X</i>    |
| 40       | 1 PC FRT NUMBER PLATE <i>Best</i>                                                                             | 50.00      | <i>30</i>   |
| 41       | 1 PC FRT NUMBER PLATE BASE <i>Rehd</i>                                                                        | 80.00      | <i>30</i>   |
| 42       | 1 SET FRT BUMPER PARKING SENSORS <i>Dangd</i>                                                                 | 250.00     | <i>200.</i> |
| 43       | 1 SET FRT GRILLE CLIPS <i>ne</i>                                                                              | 40.00      | <i>10.</i>  |
|          |                                                                                                               | 974.00     | 974.00      |
|          | <b>Labour</b>                                                                                                 |            |             |
| 44       | 1 TO CHECK WIRING                                                                                             | 50.00      | <i>30.</i>  |
| 45       | 1 TO REMOVE AND REFIT REVERSE SENSOR                                                                          | 80.00      | <i>50</i>   |
| 46       | 1 TO REMOVE AND REFIT REVERSE CAMERA                                                                          | 80.00      | <i>50</i>   |
| 47       | 1 TO SPRAY UNDERSEAL                                                                                          | 100.00     | <i>+</i>    |
| 48       | 1 (REAR) TO SPRAY PAINTING                                                                                    | 1,000.00   | <i>400.</i> |
| 49       | 1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS. | 1,000.00   | <i>400.</i> |
| 50       | 1 TO CHECK WIRING (FRONT)                                                                                     | 50.00      | <i>30</i>   |
| 51       | 1 TO REMOVE AND REFIT PARKING SENSOR CUSHION                                                                  | 80.00      | <i>50</i>   |
| 52       | 1 TO REFILL AIRCON GAS                                                                                        | 120.00     | <i>+</i>    |

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY #07-16  
AIG BUILDING, SINGAPORE 079120  
TEL: 64193000 FAX: 68357416  
ATTN: Motor Claim Department

Estimate No: EST1900076  
Date: 20 Mar 2019  
Veh Reg No: SKW7600X  
Make/Model: HYUNDAI ELANTRA  
1.6AT ABS D/AB 2WD  
4DR  
Chasis No: KMHDH41CMGU655444  
Reg. Date: 16/11/2015  
Your Ref No: SMG2669S

Claim Type: Third Party  
Accident Date: 19/03/2019  
TP Veh Reg No: SMG2669S

## Estimate Repair Cost to Vehicle No :SKW7600X

| Quantity | Description                                                                                                   | List Price | Amount       |
|----------|---------------------------------------------------------------------------------------------------------------|------------|--------------|
|          |                                                                                                               | SS         | SS           |
| 53       | 1 TO SPRAY UNDERSEAL                                                                                          | 100.00     | 100.00       |
| 54       | 1 (FRONT) TO SPRAY PAINTING                                                                                   | 1,000.00   | 400.00       |
| 55       | 1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS. | 1,000.00   | 400.00       |
|          |                                                                                                               | 4,660.00   | 4,660.00     |
|          | Total                                                                                                         |            | SS 13,794.45 |
|          | Add GST @ 7%                                                                                                  |            | 965.61       |
|          | Total Amount Payable                                                                                          |            | SS 14,760.06 |

TOTAL: SINGAPORE DOLLAR FOURTEEN THOUSAND SEVEN HUNDRED SIXTY AND CENTS SIX ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Adrian Ly  
H/s 20/03/19.  
08 days.  
total: 8431.80  
K/s: 6750.1