



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

VEHICLE NO. : SKA7901T

ACCIDENT DATE : 22-03-2019 14:30

THIRD PARTY REF. : XE3331P

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE SKA7901T TOYOTA ALTIS

DATE : 23-03-2019

Not Attached
Late arrival
L/CS
7 day 25/3/19
The photo Attached

QTY PARTS DESCRIPTION

AMOUNT (SG\$)

1	1	FRONT DOOR (RH)	Body 1200.00	
2	1	FRONT DOOR FRAME STICKER (RH)	re 75.00	
3	1	FRONT DOOR HINGE (TOP)	17 85.00	X
4	1	FRONT DOOR HINGE (LOWER)	17 85.00	X
5	1	FRONT DOOR CHECKER (RH)	17 155.00	X
6	1	FRONT DOOR OUTER HANDLE (RH)	cut 75.00	
7	1	FRONT DOOR KEY OUTER COVER (RH)	cut 25.70	
8	1	FRONT DOOR TOP OUTER MOULDING (RH)	cut 135.00	
9	1	FRONT DOOR LOCK (RH)	re 492.20	?
10	1	FRONT DOOR PROTECTOR (RH)	17.5 115.00	
11	1	FRONT DOOR PROTECTOR MOULDING (RH)	re 25.00	
12	1	FRONT DOOR WINDOW GEAR (RH)	17 230.00	X
13	1	ROCKER PANEL (RH)	re 485.00	X
14	1	REAR DOOR (RH)	Body 1002.00	
15	1	REAR DOOR HINGE (TOP)	17 85.00	
16	1	REAR DOOR HINGE (LOWER)	17 85.00	
17	1	REAR DOOR CHECKER (RH)	17 145.00	
18	1	REAR DOOR TOP OUTER MOULDING (RH)	cut 116.00	
19	1	REAR DOOR FRAME STICKER (RH)	re 75.00	
20	1	REAR DOOR OUTER HANDLE (RH)	cut 75.00	
21	1	REAR DOOR WINDOW GEAR (RH)	230.00	?
22	1	REAR DOOR LOCK (RH)	445.00	?
23	1	REAR DOOR PROTECTOR (RH)	17.5 75.00	
24	1	REAR DOOR PROTECTOR MOULDING (RH)	re 23.00	
25	1	REAR DOOR RUBBER (RH)	re 148.00	



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SKA7901T
ACCIDENT DATE : 22-03-2019 14:30
THIRD PARTY REF. : XE3331P

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
26	1	REAR FENDER (RH)	925.00 ✓
27	1	REAR WINDSCREEN MOULDING	90.00 ✓
28	1	SIDE SKIRT (RH)	705.00 ✓
29	2	REAR SHOCK ABSORBER @\$203.00	406.00 ?
30	2	REAR WHEEL HUB ASSY @\$670.00	1340.00 ?
31	1	REAR AXLE ASSY	2347.00 ?
32	1	REAR BUMPER	545.00 ✓
33	2	REAR BUMPER SIDE RETAINER @\$173.00	346.00 1pc
			12,390.90
LESS 25 %			3,097.73
TOTAL (A)			9,293.18

SPECIAL NETT ITEMS

1	2	TYRE @\$250.00	29180	500.00	1pc 70
2	2	TYRE RIM @\$300.00		600.00	1pc 25
3	1	REAR WINDSCREEN GUM		45.00	40
4	1	TOWING		150.00	120
TOTAL (C)				1,295.00	

LABOUR CHARGES

1	1	REMOVE & REFIX REAR WINDSCREEN	150.00	120
2	1	REMOVE & REFIX REAR UNDER CARRIAGE SYSTEM	250.00	120?
3	1	TO DO WHEEL ALIGNMENT	150.00	80
4	1	REMOVE & REFIX DOOR GLASS, BOARD LINING, ETC	120.00	✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SKA7901T
ACCIDENT DATE : 22-03-2019 14:30
THIRD PARTY REF. : XE3331P

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
5	1	REMOVE & REFIX SEATS, CARPETS, CUSHION, ETC	180.00 80
6	1	TO CHECK WIRING	50.00 20
7	1	REMOVE ALL NECESSARY AFFECTED PARTS FOR REPAIRS, WELD/CUT, PANEL BE- ATING & RENEW PARTS	1680.00 1100
8	1	SPRAY PAINTING	1100.00 1050
TOTAL (D)			3,680.00
ESTIMATE TOTAL			14,268.18