



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

VEHICLE NO. : SKA7901T
ACCIDENT DATE : 22-03-2019 14:30
THIRD PARTY REF. : XE3331P
ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE SKA7901T TOYOTA ALTIS

#	QTY	PARTS DESCRIPTION
1	1	FRONT DOOR (RH)
2	1	FRONT DOOR FRAME STICKER (RH)
3	1	FRONT DOOR HINGE (TOP)
4	1	FRONT DOOR HINGE (LOWER)
5	1	FRONT DOOR CHECKER (RH)
6	1	FRONT DOOR OUTER HANDLE (RH)
7	1	FRONT DOOR KEY OUTER COVER (RH)
8	1	FRONT DOOR TOP OUTER MOULDING (RH)
9	1	FRONT DOOR LOCK (RH)
10	1	FRONT DOOR PROTECTOR (RH)
11	1	FRONT DOOR PROTECTOR MOULDING (RH)
12	1	FRONT DOOR WINDOW GEAR (RH)
13	1	ROCKER PANEL (RH)
14	1	REAR DOOR (RH)
15	1	REAR DOOR HINGE (TOP)
16	1	REAR DOOR HINGE (LOWER)
17	1	REAR DOOR CHECKER (RH)
18	1	REAR DOOR TOP OUTER MOULDING (RH)
19	1	REAR DOOR FRAME STICKER (RH)
20	1	REAR DOOR OUTER HANDLE (RH)
21	1	REAR DOOR WINDOW GEAR (RH)
22	1	REAR DOOR LOCK (RH)
23	1	REAR DOOR PROTECTOR (RH)
24	1	REAR DOOR PROTECTOR MOULDING (RH)
25	1	REAR DOOR RUBBER (RH)

DATE : 23-03-2019

Not Approved
Late return
L/C 8200/2
7 day 25/3/19
the the Aff. reg.

	AMOUNT (SG\$)
Body	1200.00
ner	75.00
17	85.00 X
18	85.00 X
17	155.00 X
ner	75.00
ner	25.70
ner	135.00
ner / shld	492.20
ner	115.00
ner	25.00
17	230.00 X
ner	485.00 X
Body	1002.00
ner	85.00
ner	85.00
ner	145.00
ner	116.00
ner	75.00
ner	75.00
ner / shld	230.00
ner / shld	445.00
ner	75.00
ner	23.00
ner	148.00



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SKA7901T
ACCIDENT DATE : 22-03-2019 14:30
THIRD PARTY REF. : XE3331P

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
26	1	REAR FENDER (RH)	925.00 ✓
27	1	REAR WINDSCREEN MOULDING	90.00 ✓
28	1	SIDE SKIRT (RH)	705.00 ✓
29	2	REAR SHOCK ABSORBER @\$203.00	406.00 X
30	2	REAR WHEEL HUB ASSY @\$670.00	1340.00 7pc
31	1	REAR AXLE ASSY	2347.00 ✓
32	1	REAR BUMPER	545.00 ✓
33	2	REAR BUMPER SIDE RETAINER @\$173.00 65.	346.00 1pc
			12,390.90
LESS 25 % 507			3,097.73
TOTAL (A)			9,293.18

SPECIAL NETT ITEMS

1	2	TYRE @\$250.00 29180	500.00 1pc 70% 126
2	2	TYRE RIM @\$300.00	600.00 1pc 250
3	1	REAR WINDSCREEN GUM	45.00 40
4	1	TOWING	150.00 120
TOTAL (C)			1,295.00 536

LABOUR CHARGES

1	1	REMOVE & REFIX REAR WINDSCREEN	150.00 120
2	1	REMOVE & REFIX REAR UNDER CARRIAGE SYSTEM	250.00 150
3	1	TO DO WHEEL ALIGNMENT	150.00 80
4	1	REMOVE & REFIX DOOR GLASS, BOARD LINING, ETC	120.00 ✓

Let's Auto Centre will finance notify
the insurer of the following:
• To ensure information on repairing
• To ensure repaired part during recovery
• First claims are subject to co-insurance
• Third party liability on a "Without Prejudice" basis
• No legal action is allowed
• Supplementary item(s) must be recovered and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$9993.9
507
4996.98



簡福星摩哆工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SKA7901T
ACCIDENT DATE : 22-03-2019 14:30
THIRD PARTY REF. : XE3331P

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
5	1	REMOVE & REFIX SEATS, CARPETS, CUSHION, ETC	180.00 80
6	1	TO CHECK WIRING	50.00 20
7	1	REMOVE ALL NECESSARY AFFECTED PARTS FOR REPAIRS, WELD/CUT, PANEL BE- ATING & RENEW PARTS	1680.00 1100
8	1	SPRAY PAINTING	1100.00 1050
TOTAL (D)			3,680.00
ESTIMATE TOTAL			14,268.18 2720

10757.42
25
8626 8063.56
10783.56
8240.