

2015 FHS 417

Surveys

8122

REF C/C1119005295/E9/d342

ASSIGNMENT (Office)

Person (Person)

Chong Boon Sn

C11

Date/Time

28/3/19 @ 1:20pm

Estimated Cost

Bill to

OD / ☒ FWS / TP RIG / OD RIG / EVA / INV / MV / US

To Inspect Vehicle No.

SLB 5372R

Insured

SKN 2756K

at Workshop no

SK Automobile

Tel:

6266 0555

of

A8 Joh Guan Rd East #01-121

Policy No

MUPC SN 30419418000

Claim No

SNM19D20153302

Sum Insured

Excess

Make of Veh

D.O.A

21/03/2019

Client's Record

26/3/19 @ MOM

H.O.D. Endorsement

CA / RW / RIG / RW 24 HRS

Date/Time

1:46pm @ 25/3/19

Person Contacted

Yvonne

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SLB 5372R - X

SKN 2756K - X

ASSIGNMENT

From: Date: 26/3/2019

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: SLB 5372R
at Workshop m/s: SK Automobile
of: 48th Glen Rd East #01-121
Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1 up}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLB 5372R Yr Regn: 13/04/16

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Elantra C.C. 1-6 (159) cc

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 64424 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMFI0841CMH4144115

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Road Stone

Front

Rear

R/Bal: 3 mm R/Bal: 3 mm

L/Bal: 3 mm L/Bal: 3 mm

D.O.A: 21/3/19 D.O.I: 26/3/19

Survey held at SK Automobile

Des. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV - 62,000

PV - 45,391

NV - 16,699

17/4/19 Finalise confirm 12,150.00. 12 days (Red & 23,393.36, 66%)

RECEIVED 09 MAY 2019

Date/Time, File Pass to?

☐ : Prell. Report1) 05/5 Month ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 12

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format: MER-TP

Lump Sum / I.B.T. (\$) 12150

220

220

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 25 March 2019 1:20 PM
To: Pioneer Workshop
Cc: assignments
Subject: RE: Arrange Survey for SLB5372R (your veh: SKN2756K) D.O.A 21/03/2019

Without Prejudice

Dear Sir,

We assign LKK.

Dear LKK,

Pls pri.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Pioneer Workshop [mailto:pioneer@skauto.com.sg]
Sent: Monday, 25 March, 2019 11:57 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Re: Arrange Survey for SLB5372R (your veh: SKN2756K) D.O.A 21/03/2019

Dear Boon Sen,

Please help to arrange ADRIAN LING come to survey above vehicle.

On Mon, Mar 25, 2019 at 10:52 AM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without Prjeudice

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

To: <claimsdept@sg.cntaiping.com>

Cc: Chong Boon Sen <>

Dear Motor Claim Department,

Kindly arrange survey on **Monday 25/03/2019** for following vehicle,

Survey Before Repair

Your Vehicle No.: SKN2756K

Our Vehicle No.: SLB5372R

D.O.A: 21/03/2019

Location: 48 Toh Guan Road East # 01-121, Enterprise Hub, Singapore 608586

--

Thanks & Regards,

Yvette Zhao

SK Automobile Pte Ltd

48 Toh Guan Road East # 01-121

Enterprise Hub, Singapore 608586

D: +65 6266 0555 | F: +65 6266 3155 | pioneer@skauto.com.sg

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

--

Thanks & Regards,

Yvette Zhao

SK Automobile Pte Ltd

48 Toh Guan Road East # 01-121

Enterprise Hub, Singapore 608586

D: +65 6266 0555 | F: +65 6266 3155 | pioneer@skauto.com.sg

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Pioneer Workshop [mailto:pioneer@skauto.com.sg]
Sent: Monday, 25 March, 2019 9:27 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Fwd: Arrange Survey for SLB5372R (your veh: SKN2756K) D.O.A 21/03/2019

Dear Motor Claim Department,

Kindly arrange survey on **Monday 25/03/2019** for following vehicle,

Survey Before Repair

Your Vehicle No.: SKN2756K

Our Vehicle No.: SLB5372R

D.O.A: 21/03/2019

Location: 48 Toh Guan Road East # 01-121, Enterprise Hub, Singapore 608586

--

Thanks & Regards,

Yvette Zhao

SK Automobile Pte Ltd

48 Toh Guan Road East # 01-121

Enterprise Hub, Singapore 608586

D: +65 6266 0555 | F: +65 6266 3155 | [pioneer@skauto.com.s](mailto:pioneer@skauto.com.sg)

----- Forwarded message -----

From: Pioneer Workshop <pioneer@skauto.com.sg>
Date: Sat, Mar 23, 2019 at 5:42 PM
Subject: Arrange Survey for SLB5372R (your veh: SKN2756K) D.O.A 21/03/2019

Steve Chen (LKK Auto)

From: Pioneer Workshop <pioneer@skauto.com.sg>
Sent: Wednesday, April 17, 2019 6:02 PM
To: Steve Chen (LKK Auto)
Subject: Re: SLB5272R Finalize

Dear Steve,

Confirm \$12,150.00 and 12days

On Wed, Apr 17, 2019 at 4:54 PM Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

Dear Yvonne,

The above vehicle finalize \$12,150.00 (L/S, before GST). 12 days.

Kindly confirm.

Thanks

Best Regards,

Steve Chen| Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561| Email: SteveChen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2293J
Vehicle Details	
Vehicle No.:	SLB5372R
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Mar 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA AD 1.6 GLS AT
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	G4FGGU158673
Chassis No.:	KMHD841CMHU144115
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$17,294.00
Original Registration Date:	13 Apr 2016
First Registration Date:	13 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$17,294.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Apr 2026
PARF Rebate Amount:	\$12,970.00
Intended COE Rebate Details	
COE Expiry Date:	12 Apr 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,009.00
COE Rebate Amount:	\$32,421.00
Total Rebate Amount:	\$45,391.00

The information contained herein is correct as at 26 Mar 2019

OK



Hyundai Elantra 1.6A GLS \$64,800 \$7,880 /yr 17-Aug-2018 1,591 cc 20,000 km Sedan Available

Luxurious Black Elantra, Well Maintained By Owner, Sedem Drive With A Long Mileage Of 20k km Serviced By Hyundai Agent. Comes With 2 Digit Number Plate 100KTX, Worth Getting At A Decent Depreciation....

Posted: 11-Mar-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Save up to 25% on petrol
Compare the latest petrol discount credit cards on sgCarMart. Enjoy discounts as high as 25% on your petrol bills.
Find out more!



Hyundai Elantra 1.6A Elite \$61,800 \$7,810 /yr 02-Mar-2016 1,591 cc 12,932 km Sedan Available

1 Owner With Warranty Under Komoco Until 2021, Done Servicing Regularly And Well Maintained By Owner. Black Upholstery With Beautiful Blue Exterior, Convenience Unit, Flexible Loan Scheme Provided. No...

Car Search
Posted: 25-Mar-2019 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS Elite \$63,800 \$7,810 /yr 19-Apr-2016 1,591 cc 68,000 km Sedan Available

100% Loan Available, 1 Owner, Full Agent Komoco Maintained, Sporty White In Colour, Accident Free Unit, Higher Spec GLS Elite Model, Act Now To Test Drive Now!

Labels
Posted: 19-Mar-2019 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS \$61,800 \$7,520 /yr 25-Jul-2016 1,591 cc 24,000 km Sedan Available

100% Loan Available, 5 Model With Rear Aircon And Multi Function Control On Steering, Fully Maintained/Warranty By Agent Mileage Only 24000kms, Well Maintained By 1 Only Meticulous Owner. High CMV And...

Labels
Posted: 16-Mar-2019 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS Elite \$76,800 \$8,950 /yr 03-Nov-2016 1,591 cc 30,000 km Sedan Available

100% Loan Available, 1 Owner, Full Agent Komoco Maintained, Sporty White In Colour, Accident Free Unit, Higher Spec GLS ELITE Model, Act Now To Test Drive Now!

Labels
Posted: 16-Mar-2019 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS \$60,800 \$7,740 /yr 01-Apr-2016 1,591 cc 67,000 km Sedan Available

Face-lifted Model With Single Owner Only! Low Interest Of 1.90% For Limited Period Only! In-house Loan Available! Ongoing Warranty! Trade In Welcome! Family Oriented With Comfortable Cabin Yet Fuel Eff...

Labels
Posted: 14-Mar-2019 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS \$63,800 \$7,850 /yr 27-May-2018 1,591 cc 50,000 km Sedan Available

GPS And Reverse Camera, 1 Owner, Regular Serviced, Agent Unit, Guaranteed New Condition Trade In Welcome, Car Available In Showroom For Viewing Now, Contact For More Information.

Posted: 15-Mar-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS \$57,800 \$7,270 /yr 18-Mar-2016 1,591 cc 75,000 km Sedan Available

100% Loan Available! Reliable Yet Affordable And Low Fuel Consumption! Unit Definitely Not To Be Missed! An Excellent Choice For Family Due To Its Spacious Sitting And Car Book! 100% Accident Free! So...

Posted: 08-Mar-2019 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS \$60,800 \$7,710 /yr 11-Apr-2018 1,591 cc 53,000 km Sedan Available

High Loan Approval Rate! In House Financing Available, 1 Owner, Komoco Agent Serviced And Warranty, Low Mileage, 100% Accident Free, Original Partwork, Ideal Car For Your Family, Owner Changed New Ca...

Posted: 03-Mar-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS Elite \$68,000 \$7,610 /yr 24-Aug-2016 1,591 cc 55,500 km Sedan Available

A Comfortable Ride In This Beautiful City & Spacious Enough For A Family. Perfect Vehicle To Travel Around With Minimal Petrol Consumption. Well-taken Care By Owner & In A Superb Condition. Agent Serv...

Posted: 07-Mar-2019 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS Elite \$59,800 \$7,630 /yr 28-Jan-2016 1,591 cc 48,000 km Sedan Available

High Spec Elite Variant, Fully Maintained By Komoco Motors, 5 Years Warranty Unlimited Mileage, 100% Accident Free, STA Welcome, Sheltered Park, Like New, Highest Trade-In, Std Bank Loan, Balloon Loan...

Posted: 28-Feb-2019 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai

(Save this search criteria, to get email alerts whenever a match is found)

Model Price Depreciation Tax Cost Eng Cap Mileage Van Type

For old advertisements, view Expired ads

« Back [1 2] Next »

35 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for popular import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from cars, trucks, sedan cars, motor cars, sports cars, SUV, MPV, hatchback, to CDE cars & CMC cars. You can also buy from a car auction, hire up-car team, financial services, low mileage cars, car friends, carpark, hotel & car wash. Comments: 3 hyundai elantra, hyundai elantra Singapore, used hyundai elantra Singapore, used hyundai elantra, used vehicle Singapore or even buy used hyundai elantra Singapore.

Google AdSense

Monetize your site
With ads you can count on

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Up To 100% Loan, 5% GST, Guided R, & Shovel.



Low Mileage Used Car
Save up to 10% with 0% deposit
Car loan, Car Tax,
SGS Automobile (Pty) Ltd

Free TCOM evaluation
Free financing and 5 months maintenance
In-house workshop ensures quality service
Member of SITA and Jire purchase association
100% deposit refund for unsold/returned item

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Back (1 2) Next

Sort by Date Posted 20 results/page

26 vehicles

hyundai elantra

Advanced Search

Year	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

Search Selection Hyundai elantra Any Any 2016 Any Any Any Available



Hyundai Elantra 1.6A GLS \$62,800 \$7,320 /yr 16-Sep-2016 1,591 cc 36,000 km Sedan Available
Fully Agent Maintained! 1 Owner Only! Low Mileage Done, Flexible Bank/In House High Loan Available! Excellent Fuel Efficiency, Up To 15.8km/L.
Immaculate Condition, 100% Accident-Free! Buy With A Peace...

Autotrust Traders Pte Ltd
Posted: 26-Mar-2018 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, hyundai elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS \$62,800 \$7,320 /yr 28-Dec-2016 1,591 cc 38,700 km Sedan Available
1 Owner, Kindly Contact Us For An Appointment Or Visit Us At Our Showrooms Today, Buy And Sell With Assurance From A Credited Company At AKK
Wheels Pte Ltd. Where Quality Service Really Matters.

Posted: 25-Mar-2018 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, hyundai elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS Elite \$64,300 \$7,260 /yr 21-Nov-2016 1,591 cc - Sedan Available
Most Popular Hyundai Sedan For Your Family. Spacious & Reliable. Well Maintained & Service. No Further Repaired Needed. 1 Year Warranty Provided.
Beautiful Paintwork With Clean & Neat Interior, Bank D...

Herry Enterprises Co
Posted: 24-Mar-2018 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, hyundai elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS \$65,800 \$8,240 /yr 24-Jun-2016 1,591 cc 49,000 km Sedan Available
New Arrival, 1 Owner, Car Fully Maintained And Serviced By Agents, Car Under Warranty By Komoco Agent, Elegant Blue AD Elantra With Black Leather
Interior, High Loan Available, Trade In Are Welcome

Posted: 22-Mar-2018 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, hyundai elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Pro-Jex V2D Auto Pte Ltd - Specialist for Hyundai Car repair, servicing & maintenance
Power up for excellent performance with PRO-JEX V2D, your one-stop automobile solution provider.
Have info about this shop



Hyundai Elantra 1.6A Elite \$59,800 \$7,540 /yr 25-Feb-2016 1,591 cc 31,000 km Sedan Available
100% Loan Available, Comes With Keyless Entry And Rear Aircon, Full Agent Maintained And Still Under Warranty, Beautiful Interior And Sleek Finish.
Call To View And Test Drive Now! Extremely Low Mile...

1265
Posted: 23-Mar-2018 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, hyundai elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A Elite \$59,800 \$7,560 /yr 18-Feb-2016 1,591 cc 41,000 km Sedan Available
100% Loan Available, 1 Owner, Full Agent Komoco Maintained, Sporty White In Colour, Accident Free Unit, Higher Spec GLS Elite Model, Act Now To
Test Drive Now!

1265
Posted: 22-Mar-2018 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, hyundai elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A Elite \$59,800 \$7,620 /yr 29-Jan-2016 1,591 cc 53,000 km Sedan Available
100% Loan Available, Comes With Keyless Entry And Rear Aircon, Full Agent Maintained And Still Under Warranty, Beautiful Interior And Sleek Finish.
Call To View And Test Drive Now! Extremely Low Mile...

1265
Posted: 21-Mar-2018 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, hyundai elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A Elite \$59,800 \$7,560 /yr 18-Feb-2016 1,591 cc 40,000 km Sedan Available
100% Loan Available, Comes With Keyless Entry And Rear Aircon, Full Agent Maintained And Still Under Warranty, Beautiful Interior And Sleek Finish.
Call To View And Test Drive Now! Extremely Low Mile...

1265
Posted: 21-Mar-2018 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, hyundai elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A Elite \$60,800 \$7,610 /yr 21-Mar-2016 1,591 cc 37,212 km Sedan Available
Latest Elite Model, Top Top Excellent Condition, 1 Owner, 100% Accident Free, In House/Bank Loans Available, Call Us At Our Showroom For An
Appointment Today, Buy And Sell With Assurance From A Cred...

Compuart
Posted: 21-Mar-2018 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, hyundai elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/03/2019 08:15
Date Of Accident	21/03/2019 18:20
Exact Location Of Accident	TPE TOWARDS YIO CHU KANG (JALAN KAYU EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB5372R
Insured/Policyholder	
Name Of Registered Owner	SIM JUN XIANG DANIEL
NRIC No	S8622293J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81121677
Alternative Phone No	OFFICE-81121677

Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELANTRA-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B28931975QMY
Cover Note Number	

Driver

Name of Driver	LIM HUI NING CHRISTIANA
NRIC No	S8838948D
Date Of Birth	12/10/1988
Occupation	INDOOR
Date Of Driving Pass	30/12/2009
Driving Experience	9 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97455658
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	15 FERNVALE LANE #10-16
Postcode	797497
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	STILL DOWNLOADING
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKN2756K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHC8583X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

A : SUB 5372 R

B : SKN 2756 E

C : SHC 8583 X

TPE -> Yio Chu Kang
(Before Jln Kayu)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2/3/12 @ 1220 hrs, I was travelling on lane 1 on TPE towards Yio Chu Kang before Jln Kayu.

It was raining heavily, traffic was moving smoothly. The vehicle in front of me slow-down and I follow suit.

My vehicle stopped and was stationary for a few seconds. Suddenly the vehicle behind me hit my rear. The impact caused my vehicle to move forward to hit vehicle in front. My vehicle was damaged as a result of the accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SK Automobile Pte. Ltd.
(Co Reg. No. 201500047H)
48 Toh Guan Road Esat #01-121
Enterprise Hub S(608586)
Tel: 6266 0555 Fax : 6266 3155

[Signature] 27/3/19

TO	: CN TAIPING	DATE	: 23-Mar-19
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
ESTIMATE REPORT	: Steve (LKR) w/ m/sic	26/3/19	3:30pm
OWNER PARTICULAR		VEHICLE DETAILS	
NAME	: L15	VEHICLE NO.	: SLB5372R
ADDRESS	: Ag Al	MODEL / MAKE	: HYUNDAI AVANTE
TEL. NO.	: Ag Al	CHASSIS NO.	: KMHD841CMHU144115
OWNER INSURANCE	: MSIG	ACCIDENT DETAIL	
POLICY NO.	: B28931975QMY	DATE	: 25/3/2019
		TIME	: 18:20 HRS
PERSON INCHARGE	:		

QUOTATION SUMMARY PAGE 01
CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BOOT LID	1	\$ 1,690.67	\$ 1,690.67
2	REAR BOOT LID LOGO EMBLEM	1	\$ 82.14	\$ 82.14
3	REAR BOOT LID ELITE EMBLEM	1	\$ 65.32	\$ 65.32
4	REAR BOOT LID ELANTRA EMBLEM	1	\$ 78.42	\$ 78.42
5	REAR BOOT LID REFLECTOR LED LAMP LH/RH	2	\$ 664.90	\$ 1,329.80
6	REAR BOOT LID OUTER LOCK HANDLE SWITCH WITH REVERSE CAMERA	1	\$ 652.97	\$ 652.97
7	REAR BOOT LID NUMBER PLATE LAMP LH/RH	2	\$ 55.65	\$ 111.30
8	REAR BOOT LID HINGES LH/RH	2	\$ 145.42	\$ 290.84
9	REAR BOOT LID INNER UPHOLSTERY TRIM	1	\$ 358.31	\$ 358.31
10	REAR BOOT LID INNER HANDLE	1	\$ 112.10	\$ 112.10
11	REAR BOOT LID RUBBER GUIDE STOPPER LH/RH	2	\$ 40.29	\$ 80.58
12	REAR BOOT LID MECHANISM LOCK	1	\$ 208.70	\$ 208.70
13	REAR BOOT LID WEATHER STRIP	1	\$ 92.50	\$ 92.50
14	REAR BUMPER	1	\$ 489.24	\$ 489.24
15	REAR BUMPER REFLECTOR LH/RH	2	\$ 31.90	\$ 63.80
16	REAR BUMPER SIDE RETAINER LH/RH	2	\$ 44.30	\$ 88.60
17	REAR BUMPER INNER SIDE SHIELD RH	1	\$ 145.65	\$ 145.65
18	REAR BUMPER LOWER UNDER COVER LH	1	\$ 151.32	\$ 151.32
19	REAR BUMPER TOP BRACKET LH/RH	2	\$ 25.71	\$ 51.42
20	REAR BUMPER REINFORCEMENT	1	\$ 548.42	\$ 548.42
21	REAR BUMPER INNER BOOT LID ANTENA SENSOR	1	\$ 325.61	\$ 325.61
22	REAR BUMPER LOWER DIFFUSER	1	\$ 280.10	\$ 280.10
23	REAR BUMPER INNER BOOT LID ANTENA SENSOR WIRE HARNESS	1	\$ 198.27	\$ 198.27
24	REAR BLIND SPOT DETECTION SENSOR LH	1	\$ 1,660.10	\$ 1,660.10
25	REAR BLIND SPOT DETECTION SENSOR BRACKET LH	1	\$ 186.20	\$ 186.20
26	REAR BLIND SPOT DETECTION SENSOR WIRE HARNESS LH	1	\$ 219.40	\$ 219.40
27	REAR BLIND SPOT DETECTION SENSOR ABSORBER LH	1	\$ 97.10	\$ 97.10

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
28	REAR TAILLAMP LED LH/RH <i>LH ? RH ? OR</i>	2	\$ 876.90	\$ 1,753.80
29	REAR TAILLAMP INNER PANEL LH/RH <i>X NM</i>	2	\$ 358.78	\$ 717.56
30	REAR END PANEL <i>/ DD</i>	1	\$ 480.72	\$ 480.72
31	REAR END PANEL INNER TOP GARNISH <i>/ OR</i>	1	\$ 159.80	\$ 159.80
32	REAR END PANEL INNER BOOT LID ANTENA SENSOR <i>? X NM</i>	1	\$ 325.61	\$ 325.61
33	REAR END PANEL LOCK STRIKER <i>X NM</i>	1	\$ 43.70	\$ 43.70
34	SPARE TYRE PANEL <i>/ DD</i>	1	\$ 789.48	\$ 789.48
35	SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD <i>/ TN</i>	1	\$ 219.10	\$ 219.10
36	SPARE TYRE RETAINER LOCK <i>? / OR</i>	1	\$ 10.90	\$ 10.90
37	SPARE TYRE SIDE PANEL LH/RH <i>X NM</i>	2	\$ 245.62	\$ 491.24
38	REAR SUB CHASSIS FRAME LH/RH <i>X NM</i>	2	\$ 1,189.10	\$ 2,378.20
39	REAR SUB CHASSIS FRAME TOP PANEL LH/RH <i>X NM</i>	2	\$ 813.14	\$ 1,626.28
40	REAR FENDER LH/RH <i>X NM RH-P LH-R</i>	2	\$ 1,769.12	\$ 3,538.24
41	REAR FENDER INNER UPHOLSTERY TRIM LH/RH <i>LH / TN RH X</i>	2	\$ 207.90	\$ 415.80
42	REAR FENDER INNER SHIELD LH/RH <i>X NM</i>	2	\$ 112.30	\$ 224.60
43	REAR FENDER STONE PROTECTIVE STICKER LH/RH <i>X NM LU, 2</i>	2	\$ 27.02	\$ 54.04
44	REAR WINDSCREEN MOULDING <i>X NM</i>	1	\$ 129.80	\$ 129.80
45	REAR EXHAUST SILENCER BOX <i>/ DD</i>	1	\$ 789.00	\$ 789.00
46	REAR EXHAUST ALUMINIUM HEAT SHIELD <i>/ DD</i>	1	\$ 130.00	\$ 130.00
47	FRONT GRILLE <i>/ OR</i>	1	\$ 1,082.90	\$ 1,082.90
48	FRONT GRILLE LOGO EMBLEM <i>/ NM</i>	1	\$ 56.90	\$ 56.90
49	FRONT GRILLE CHROME MOULDING <i>? X CRU (C) NM</i>	1	\$ 256.20	\$ 256.20
50	FRONT HEADLAMP LH/RH <i>X LH / RH / OR</i>	2	\$ 1,756.40	\$ 3,512.80
51	FRONT BUMPER <i>X / OR</i>	1	\$ 675.94	\$ 675.94
52	FRONT BUMPER REINFORCEMENT <i>? X R</i>	1	\$ 548.49	\$ 548.49
53	FRONT BUMPER TOP RUBBER SEAL <i>? X NM</i>	1	\$ 65.30	\$ 65.30
54	FRONT BUMPER SIDE RETAINER LH/RH <i>RH / LH / OR</i>	2	\$ 43.61	\$ 87.22
55	FRONT BUMPER CORNER RETAINER LH/RH <i>? RH / LH / OR</i>	2	\$ 86.70	\$ 173.40
56	FRONT BUMPER INNER SPONGE <i>? / OR</i>	1	\$ 212.83	\$ 212.83
57	FRONT BUMPER TOP BRACKET <i>? X NM</i>	2	\$ 86.70	\$ 173.40
58	FRONT BUMPER LOWER BEAM <i>? NM X</i>	1	\$ 81.00	\$ 81.00
59	FRONT BUMPER LOWER UNDER COVER <i>X NM</i>	1	\$ 321.57	\$ 321.57
60	FRONT BUMPER NUMBER PLATE GARNISH <i>/ DD</i>	1	\$ 189.50	\$ 189.50
61	FRONT SUPPORT PANEL <i>? / CRU</i>	1	\$ 1,159.70	\$ 1,159.70
62	FRONT SUPPORT PANEL TOP GARNISH <i>? / OR</i>	1	\$ 179.50	\$ 179.50
63	AIRCON CONDENSER <i>? X NM</i>	1	\$ 1,125.50	\$ 1,125.50
64	AIRCON CONDENSER AIR GUIDE LH/RH <i>? LH / RH / CRU</i>	2	\$ 38.90	\$ 77.80

TOTAL PRICE \$ 33,916.70

LESS -20% \$ (6,783.34)

SUB TOTAL PRICE \$ 27,133.36

14,443.29
- 20%
11,554.63

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BOOT LID REFLECTOR LED LAMP CLIPS SET LH/RH / <i>NEC</i>	2	\$ 10.00	\$ 20.00 <i>10</i>
2	REAR BOOT LID INNER UPHOLSTERY TRIM CLIPS SET / <i>NEC</i>	1	\$ 50.00	\$ 50.00 <i>20</i>
3	REAR BOOT LID SEALANT / <i>NEC</i>	1	\$ 100.00	\$ 100.00 <i>20</i>
4	REAR BUMPER REVERSE SENSOR SET / <i>NR</i>	1	\$ 280.00	\$ 280.00 <i>210</i>
5	REAR BUMPER CLIPS SET / <i>NEC</i>	1	\$ 60.00	\$ 60.00 <i>20</i>
6	REAR TAILLAMP CLIPS SET LH/RH / <i>NEC</i>	2	\$ 20.00	\$ 40.00 <i>10</i>
7	REAR TAILLAMP INNER PANEL SEALANT LH/RH <i>?</i> X <i>NR</i>	2	\$ 30.00	\$ 60.00 X
8	REAR END PANEL INNER TOP GARNISH CLIPS SET / <i>NEC</i>	1	\$ 30.00	\$ 30.00 <i>10</i>
9	REAR END PANEL SEALANT / <i>NEC</i>	1	\$ 80.00	\$ 80.00 <i>20</i>
10	SPARE TYRE PANEL SEALANT <i>?</i> <i>NEC</i>	1	\$ 100.00	\$ 100.00 <i>30</i>
11	REAR FENDER INNER UPHOLSTERY TRIM CLIPS SET LH/RH / <i>NEC</i>	2	\$ 60.00	\$ 120.00 <i>20</i>
12	REAR FENDER INNER SHIELD CLIPS SET LH/RH <i>?</i> LH / <i>NEC</i>	2	\$ 40.00	\$ 80.00 <i>10</i>
13	REAR EXHAUST GASKET / <i>NEC</i>	1	\$ 25.00	\$ 25.00 <i>20</i>
14	REAR WINDSCREEN SEALANT WITH PRIMER X <i>NR</i>	1	\$ 100.00	\$ 100.00 X
15	FRONT GRILLE CLIPS SET / <i>NEC</i>	1	\$ 30.00	\$ 30.00 <i>10</i>
16	FRONT BUMPER CLIPS SET / <i>NEC</i>	1	\$ 60.00	\$ 60.00 <i>20</i>
17	FRONT BUMPER RIVETS SET / <i>NEC</i>	1	\$ 50.00	\$ 50.00 <i>20</i>
18	FRONT BUMPER NUMBER PLATE WITH CASING SET / <i>NR</i>	1	\$ 65.00	\$ 65.00 <i>35</i>
19	FRONT SUPPORT PANEL TOP GARNISH CLIPS SET / <i>NEC</i>	1	\$ 20.00	\$ 20.00 <i>10</i>
20	FRONT FENDER INNER SHIELD CLIPS SET LH/RH / <i>NEC</i>	2	\$ 60.00	\$ 120.00 <i>10</i>
21	RADIATOR COOLANT <i>?</i> / <i>NEC</i>	1	\$ 80.00	\$ 80.00 <i>20</i>

TOTAL

\$ 1,570.00

515

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING REAR PORTION

TO DISMANTLE & REPLACED WITH PANEL (Rear) BEATING ALL THE ACCIDENT PORTION	\$ 2,000.00	800	
TO SPRAY PAINTING ALL THE ACCIDENT (Rear) PORTION & POLISHING AFFECTED AREA	\$ 1,800.00	900	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 200.00	30	
TO PERFORM LIGHTING & WIRING CHECK	\$ 90.00	30	
TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION	\$ 380.00	X N/A	
TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR	\$ 250.00	? / 120	
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT TO PERFORM FACILITATE REPAIRS	\$ 260.00	X N/A	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00	20	
TO DISMANTLE & REPLACED REAR BOOT LID REVERSE CAMERA WITH SETTING	\$ 80.00	20	
TO DISMANTLE & REPLACED REAR EXHAUST SILENCER BOX WITH REALIGN EXHAUST MID PIPE & RUBBER MOUNTING	\$ 180.00	80	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	50	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	50	

TOTAL

\$ 5,680.00

2080

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL <i>(front)</i> BEATING ALL THE ACCIDENT PORTION	\$ 600.00	500	
TO SPRAY PAINTING ALL THE ACCIDENT <i>(front)</i> PORTION & POLISHING AFFECTED AREA	\$ 600.00	400	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 40.00	20	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	X N/A	
TO DISMANTLE & REINSTALL AIRCON CONDENSOR WITH REFILL AIRCON GAS	\$ 120.00	? / 60	
TO DISMANTLE & REINSTALL RADIATOR WITH REFILL RADIATOR COOLANT & HIGH PRESSURE TEST	\$ 120.00	? / 60	

TOTAL \$ 1,560.00

1040 + 2080 = 3120 ✓

ESTIMATE REPORT

TOTAL PARTS COST : \$ 28,703.36
TOTAL LABOUR COST : \$ 7,240.00
TOTAL REPAIR COST : \$ 35,943.36

APPROVED DETAILS

EXCESS :
NO. OF REPAIR DAYS :
RE-SURVEY :
P / P OR L / S :

DATE / TIME OF SURVEY :
SURVEYED BY / FROM :
CONTACT NUMBER :
FAX NUMBER :
EMAIL ADDRESS :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 11,554-63

N- 515

L- 3120

15,189-63

L/S- 12,151.70

= 12,150 ✓

SK Automobile Pte. Ltd.
(Co Reg. No. 201500047H)
48 Toh Guan Road Esat #01-121
Enterprise Hub S(608586)
Tel: 6266 0555 Fax : 6266 3155

[Signature] 27/3/19

TO	: CN TAIPING	DATE	: 23-Mar-19
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
ESTIMATE REPORT	: <i>Steve (LKR) with approval 26/3/19 3:30pm</i>		
OWNER PARTICULAR		VEHICLE DETAILS	
NAME	: <i>12 days</i> <i>LIS / [Signature]</i>	VEHICLE NO.	: SLB5372R
ADDRESS	: <i>Ry AL [Signature]</i>	MODEL / MAKE	: HYUNDAI AVANTE
TEL. NO.	: <i>Mj AL [Signature]</i>	CHASSIS NO.	: KMHD841CMHU144115
OWNER INSURANCE	: MSIG	ACCIDENT DETAIL	
POLICY NO.	: B28931975QMY	DATE	: 25/3/2019
		TIME	: 18:20 HRS
PERSON INCHARGE	:		

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BOOT LID / <i>DD</i>	1	\$ 1,690.67	\$ 1,690.67
2	REAR BOOT LID LOGO EMBLEM / <i>NEC</i>	1	\$ 82.14	\$ 82.14
3	REAR BOOT LID ELITE EMBLEM / <i>NEC</i>	1	\$ 65.32	\$ 65.32
4	REAR BOOT LID ELANTRA EMBLEM / <i>NEC</i>	1	\$ 78.42	\$ 78.42
5	REAR BOOT LID REFLECTOR LED LAMP LH/RH / <i>OR ? LH / RH</i>	2	\$ 664.90	\$ 1,329.80
6	REAR BOOT LID OUTER LID HANDLE SWITCH WITH REVERSE CAMERA / <i>MM</i>	1	\$ 653.07	\$ 653.07
7	REAR BOOT LID NUMBER PLATE LAMP LH/RH / <i>MM</i>	2	\$ 55.65	\$ 111.30
8	REAR BOOT LID HINGEE LH/RH / <i>P</i>	2	\$ 105.42	\$ 210.84
9	REAR BOOT LID INNER UPHOLESTERY TRIM / <i>MM</i>	1	\$ 358.31	\$ 358.31
10	REAR BOOT LID INNER HANDLE / <i>MM</i>	1	\$ 112.10	\$ 112.10
11	REAR BOOT LID RUBBER GUIDE STOPPER LH/RH / <i>MM</i>	2	\$ 40.30	\$ 80.60
12	REAR BOOT LID MECHANISM LOCK / <i>BT</i>	1	\$ 208.70	\$ 208.70
13	REAR BOOT LID WEATHER STRIP / <i>TN</i>	1	\$ 92.50	\$ 92.50
14	REAR BUMPER / <i>OR</i>	1	\$ 489.24	\$ 489.24
15	REAR BUMPER REFLECTOR LH/RH / <i>RH LH / OR</i>	2	\$ 31.90	\$ 63.80
16	REAR BUMPER SIDE RETAINER LH/RH / <i>RH LH / OR</i>	2	\$ 44.30	\$ 88.60
17	REAR BUMPER INNER SIDE SHIELD RH / <i>MM</i>	1	\$ 145.65	\$ 145.65
18	REAR BUMPER LOWER UNDER COVER LH / <i>OR</i>	1	\$ 151.32	\$ 151.32
19	REAR BUMPER TOP BRACKET LH/RH / <i>MM</i>	2	\$ 25.71	\$ 51.42
20	REAR BUMPER REINFORCEMENT / <i>DD</i>	1	\$ 548.42	\$ 548.42
21	REAR BUMPER INNER BOOT LID ANTENA SENSOR / <i>OR</i>	1	\$ 325.61	\$ 325.61
22	REAR BUMPER LOWER DIFFUSER / <i>CMY</i>	1	\$ 280.10	\$ 280.10
23	REAR BUMPER INNER BOOT LID ANTENA SENSOR WIRE HARNESS / <i>TN</i>	1	\$ 198.27	\$ 198.27
24	REAR BLIND SPOT DETECTION SENSOR LH / <i>MM</i>	1	\$ 1,660.10	\$ 1,660.10
25	REAR BLIND SPOT DETECTION SENSOR BRACKET LH / <i>MM</i>	1	\$ 186.30	\$ 186.30
26	REAR BLIND SPOT DETECTION SENSOR WIRE HARNESS LH / <i>MM</i>	1	\$ 219.40	\$ 219.40
27	REAR BLIND SPOT DETECTION SENSOR ABSORBER LH / <i>MM</i>	1	\$ 97.10	\$ 97.10

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
28	REAR TAILLAMP LED LH/RH LH / RH ✓	2	\$ 876.90	\$ 1,753.80
29	REAR TAILLAMP INNER PANEL LH/RH LH / RH ✓	2	\$ 358.78	\$ 717.56
30	REAR END PANEL / DD	1	\$ 480.72	\$ 480.72
31	REAR END PANEL INNER TOP GARNISH / OR	1	\$ 159.80	\$ 159.80
32	REAR END PANEL INNER BOOT LID ANTENNA SENSOR LH / RH ✓	1	\$ 325.81	\$ 325.81
33	REAR END PANEL LOCK STRIKER LH / RH ✓	1	\$ 43.78	\$ 43.78
34	SPARE TYRE PANEL / DD	1	\$ 789.48	\$ 789.48
35	SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD / TN	1	\$ 219.10	\$ 219.10
36	SPARE TYRE RETAINER LOCK / OR	1	\$ 10.90	\$ 10.90
37	SPARE TYRE SIDE PANEL LH/RH LH / RH ✓	2	\$ 245.63	\$ 491.24
38	REAR SUB CHASSIS FRAME LH/RH LH / RH ✓	2	\$ 1,169.10	\$ 2,338.20
39	REAR SUB CHASSIS FRAME TOP PANEL LH/RH LH / RH ✓	2	\$ 813.14	\$ 1,626.28
40	REAR FENDER LH/RH LH / RH ✓	2	\$ 1,769.12	\$ 3,538.24
41	REAR FENDER INNER UPHOLSTERY TRIM LH/RH LH / TN RH X2	2	\$ 207.90	\$ 415.80
42	REAR FENDER INNER SHIELD LH/RH LH / RH ✓	2	\$ 112.30	\$ 224.60
43	REAR FENDER STONE PROTECTIVE STICKER LH/RH LH / RH ✓	2	\$ 27.02	\$ 54.04
44	REAR WINDSCREEN MOULDING LH / RH ✓	1	\$ 120.00	\$ 120.00
45	REAR EXHAUST SILENCER BOX / DD	1	\$ 789.00	\$ 789.00
46	REAR EXHAUST ALUMINIUM HEAT SHIELD / DD	1	\$ 130.00	\$ 130.00
47	FRONT GRILLE / OR	1	\$ 1,082.90	\$ 1,082.90
48	FRONT GRILLE LOGO EMBLEM / ALP	1	\$ 56.90	\$ 56.90
49	FRONT GRILLE CHROME MOULDING / CH	1	\$ 256.20	\$ 256.20
50	FRONT HEADLAMP LH/RH LH / RH ✓	2	\$ 1,756.40	\$ 3,512.80
51	FRONT BUMPER LH / RH ✓	1	\$ 675.04	\$ 675.04
52	FRONT BUMPER REINFORCEMENT LH / RH ✓	1	\$ 548.40	\$ 548.40
53	FRONT BUMPER TOP RUBBER SEAL LH / RH ✓	1	\$ 65.30	\$ 65.30
54	FRONT BUMPER SIDE RETAINER LH/RH RH / LH ✓	2	\$ 43.61	\$ 87.22
55	FRONT BUMPER CORNER RETAINER LH/RH LH / RH ✓	2	\$ 86.70	\$ 173.40
56	FRONT BUMPER INNER SPONGE LH / RH ✓	1	\$ 212.83	\$ 212.83
57	FRONT BUMPER TOP BRACKET LH / RH ✓	2	\$ 66.70	\$ 133.40
58	FRONT BUMPER LOWER BEAM LH / RH ✓	1	\$ 81.00	\$ 81.00
59	FRONT BUMPER LOWER UNDER COVER LH / RH ✓	1	\$ 321.57	\$ 321.57
60	FRONT BUMPER NUMBER PLATE GARNISH / DD	1	\$ 189.50	\$ 189.50
61	FRONT SUPPORT PANEL LH / RH ✓	1	\$ 1,159.70	\$ 1,159.70
62	FRONT SUPPORT PANEL TOP GARNISH LH / RH ✓	1	\$ 179.50	\$ 179.50
63	AIRCON CONDENSER LH / RH ✓	1	\$ 1,125.50	\$ 1,125.50
64	AIRCON CONDENSER AIR GUIDE LH/RH LH / RH ✓	2	\$ 38.90	\$ 77.80

TOTAL PRICE	\$ 33,916.70	\$17,495.80
LESS -20%	\$ (6,783.34)	\$ (3,499.16)
SUB TOTAL PRICE	\$ 27,133.36	\$13,996.64

QUOTATION SUMMARY

PAGE 03

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BOOT LID REFLECTOR LED LAMP CLIPS SET LH/RH / <i>NEC</i>	2	\$ 10.00	\$ 20.00 <i>10</i>
2	REAR BOOT LID INNER UPHOLSTERY TRIM CLIPS SET / <i>NEC</i>	1	\$ 50.00	\$ 50.00 <i>20</i>
3	REAR BOOT LID SEALANT / <i>NEC</i>	1	\$ 100.00	\$ 100.00 <i>20</i>
4	REAR BUMPER REVERSE SENSOR SET / <i>NR</i>	1	\$ 280.00	\$ 280.00 <i>20</i>
5	REAR BUMPER CLIPS SET / <i>NEC</i>	1	\$ 60.00	\$ 60.00 <i>27</i>
6	REAR TAILLAMP CLIPS SET LH/RH / <i>NEC</i>	2	\$ 20.00	\$ 40.00 <i>10</i>
7	REAR TAILLAMP INNER PANEL SEALANT LH/RH / <i>NEC</i>	2	\$ 30.00	\$ 60.00 <i>X</i>
8	REAR END PANEL INNER TOP GARNISH CLIPS SET / <i>NEC</i>	1	\$ 30.00	\$ 30.00 <i>10</i>
9	REAR END PANEL SEALANT / <i>NEC</i>	1	\$ 80.00	\$ 80.00 <i>20</i>
10	SPARE TYRE PANEL SEALANT / <i>NEC</i>	1	\$ 100.00	\$ 100.00 <i>30</i>
11	REAR FENDER INNER UPHOLSTERY TRIM CLIPS SET LH/RH / <i>NEC</i>	2	\$ 60.00	\$ 120.00 <i>20</i>
12	REAR FENDER INNER SHIELD CLIPS SET LH/RH / <i>NEC</i>	2	\$ 40.00	\$ 80.00 <i>10</i>
13	REAR EXHAUST GASKET / <i>NEC</i>	1	\$ 25.00	\$ 25.00 <i>20</i>
14	REAR WINDSCREEN SEALANT WITH PRIMER / <i>NEC</i>	1	\$ 100.00	\$ 100.00 <i>10</i>
15	FRONT GRILLE CLIPS SET / <i>NEC</i>	1	\$ 30.00	\$ 30.00 <i>20</i>
16	FRONT BUMPER CLIPS SET / <i>NEC</i>	1	\$ 60.00	\$ 60.00 <i>20</i>
17	FRONT BUMPER RIVETS SET / <i>NEC</i>	1	\$ 50.00	\$ 50.00 <i>25</i>
18	FRONT BUMPER NUMBER PLATE WITH CASING SET / <i>NEC</i>	1	\$ 65.00	\$ 65.00 <i>10</i>
19	FRONT SUPPORT PANEL TOP GARNISH CLIPS SET / <i>NEC</i>	1	\$ 20.00	\$ 20.00 <i>10</i>
20	FRONT FENDER INNER SHIELD CLIPS SET LH/RH / <i>NEC</i>	2	\$ 60.00	\$ 120.00 <i>20</i>
21	RADIATOR COOLANT / <i>NEC</i>	1	\$ 80.00	\$ 80.00 <i>20</i>

TOTAL

\$ 1,570.00 \$515.00

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING REAR PORTION

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 2,000.00	888	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,800.00	900	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 200.00	30	
TO PERFORM LIGHTING & WIRING CHECK	\$ 90.00	30	
TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION	\$ 380.00	X	
TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR	\$ 250.00	? \$ 120.00	
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT TO PERFORM FACILITATE REPAIRS	\$ 260.00	X	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00	20	
TO DISMANTLE & REPLACED REAR BOOT LID REVERSE CAMERA WITH SETTING	\$ 80.00	20	
TO DISMANTLE & REPLACED REAR EXHAUST SILENCER BOX WITH REALIGN EXHAUST MID PIPE & RUBBER MOUNTING	\$ 180.00	80	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	50	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	50	

TOTAL \$ 5,680.00 \$2,080.00

QUOTATION SUMMARY

PAGE 05

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 600.00	500	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 600.00	400	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 40.00	20	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	Y	
TO DISMANTLE & REINSTALL AIRCON CONDENSOR WITH REFILL AIRCON GAS	\$ 120.00	9 60.00	
TO DISMANTLE & REINSTALL RADIATOR WITH REFILL RADIATOR COOLANT & HIGH PRESSURE TEST	\$ 120.00	7 60.00	

TOTAL \$ 1,560.00

ESTIMATE REPORT

TOTAL PARTS COST	:	\$ 28,703.36
TOTAL LABOUR COST	:	\$ 7,240.00
TOTAL REPAIR COST	:	\$ 35,943.36

APPROVED DETAILS

EXCESS :
NO. OF REPAIR DAYS :
RE-SURVEY :
P / P OR L / S :

DATE / TIME OF SURVEY :
SURVEYED BY / FROM :
CONTACT NUMBER :
FAX NUMBER :
EMAIL ADDRESS :

Parts	\$ 13,996.64
SN	\$ 515.00
	\$ 14,511.64
Labour	\$ 3,120.00
	\$ 17,631.64
L/s less 20%	\$ 3,526.33
	\$ 14,105.31

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 May 2019		09 May 2019 14:37 Edit Adj Rpt	S\$12,150.00 Edit Estimates	S\$12,150.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Co. Reg. No.: -								
Main Claimant:	SIM JUN XIANG DANIEL , ID: S86222933								
Vehicle Reg. No.:	SLB5372R	Date of Loss:	21/03/2019 18:00 - :59 [35 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201533C02	Policy/Cover Note No.:	DMPCSN30419418000						
Vehicle Reg. No. (Insured):	SKN2756K	Policy No. (Claimant):	B28931975QMY						
		Excess:	S\$0.00						
Repairer:	SK Automobile Pte Ltd (Toh Guan) 48 Toh Guan Road East #01-121, Enterprise Hub, 608586 Jurong East - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 21/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLB5372R (SNM19D201533C02)**
[SKN2756K]

TP
SIM JUN XIANG DANIEL
Mar 21 2019 6:00PM
[-]
SK Automobile Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	TC AutoClinic Pte Ltd (Lok Yang)	Thumbnail	Print
1	23/03/19 08:36	Accident Statement	 Load HTML	
Photos/Images			3 per page	☒
No	Finalized On	TC AutoClinic Pte Ltd (Lok Yang)	Thumbnail	Print
1	23/03/19 08:25	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
2	23/03/19 08:25	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
3	23/03/19 08:25	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
4	23/03/19 08:25	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
5	23/03/19 08:25	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
6	23/03/19 08:25	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
7	23/03/19 08:25	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/05/19 15:03	General View	 Load JPG	☒
2	09/05/19 15:03	General View	 Load JPG	☒
3	09/05/19 15:03	General View	 Load JPG	☒
4	09/05/19 15:03	General View	 Load JPG	☒
5	09/05/19 15:03	Odometer Reading	 Load JPG	☒
6	09/05/19 15:03	General View	 Load JPG	☒
7	09/05/19 15:03	General View	 Load JPG	☒
8	09/05/19 15:03	Chassis Number	 Load JPG	☒
9	09/05/19 15:03	General View	 Load JPG	☒
10	09/05/19 15:03	General View	 Load JPG	☒
11	09/05/19 15:03	General View	 Load JPG	☒
12	09/05/19 15:03	General View	 Load JPG	☒
13	09/05/19 15:03	General View	 Load JPG	☒
14	09/05/19 15:03	General View	 Load JPG	☒
15	09/05/19 15:03	General View	 Load JPG	☒
16	09/05/19 15:03	General View	 Load JPG	☒
17	09/05/19 15:03	General View	 Load JPG	☒
18	09/05/19 15:03	General View	 Load JPG	☒
19	09/05/19 15:03	General View	 Load JPG	☒
20	09/05/19 15:03	General View	 Load JPG	☒
21	09/05/19 15:03	General View	 Load JPG	☒
22	09/05/19 15:03	General View	 Load JPG	☒
23	09/05/19 15:03	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	TC AutoClinic Pte Ltd (Lok Yang)	Thumbnail	Print
24	09/05/19 15:03	General View		☒
25	09/05/19 15:03	General View		☒
26	09/05/19 15:03	General View		☒
27	09/05/19 15:03	General View		☒
28	09/05/19 15:03	General View		☒
29	09/05/19 15:03	General View		☒
30	09/05/19 15:03	General View		☒
31	09/05/19 15:03	General View		☒
32	09/05/19 15:03	General View		☒
33	09/05/19 15:03	General View		☒
34	09/05/19 15:03	General View		☒
35	09/05/19 15:03	General View		☒
36	09/05/19 15:03	General View		☒
37	09/05/19 15:03	General View		☒
38	09/05/19 15:03	General View		☒
39	09/05/19 15:03	General View		☒
40	09/05/19 15:03	General View		☒
41	09/05/19 15:03	General View		☒
42	09/05/19 15:03	General View		☒
43	09/05/19 15:03	General View		☒
44	09/05/19 15:03	General View		☒
45	09/05/19 15:03	General View		☒
46	09/05/19 15:03	General View		☒
47	09/05/19 15:03	General View		☒
48	09/05/19 15:03	General View		☒
49	09/05/19 15:03	General View		☒
50	09/05/19 15:03	General View		☒
51	09/05/19 15:03	General View		☒
52	09/05/19 15:03	General View		☒
53	09/05/19 15:03	General View		☒
54	09/05/19 15:03	General View		☒
55	09/05/19 15:03	General View		☒
56	09/05/19 15:03	General View		☒
57	09/05/19 15:03	General View		☒
58	09/05/19 15:03	General View		☒
59	09/05/19 15:03	General View		☒
60	09/05/19 15:03	General View		☒
61	09/05/19 15:03	General View		☒
62	09/05/19 15:03	General View		☒
63	09/05/19 15:03	General View		☒
64	09/05/19 15:03	General View		☒
65	09/05/19 15:03	General View		☒
66	09/05/19 15:03	General View		☒
67	09/05/19 15:03	General View		☒
68	09/05/19 15:03	General View		☒
69	09/05/19 15:03	General View		☒
70	09/05/19 15:03	General View		☒
71	09/05/19 15:03	General View		☒
72	09/05/19 15:03	General View		☒
73	09/05/19 15:03	General View		☒

Assessment Reports			1 per page	☒
No	Finalized On	TC AutoClinic Pte Ltd (Lok Yang)	Thumbnail	Print
74	09/05/19 15:03	General View	 Load JPG	☒
75	09/05/19 15:03	General View	 Load JPG	☒
76	09/05/19 15:03	General View	 Load JPG	☒
77	09/05/19 15:03	General View	 Load JPG	☒
78	09/05/19 15:03	General View	 Load JPG	☒
79	09/05/19 15:03	General View	 Load JPG	☒
80	09/05/19 15:03	General View	 Load JPG	☒
81	09/05/19 15:03	General View	 Load JPG	☒
82	09/05/19 15:03	General View	 Load JPG	☒
83	09/05/19 15:03	General View	 Load JPG	☒
84	09/05/19 15:03	General View	 Load JPG	☒
85	09/05/19 15:03	General View	 Load JPG	☒
86	09/05/19 15:03	General View	 Load JPG	☒
87	09/05/19 15:03	General View	 Load JPG	☒
88	09/05/19 15:03	General View	 Load JPG	☒
89	09/05/19 15:03	General View	 Load JPG	☒
90	09/05/19 15:03	General View	 Load JPG	☒
91	09/05/19 15:03	General View	 Load JPG	☒
92	09/05/19 15:03	General View	 Load JPG	☒
93	09/05/19 15:03	General View	 Load JPG	☒
94	09/05/19 15:03	General View	 Load JPG	☒
95	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
96	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
97	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
98	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
99	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
100	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
101	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
102	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
103	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
104	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
105	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
106	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
107	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
108	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
109	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
110	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
111	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
112	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
113	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
114	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
115	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
116	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
117	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
118	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
119	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
120	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
121	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
122	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
123	09/05/19 15:03	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	TC AutoClinic Pte Ltd (Lok Yang)	Thumbnail	Print
124	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
125	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
126	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
127	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
128	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
129	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
130	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
131	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
132	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
133	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
134	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
135	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
136	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
137	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
138	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
139	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
140	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
141	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
142	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
143	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
144	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
145	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
146	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
147	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
148	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
149	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
150	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
151	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
152	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
153	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
154	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
155	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
156	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
157	09/05/19 15:03	Reinspection Photo	 Load JPG	☒
158	09/05/19 15:04	Reinspection Photo	 Load JPG	☒
159	09/05/19 15:04	Reinspection Photo	 Load JPG	☒
160	09/05/19 15:04	Reinspection Photo	 Load JPG	☒
161	09/05/19 15:04	Reinspection Photo	 Load JPG	☒
162	09/05/19 15:04	Reinspection Photo	 Load JPG	☒
163	09/05/19 15:04	Reinspection Photo	 Load JPG	☒
164	09/05/19 15:04	Reinspection Photo	 Load JPG	☒
165	09/05/19 15:04	Reinspection Photo	 Load JPG	☒
166	09/05/19 15:04	Reinspection Photo	 Load JPG	☒
167	09/05/19 15:04	Reinspection Photo	 Load JPG	☒
168	09/05/19 15:04	Reinspection Photo	 Load JPG	☒
169	09/05/19 15:04	Reinspection Photo	 Load JPG	☒
170	09/05/19 15:04	Reinspection Photo	 Load JPG	☒
171	09/05/19 15:04	Reinspection Photo	 Load JPG	☒
172	09/05/19 15:04	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	TC AutoClinic Pte Ltd (Lok Yang)	Thumbnail	Print
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	09/05/19 14:38	pri contact	 Load PDF	
No	Finalized On	TC AutoClinic Pte Ltd (Lok Yang)	Thumbnail	Print
1	23/03/19 08:33	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	23/03/19 08:33	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	☒
3	23/03/19 08:33	Sketch Plan #3 [Linked Accident Report Documents]	 Load JPG	☒
4	23/03/19 08:33	Sketch Plan #4 [Linked Accident Report Documents]	 Load JPG	☒
5	23/03/19 08:33	Sketch Plan #5 [Linked Accident Report Documents]	 Load JPG	☒

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	TC AutoClinic Pte Ltd (Lok Yang)	Thumbnail	Print
1	23/03/19 08:36	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	TC AutoClinic Pte Ltd (Lok Yang)	Thumbnail	Print
1	23/03/19 08:25	Accident Photo	 Load JPG	☒
2	23/03/19 08:25	Accident Photo	 Load JPG	☒
3	23/03/19 08:25	Accident Photo	 Load JPG	☒
4	23/03/19 08:25	Accident Photo	 Load JPG	☒
5	23/03/19 08:25	Accident Photo	 Load JPG	☒
6	23/03/19 08:25	Accident Photo	 Load JPG	☒
7	23/03/19 08:25	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	TC AutoClinic Pte Ltd (Lok Yang)	Thumbnail	Print
1	23/03/19 08:33	Sketch Plan	 Load TIF	
2	23/03/19 08:33	Sketch Plan #2	 Load JPG	☒
3	23/03/19 08:33	Sketch Plan #3	 Load JPG	☒
4	23/03/19 08:33	Sketch Plan #4	 Load JPG	☒
5	23/03/19 08:33	Sketch Plan #5	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19005295/EQD3E2

Date: 16/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN30419418000

Claimant Vehicle
No: SLB5372RInsured Vehicle
No: SKN2756K

Date of Loss: 21/03/2019

Nature of Claim: TP

Claim
No: SNM19D201533C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLB5372R

Make & Model: HYUNDAI ELANTRA, 1.6 (A)

Reg. Date: 13/04/2016 (Man. Year: 2016)

Colour: Red

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: G4FGGU158673

Chassis No: KMHD841CMHU144115

Odometer: 64424 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Roadstone 7 mm

Rear Left Side: Roadstone 7 mm

Front Right Side: Roadstone 7 mm

Rear Right Side: Roadstone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,703.36	12,069.63	16,633.73	57.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,240.00	3,120.00	4,120.00	56.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,943.36	15,189.63	20,753.73	57.74
Approved Total (Overridden) (S\$)		12,150.00		
(S\$)	35,943.36	12,150.00	23,793.36	66.20
+ GST 7.00/7.00% (S\$)	2,516.04	850.50	1,665.54	66.20
Nett Amount (S\$)	38,459.40	13,000.50	25,458.90	66.20

INSPECTION

Date of Assignment: 09/05/2019

Date Inspected: 26/03/2019 Inspected At:

SK Automobile Pte Ltd (Toh Guan)
48 Toh Guan Road East #01-121,
Enterprise Hub
Singapore 608586

Estimated Period of Repair: 12.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 May 2019)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB5372R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	1,690.67 FL	*1,048.00 FL
2	1		*REAR BOOT LID LOGO EMBLEM	Necessary	82.14 FL	*34.00 FL
3	1		*REAR BOOT LID ELITE EMBLEM	Necessary	65.32 FL	*32.00 FL
4	1		*REAR BOOT LID ELANTRA EMBLEM	Necessary	78.42 FL	*32.00 FL
5	2		*REAR BOOT LID REFLECTOR LED LAMP LH / RH	Broken	1,329.80 FL	*1,329.80 FL
6	1		*REAR BOOT LID OUTER LOCK HANDLE SWITCH WITH REVERE CAMERA	Not Necessary	652.97 FL	*- FL
7	2		*REAR BOOT LID NUMBER PLATE LAMP LH / RH	Not Necessary	111.30 FL	*- FL
8	2		*REAR BOOT LID HINGES LH / RH	Repair	290.84 FL	*- FL
9	1		*REAR BOOT LID INNER UPHOLSTERY TRIM	Not Necessary	358.31 FL	*- FL
10	1		*REAR BOOT LID INNER HANDLE	Not Necessary	112.10 FL	*- FL
11	2		*REAR BOOT LID RUBBER GUIDE STOPPER LH / RH	Not Necessary	80.58 FL	*- FL
12	1		*REAR BOOT LID MECHANISM LOCK	Bent	208.70 FL	*208.70 FL
13	1		*REAR BOOT LID WEATHER STRIP	Torn	92.50 FL	*92.50 FL
14	1		*REAR BUMPER	Broken	489.24 FL	*489.24 FL
15	2		*REAR BUMPER REFLECTOR LH / RH	Broken	63.80 FL	*63.80 FL
16	2		*REAR BUMPER SIDE RETAINER LH / RH	Broken	88.60 FL	*88.60 FL
17	1		*REAR BUMPER INNER SIDE SHIELD RH	Not Necessary	145.65 FL	*- FL
18	1		*REAR BUMPER LOWER UNDER COVER LH	Broken	151.32 FL	*151.32 FL
19	2		*REAR BUMPER TOP BRACKET LH / RH	Not Necessary	51.42 FL	*- FL
20	1		*REAR BUMPER REINFORCEMENT	Dented	548.42 FL	*328.00 FL
21	1		*REAR BUMPER INNER BOOT LID ANTENA SENSOR	Broken	325.61 FL	*220.00 FL
22	1		*REAR BUMPER LOWER DIFFUSER	Cut	280.10 FL	*280.10 FL
23	1		*REAR BUMPER INNER BOOT LID ANTENA SENSOR WIRE HARNESS	Torn	198.27 FL	*198.27 FL
24	1		*REAR BLIND SPOT DETECTION SENSOR LH	Not Necessary	1,660.10 FL	*- FL
25	1		*REAR BLIND SPOT DETECTION SENSOR BRACKET LH	Not Necessary	186.20 FL	*- FL
26	1		*REAR BLIND SPOT DETECTION SENSOR WIRE HARNESS LH	Torn	219.40 FL	*219.40 FL
27	1		*REAR BLIND SPOT DETECTION SENSOR ABSORBER LH	Not Necessary	97.10 FL	*- FL
28	2		*REAR TAILLAMP LED LH / RH	Broken	1,753.80 FL	*1,753.80 FL
29	2		*REAR TAILLAMP INNER PANEL LH / RH	Not Necessary	717.56 FL	*- FL
30	1		*REAR END PANEL	Dented	480.72 FL	*480.72 FL
31	1		*REAR END PANEL INNER TOP GARNISH	Broken	159.80 FL	*159.80 FL
32	1		*REAR END PANEL INNER BOOT LID ANTENA SENSOR	Not Necessary	325.61 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
33	1		*REAR END PANEL LOCK STRIKER	Not Necessary	43.70 FL	*- FL
34	1		*SPARE TYRE PANEL	Dented	789.48 FL	*789.48 FL
35	1		*SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD	Torn	219.10 FL	*219.10 FL
36	1		*SPARE TYRE RETAINER LOCK	Broken	10.90 FL	*10.90 FL
37	2		*SPARE TYRE SIDE PANEL LH / RH	Not Necessary	491.24 FL	*- FL
38	2		*REAR SUB CHASSIS FRAME LH / RH	Not Necessary	2,378.20 FL	*- FL
39	2		*REAR SUB CHASSIS FRAME TOP PANEL LH / RH	Not Necessary	1,626.28 FL	*- FL
40	2		*REAR FENDER LH / RH	Repair	3,538.24 FL	*- FL
41	1		*REAR FENDER INNER UPHOLSTERY TRIM LH / RH	N/S Torn / O/S Not Necessary	415.80 FL	*207.90 FL
42	2		*REAR FENDER INNER SHIELD LH / RH	Not Necessary	224.60 FL	*- FL
43	2		*REAR FENDER STONE PROTECTIVE STICKER LH / RH	Necessary	54.04 FL	*54.04 FL
44	1		*REAR WINDSCREEN MOULDING	Not Necessary	129.80 FL	*- FL
45	1		*REAR EXHAUST SILENCER BOX	Dented	789.00 FL	*789.00 FL
46	1		*REAR EXHAUST ALUMINIUM HEAT SHIELD	Dented	130.00 FL	*130.00 FL
47	1		*FRONT GRILLE }	Broken	1,082.90 FL	*461.00 FL
48	1		*FRONT GRILLE CHROME MOULDING }		256.20 FL	*- FL
49	1		*FRONT GRILLE LOGO EMBLEM	Necessary	56.90 FL	*56.90 FL
50	2		*FRONT HEADLAMP LH / RH	Broken	3,512.80 FL	*2,399.60 FL
51	1		*FRONT BUMPER	Broken	675.94 FL	*494.40 FL
52	1		*FRONT BUMPER REINFORCEMENT	Repair	548.49 FL	*- FL
53	1		*FRONT BUMPER TOP RUBBER SEAL	Not Necessary	65.30 FL	*- FL
54	2		*FRONT BUMPER SIDE RETAINER LH / RH	Broken	87.22 FL	*87.22 FL
55	2		*FRONT BUMPER CORNER RETAINER LH / RH	Broken	173.40 FL	*173.40 FL
56	1		*FRONT BUMPER INNER SPONGE	Broken	212.83 FL	*118.70 FL
57	2		*FRONT BUMPER TOP BRACKET	Not Necessary	173.40 FL	*- FL
58	1		*FRONT BUMPER LOWER BEAM	Not Necessary	81.00 FL	*- FL
59	1		*FRONT BUMPER LOWER UNDER COVER	Not Necessary	321.57 FL	*- FL
60	1		*FRONT BUMPER NUMBER PLATE GARNISH	Dented	189.50 FL	*35.00 FL
61	1		*FRONT SUPPORT PANEL	Crushed	1,159.70 FL	*949.30 FL
62	1		*FRONT SUPPORT PANEL TOP GARNISH	Broken	179.50 FL	*179.50 FL
63	1		*AIRCON CONDENSER	Not Necessary	1,125.50 FL	*- FL
64	2		*AIRCON CONDENSER AIR GUIDE LH / RH	Crushed	77.80 FL	*77.80 FL
65	2		*SET REAR BOOT LID REFLECTOR LED LAMP CLIPS LH / RH	Necessary	20.00 FS	*10.00 FS
66	1		*SET REAR BOOT LID INNER UPHOLSTERY TRIM CLIPS	Necessary	50.00 FS	*20.00 FS
67	1		*REAR BOOT LID SEALANT	Necessary	100.00 FS	*20.00 FS
68	1		*SET REAR BUMPER REVERSE SENSOR	Broken	280.00 FS	*200.00 FS
69	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*20.00 FS
70	2		*SET REAR TAILLAMP CLIPS LH / RH	Necessary	40.00 FS	*10.00 FS
71	2		*REAR TAILLAMP INNER PANEL SEALANT LH / RH	Not Necessary	60.00 FS	*- FS
72	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
73	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*20.00 FS
74	1		*SPARE TYRE PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
75	2		*SET REAR FENDER INNER UPHOLSTERY TRIM CLIPS LH / RH	Necessary	120.00 FS	*20.00 FS
76	2		*SET REAR FENDER INNER SHIELD CLIPS LH / RH	Necessary	80.00 FS	*10.00 FS
77	1		*REAR EXHAUST GASKET	Necessary	25.00 FS	*20.00 FS
78	1		*REAR WINDSCREEN SEALANT WITH PRIMER	Not Necessary	100.00 FS	*- FS
79	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FS	*10.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
80	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*20.00 FS
81	1		*SET FRONT BUMPER RIVETS	Necessary	50.00 FS	*20.00 FS
82	1		*SET FRONT BUMPER NUMBER PLATE WITH CASING	Dented	65.00 FS	*35.00 FS
83	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
84	2		*SET FRONT FENDER INNER SHIELD CLIPS LH / RH	Necessary	120.00 FS	*10.00 FS
85	1		*RADIATOR COOLANT	Necessary	80.00 FS	*20.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	35,486.70	14,958.29
- List Item Discount on L Items 20.00/20.00% (\$\$)	6,783.34	2,888.66
Total Parts (\$\$)	28,703.36	12,069.63

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION (REAR)	New	2,000.00	800.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA (REAR)	New	1,800.00	900.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	200.00	30.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	90.00	30.00
5	TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION	New	380.00	0.00
6	TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR	New	250.00	120.00
7	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT TO PERFORM FACILITATE REPAIRS	New	260.00	0.00
8	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	New	80.00	20.00
9	TO DISMANTLE & REPLACED REAR BOOT LID REVERSE CAMERA WITH SETTING	New	80.00	20.00
10	TO DISMANTLE & REPLACED REAR EXHAUST SILENCER BOX WITH REALIGN EXHAUST MID PIPE & RUBBER MOUNTING	New	180.00	80.00
11	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	New	280.00	50.00
12	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	New	80.00	30.00
13	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION (FRONT)	New	600.00	500.00
14	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA (FRONT)	New	600.00	400.00
15	TO APPLY ANTI-RUST & TUFF KOTE	New	40.00	20.00
16	TO PERFORM LIGHTING & WIRING CHECK	New	80.00	0.00
17	TO DISMANTLE & REINSTALL AIRCON CONDENSOR WITH REFILL AIRCON GAS	New	120.00	60.00
18	TO DISMANTLE & REINSTALL RADIATOR WITH REFILL RADIATOR COOLANT & HIGH PRESSURE TEST	New	120.00	60.00
Gross Labour Cost (\$\$)			7,240.00	3,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >