FASTECT AUTO PTE LTD BLK1 KAKI BUKIT AVE 6 #01-46,48,50 AUTOBAY SINGAPORE 417883 VEHICLE NO:SJQ 161K **PARTICULAR** QTY De Hom \$1,660.00 -1350 **REAR BUMPER** 1 PCS \$170.00 X 11 **REAR BUMPER SIDE RETAINERS @\$85.00** 2 PCS un \$50.00 **REAR BUMPER CLIPS** 1 SET \$220.00 📈 REAR BUMPER REINFORCEMENT 1 PCS \$691.00 0 **REAR END PANEL** 1 PCS \$280.00 2005. REAR BUMPER REVERSE SENSOR 1 SET \$3,071.00 LABOUR CHARGES: \$50.00 20 TO CHECK WIRING \$80.00 TO DISMANTLE & REPLACING REVERSE SENSOR \$120.00 60 TO DISMANTE & REFIX SEAT, CUSHION UPHOLSTERY 11 \$50.00 × TO SPRAY RUST PROOFING \$800.00 400 LABOUR FOR PANEL BEATING & REPLACING PARTS \$800.00 400 TO PUTTY & SPRAY PAINTING TO \$4,971.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9-1400 202 9-1120 5N+142-1130 2250 202 1800